


80-inch Hot Strip Mill - R3 Area Orientation

Baseline vocabulary and spatial context for model comprehension. This is a conceptual test aid, not a plant layout or engineering drawing.

Document ID	Incident	Record type	Status
R3-DEF-001	R3 carrier beam - 10/14/2024	Application test evidence	Synthetic / controlled



Terms the model should be able to resolve

Term	Working meaning in this test case	Boundary / caution	Status
R3 roughing mill stand	The third stand in the roughing mill area referenced by the incident.	Exact bay coordinates and elevations are not provided.	Historical source fact
Exit carrier beam	The beam reported as falling from the yoke into the mill pit.	Its detailed design and retention method require an equipment record.	Historical source fact
Yoke	The upper support location on which the carrier-beam link was reported to rest.	The drawing geometry and permitted link movement are not established here.	Historical source fact

Term	Working meaning in this test case	Boundary / caution	Status
R3 mill pit	The below-floor work area into which the beam fell.	Access controls and confined-space classification require separate records.	Historical source fact
Sled and scaffold platform	Objects in the pit on which the beam landed.	As-found locations and damage are evidence, not shown to scale here.	Historical source fact
Top operator side	The side from which a small mill window liner was reported to fall.	Compass direction is intentionally not assigned.	Historical source fact

What this document does not establish

- The mechanical retention design or required stopper arrangement.
- The exact pre-event position of the link inside the yoke.
- Whether the raised roll-balance condition was permitted by procedure.
- The sequence or physical mechanism that caused the beam to leave the yoke.