

Safety Incident Report

Document No: INC-00018 | Refinery Operations — Confidential Internal Document

Incident Date	24 Jun 2023	Severity	MAJOR
Zone	Fluid catalytic cracker	Reported By	Suman Acharya (Panel Operator)
Status	Closed	Investigation Lead	Anita Limbu (Safety Officer)

1. Incident Description

A major safety event was reported in the Fluid Catalytic Cracker (FCC) unit during the 14:00-22:00 shift. The reporting operator identified an abnormal process condition during routine panel monitoring and initiated the site's incident escalation procedure. The unit was brought to a safe operating condition without injury to personnel.

2. Immediate Response

Shift supervisor was notified within the required response window. Affected equipment in the FCC unit was placed under increased monitoring, and the Process Safety & HSE team attended the unit to assess the condition. No evacuation was required; the incident was contained to the immediate process area.

3. Root Cause Summary

Investigation attributed the event to a process deviation in the FCC unit consistent with known degradation patterns on rotating equipment in this zone (compressor surge / bearing wear). Contributing factors and full root-cause detail are recorded in the associated corrective work order for the affected equipment.

4. Corrective Action

Corrective action was logged and closed following inspection and remediation of the affected equipment. The Reliability team has been directed to review the maintenance interval for comparable rotating equipment in the FCC unit as a preventive measure.

Investigated by	Anita Limbu	Signature	
Closed by	HSE Manager	Date Closed	01 Jul 2023