




Nothing but **HEAVY DUTY.**

MILWAUKEE VIETNAM Trace Forward

Process & Equipment Selection Framework



Layout Direction				Console Line							Packing Line	
Process				Assembly	Openlink			Functional Test (EOL)			Packing	
Data Requirement				N/A	Tool ID/Dummy Qr + MPBID			Tool ID/Dummy Qr + Test Result			Tool ID/Dummy Qr + MPBID + S/N	
Implementation Method				N/A	Openlink Auto	M18 OL Adapter portable	Openlink Portable Scanner	Tool ID Reader	Dummy QR Reader	MPBID Reader	Onekey (Onekey Machine)	Non-Onekey (Product Checkpoint unit -PCU)
												
Model	Has Openlink	M18	N/A		High	Middle	Low	High	Middle	Low	High	Middle
		M12	N/A		N/A	N/A	High	High	Middle	Low	High	Middle
		MX/OPE	N/A		N/A	High	Middle	High	Middle	Low	High	Middle
	Non-Openlink	All model	N/A		N/A	N/A	N/A	N/A	High	N/A	N/A	High

➤ Note:

For each model and process, select the implementation method in the following order:

If a higher-priority option is not available, use the next available option.




EOL machine

M18 EOL Adapter Portable




EOL Adapter Customize



1. QR scanning & Openlink-TraceForward interface
2. Direct physical contact with the Tools during operation.
3. Converts and supplies power to the tool
4. Flexible and movable, not fixed to the machine.

1. QR scanning & Openlink-TraceForward interface
2. Direct physical contact with the Tools during operation.
3. Converts and supplies power to the tool
4. Fixed to the machine.




Openlink machine

EOL Adapter Customize




1. QR scanning & Openlink-TraceForward interface
2. Direct physical contact with the Tools during operation.
3. Converts and supplies power to the tool
4. Fixed to the machine.



M18 OL Adapter Portable




1. QR scanning & Openlink-TraceForward interface
2. Direct physical contact with the Tools during operation.
3. Extends the tool power supply cable.
4. Flexible and movable, not fixed to the machine.



Openlink Portable scanner



1. QR scanning & Openlink-TraceForward interface.
2. Doesn't contact with the tool during operation
3. Flexible and movable, not fixed to the machine.





Nothing but **HEAVY DUTY.**[®]

THE END