PLC - Path-Element Interaction

Group A2_E
Diogo Oliveira
João Pinheiro
Lorena Fernández
Nuno Pacheco

In order to better describe the interaction between paths and conveyors/machines, it was decided to represent them with the following diagrams and blocks, instead of doing an exhaustive description of all possible paths, conveyors and machines in an UML Sequence Diagram.

A conveyor/machine has the following variables accessible from outside of the block:

- Freel_x and FreeO directly connected to the blocks next to it;
- Sendx() and PushO_x connected to multiple paths that can use the block.

A path has the connections to the conveyors/machines, an activation variable (activatePath()), an EndOfPath variable and a confirmation that the MES have received the EndOfPath.







