## ASSIGNMENT 1

```
int moisture = 0;
void setup()
 pinMode(A0, OUTPUT);
 pinMode(A1, INPUT);
 Serial.begin(9600);
 pinMode(8, OUTPUT);
}
void loop()
{
 // Apply power to the soil moisture sensor
 digitalWrite(A0, HIGH);
 delay(10); // Wait for 10 millisecond(s)
 moisture = analogRead(A1);
 // Turn off the sensor to reduce metal corrosion
 // over time
 digitalWrite(A0, LOW);
 Serial.println(moisture);
 digitalWrite(8, LOW);
}
```

