NO KICKDOWN [GW6A-EL, GW6AX-EL]

id050320101600

TROUBLESHO OTING ITEM	No kickdown		
DESCRIPTION	Does not downshift when accelerator pedal is fully depressed within kickdown range.		
POSSIBLE	1. Signal malfunction		
CAUSE	APP sensor malfunction		

Diagnostic procedure

STEP	INSPECTION		ACTION
1	INSPECT SIGNAL PARTS FOR MALFUNCTION	Yes	Repair or replace any malfunctioning parts according to the
	Inspect the value at the following PCM PID using		inspection result.
	the M-MDS.	No	Symptom troubleshooting is completed.
	(See ON-BOARD DIAGNOSTIC TEST		
	[SKYACTIV-D 2.2].)		
	APP (APP sensor)		
	Is there any malfunction?		