FRONT SIDE FRAME (PARTIAL CUTTING) REMOVAL [PANEL REPLACEMENT]

id098008742100


Symbol Mark

SYMBOL MARK	MEANING
	SPOT WELDING
	ROUGH CUT LOCATION


ac5jjb00000063

Removal Procedure

- 1. Drill the 4 locations indicated by (A) shown in the figure, then remove suspension mounting reinforcement and outer frame reinforcement.
- Rough cut location indicated by (B) shown in the figure.
 Drill the 6 locations indicated by (C) shown in the figure, then remove the front side frame (inner).



4. Rough cut location indicated by (D) shown in the figure.5. Drill the 3 locations indicated by (E) shown in the figure.



6. Remove the front side frame (outer).