## **KEYLESS BEEPER INSPECTION**

id091400515100

 Because no oscillation circuit is integrated in the keyless beeper, a beep sound is not heard by applying rated voltage to the keyless beeper itself. To inspect the keyless beeper, refer to symptom troubleshooting. (See ANSWER-BACK BUZZER DOES NOT SOUND [SECURITY AND LOCKS].)