

SM-G928X_REV0.6_LDU

2015.07.02

sheet01: GSM/WCDMA/LTE RF

sheet02: TRANCEIVER, DRX

sheet03: S333, CP_PMIC

sheet04: SENSORS, HUB, GPS, BT/WIFI, NFC

sheet05: AP(ISTOR), SIM SOCKET


sheet06: AP(ISTOR) POWER PART


sheet07: AP PMIC, SUB PMIC, Wireless Charging, MST


sheet08: AUDIO, SUB PCB CON.


sheet09: CAMERA, DISPLAY, DCDC


		PAM1000	U9407	RF part	U9344 R5100/R5101 UCP302 R3035/R3036	SIM5000/SIM500 R3019/R3457 R5093/R5094
1	928F/3CA/SS	FHIM1160-HSE	HFQ8X4WJB-381	BAND 20	3CA S5M933DA02-6031 R3035 3CA SA5333DA01-L030 R5100	SIM5000 R5094 R3019
	928C/2CA/SS	LMT WITFO -H26	MF08X4WJ8-301	BAND 20	2CA S5M933DA02-6331 R3036 2CA SA5333DA01-L330 R5101	SIM5000 R5094 R3019
	928[/3CA/\$\$	SEY 780 42	WF08X4WJ8-304	BAND 28 + BAND 48	3CA S5M933DA02-6031 R3035 3CA SA5333DA01-L030 R5100	SIM5000 R5094 R3019
	928G/2CA/SS	SEY 780 42	HF08X4WJ8-304	BAND 28 + BAND 40	2CA S5M933DA02-6331 R3036 2CA SA5333DA01-L330 R5101	SIM5000 R5094 R3019
	9287C/2CA/DS	SEY 780 42	ME06X4878-304	BAND 28 • BAND 40/41	2CA S5M933DA02-6331 R3036 2CA SA5333DA01-L330 R5101	SIM5001 R5093 R3457

























Setup(2015-05-20)_HHP



AON1605(TR7000): IT'S Wrong Polarity possibility. Check the Pin1 2007-010848(R10004): Check! Bott om Surface of Component

Setup(2015-05-20)_HHP



AON1605(TR7000): IT'S Wrong Polarity possibility. Check the Pin1 2007-010848(R10004): Check! Bott om Surface of Component