7-1. Components on the Rear Case





7-2. Pre-requisite



7-3. Parts which must be changed after repair

BOM description & part code	Image	Remarks
A/S-TAPE MAIN WINDOW [GH81-16187A]		Replace for OCTA repair
A/S-TAPE LCD GASKET SIDE [GH81-16209A]		

7-4. Disassembly



- 1) Put the device on hot plate as following below heating condition and detach OCTA.
- SOC 68%↓: 70°C/10~20 minute
- SOC 68%↑: 70°C/10~20 minute
- * Please confirm the heating condition released lastly, and follow it.



2 Detach the LCD assembly.



※ Caution

1) Be care of scratch

3 Unscrew 18 Point and disassemble SIM Tray from device.





X Caution

1) Be care of scratch

4 Disa

Disassemble Rear.



X Caution

1) Be care of Rear damage

- **※** Caution
- 1) Be care of scratch
- 2) Be care of Rear and connector damage

5 Unscrew PBA 2points.



6 Disassemble Front CAM connector of PBA.



- **※** Caution
- 1) Be careful not to damage the PBA

- **X** Caution
- 1) Be careful not to damage the PBA

7 Detach other components.



8 Detach SPK from Front Ass'y.



- ***** Caution
- 1) Be care of several kinds of damage

- Caution
- 1) Be careful not to damage the SPK.

9 Detach RCV from Front Ass'y.




10 Detach Motor from Front Ass'y.



- Caution
- 1) Be careful not to damage the RCV.

- Caution
- 1) Be careful not to damage the Motor.

7-5. Assembly



1 Attach SPK on Front Ass'y.



2 Attach RCV on Front Ass'y.



- Caution
- 1) Be care of SPK damage.


※ Caution

1) Be care of RCV damage.

3 Attach Motor on Front Ass'y.



4 Attach Front CAM, MAIN CAM on PBA.



- Caution
- 1) Be care of Motor damage.

- Caution
- 1) Be care of PBA damage

5 Ass

Assemble PBA to Front case and tightened 2 points of PBA screw.

* Torque Value : 1.0±0.1kgfcm



Assemble the REAR in sequence. (1.Bottom 2. Top)



- Caution
- 1) Be care of scratch and REAR damage
- 2) Check for contact damage.(red area)

- Caution
- 1) Be care of scratch and REAR damage
- 2) Check for contact damage.(red area)

7


Screw insertion 18 Point.

* Torque Value : 1.3 ± 0.1 kgfcm



8

Assemble rework tape on OCTA.



Caution

1) Be care of Rear damage

X Caution

1) Be care of Tape damage

