

SM-G928T_REV0.6

2015.07.03

sheet01: GSM/WCDMA/LTERF

sheet02: TRANCEIVER, DRX

sheet03: S333, CP_PMIC

sheet04: SENSORS, HUB, GPS, BT/WIFI, NFC


sheet05: AP(ISTOR), SIM SOCKET


sheet06: AP(ISTOR) POWER PART


sheet07: AP PMIC, SUB PMIC, Wireless Charging, MST


sheet08: AUDIO, SUB PCB CON.


sheet09: CAMERA, DISPLAY, DCDC
























Model: Revision: Manufacture Count: Charge: Contact: Date: Routing: Resin:


Setup(2015-05-20)_HHP



AON1605(TR7000): IT'S Wrong Polarity possibility. Check the Pin1 2007-010848(R10004): Check! Bott om Surface of Component

Model: Revision: Manufacture Count: Charge: Contact: Date: Routing: Resin:

Setup(2015-05-20)_HHP



AON1605(TR7000): IT'S Wrong Polarity possibility. Check the Pin1 2007-010848(R10004): Check! Bott om Surface of Component