

SM_A810S_REV0.5

2016.08.18

sheet01: GSM/WCDMA/LTE/CDMARF

sheet02: TRANSCEIVER(SHNNON933) / CP(SHANNON333) / CP PMIC

sheet03: BT/WIFI/GPS/TDMB/NFC

sheet04: AP (EXYNOS7420 - ISTOR)


sheet05: AP (EXYNOS7420 - ISTOR)


sheet06: PMIC/IF PMIC/BATTERY CON


sheet07: AUDIO/ IF SUB CON


sheet08: SIM / SD / BTP / SENSOR / OCTA / CAM / UPPER SUB


| Topon | Topo
























VX_Setup(2016-01-20)_HHP



AON1605(TR7001): IT'S Wrong Polar ity possibility. Check the Pin1

Model : Revision :

Manufacture Count:

Charge:
Contact:
Date:
Routing:
Resin:

⊠	
H	
+	
×	

0	
Φ	
Φ	
0	
⊠	
H	
+	
×	

0	
Φ	
0	Г
0	
	Г
⊠	
8	
+	Г
×	

0	
Θ	
Φ	Г
0	
0	Г
⊠	
B	
+	
×	

⊖	
Φ	
0	П
0	
⊠	
B	
+	
×	Г

VX_Setup(2016-01-20)_HHP



AON1605(TR7001): IT'S Wrong Polar ity possibility. Check the Pin1

Model : Revision :

Manufacture Count:

Charge:
Contact:
Date:
Routing:
Resin: