			18.7	M16C	Mover
			19.7	P2SSE	Colocar en posición
Soltar	RL1	2.0	2.0	RL1	Soltar
Lcd 16x2					Cable MH blanco
Alcanzar	R16A	11.4	17.0	R16C	Alcanzar
Asir	G1A	2.0	2.0	G1A	Asir
			18.7	M16C	Mover
			19.7	P2SSE	Colocar en posición
Soltar	RL1	2.0	2.0	RL1	Soltar
Protoboar					Cable café lcd
Alcanzar	R12A	9.6	9.6	R12A	Alcanzar
Asir	G1A	2.0	2.0	G1A	Asir
			12.2	M10B	Mover
			19.7	P2SSE	Colocar en posición
Soltar	RL1	2.0	2.0	RL1	Soltar
Protoboar					Cable negro lcd
Alcanzar	R12A	9.6	9.6	R12A	Alcanzar
Asir	G1A	2.0	2.0	G1A	Asir
			12.2	M10B	Mover
			19.7	P2SSE	Colocar en posición
Soltar	RL1	2.0	2.0	RL1	Soltar
Protoboar					Cable blanco lcd
Alcanzar	R12A	9.6	9.6	R12A	Alcanzar
Asir	G1A	2.0	2.0	G1A	Asir
			12.2	M10B	Mover
			19.7	P2SSE	Colocar en posición
Soltar	RL1	2.0	2.0	RL1	Soltar
Protoboar					Cable blanco lcd
Alcanzar	R12A	9.6	9.6	R12A	Alcanzar
Asir	G1A	2.0	2.0	G1A	Asir
			12.2	M10B	Mover
			19.7	P2SSE	Colocar en posición
Soltar	RL1	2.0	2.0	RL1	Soltar
	TMU Totales	1	287.3		