

CÓDIGO	REVISÃO	DATA
FRGH.049		

REGISTRO DE INVESTIGAÇÃO DE PRODUTO

Caso algum campo não seja aplicável, preencha com N/A.

1. IDENTIFICAÇÃO DO PRODUTO

Produto:	HealthGo Air
Data:	06/05/2026
Número de Série / Lote:	202510130003
HGID:	25090920
Cliente (caso aplicável):	Tiago Costa De Almeida

2. INFORMAÇÕES DO PROBLEMA

PROBLEMA RELATADO PELO CLIENTE:
Equipamento piscando o Led vermelho
PROBLEMA CONSTATADO PELO SUPORTE:
Problema na autenticação de componentes internos

3. ANÁLISE TÉCNICA INTERNA

RESULTADO DA INVESTIGAÇÃO:
Foi realizado o teste de reset do equipamento, subimos o firmware 561 de testes e a versão de Software com Debug para analisar os logs. O equipamento está com falha de autenticação no HTU, provavelmente há falha na placa ou na solda. Necessário recolhimento para tratativa.
OBSERVAÇÕES:
GoPremium: NÃO

CÓDIGO	REVISÃO	DATA
FRGH.049		

4. EVIDÊNCIA FOTOGRÁFICA

```

C:\WINDOWS\system32\cmd. X + v
2026-05-06T14:32:01.2006492-03:00 INF Prediction parameter retrieved successfully predictionParam=102
2026-05-06T14:32:01.2011764-03:00 INF Heartbeat persistence-only mode stopped
2026-05-06T14:32:01.2011764-03:00 INF Sensor monitor started
2026-05-06T14:32:02.2617429-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="\x1b[0;31mE (3022) gpio: gpio_in
tall_isr_service(502): GPIO isr service already installed\x1b[0m\n"
2026-05-06T14:32:02.2713683-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="CHAMBER: Erro em htU31d_update().
\n"
2026-05-06T14:32:02.471089-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="MBER: Erro em htU31d_update(). \n"
2026-05-06T14:32:02.6704203-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="R: Erro em htU31d_update(). \n"
2026-05-06T14:32:02.8711878-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="AMBER: Erro em htU31d_update(). \
n"
2026-05-06T14:32:03.0703872-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="Erro em htU31d_update(). \n"
2026-05-06T14:32:03.2711129-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="MBER: Erro em htU31d_update(). \n
"
2026-05-06T14:32:03.4711394-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="ER: Erro em htU31d_update(). \n"
2026-05-06T14:32:03.6700594-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="HTU31D: htU31d_reset(). \n"
2026-05-06T14:32:03.6705681-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="ro em htU31d_update(). \n"
2026-05-06T14:32:03.8613331-03:00 WRN Received error from device error=INITIALIZATION_FAIL
2026-05-06T14:32:03.8619348-03:00 WRN FULL ERROR protoErr="payloadType:ERROR_EVENT errorCode:INITIALIZATION_FAIL descrip
tion:"\n\nSM: INITIALIZE Erro no logger. \n\n"
2026-05-06T14:32:03.8624784-03:00 WRN ERROR CODE ErrorCode=INITIALIZATION_FAIL
2026-05-06T14:32:03.8630355-03:00 WRN ERROR DESCRIPTION Description="\nSM: INITIALIZE Erro no logger. \n"
2026-05-06T14:32:03.8706592-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="TU31D: Erro 1 em i2c_writing(): 4
, sensor 0 reset. \n"
2026-05-06T14:32:03.8712387-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="CHAMBER: Erro em htU31d_update().
\n"
2026-05-06T14:32:04.0711263-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="BER: Erro em htU31d_update(). \n"
2026-05-06T14:32:04.4704037-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="o em htU31d_update(). \n"
2026-05-06T14:32:04.6705751-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="htU31d_update(). \n"
2026-05-06T14:32:04.8705042-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="d_update(). \n"
  
```

5. DISPOSIÇÃO FINAL


X Recolhimento do produto

Atualização de firmware

Recalibração Remota

CÓDIGO	REVISÃO	DATA
FRGH.049		

ASSINATURA

A handwritten signature in black ink, appearing to read 'André Luiz de Souza', is written across the signature box. The signature is stylized with a large, sweeping horizontal stroke and a vertical stroke intersecting it.

Analista responsável: André Luiz de Souza