

CÓDIGO	REVISÃO	DATA
FRGH.049		

REGISTRO DE INVESTIGAÇÃO DE PRODUTO

Caso algum campo não seja aplicável, preencha com N/A.

1. IDENTIFICAÇÃO DO PRODUTO

Produto:	HealthGo Air
Data:	20/04/2026
Número de Série / Lote:	202603230019
HGID:	26040203
Cliente (caso aplicável):	Bios Nucleo Do Aparelho Digestivo Ltda

2. INFORMAÇÕES DO PROBLEMA

PROBLEMA RELATADO PELO CLIENTE:
O aparelho está piscando o led vermelho intermitentemente e não reconhece o dispositivo no Software.
PROBLEMA CONSTATADO PELO SUPORTE:
Falha de autenticação da placa

3. ANÁLISE TÉCNICA INTERNA

RESULTADO DA INVESTIGAÇÃO:
Foi realizado uma ação corretiva para solucionar o problema do aparelho com o led vermelho em conjunto com o Chefe da Engenharia. Alteramos o Software, o Firmware e identificamos no terminal de logs falha no sensor TGS2611. Necessário recolhimento para investigação.
OBSERVAÇÕES:
Equipamento NOVO, nunca utilizado!

CÓDIGO	REVISÃO	DATA
FRGH.049		

4. EVIDÊNCIA FOTOGRÁFICA

```

2026-04-28T10:41:49.5128725-03:00 WRN ERROR CODE ErrorCode=INITIALIZATION_FAIL
2026-04-28T10:41:49.5128725-03:00 WRN ERROR DESCRIPTION Description="\nSM: INITIALIZE Erro no logger. \n"
2026-04-28T10:41:49.514259-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="SM: INITIALIZE Erro no logger. \n"
2026-04-28T10:41:49.5511228-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="MCP3564: canal 3 fora dos limites, conversor 0. \n"
2026-04-28T10:41:49.7512195-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="MCP3564: canal 3 fora dos limites, conversor 0. \n"
2026-04-28T10:41:49.9507985-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="MCP3564: canal 3 fora dos limites, conversor 0. \n"
2026-04-28T10:41:50.1508778-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="MCP3564: canal 3 fora dos limites, conversor 0. \n"
2026-04-28T10:41:50.3509002-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="MCP3564: canal 3 fora dos limites, conversor 0. \n"
2026-04-28T10:41:50.5509009-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="MCP3564: canal 3 fora dos limites, conversor 0. \n"
2026-04-28T10:41:50.751073-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="MCP3564: canal 3 fora dos limites, conversor 0. \n"
2026-04-28T10:41:50.9513477-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="MCP3564: canal 3 fora dos limites, conversor 0. \n"
2026-04-28T10:41:51.1514742-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="MCP3564: canal 3 fora dos limites, conversor 0. \n"
2026-04-28T10:41:51.3508723-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="MCP3564: canal 3 fora dos limites, conversor 0. \n"
2026-04-28T10:41:51.5109942-03:00 WRN Received error from device error=INITIALIZATION_FAIL
2026-04-28T10:41:51.5118842-03:00 WRN FULL ERROR protoErr="payloadType:ERROR_EVENT errorCode:INITIALIZATION_FAIL description:""\nSM: INITIALIZE Erro no log
ger. \n""
2026-04-28T10:41:51.512389-03:00 WRN ERROR CODE ErrorCode=INITIALIZATION_FAIL
2026-04-28T10:41:51.512389-03:00 WRN ERROR DESCRIPTION Description="\nSM: INITIALIZE Erro no logger. \n"
2026-04-28T10:41:51.514368-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="SM: INITIALIZE Erro no logger. \n"
2026-04-28T10:41:51.5508741-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="MCP3564: canal 3 fora dos limites, conversor 0. \n"
2026-04-28T10:41:51.7517504-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="MCP3564: canal 3 fora dos limites, conversor 0. \n"
2026-04-28T10:41:51.9516723-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="MCP3564: canal 3 fora dos limites, conversor 0. \n"
2026-04-28T10:41:52.1503277-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="MCP3564: canal 3 fora dos limites, conversor 0. \n"
2026-04-28T10:41:52.3509442-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="MCP3564: canal 3 fora dos limites, conversor 0. \n"
2026-04-28T10:41:52.5516877-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="MCP3564: canal 3 fora dos limites, conversor 0. \n"
2026-04-28T10:41:52.7511023-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="MCP3564: canal 3 fora dos limites, conversor 0. \n"
2026-04-28T10:41:52.9513344-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="MCP3564: canal 3 fora dos limites, conversor 0. \n"
2026-04-28T10:41:53.1508696-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="MCP3564: canal 3 fora dos limites, conversor 0. \n"
2026-04-28T10:41:53.3508693-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="MCP3564: canal 3 fora dos limites, conversor 0. \n"
2026-04-28T10:41:53.5102856-03:00 WRN Received error from device error=INITIALIZATION_FAIL
2026-04-28T10:41:53.5102856-03:00 WRN FULL ERROR protoErr="payloadType:ERROR_EVENT errorCode:INITIALIZATION_FAIL description:""\nSM: INITIALIZE Erro no log
ger. \n""
2026-04-28T10:41:53.5129211-03:00 WRN ERROR CODE ErrorCode=INITIALIZATION_FAIL
2026-04-28T10:41:53.5129211-03:00 WRN ERROR DESCRIPTION Description="\nSM: INITIALIZE Erro no logger. \n"
2026-04-28T10:41:53.5135118-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="SM: INITIALIZE Erro no logger. \n"
2026-04-28T10:41:53.5516722-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="MCP3564: canal 3 fora dos limites, conversor 0. \n"
2026-04-28T10:41:53.7509338-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="MCP3564: canal 3 fora dos limites, conversor 0. \n"
2026-04-28T10:41:53.9516052-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="MCP3564: canal 3 fora dos limites, conversor 0. \n"
2026-04-28T10:41:54.1512165-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="MCP3564: canal 3 fora dos limites, conversor 0. \n"

```

5. DISPOSIÇÃO FINAL


X Recolhimento do produto

Atualização de firmware

Recalibração Remota

CÓDIGO	REVISÃO	DATA
FRGH.049		

ASSINATURA

A handwritten signature in black ink, appearing to read 'André Luiz de Souza', is written over a horizontal line. The signature is stylized with a large, sweeping 'A' and a long, horizontal stroke.

Analista responsável: André Luiz de Souza