

CÓDIGO	REVISÃO	DATA
FRGH.049		

REGISTRO DE INVESTIGAÇÃO DE PRODUTO

Caso algum campo não seja aplicável, preencha com N/A.

1. IDENTIFICAÇÃO DO PRODUTO

Produto:	HealthGo Air
Data:	09/04/2026
Número de Série / Lote:	202509260008
HGID:	26021005
Cliente (caso aplicável):	Kaline Bezerra Nobre

2. INFORMAÇÕES DO PROBLEMA

PROBLEMA RELATADO PELO CLIENTE:
Aparelho piscando o led vermelho
PROBLEMA CONSTATADO PELO SUPORTE:
Aparelho com falha na autenticação do HTU

3. ANÁLISE TÉCNICA INTERNA

RESULTADO DA INVESTIGAÇÃO:
O HTU não autentica no software e nem na autenticação padrão do aparelho. Provavelmente há um deslocamento na placa ou até mesmo uma falha de encaixe. Necessário recolhimento para investigação.
OBSERVAÇÕES:
N/A

4. EVIDÊNCIA FOTOGRÁFICA

CÓDIGO	REVISÃO	DATA
FRGH.049		

```

C:\WINDOWS\system32\cmd. X + v
2026/04/06 14:50:15 C:/Users/HealthGo/healthgo/air_desktop/internal/dal/sql_breath.go:228 record not found
[0.000ms] [rows:0] SELECT * FROM 'breaths' WHERE exam_id = 4 AND 'breaths'.'deleted_at' IS NULL ORDER BY 'breaths'.'id'
DESC LIMIT 1
2026/04/06 14:50:15 C:/Users/HealthGo/healthgo/air_desktop/internal/dal/sql_breath.go:228 record not found
[0.529ms] [rows:0] SELECT * FROM 'breaths' WHERE exam_id = 3 AND 'breaths'.'deleted_at' IS NULL ORDER BY 'breaths'.'id'
DESC LIMIT 1
2026-04-06T14:50:16.6159019-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="\x1b[0;31mE (3112) gpio: gpio_ins
tall_isr_service(502): GPIO isr service already installed\x1b[0m\n"
2026-04-06T14:50:18.216446-03:00 WRN Received error from device error=INITIALIZATION_FAIL
2026-04-06T14:50:18.217-03:00 WRN FULL ERROR protoErr="payloadType:ERROR_EVENT errorCode:INITIALIZATION_FAIL descripti
on:"\n\nSM: INITIALIZE Erro no logger. \n\n"
2026-04-06T14:50:18.217562-03:00 WRN ERROR CODE ErrorCode=INITIALIZATION_FAIL
2026-04-06T14:50:18.2181057-03:00 WRN ERROR DESCRIPTION Description="\nSM: INITIALIZE Erro no logger. \n"
2026-04-06T14:50:20.2158201-03:00 WRN Received error from device error=INITIALIZATION_FAIL
2026-04-06T14:50:20.2165962-03:00 WRN FULL ERROR protoErr="payloadType:ERROR_EVENT errorCode:INITIALIZATION_FAIL descr
ption:"\n\nSM: INITIALIZE Erro no logger. \n\n"
2026-04-06T14:50:20.2172019-03:00 WRN ERROR CODE ErrorCode=INITIALIZATION_FAIL
2026-04-06T14:50:20.2172019-03:00 WRN ERROR DESCRIPTION Description="\nSM: INITIALIZE Erro no logger. \n"
2026-04-06T14:50:22.2162917-03:00 WRN Received error from device error=INITIALIZATION_FAIL
2026-04-06T14:50:22.2162917-03:00 WRN FULL ERROR protoErr="payloadType:ERROR_EVENT errorCode:INITIALIZATION_FAIL descr
ption:"\n\nSM: INITIALIZE Erro no logger. \n\n"
2026-04-06T14:50:22.2168395-03:00 WRN ERROR CODE ErrorCode=INITIALIZATION_FAIL
2026-04-06T14:50:22.2173928-03:00 WRN ERROR DESCRIPTION Description="\nSM: INITIALIZE Erro no logger. \n"
2026-04-06T14:50:24.2164635-03:00 WRN Received error from device error=INITIALIZATION_FAIL
2026-04-06T14:50:24.2164635-03:00 WRN FULL ERROR protoErr="payloadType:ERROR_EVENT errorCode:INITIALIZATION_FAIL descr
ption:"\n\nSM: INITIALIZE Erro no logger. \n\n"
2026-04-06T14:50:24.2171551-03:00 WRN ERROR CODE ErrorCode=INITIALIZATION_FAIL
2026-04-06T14:50:24.217716-03:00 WRN ERROR DESCRIPTION Description="\nSM: INITIALIZE Erro no logger. \n"

```

5. DISPOSIÇÃO FINAL


X Recolhimento do produto

Atualização de firmware

Recalibração Remota

CÓDIGO	REVISÃO	DATA
FRGH.049		

ASSINATURA

A handwritten signature in black ink, appearing to read 'André Luiz de Souza', is written over a horizontal line within a rectangular box.

Analista responsável: André Luiz de Souza