

[illegible]

No.	Task /Activity	Hazard and Consequence		Initial Risk			Mitigating Controls	Residual Risk		
	Sequential Steps	Hazard	Consequence	Probability	Consequence Severity	Risk Rating	Measures to Reduce Risk to ALARP	Probability	Consequence Severity	Risk Rating
1	Review TRA and TBT	Miscommunication	Personnel Injury / Environmental Pollution	1	2	2	Situational awareness and proper use of PPE. Hard hats, impact gloves, cotton gloves, latex gloves, steel toed boots, safety glasses, side shields and face shield	1	1	1
2	Prior to any task being undertaken ensure that all personnel are aware of the hazards involved.	Electrical shock, possible slips trips and falls. Pinch points poor body position. Hydraulic discharge and spills.	Personnel Injury / Environmental Pollution	2	3	6	All personnel must be aware of their surrounds and weather conditions. Use proper Manual Handling techniques, i.e., Always use proper body positioning, lift with legs, and obtain second personnel when loads are over 40lbs. Read all SDS on chemicals used, use PPE that is specified in SDS and be aware of where all spill kits are located.	2	2	4
3	Obtain all equipment, tools, and supplies to complete fiber re-termination.	Damage to equipment, reaction from chemicals used.	Personnel Injury / Environmental Pollution	2	2	4	Personnel are to obtain proper tools for re-termination of fiber. Use proper PPE. Check all equipment that they are in good working conditions. Review all instructions for equipment being used for task. If equipment is found faulty take out of service, red tag and inform supervisor.	1	1	2
4	Ensure that light source has been shut down. (Rack nodes)	Damage to equipment and eye injury.	Personnel Injury / Environmental Pollution	2	3	6	NEVER LOOK DOWN THE END OF A FIBER IF LIGHT SOURCE IS ON.	2	2	4
5	<i>If J-box needs to be open, ensure that power has been turned off. Review LOTO TRA.</i>	Damage to equipment, electrical shock.	Personnel Injury / Environmental Pollution	2	3	6	NEVER OPEN J-BOX UNLESS POWER HAS BEEN SHUT DOWN.	2	2	4
6	Re-termination of fiber optics	Damage to equipment, hand and eye injuries.	Personnel Injury / Environmental Pollution	2	2	4	Personnel are to use proper PPE and use the proper equipment for re-termination of fiber optics. Place all broken and cut fiber optics in proper contain for disposal.	1	1	2

7	Test system for telemetry	Damage to equipment and eye injuries	Personnel Injury / Environmental Pollution	2	3	6	If LOTO was performed remove Lock-out locks from grounding wheels and main breaker. Personnel will be in constant communications with pilot as system is being tested. Turn on light source (Rack Nodes) to test for light levels.	2	2	4
8	If J-box was open secure all fiber optics and close J-box.	Damage to equipment	Personnel Injury / Environmental Pollution	2	3	6	Personnel is to be sure that fiber optics have been secured inside box and to make sure that box has been closed to prevent opening or water intrusion.	2	2	4
9	Clean up all areas of all tools and equipment. Clean and stow all tools in proper location	Slip trips and falls. Dropped objects and hydraulic discharge.	Personnel Injury / Environmental Pollution	2	2	4	Clean and put away all tools and chemicals in their proper locations. Oil absorbent pads and rags to be placed in proper container for disposal. Secure all ladders and ropes if used.	1	1	2
TRA Approval		Name	Position	Signature		Date				
By signing, the Approver confirms that the TRA has been reviewed and considers the task acceptable to proceed with residual risk meeting the acceptance criteria of DO Risk Matrix.										

*Reference DO-HSE-FRM-140 for DeepOcean Risk Assessment Matrix (RAM) and Guidewords