
2022 Chevrolet Silverado 1500 - 4WD LTD (RPO J21, VIN Digit 5 = Y) (3GCUYGEDXNG211028) Cheyenne LTD, Silverado 1500 LTD Service Manual 15539690 | Body Repair | Bumpers and Fascias | Repair Instructions |

Document ID: 5633756

Front Bumper Impact Bar Adjustment


Removal Procedure

1. Measure and document the impact bar to headlamps dimensions and the impact bar to fenders dimensions and note how far to move the impact bar right, left, up, and down to achieve an equal gap to the fenders and headlamps.





2. Front Bumper Impact Bar (1) » Remove — Front Bumper Impact Bar Removal and Installation



© 2023 General Motors. All rights reserved.


05.01.2023, 15:29 Document ID: 5633756

3. With a grease pencil, mark the top and side bumper adjustment bracket (2).




4. Loosen the 6 impact bar adjustment bracket bolts (1) and move the 2 adjustment brackets (2) to the pre determined measurements taken.

Installation Procedure



Caution: Refer to Fastener Caution.

1. Tighten the 6 impact bar adjustment bracket bolts (1). Fastener Specifications





2. Front Bumper Impact Bar (1) » Install — Front Bumper Impact Bar Removal and Installation