REQUESTED BY:

REFERENCE NO:

PPPC TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 1 OF 86

RUN DATE: 10/2/2023

RUN TIME: 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE:

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

NO: ALL

ATA NO: ALL

ZONE: ALL

DISPOSITION CODE: ALL

2C

DEFECT TYPE: ALL

TRADE: ALL

CUST ENDORSE: ALL

AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

JIRL CODE :					TYPE CODE:	ORIGINATOR: ALL			
	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL0017	500	NRR	ΑE	2800	TA28000201	PERFORM A/C DE-FUELLING FOR MAINTENANCE	L001	COMP	09/20/2023
	WNG								0.0
								-	0.0
(JL0025	500	NRR	AE	2800	TA28000201	PERFORM A/C FUEL SUMP DRAIN FOR FUEL TANK MAINTENANCE		00110	
JL0025	F/T	MIXIX	AL	2000	1A20000201	PERFORM AND FUEL SUMP DRAIN FOR FUEL TAINS MAINTENAINGE	L002	COMP	09/24/2023
	.,,								0.0
								-	0.0
JL0033	100	NRP	ΑE	07	777-BM-CONTROL-	TOWING A/C FOR MAINTENANCE/OPERATIONAL NEEDS	L003	WIP	09/20/2023
	FUS				CARD-01				0.0
						1C 1 PERFORM AIRPLANE TOWING FROM OUTSIDE 3 BAY TO BAY9.			5.0
								-	5.0
(JL0041	100	NRP	ΑE	0711	777-900002-01-1-01	JACK THE AIRPLANE FOR MAINTENANCE	L004	WIP	09/20/2023
	FUS					REF TO XMN TASK CARD: TA07000101-BOE	200.	••••	0.0
						1C 1 REMOVE BODY FAIRING 191SL &192SR			0.0
						1C 2 AIR MOD SIMULATION PREPARATION			0.0
						1C 3 LIFT THE AIRCRAFT WITH JACK			0.0
						1C 4 LOWER THE AIRCRAFT OFF OF THE JACK			0.0
						2C 5 REINSTALL THE BODYFAIRING191SL&192SR			0.0
						2C 6 AIR MODE SIMULATION RESTORATION			0.0
						2C 7 PERFORM WOW LOAD SENSOR CALIBRATION			0.0
								-	0.1
JL0058	200	NRR	Al	2500	777-53-904-00-01	CABIN G1 GALLERY R112 TOASTER MACHINE TRACK FOUND DAMAGE	L005	OPEN	09/20/2023
	CAB								4.0
								-	4.0
11 0000	200	NRR	۸۱/	2500	777 52 004 00 04	CARINA YOU WAS COMPARTMENT INNER DOOD OF CONTOUR DAY FOLLING DAMAGE			
JL0066	200 CAB	NKK	AV	2500	777-53-904-00-01	CABIN VCC V01 COMPARTMENT INNER DOOR CLOSE SWITCH BOX FOUND DAMAGE	L006	OPEN	09/20/2023
	CAB								0.0
								-	0.0
L0074	200	NRP	SS	25	777-25-050-08-CX-R-	PEY SEAT CONSOLE PTV ARM OPERATION FOUND TIGHTEN AT 30D E F G 31A C 32H K TOTAL:8EA	L007	OPEN	09/20/2023
	CAB				01				8.0
								-	
									8.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 2 OF 86

RUN DATE : 10/2/2023

4.0

RUN TIME : 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

IOD NG	ZONE	STG		A.T.*	TYPE CODE:	ORIGINATOR		1011	STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
JL0082	200 CAB	NRR	Al	2541	777-53-904-00-01	SPEC NO.B777-25-3-7179 -CABIN Z	ONE B LAV 3F-RC TOILET SEAT COVER BUMPER FUNCTION DISAPPEARED	L008	WIP	10/01/2023 4.0
JL0090	200 CAB	NRR	Al	2541	777-53-904-00-01	CABIN ZONE A LAV A TOILET SEAT	COVER BUMPER FUNCTION DISAPPEARED	L009	WIP	4.0 10/01/2023 4.0
JL0108	200 CAB	NRR	Al	2541	777-53-904-00-01	CABIN ZONE A LAV A FAUCET FOU	ND DAMAGE	L010	WIP	4.0 09/28/2023 4.0
JL0116	200 CAB	NRR	Al	2531	777-53-904-00-01	CABIN ZONE A G1 GALLERY PLACA	ARD FOUND CHIPPED	L011	WIP	4.0 09/29/2023 3.0
L0124	200 CAB	NRR	Al	2500	777-53-908-00-01	CABIN FB2 STOWAGE COMPARTM	ENT S1CA TOP DOOR SNUBBER FOUND WEAK	L012	COMP	3.0 09/28/2023 1.0
L0132	200 CAB	NRR	Al	2500	777-53-908-00-01	CABIN FB2 STOWAGE COMPARTM	ENT S2CA TOP DOOR SNUBBER FOUND WEAK	L013	COMP	1.0 09/28/2023 1.0
L0140	200 CAB	NRR	AI	2531	777-53-908-00-01	CABIN ZONE B GALLERY G2 PLACA	ARD FOUND CHIPPED	L014	OPEN	1.0 09/20/2023 4.0
L0157	200 CAB	NRR	Al	2531	777-53-908-00-01	CABIN ZONE B GALLERY G3 PLACA	ARD FOUND CHIPPED	L015	- OPEN	4.0 09/20/2023 4.0
L0165	200 CAB	NRR	SS	2525	777-C252440-04-02- 01	EY PAX SEAT BACKREST TABLE FI	ND TIGHT AT :40H J K 41H J K 42H J K 43H J K 44H J K 45H J K 46H J K TTL:21EA	L016	WIP	4.0 09/25/2023 4.0

ORIGINATING CUST REF NO:

515653

REQUESTED BY:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

PAGE: RUN DATE: 10/2/2023

3 OF 86

REFERENCE NO: BMS571R1-2 (By JSN) RUN TIME : 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

ALL

OTTLE GODE :	ZONE	STG			111 2 0052.	ortion viront.			STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL0173	200	NRR	Al	2500	777-53-912-00-01	CABIN DOOR 3 FWD CENTER PARTITION ATTA	CHED MAGAZINE RACK FOUND WORN 4 EA	L017	COMP	09/28/2023
	CAB									4.0
									-	4.0
XJL0181	200	NRR	Al	2500	777-53-904-00-01	CABIN FIRST CLASS TABLE SNUBBER FOUND \	VEAK AT 1A 2D 1K	L018	OPEN	09/20/2023
	CAB									12.0
									-	12.0
KJL0199	200	NRR	Al	2500	777-53-904-00-01	CABIN VCC V01 COMPARTMENT DOOR LATCH	BUMPER FOUND MISSING	L019	OPEN	09/20/2023
	CAB									1.0
									-	1.0
XJL0207	200	NRR	SS	2525	777-C252440-04-02- 01		:39D E F G 40D E F G 41D E F G 42D E F G 43D E F G 44D E F G 45D E F	L020	WIP	09/25/2023
	CAB				01	G 46D E F G				6.0
									-	6.0
KJL0215	100	NRR	Al	2580	777-53-822-00-01	FWD CARGO COMPARTMENT BILGE AREA INSI	JLATION BLANKET FOUND DIRTY	L021	OPEN	09/20/2023
	LWR									8.0
									-	8.0
KJL0223	200	NRR	Al	2541	777-53-904-00-01	CABIN ZONE A LAV B WASTE BIN FLAP DOOR N	IALFUNCTION	L022	WIP	09/29/2023
	CAB									4.0
									-	4.0
KJL0231	100	NRR	Al	2580	777-53-822-00-01	FWD CARGO COMPARTMENT BILGE AREA INSI	JLATION BLANKET FOUND TORN.	L023	OPEN	09/20/2023
	LWR									8.0
									-	8.0
KJL0249	100	NRR	Al	2580	777-53-818-00-01	FWD CARGO COMPARTMENT S/W AREA INSUL	ATION BLANKET FOUND TORN.	L024	OPEN	09/20/2023
	LWR									16.0
									-	16.0
(JL0256	200	NRR	Al	2541	777-53-904-00-01	CABIN ZONE A LAV B WATER ACCESS PANEL E	OX LOWER HOOK LOOSE	L025	WIP	09/29/2023
	CAB									5.0
									-	5.0

JSN RANGE SELECTED:

ORIGINATING CUST REF NO:

REQUESTED BY:

PROJECT: XJ

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

A/C TYPE: 777

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

A/C REGN: B-KPV

PAGE: 4 OF 86 RUN DATE :

10/2/2023

9:39

REFERENCE NO: BMS571R1-2 RUN TIME:

STATUS: ALL

CUSTOMER: CX

ORIG-STAGE: ALL PERIOD: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

CHECK TYPE:

2C

ESTIMATED MHR: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL STAGE: ALL AREA: ALL

CTRL CODE:

515653

ΑΠ

ALL

TYPE CODE: ORIGINATOR: ALL **STATUS** UPDATED DATE ZONE STG JOB NO AREA TD ATA ORIG CUST REF NO. CTRL SH NO DEFECT DESCRIPTION JSN STATUS EST Mhr NRR XJL0264 ΑI 2580 777-53-822-00-01 100 FWD CARGO COMPARTMENT BILGE AREA INSULATION BLANKET CLAMPS FOUND MISSING L026 **OPEN** 09/20/2023 LWR 1.0 1.0 XJL0272 100 NRR ΑI 2580 777-53-862-00-01 AFT CARGO COMPARTMENT BILGE AREA INSULATION BLANKET FOUND TORN. L027 COMP 09/30/2023 LWR 8.0 8.0 XJL0280 100 NRR ΑI 2580 777-53-862-00-01 AFT CARGO COMPARTMENT BILGE AREA INSULATION BLANKET FOUND DIRTY. L028 COMP 09/30/2023 LWR 16.0 16.0 XJL0298 100 NRR ΑI 2580 777-53-862-00-01 AFT CARGO COMPARTMENT BILGE AREA INSULATION BLANKET CLAMPS FOUND MISSING. L029 **OPEN** 09/20/2023 LWR 1.0 1.0 XJL0306 100 NRR ΑI 2580 777-53-854-00-01 AFT CARGO COMPARTMENT SIDEWALL AREA INSULATION BLANKET FOUND TORN. L030 OPEN 09/20/2023 LWR 16.0 16.0 XJL0314 200 NRR ΑI 5600 777-53-904-00-01 CABIN A ZONE L2 WINDOW DUST COVER FOUND SCRATCHED L031 WIP 10/02/2023 CAB 4.0 XJL0322 100 NRR ΑI 5300 777-53-874-00-01 BULK CARGO COMPARTMENT FLOOR PANEL SCREWS FOUND WORN. L032 **OPEN** 09/20/2023 LWR 1.0 NRR BULK CARGO COMPARTMENT BILGE AREA INSULATION BLANKET FOUND BROKEN XJL0330 100 ΑI 2580 777-53-874-00-01 L033 COMP 09/30/2023 LWR 5.0 5.0 XJL0348 200 NRR SS 2525 777-C252440-04-02-EY PAX SEAT BACKREST TABLE FND TIGHT AT: 59H J K 60H J K 61H J K 62H J K 63H J K 64H J K 65H J K 66H J K 67H J L034 WIP 09/25/2023 01 K 68H J K 69H J K 70H J K 71H J K TTL:39EA CAB 8.0 8.0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE:

RUN TIME :

5 OF 86

1.0

RUN DATE: 10/2/2023 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

ATA NO: ALL

PERIOD: ALL ZONE: ALL

ESTIMATED MHR: ALL DISPOSITION CODE: ALL

ORIGINATING CUST REF NO:

ALL

CUST ENDORSE: ALL

STAGE: ALL

DEFECT TYPE: ALL TRADE: ALL AREA: ALL

CTRL CODE :					TYPE CODE:	ORIGINATOR:	ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL0355	200	NRR	SS	2525	777-C252440-04-02- 01		D TIGHT AT : 39A C 40A B C 41A B C 42A B C 43A B C 44A B C 45A B C 46A B C	L035	WIP	09/25/2023
	CAB				01	TTL:20EA				4.0
									-	4.0
XJL0363	100	NRR	Al	2580	777-53-874-00-01	BULK CARGO COMPARTMENT SIDEW	WALL AREA INSULATION BLANKET FOUND BROKEN	L036	OPEN	09/20/2023
	LWR									4.0
									-	4.0
XJL0371	100	NRR	Al	2580	777-53-874-00-01		E AREA INSULATION BLANKET FOUND DIRTY	1.027	COMP	
7020071	LWR	TVICE	711	2000	111-00-014-00-01	BOLK CANGO COMITARTIMENT BILOL	ANLA INCOLATION DEANILET FOUND DINTT	L037	COMP	09/30/2023
									-	5.0
										5.0
XJL0389	200 CAB	NRR	ΑI	2541	777-53-904-00-01	CABIN ZONE B LAV D FAUCET FOUND	D MALFUNCTION	L038	WIP	09/28/2023
	CAB									4.0
									-	4.0
XJL0397	200	NRR	Al	5600	777-53-904-00-01	CABIN A ZONE R1 WINDOW DUST COV	OVER FOUND SCRATCHED	L039	WIP	10/02/2023
	CAB									4.0
									-	4.0
XJL0405	100	NRR	Al	2552	777-53-818-00-01	FWD CGO COMP'T CEILING PNL FIREF	EPROOF TAPE FOUND AGED.	L040	OPEN	09/20/2023
	LWR									1.0
									-	1.0
XJL0413	100	NRR	Al	2552	777-53-818-00-01	FWD CGO COMP'T S/W PNL FIREPRO	ONE TAPE FOLIND AGED	1044	ODEN	
X3E0413	LWR	IVIXIX	Ai	2002	777-00-010-00-01	TWD 000 COMIT TOWN NET INCH NO.	TALE TOURD ACED.	L041	OPEN	09/20/2023
									-	1.0
										1.0
XJL0421	200	NRR	Al	2531	777-53-908-00-01	CABIN ZONE B GALLERY G2 COMPAR	RTMENT 210 DOOR LATCH DAMAGE	L042	COMP	09/28/2023
	CAB									3.0
									-	3.0
XJL0439	100	NRR	Al	2552	777-53-854-00-01	AFT CGO COMP'T CEILING PNL FIREP	PROOF TAPE FOUND AGED.	L043	OPEN	09/20/2023
	LWR									1.0
										1.0

DISTRIBUTION: 0PPC REQUESTED BY: 515653 TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: RUN DATE: 10/2/2023

RUN TIME :

6 OF 86

9:39

6.0

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

STATUS: ALL ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL

REFERENCE NO: BMS571R1-2

ATA NO: ALL

ZONE: ALL

DISPOSITION CODE: ALL

STAGE: ALL

TRADE: ALL DEFECT TYPE: ALL CUST ENDORSE: ALL AREA: ALL

CTRL CODE

CTRL CODE:					TYPE CODE:	ORIGINATOR:	ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL0447	100 LWR	NRR	Al	2552	777-53-854-00-01	AFT CGO COMP'T S/W PNL FIREPROC	OF TAPE FOUND AGED.	L044	OPEN	09/20/2023
	LWK									1.0
									-	1.0
XJL0454	100	NRR	Al	2552	777-53-822-00-01	FWD CGO COMPARTMENT FLOOR PN	NL SCREWS FOUND WORN.	L045	OPEN	09/20/2023
	LWR									1.0
									-	1.0
XJL0462	200	NRR	Al	2531	777-53-908-00-01	CABIN ZONE B GALLERY G3 OVEN 3 4	4 5 DOOR EXTERNAL PLACARD FOUND CHIPPED	L046	OPEN	09/20/2023
	CAB									3.0
									-	3.0
XJL0470	200	NRR	Al	2524	777-53-912-00-01	CABIN L/R 3 DOOR O/B FWD CLOSETS	S TOP SEAL FOUND DAMAGE	L047	OPEN	09/20/2023
	CAB									6.0
									-	6.0
XJL0488	100	LOG	Al	25		AS PER CX B-KPV OPEN TL ENTRIES	TL3517: EQUIP COOLING FAN R(STATUS)	L048	OPEN	09/20/2023
	LWR									0.0
						1C 1 PLS MAKE LOG BOOK	ENTRY.			0.2
									-	0.2
XJL0496	100	NRR	Al	2552	777-53-818-00-01	FWD CGO COMP'T CEILING PNL SCRE	EWS FOUND WORN.	L049	OPEN	09/20/2023
	LWR									1.0
									-	1.0
XJL0504	100	NRR	ΑI	2552	777-53-818-00-01	FWD CGO COMPARTMENT S/W PNL S	SCREWS FOUND WORN.	L050	OPEN	09/20/2023
	LWR									1.0
									-	1.0
XJL0512	200	NRR	Al	2524	777-53-912-00-01	CABIN R 3 DOOR O/B FWD CLOSETS F	FWD SEAL RETAINER FOUND DETACHED	L051	WIP	09/30/2023
	CAB									6.0
									-	6.0
XJL0520	200	NRR	Al	2524	777-53-912-00-01	CABIN L3 DOOR O/B FWD CLOSETS F	WD SEAL RETAINER FOUND DETACHED	L052	WIP	09/30/2023
	CAB									6.0
									-	

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: RUN DATE: 10/2/2023

RUN TIME:

7 OF 86

9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

ATA NO: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

ALL

TRADE: ALL

CUST ENDORSE: ALL

ZONE: ALL AREA: ALL

DISPOSITION CODE: ALL

STAGE: ALL

CTRL CODE:

DEFECT TYPE: ALL

TYPE CODE:

ODICINIATOR

ODE:	ORIGINATOR:	ALL

TRL CODE :					TYPE CODE:	URIGINATUR: ALL				
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
KJL0538	100	NRR	Al	2552	777-53-854-00-01	AFT CGO COMP'T CEILING PNL SCREWS FOUN	D WORN.	L053	OPEN	09/20/2023
	LWR									1.0
									-	1.0
(JL0546	100	NRR	Al	2552	777-53-854-00-01	AFT CGO COMPARTMENT S/W PNL SCREWS F	DUND WORN.	L054	OPEN	09/20/2023
	LWR									1.0
									-	1.0
JL0553	100	NRR	Al	2552	777-53-862-00-01	AFT CGO COMPARTMENT FLOOR PNL SCREW	S FOUND WORN.	L055	OPEN	09/20/2023
	LWR									1.0
									-	1.0
JL0561	200	NRR	SS	2525	777-C252440-04-02-	EY PAX SEAT BACKREST TABLE FND TIGHT AT	:59A B C 60A B C 61A B C 62A B C 63A B C 64A B C 65A B C 66A B C 67A	L056	WIP	09/25/2023
	CAB				01	B C 68A B C 69A B C 70A B C 71A B C 72A C TTL	41EA			8.0
									-	8.0
JL0579	200	NRR	SS	2525	777-C252440-04-02-	EY PAX SEAT BACKREST TABLE FND TIGHT AT	: 60D E F G 61D E F G 62D E F G 63D E F G 64D E F G 65D E F G 66D E F	L057	WIP	09/25/2023
	CAB				01	G 67D E F G 68D E F G 69D E G 70D E G 71D E G	72D E G TTL: 48EA	2007	****	9.0
									-	9.0
JL0587	400	NRP	CL	7100	777-900001-01-1-01	#1 ENG BOTH FAN COWLS DIRTY.		L058	WIP	09/27/2023
.020007	ENG		0_		00000. 0 0.	", <u> </u>		2036	VVIF	4.0
									-	
JL0595	400	NRP	CL	7100	777-900001-01-1-01	#2 ENG BOTH FAN COWLS DIRTY.		1.050	MID	4.0
320393	ENG	INIXE	CL	7100	777-900001-01-1-01	#2 ENG BOTTT AN COWLS DIKTT.		L059	WIP	09/27/2023 4.0
									_	
II 0000	400	NDD	01	4000	777 000004 04 4 04	ADU GAVITV DIDTV				4.0
JL0603	400 ENG	NRP	CL	4900	777-900001-01-1-01	APU CAVITY DIRTY.		L060	WIP	09/28/2023
	LITO								_	6.0
										6.0
JL0611	400 ENG	NRP	CL	7100	777-900001-01-1-01	#1 ENG GEARBOX AREA DIRTY		L061	WIP	09/29/2023
	ENG									6.0
									-	6.0

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PERIOD: ALL

PAGE: RUN TIME :

ESTIMATED MHR: ALL

8 OF 86

RUN DATE: 10/2/2023 9:39

8.0

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

ORIG-STAGE: ALL ATA NO: ALL ORIGINATING CUST REF NO: ZONE: ALL DISPOSITION CODE: ALL ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

TYPE CODE CTDL CODE ODICINIATOD .

STATUS: ALL

CTRL CODE :					TYPE CODE:	ORIGINATOR :	ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL0629	400	NRP	CL	7100	777-900001-01-1-01	#2 ENG GEARBOX AREA DIRTY		L062	WIP	09/28/2023
	ENG									6.0
									-	6.0
XJL0637	400	NRP	CL	7800	777-900001-01-1-01	#1 ENG BOTH TR COWL DIRTY.		L063	WIP	09/29/2023
	ENG									6.0
									-	6.0
XJL0645	400	NRP	CL	7800	777-900001-01-1-01	#2 ENG BOTH TR COWL DIRTY.		L064	WIP	09/28/2023
	ENG									6.0
									-	6.0
XJL0652	400	NRP	CL	5400	777-900001-01-1-01	#2 PYLON AFT CAVITY DIRTY		L065	WIP	09/28/2023
	ENG									4.0
									-	4.0
XJL0660	400	NRP	CL	5400	777-900001-01-1-01	#1 PYLON AFT CAVITY DIRTY		L066	WIP	09/29/2023
	ENG							2000		4.0
									-	4.0
XJL0678	400	NRP	PT	7100	777-900001-01-1-01	#2 ENG NOSE COWL INLET ACOUSTIC	SURFACE PAINT IN POOR CONDITION.	L067	OPEN	09/20/2023
	ENG							2007	OI LIV	8.0
									-	8.0
XJL0686	400	NRP	PT	7100	777-900001-01-1-01	#1 ENG NOSE COWLINI ET ACOLISTIC	SURFACE PAINT IN POOR CONDITION.	L068	OPEN	09/20/2023
7,020000	ENG	1414	• •	7 100	777 000001 01 1 01	# LITO HOOL COME INCLET /10000110	CONTROL TAINT IN CONTROL	L000	OPEN	8.0
									-	
XJL0694	400	NRP	PT	7800	777-900001-01-1-01	#2 ENG BOTH TO COM/LEYTEDNAL DI	JCT AFT ACOUSTIC SURFACE PAINT IN POOR CONDITION.	1.000	ODEN	8.0
AJE0094	ENG	MIXE	F 1	7000	777-900001-01-1-01	#2 ENG BOTT IN COME EXTERNAL DO	TOTALLACOUSTIC SOIN ACE PAINT IN FOOK CONDITION.	L069	OPEN	09/20/2023
									-	8.0
V II 0700	400	NDD	D.T.	7000	777 000004 04 4 04	#4 5NO DOTUTO COM SVT5DNA DI	NOT LET LOCUETIO CURE LOE DUNT IN DOCO COMBITION			8.0
XJL0702	400 ENG	NRP	PT	7800	777-900001-01-1-01	#TENG BOTH TR COWL EXTERNAL DU	JCT AFT ACOUSTIC SURFACE PAINT IN POOR CONDITION.	L070	OPEN	09/20/2023
									_	8.0
										8.0

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

PAGE: 9 OF 86 RUN DATE: 10/2/2023

1.0

(By JSN) RUN TIME: 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL JSN RANGE SELECTED: ALL ESTIMATED MHR: ALL

ATA NO: ALL DISPOSITION CODE: ALL ORIGINATING CUST REF NO: ALL ZONE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

STRL CODE :					TYPE CODE:	ORIGINATOR: ALL				
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
JL0710	400	NRP	PT	7100	777-900001-01-1-01	#2 ENG RH FAN COWL INNER LOWER SURFACE PAINT IN P	OOR CONDITION.	L071	OPEN	09/20/2023
	ENG									8.0
									-	8.0
JL0728	400	NRP	SM	7100	777-900001-01-1-01	#2 ENG NOSE COWL LIP SKIN MULTIPLE FND CORROSION.		L072	WIP	09/24/2023
	ENG									0.0
						1C 1 REMOVE THE LIP SKIN CORROSION				60.0
						1C 2 PTOTECT THE REWORK AREA				4.0
						1C 3 NDT THICKNESS CHK				130.0
						1C 4 NDT CRACK CHK				20.0
									-	214.0
JL0736	400	NRP	SM	7100	777-900001-01-1-01	#1 ENG NOSE COWL LIP SKIN MULTIPLE FND CORROSION.		L073	WIP	09/23/2023
	ENG									0.0
						1C 1 REMOVE THE LIP SKIN CORROSION				40.0
						1C 2 PTOTECT THE REWORK AREA				4.0
						1C 3 NDT THICKNESS CHK				130.0
						1C 4 NDT CRACK CHK				20.0
									-	194.0
JL0744	400	NRP	SM	5400	777-900001-01-1-01	#2 PYLON ACC PNL 12EA ANCHOR NUTS FND BROKEN.		L074	WIP	09/28/2023
	ENG									6.0
									-	6.0
L0751	400	NRP	SM	5400	777-900001-01-1-01	#1 PYLON ACC PNL 13EA ANCHOR NUTS FND BROKEN.		L075	WIP	09/28/2023
	ENG							2070	****	6.0
									-	
II 0700	400	NDD	۸.	5400	777 000004 04 4 04	//2 D.// O.V. 4 O.S. D.// 4 O.S. A. O.S. D.// 4 D. T. J. D. T. J. D. W. D. V.				6.0
JL0769	400 ENG	NRP	AE	5400	777-900001-01-1-01	#2 PYLON ACC PNL 12EA SCREWS HEAD FND WORN.		L076	WIP	09/28/2023
	LING									2.0
										2.0
L0777	200	NRR	Al	25	777-53-920-00-01	M/D L LAV I/B AFT BABY BASSINET TABLE MIRROR BUMPER	RMISSING	L077	COMP	09/26/2023
	CAB									1.0
									-	1.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

PC TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

TYPE CODE:

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 10 OF 86

RUN DATE: 10/2/2023

RUN TIME: 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

ORIGINATOR: ALL

CTRL CODE:

TRL CODE .					TIPE CODE.	ORIGINATOR. ALL				
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
JL0785	400	NRP	AE	5400	777-900001-01-1-01	#1 PYLON ACC PNL 13EA SCREWS HEAD FND W	DRN.	L078	WIP	09/28/2023
	ENG									2.0
									-	2.0
JL0793	200	NRR	Al	25	777-53-920-00-01	M/D L LAV I/B AFT BIG MIRROR FOUND CRACKED		L079	OPEN	09/20/2023
	CAB							2010	01 211	4.0
									-	
										4.0
JL0801	200	LOG	AV	23			D A090: ES0 10 1- EENABLED SYSTEM, HARDWARE, LONGED PARKING PROCEDURES, CABIN ETECHLOG IPAD	L080	WIP	10/01/2023
	CAB					DEACTIVATEDADD RAISED FOR DEACTIVATION 2-2.1.4.2,ACTIONED IN ACCORDANCE WITH OTHE	OF CABIN ETECHLOG IPAD AS PER ELPM CHAPTER R ELPM CHAPTER 2-2.1.4.2.(PLS REF TO ATTACHED "CX DEFERRAL			0.0
						REPORT" FOR THE REQUIRED ACTION ITEM)  1C 1 PLS MAKE LOG BOOK ENTRY				0.2
									-	0.2
L0819	200	NRR	Al	25	777-53-920-00-01	M/D L LAV FLOOR PAN FOUND CRACKED		L081	OPEN	09/20/2023
	CAB									4.0
									-	4.0
JL0827	400	NRP	GW	5400	777-900001-01-1-01	#1 PYLON ACC PNL 8EA SCREWS SEIZED.		L082	WIP	09/30/2023
	ENG							2002	****	8.0
									-	
	400	NDD	0144	5400	<b>777</b> 000004 04 4 04	// D.// O.V. A.O. D.W. O.E.A. O.D.E.W.O. O.E.J.E.D.				8.0
L0835	400 ENG	NRP	GW	5400	777-900001-01-1-01	#2 PYLON ACC PNL 9EA SCREWS SEIZED.		L083	WIP	09/30/2023
	LING									9.0
									-	9.0
L0843	200	NRR	Al	25	777-53-916-00-01	G4R GALLEY FAUCET FOUND WATER LEAKING		L084	WIP	09/25/2023
	CAB									0.0
						1C 1 REPLACE GALLEY FAUCET				3.0
						1C 2 C/O GALLEY FAUCET WATER LEA	K CHECK			0.5

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 11 OF 86

ESTIMATED MHR: ALL

RUN DATE: 10/2/2023

RUN TIME: 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL JSN RANGE SELECTED: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL ORIGINATING CUST REF NO: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

	_ , ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	_				_		THE THE THE	01/10E: /1EE		
TRL CODE		0.7.0			TYPE CODE:			ORIGINATOR: ALL		STATUS	UPDATED DA
OB NO	ZONE AREA	SIG	TD	ATA	ORIG CUST REF NO.	CTRI	SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
L0850	200	LOG	SS	25	ONIO COOT INEL INC.			PV DEFERRAL REPORT ITEM ADD A091: 251 6- 08 SEAT BELT PROBLEM. REF CMADD CM503		OPEN	09/20/2023
L0030	CAB	LOG	00	20				v det ekkal report tien add aggi. 2310- 00 seat beet problem. Ret ginadd girgol I, 18A, 19A, 20A, 21A, 22A, 23A, 24A, 25A, 25G, 26A, 26K AIRBAG SEAT BELT INFLATOR REPLACED A	2000	OPEN	
	O/ LD					INFLA		RY DATE: 0621 / MAF DATE: A0711, LESS THAN 2 YEARS LIFE BUT OVER 100 DAY. (CONTINUE	E TO SWS		0.0
							1	AS PER CMADD 503 INSTRUCTION NEW INFLATOR EXPIRY DATE LESS THAN 2 YEARS LIFE RAISED ADD. ACTIONED IAW CMM 25-02-05 REV SEP 2020. (PLS REF TO ATTACHED "CX DE THE REQUIRED ACTION ITEMS)			0.0
						1C	2	PLS MAKE LOG BOOK ENTRY			0.2
										-	0.:
L0868	200	NRR	Al	25	777-53-916-00-01	M/D H	LAV FAL	CET FOUND WATER LEAKING	L086	WIP	09/28/2023
	CAB										0.0
						1C	1	REPLACE LAV FAUCET			4.0
						1C	2	C/O LAV FAUCET WATER LEAK CHECK			0.5
										-	4.
.0876	400	LOG	AV	71				PV DEFERRAL REPORT ITEM ADD A095: OB2 9 ITEM NOT FOUND IN FAULT TREE (REFER TO	,,	OPEN	09/20/2023
	ENG					CHEC	K FOLLO	11 IDG FILTER BLOCKED INDICATION ON MFD. AMM 12-22-07-200-802 IDG OIL FILTER CONDIT (ED. IDG DPI RED BUTTON INSPECTED FOUND NOT EXTENDED. FILTER REMOVED AND INSF			0.0
							EBRIS. FIL 1	TER REPLACED IAW 24-11-01-000-801-001.(CONTINUE TO SWS ITEM 1)	10 00 07 000 000 FOR		0.0
						10	ı	FAULT STILL REMAINS DURING EGR IDLE. DEFECT DEFERRED. ADD RAISED AS PER AMM 1 INSPECTION EVERY 7 DAYS 4 TIMES FOR DPI EXTENSION. ACTIONED IN ACCORDANCE WIT REV 05 MAY 2023. (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED A	ΓΗ AMM 12-22-07-200-802		0.0
						1C	2	REV 03 MAY 2023. (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED AT PLS MAKE LOG BOOK ENTRY.	JIION ITEMS)		0.2
										-	 0
_0884	100	LOG	AE	53		AS PE	ER B-KPV	A/C EXTERNAL DEFECT/REPAIR LIST ITEM FUS 3 : RH FX SKIN TOTAL 29EA HEAT DAMAGE A	T L088	OPEN	09/20/2023
	FUS					FASTE	ENERS DI	E LIGHTNING STRIKE LOC FROM STN 200 TO 2200 AND STR S36R TO S45R.			0.0
						1C	1	PLS MAKE LOG BOOK ENTRY			0.2
										-	0
L0892	200	NRR	CL	2524	777-53-920-00-01	CAB A	ALL CURT	AINS FOUND DIRTY	L089	WIP	09/22/2023
	CAB								2000	**	0.0
						1C	1	REMOVE ALL CABIN CURTAIN			2.0
						1C	2	CLEAN THE CURTAIN			10.0
						1C	3	INSTALL CAB ALL CURTAIN			6.0
										-	
											18.

0PPC DISTRIBUTION:

515653

ORIGINATING CUST REF NO: ALL

REQUESTED BY:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

12 OF 86 PAGE:

RUN DATE: 10/2/2023

REFERENCE NO: BMS571R1-2 (By JSN) RUN TIME : 9:39

PROJECT: XJ	CUSTOMER: CX	A/C TYPE: 777	A/C REGN: B-KPV	CHECK TYPE · 2C
FROJECI. AJ	COSTONER. CA	A/C LIFE . ///	AVC REGIN. D-REV	CHECK LIPE . 2C

TYPE CODE:

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATOR: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE:

TRL CODE :					TYPE CODE:	ORIGINATOR: A	ALL		0.74.71.10	
	ZONE	STG							STATUS	UPDATED DATE
IOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
JL0900	200	NRR	CL	2527	777-53-904-00-01	COCKPIT ALL CARPETS FOUND WORN		L090	WIP	09/22/2023
	CAB									0.0
						1C 1 REMOVE COCKPIT FLOOR				2.0
						1C 2 FABICATE COCKPIT FLOOR 1C 3 INSTALL COCKPIT FLOOR				10.0 6.0
						TC 3 INSTALL COCKPIT FLOOR	CARPET		_	
	000	NDD		0.5	777 50 004 00 04	WAAND WADOOD OALLEY AREA ELOODA	IAT THEFOUGH FOUND AGED			18.0
JL0918	200 CAB	NRR	Al	25	777-53-904-00-01	#1 AND #2 DOOR GALLEY AREA FLOOR N	AT THRESHOLD FOUND AGED	L091	OPEN	09/20/2023
	O/ LD								_	8.0
										8.0
JL0926	200	NRR	Al	25	777-53-904-00-01	#4 AND #5 DOOR GALLEY AREA FLOOR N	AT THRESHOLD FOUND AGED	L092	WIP	10/02/2023
	CAB									8.0
									-	8.0
JL0934	200	NRR	Al	25	777-53-920-00-01	M/D L AND M LAV WASTE COMPT DOOR I	NSIDE 2EA SCREWS MISSING.	L093	COMP	09/28/2023
	CAB									1.0
									-	1.0
JL0942	200	NRR	Al	25	777-53-912-00-01	M/D G LAV TOILET SHROUD AFT CLOURS	E PANEL LOWER AREA CRACKED	L094	WIP	09/26/2023
	CAB									0.0
									-	0.0
JL0959	200	NRR	Al	25	777-53-912-00-01	M/D G LAV UPPER CLOSE OUT SEAL FOU	NS DETACHED	L095	OPEN	09/20/2023
	CAB									1.0
									-	1.0
IL0967	200	LOG	Al	25		AS PER CX B-KPV DEFERRAL REPORT IT	EM ADD A097: PBE EXPIRED. QTY 1 EXPIRED AT LOCATION FWD FACE OF	L096	COMP	09/28/2023
	CAB					AFT BULKHEAD ABOVE 2 ND OBSERVER S REQUIRED ACTION ITEMS)	SEAT. (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE			0.0
						1C 1 PLS MAKE LOG BOOK EN	TRY.			0.2
									-	0.2
JL0975	200	LOG	Al	35			EM ADD A098: OFCR PORTABLE BREATHING EQUIPMENTS FOUND EXPIRED.	L097	COMP	09/30/2023
	CAB						R PBE. (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE			0.0
						REQUIRED ACTION ITEMS)  1C 1 PLS MAKE LOG BOOK EN	TRY.			0.2
									-	0.2

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

DEFECT TYPE: ALL

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

AREA: ALL

PAGE: 13 OF 86 RUN DATE: 10/2/2023

RUN TIME :

STAGE: ALL

9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ATA NO: ALL ORIGINATING CUST REF NO: ZONE: ALL DISPOSITION CODE: ALL ALL CUST ENDORSE: ALL

CTRL CODE : TYPE CODE: ORIGINATOR · ALL

TRADE: ALL

CTRL CODE :					TYPE CODE:	ORIGINATOR: ALL			
	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL0983	200	LOG	Al	35		AS PER CX B-KPV DEFERRAL REPORT ITEM ADD A099: OFAR PORTABLE BREATHING EQUIPMENTS FOUND EXPIRED. REPLACEMENT DEFERRED FOR TWO PBE AT OFAR STATION. (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR	L098	COMP	09/28/2023
	CAB					THE REQUIRED ACTION ITEMS)			0.0
						1C 1 PLS MAKE LOG BOOK ENTRY			0.2
								-	0.2
XJL0991	200	NRR	Al	2524	777-C252420-01-04- 02	CABIN FB2 SEAT RETRACTABLE ARMREST FOUND STIFF TO OPERATE FROM 11D TO 20D TTL 10EA	L099	OPEN	09/20/2023
	CAB				02				27.5
								-	27.5
XJL1007	200	NRR	SS	2527	777-53-912-00-01	M/D ALL AISLE AREA FLOOR CARPETS FOUND WORN	L100	WIP	09/22/2023
	CAB								0.0
						1C 1 REMOVE M/D ALL AISLE AREA FLOOR CARPETS FLOOR CARPETS.			44.0
						1C 2 REMOVE SEAT TRACK COVER			2.0
						1C 3 FABRICATE M/D ALL AISLE AREA FLOOR CARPETS FLOOR CARPETS.  1C 4 INSTALL M/D ALL AISLE AREA FLOOR CARPETS FLOOR CARPETS.			68.0 88.0
						2C 5 INSTALL SEAT TRACK COVER			2.0
						20 0 MONEE OLIVI HVOROGVER		-	204.0
XJL1015	200	NRR	Al	25	777-53-912-00-01	G LAV FWD O/B SIDE CLOSE OUT SEAL FOUND MISSING	L101	COMP	09/26/2023
	CAB						LIUI	COM	2.0
								-	2.0
XJL1023	200	NRR	Al	2524	777-C252420-01-04-	CABIN FB2 SEAT RETRACTABLE ARMREST FOUND STIFF TO OPERATE FROM 21D TO 26D TTL 5EA	L102	OPEN	09/20/2023
X0L1020	CAB	MAC	711	2024	02	ONDITY BE DEATH RETURNING FROM STILL TO SEE THE FEW ET DE TO 200 THE SEX	L102	OPEN	27.5
								_	
V II 4004	000	NDD		0504	777 0050400 04 04				27.5
XJL1031	200 CAB	NRR	Al	2524	777-C252420-01-04- 02	CABIN FB2 SEAT RETRACTABLE ARMREST FOUND STIFF TO OPERATE FROM 11G TO 16G TTL 5EA	L103	OPEN	09/20/2023
	0, 12							_	16.5
									16.5
XJL1049	200 CAB	NRR	Al	25	777-53-916-00-01	G4 GALLEY L/H FWD EMERGENCY EQUIPMENT RACK HANDLE CRACKED	L104	COMP	09/28/2023
	CAD								1.0
								-	1.0
XJL1056	200	NRR	Al	2524	777-C252420-01-04- 02	CABIN FB2 SEAT RETRACTABLE ARMREST FOUND STIFF TO OPERATE FROM 16G TO 26G TTL 10EA	L105	OPEN	09/20/2023
	CAB				02				44.0
								-	44.0

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 14 OF 86

RUN DATE: 10/2/2023

RUN TIME : 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

ORIGINATING CUST REF NO:

DEI EOI IIII		-			TIVIDE: AL			OTAGE: ALL		
TRL CODE :					TYPE CODE:	ORIGINATOR :	ALL		STATUS	UPDATED DA
OB NO	ZONE AREA	SIG	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
L1064	200	NRR	Al	25	777-53-916-00-01					
_1004	CAB	INIXIX	AI	23	777-53-916-00-01	G4 GALLEY L/H FWD VERTICAL BUMPE	ER LOWER AREA ATTACH SCREWS MISSING	L106	COMP	09/28/2023
	O/ LD									1.0
									-	1.0
_1072	200	LOG	Al	35			ITEM ADD A100: CABIN PORTABLE BREATHING EQUIPMENTS FOUN	2.0.	COMP	09/28/2023
	CAB						O SATISFY MEL REQUIREMENTS. REPLACEMENTS OF FIVE CABIN F TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTI			0.0
						1C 1 PLS MAKE LOG BOOK I		,		0.2
									-	0.2
_1080	200	NRR	Al	25	777-53-920-00-01	M/D M LAV DOOR FRAME O/B EDGE SE	EAL FOUND DETACHED	L108	OPEN	09/20/2023
	CAB									1.0
									-	1.0
L1098	200	LOG	AV	23		AS PER CX R-KPV DEFERRAL REPORT	ITEM ADD A101: 23 COMMUNICATIONS,ON CHK FOUND VHF-R ANTE	ENNA (LWR) L109	WIP	09/30/2023
_1000	CAB	200	710	20			G AND ERODEDTO ADD DUE TIME, VHF-R SYSTEM IS CONSIDERED	, ,	VVIP	
						VHF-L OPERATES NORMAL. ACTIONED ATTACHED "CX DEFERRAL REPORT" FO	IN ACCORDANCE WITH OTHER MEL 23-12-01 REV MAY23 (PLS REF	ГО		0.0
						1C 1 PLS MAKE LOG BOOK I				0.2
						2C 2 REPLACE R SYSTEM (U	INDER AFT CGO) VHF ANTENNA			4.0
							ON TEST OF VHF ANTENNA			1.0
						2C 4 C/0 R VHF ANTENNA (U	NDER AFT CGO) PAINT/MARK PROCEDURE			2.0
									-	7.2
L1106	200	NRR	Al	25	777-53-920-00-01	M/D DOOR O/H PANEL ATTACH LANYA	RDS TOTAL 11EA BROKEN	L110	WIP	10/02/2023
	CAB									1.0
									-	1.0
L1114	200	NRR	Al	2524	777-C252420-01-04-	CABIN FB2 SEAT RETRACTABLE ARMF	REST FOUND STIFF TO OPERATE FROM 11A TO 22A TTL 12EA	L111	OPEN	09/20/2023
	CAB				01			2111	01 211	44.0
									-	44.0
L1122	200	NRR	AI	25	777-53-920-00-01	M/D M LAV FLOOR PAN I/B EDGE RETA	INED FOLIND LOOSEN	1440	ODEN	
_1122	CAB	INIXIX	Ai	23	777-33-920-00-01	W/D W LAV I LOOK FAIN I/D LDGL KLTA	INERT COIND ECOSEN	L112	OPEN	09/20/2023
									_	1.0
										1.0
_1130	200	NRR	Al	2524	777-C252420-01-04- 01	CABIN FB2 SEAT RETRACTABLE ARMF	EST FOUND STIFF TO OPERATE FROM 22A TO 26A TTL 12EA	L113	OPEN	09/20/2023
	CAB				• •					22.0
									-	22.0

REQUESTED BY:

REFERENCE NO:

515653

BMS571R1-2

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: RUN DATE: 10/2/2023 RUN TIME :

15 OF 86

9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

STATUS: ALL

TRADE: ALL

ORIG-STAGE: ALL

ATA NO: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

DEFECT TYPE: ALL

ALL

CUST ENDORSE: ALL

ZONE: ALL AREA: ALL

DISPOSITION CODE: ALL

STAGE: ALL

DE: 201 111	/	•			110002.70	The state of the s	OTAGE: ALL		
CTRL CODE					TYPE CODE:	ORIGINATOR: ALL		STATUS	UPDATED DATE
JOB NO	ZONE AREA	STG	TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL1148		NRR	Al	2524	777-C252420-01-04-	CABIN FB2 SEAT RETRACTABLE ARMREST FOUND STIFF TO OPERATE FROM 11K TO 12K TTL 2EA			
AJL1140	200 CAB	INKK	AI	2324	01	CABIN FB2 SEAT RETRACTABLE ARMREST FOUND STIFF TO OPERATE FROM TIK TO 12K TTL 2EA	L114	OPEN	09/20/2023
	0, 1,5								11.0
									11.0
XJL1155	200	NRR	Al	25	777-53-920-00-01	M/D G6 GALLEY #7 COFFEE MAKER FOUND WATER LEAKING	L115	WIP	09/26/2023
	CAB								0.0
						1C 1 REPLACE COFFEE MAKER  1C 2 C/O COFFEE MAKER FUNCTIONAL TEST			1.0 0.5
						TO 2 C/O COFFEE MAKER FUNCTIONAL TEST			
									1.5
XJL1163	200 CAB	NRR	Al	2524	777-C252420-01-04- 01	CABIN FB2 SEAT RETRACTABLE ARMREST FOUND STIFF TO OPERATE FROM 12K TO 26K TTL 14EA	L116	OPEN	09/20/2023
	CAB								38.5
									38.5
XJL1171	200	NRR	Al	2524	777-C252420-01-05-	CABIN FB2 SEAT BACK SHELL NOMEX TRIM FOUND DETACHED AT COLUMN D 15EA	L117	WIP	09/26/2023
	CAB				02				22.5
									22.5
XJL1189	200	NRR	Al	2524	777-C252420-01-05-	CABIN FB2 SEAT BACK SHELL NOMEX TRIM FOUND DETACHED AT COLUMN G 13EA	L118	WIP	09/26/2023
	CAB				02				19.5
									19.5
XJL1197	200	NRR	Al	2524	777-C252420-01-05-	CABIN FB2 SEAT BACK SHELL NOMEX TRIM FOUND DETACHED AT COLUMN A 14EA	L119	WIP	09/26/2023
	CAB				01		Ello	****	21.0
V II 4005	200	NDD	Α.Ι	0504	777-C252420-01-05-	OARIN FRO OF AT RACK CUELL MONEY TRIM FOLIND RETACUER AT COLUMNIX 44F A			21.0
XJL1205	200 CAB	NRR	Al	2524	777-C252420-01-05- 01	CABIN FB2 SEAT BACK SHELL NOMEX TRIM FOUND DETACHED AT COLUMN K 11EA	L120	WIP	09/26/2023
	O/ID								16.5
									16.5
XJL1213	200	NRR	Al	25	777-53-912-00-01	M/D #3 TO #4 DOOR L/H PARTITION BABY BASSINET SCREWS FOUND LOOSEN	L121	WIP	10/01/2023
	CAB								1.0
									1.0

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

AREA: ALL

PAGE: 16 OF 86

RUN TIME :

STAGE: ALL

RUN DATE: 10/2/2023

9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL CTRL CODE: ORIGINATOR: ALL

CIRL CODE:					TYPE CODE:	ORIGINATOR	R: ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL1221	200	NRR	Al	25	777-53-912-00-01	M/D #3 TO #4 DOOR L/H PARTITIO	ON BABY BASSINET LOWER BUMPER FOUND MISSING	L122	COMP	09/25/2023
	CAB									1.0
									-	1.0
XJL1239	400	LOG	AE	71			PORT ITEM PADD P023: HTP T13 WORK ORDER (WO) / WORK CARD REF W/O ORM AN EDTO VERIFICATION FLT DUE TO FUEL & OIL SYSTEM DISTURBED ON	L123	COMP	09/22/2023
	ENG					BOTH ENGINES. PERFORM AN ED	TO VERIFICATION FLIGHT DUE TO FUEL & OIL SYSTEM DISTURBED ON BOTH			0.0
						ENGINES.(CONTINUE TO SWS ITE 1C 1 ACTIONED IN ACC	.M 1) CORDANCE WITH OTHER EEPM 3-1 REV AUG 2022. (PLS REF TO ATTACHED "CX DEFERRAL			0.0
							E REQUIRED ACTION ITEMS)			0.2
						TO 2 PLS MAKE LOG BO	OUR ENTRY		-	
XJL1247	200	NRR	Al	25	777-53-912-00-01	M/D #3 TO #4 DOOR R/H PARTITIO	ON 1EA MAGAZINE RACK FOUND BROKEN	1.404	WID	0.2
AJL 1247	CAB	INIXIX	Ai	25	777-33-312-00-01	W/D #3 TO #4 DOOK K/ITFAKTITIC	THE WASAZINE NACK FOUND BNOKEN	L124	WIP	10/01/2023
									-	
XJL1254	200	NRR	Al	25	777-53-912-00-01	M/D #3 TO #4 DOOD OTD DADTITI	ON 1EA MAGAZINE RACK FOUND BROKEN	1.405	MID	1.0
AUL 1204	CAB	MIXIX	Ai	25	777-55-512-60-61	WID #3 TO #4 DOOK OTK! AKTIN	ON TEA MIAGAZINE NAON TOUND BRONEN	L125	WIP	10/01/2023
									-	
XJL1262	200	NRR	Al	25	777-53-916-00-01	CAL CLY LOWER COMPT AET TIE	DOWN COVER FOUND DETACHED	L126	OPEN	1.0
X0E1202	CAB	MICH	711	20	777-50-510-60-61	OFE GET LOWER GOWN 174 T TIE	BOWN GOVERT GOING BETAGLIEB	L126	OPEN	09/20/2023
									-	
XJL1270	200	NRR	AI	25	777-53-916-00-01	CAL CLV LA 11 LA 12 COMPT CTP	PARTITION 2EA TURN BUTTON FOUND STIFF	1.407	WIP	1.0
AJL 1270	CAB	MIXIX	Ai	25	777-33-910-00-01	G4L GLT L4-TT.L4-TZ COMFT OTK	FAITHON ZEA TONN BUTTONT GUND STILL	L127	WIP	10/01/2023
									-	
XJL1288	200	NRR	AI	25	777-53-916-00-01	G4L GLY 421 COMPT LOWER EDG	SE TUDN DUTTON FOUND STIEF	1.400	MID	1.0
X3L 1200	CAB	MIXIX	Ai	25	777-55-510-60-61	O-L OLT -21 OOM T LOWLK LDC	DE TOTAL BOTTON'T COMP CITIET	L128	WIP	10/01/2023
									-	
XJL1296	200	NRR	Al	25	777-53-916-00-01	G4R GLY R4-12 ICE DRAWER TRA	AV EQUIND LOQSEN	1.400	WIP	1.0
X0L1290	CAB	MIXIX	Ai	25	777-55-510-60-61	GAN GET NA-12 ICE DINAWEN THA	AT FOUND LOUGEN	L129	VVIP	10/01/2023
									-	
										2.0

DISTRIBUTION: 0PPC REQUESTED BY: 515653

## TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 17 OF 86 RUN DATE: 10/2/2023

RUN TIME :

9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

ALL

ATA NO: ALL

ZONE: ALL AREA: ALL

DISPOSITION CODE: ALL

DEFECT TYPE: ALL

REFERENCE NO:

TRADE: ALL

CUST ENDORSE: ALL

STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

TINE CODE.					TITE CODE.	ONIGINATOR.	ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
(JL1304	200	NRR	Al	25	777-53-916-00-01	G4R GLY R4-31.R4-21 COMPT DOOR T	URN BUTTON FOUND MALFUNCTION	L130	WIP	09/29/2023
	CAB									2.0
									-	2.0
KJL1312	200	NRR	Al	25	777-53-916-00-01	G4R GLY FWD EQUIPMENT RACK HAN	DLE FOUND CRACKED	L131	OPEN	09/20/2023
	CAB									1.0
									-	1.0
KJL1320	200	NRR	Al	25	777-53-916-00-01	G4R GLY AFT O/B EDGE SEAL LOOSE	N.	L132	OPEN	09/20/2023
	CAB									2.0
									-	2.0
JL1338	400	LOG	AV	29			ITEM PADD P024: REFER_TL REFER TO TL ITEM REF TL3501, BOTH ENG	L133	OPEN	09/20/2023
	ENG						STALLATION. PADD RAISED TO CALL OUT EDTO VERIFICATION FLIGHT AS PER RDANCE WITH OTHER AEO-29704 REV 00. (PLS REF TO ATTACHED "CX			0.0
						DEFERRAL REPORT" FOR THE REQUIR	ED ACTION ITEMS)			
						1C 1 PLS MAK LOG BOOK E	NIRY.			0.2
									-	0.2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 18 OF 86

RUN DATE: 10/2/2023

RUN TIME: 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

CUST ENDORSE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

ALL

ATA NO: ALL

ZONE: ALL AREA: ALL

DISPOSITION CODE: ALL

STAGE: ALL

DEFECT TYPE: ALL CTRL CODE:

TRADE: ALL

TYPE CODE: ORIGINATOR: ALL

	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL1346	400 ENG	LOG	SS	72	ORIG CUST REF NO.	AS PER CX B-KPV DEFERRAL REPORT ITEM SADD S087: ***THIS TASK TO C/OUT REPAIR AS TERMINATIVE ACTION***#2 ENGINE FAN BLADES #1, #14 AND #17 HAVE CONCAVE SURFACE COATING LOSS AND BLADES #14 AND #17 HAVE METAL TIP CAP EXPOSED. #2 ENGINE FAN BLADES #1 #14 AND #17 INSPECTED WITHIN AMM 72-21-02 LIMITS.(CONTINUE TO SWS ITEM 1)  1C 1 NIL DISBOND ON METAL TIP CAPS OF BLADES #14 AND #17 TO SADD FOR COATING REPAIR OR REPEAT INSPECTION WITHIN 150 CYCLES IAW AMM 72-21-02 REV JAN 20. (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)  1C 2 PLS MAKE LOG BOOK ENTRY 2C 3 REMOVE THE FAN ROTOR SPINNER ASSY 2C 4 REMOVE THE SUBJECT FAN BLADES 2C 5 DO AN INSPECTION TO THE REMOVAL FAN BLADES 2C 6 INSTALL REMOVAL THE SUBJECT FAN BLADES 3C 7 INSTALL REMOVAL FAN ROTOR SPINNER ASSY 3C 8 PERFORM LPT VIBRATION SURVEY 4C 9 PERFORM FAN BLADE TIP CLEARANCE INSPECTION 5C 10 REMOVE LOOSE OR DAMAGED BLACK POLYURETHANE FILM FROM THE VISUAL TIP CAP METAL AREAS OF NO.14	L134	WIP	09/23/2023 0.0 0.0 0.2 4.0 6.0 2.0 8.0 6.0 2.0 16.0 6.0
						AND NO.17 FAN BLADES  5C 11 DO AN INSPECTION TO THE VISUAL TIP CAP METAL AREAS OF NO.14 AND NO.17 FAN BLADES TO CHECK FOR THE TIP CAP DISBOND  5C 12 CLEAN AND DO THE REPAIR TO VISUAL TIP CAP METAL AREAS OF NO.14 AND NO.17 FAN BLADES  5C 13 DO AN INSPECTION TO TO VISUAL TIP CAP METAL REPAIR AREAS OF NO.14 AND NO.17 FAN BLADES  6C 14 CUT AWAY THE LOOSE OR TORN POLYURETHANE COATING AND ACCEPT THE CONDITION OF ALL THE SUBJECT FAN BLADES THAT THE DAMAGE AREAS(NOT INCLUDING VISUAL TIP CAP METAL AREAS)EXCEED THE REPAIR LIMIT			0.5 10.0 0.5 4.0
XJL1353	200 CAB	NRR	AI	2524	777-C252420-01-05- 01	CABIN FB2 SEAT SHELL RETRACTABLE TABLE FOUND STIFF TO OPERATE AT COLUMN A	L135	WIP	65.2 09/28/2023 35.0
XJL1361	200 CAB	NRR	Al	2524	777-C252420-01-05- 01	CABIN FB2 SEAT SHELL RETRACTABLE TABLE FOUND STIFF TO OPERATE AT COLUMN K	L136	WIP	10/01/2023 32.5 32.5
XJL1379	200 CAB	NRR	Al	2524	777-C252420-01-05- 01	CABIN FB2 SEAT SHELL RETRACTABLE TABLE FOUND STIFF TO OPERATE AT COLUMN D	L137	WIP	10/02/2023 32.5 32.5

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 19 OF 86

ESTIMATED MHR: ALL

RUN DATE: 10/2/2023

RUN TIME: 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE : TYPE CODE: ORIGINATOR : ALL

JOB NO	ZONE AREA	STG	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS STATUS	UPDATED DATE
(JL1387	200	NRR	Al	2524	777-C252420-01-05-		E TABLE FOUND STIFF TO OPERATE AT COLUMN G	L138	WIP	10/01/2023
	CAB				01			2100	****	32.5
									-	32.5
JL1395	200	LOG	SS	25			ITEM SADD S110: HTP T13 WORK ORDER (WO) / WORK CARD REF W/O 9571960	L139	OPEN	09/20/2023
	CAB					6FC'S AFTER OCTOBER 7, 2022 UNTIL I	TO PERFORM AEO-27666 PART-2 AND AEO-27669 PART 2 NO LATER THAN DECEMBER 31, 2024. THE 6 FLIGHT CYCLES WILL BE FERRY FLIGHTS WITH NO DDIMENT OF THE MODICATION AS PER (CONTINUE TO SWS ITEM 1)			0.0
						1C 1 AEO-27666 PART 2 AND PER INSTRUCTIONS IN	AEO-27669 PART 2. CLEAR SADD RAISED AGAINST THIS AEO PART 1. XFRD TO SADD AS AEO-29541 REV 00 ACTIONED IN ACCORDANCE WITH AMM 25-11-01 REV 05 MAY 2023.(PLS DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)			0.0
						1C 2 PLS MAKE LOG BOOK I	,			0.2
									-	0.2
JL1403	200	NRR	ΑI	2524	777-C252420-01-05- 01		D TO OPERATE AT 19D-26D 24A 22A 16A 12A 11A 12G 11K 18G 21G 22G 24G 25G	L140	WIP	09/23/2023
	CAB				O1	26G 17K 18K 19K 21K 22K 23K				72.8
									-	72.8
L1411	200	LOG	Al	25			ITEM SADD S112: HTP T13(WO)REPLACEMENT OF EMERGENCY ESCAPE	L141	OPEN	09/20/2023
	CAB						ILS: W/O: 9571786/1 P/N: 62771-128 S/N: 2039 ACTIONED IAW AMM 25-66-01 REV IL SPARES. ACTIONED IAW AMM 25-66-01 REV 05 MAY 2023.(PLS REF TO OR THE REOLURED ACTION ITEMS)			0.0
						1C 1 PLS MAKE LOG BOOK I				0.2
									-	0.2
L1429	200	LOG	ΑI	25			ITEM SADD S113: HTP T13 WORK ORDER (WO) / WORK CARD REF W/O 9571787	L142	OPEN	09/20/2023
	CAB						NCY ESCAPE SLIDE ASSEMBLY. XFRD TO SADD DUE TO NIL SPARES. AY 2023.(PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE			0.0
						1C 1 PLS MAKE LOG BOOK I	ENTRY.			0.2
									-	0.2
IL1437	200	LOG	Al	25			ITEM SADD S114: HTP T13 REF W/O: 9571788/1 REPLACEMENT OF OFF-WING	L143	OPEN	09/20/2023
	CAB			EMERGENCY ESCAPE SLIDE ASSEMBLY. XFRD TO SADD DUE TO NIL SPARES. ACTIONED IAW AMM 25-65-01 REV 05 MAY 2023. LH OFF WING SLIDE RAFT DETAILS: P/N: 5A3109-1 S/N: ST0958(PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)	ETAILS: P/N: 5A3109-1 S/N: ST0958(PLS REF TO ATTACHED "CX DEFERRAL			0.0		
						1C 1 PLS MAKE LOG BOOK I				0.2
									-	0.2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 20 OF 86

RUN DATE: 10/2/2023

RUN TIME : 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

ATA NO: ALL

PERIOD: ALL

ESTIMATED MHR: ALL DISPOSITION CODE: ALL

ORIGINATING CUST REF NO:

ALL DEFECT TYPE: ALL

TRADE: ALL

CUST ENDORSE: ALL

ZONE: ALL AREA: ALL

STAGE: ALL

TYPE CODE: CTRL CODE : ORIGINATOR · ALL

CTRL CODE:					TYPE CODE:	ORIGINATOR :	ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL1445	200	LOG	Al	25			ORT ITEM SADD S115:HTP T13 (WO) REF W/O: 9571790 /1 REPLACEMENT OF	L144	OPEN	09/20/2023
	CAB						· L4. XFRD TO SADD DUE TO NIL SPARES ACTIONED IAW AMM 25-66-01 REV 05 -339 S/N M8187 (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE			0.0
						1C 1 PLS MAKE LOG BOO	DK ENTRY.			0.2
									-	0.2
XJL1452	200	LOG	Al	25			ORT ITEM SADD S116: HTP T13 (WO) REF W/O: 9571791 /1REPLACEMENT OF	L145	OPEN	09/20/2023
	CAB						· L5 B. ACTIONED IAW AMM 25-66-01 REV 05 MAY 2023. L5 SLIDE RAFT DETAILS: P/N: TACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)			0.0
						1C 1 PLS MAKE LOG BOO	,			0.2
									-	0.2
XJL1460	200	LOG	Al	25			ORT ITEM SADD S117: REF W/O: 9571792 /1 REPLACEMENT OF EMERGENCY ID TO SADD DUETO NIL SPARE. ACTIONED IAW AMM	L146	OPEN	09/20/2023
	CAB						/RAFT DETAILS: P/N: 65344-428 S/N: 0274(PLS REF TO ATTACHED "CX DEFERRAL			0.0
						1C 1 PLS MAKE LOG BOO	OK ENTRY.			0.2
									-	0.2
XJL1478	200	LOG	Al	25			ORT ITEM SADD S118: HTP T13 (WO) REF W/O: 9571794 /1 REPLACEMENT OF	L147	OPEN	09/20/2023
	CAB					2023 L2 SLIDE RAFT DETAILS: P/N:62	L2. XFRD TO SADD DUE TO NIL SPARE. ACTIONED IAW AMM 25-66-01 REV 05 MAY 2771-127 S/N: M8984(PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE			0.0
						REQUIRED ACTION ITEMS)  1C 1 PLS MAKE LOG BOO	OK ENTRY.			0.2
									-	0.2
XJL1486	200	LOG	Al	25		AS PER CX R-KPV DEFERRAL REPO	ORT ITEM SADD S119: HTP T13 WORK ORDER (WO) / WORK CARD REF W/O:	L148	OPEN	09/20/2023
	CAB					9571795 REPLACEMENT OF EMERGI ACTIONED IAW AMM 25-66-01 REV 0:	ENCY ESCAPE SLIDE/RAFT -R4. R4 SLIDE RAFT DETAILS: P/N: 63604-324 S/N: 0034 5 MAY 2023.(PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE	2140	OI LIN	0.0
						REQUIRED ACTION ITEMS)  1C 1 PLS MAKE LOG BOO	OK ENTRY			0.2
									-	0.2
XJL1494	200	NRR	SS	25	777-53-904-00-01	CABIN F/C SEAT PARTIITON AISLE T	TEDLAR FOUND SCEATCHED AT 1D 2D(TOTAL 2EA)	L149	WIP	09/23/2023
	CAB									0.0
							PARTITION SIDE BUMPER 1D 2D			1.0
							N SIDE BUMPER 1D 2D TEDLAR REPLACE			22.0
						1C 3 REINSTALL F/C SEA	T PARTITION SIDE BUMPER 1D 2D			1.0
									-	24.0

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

DEFECT TYPE: ALL

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

AREA: ALL

PAGE: 21 OF 86

RUN TIME :

STAGE: ALL

RUN DATE: 10/2/2023

9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL ALL CUST ENDORSE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

TRADE: ALL

CIRL CODE :					TYPE CODE:	ORIGINATOR	: ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
KJL1502	200	LOG	AV	33			ORT ITEM SADD S120: OB2 9 ITEM NOT FOUND IN FAULT TREE (REFER TO	L150	OPEN	09/20/2023
	CAB					OFAR BACK-UP LIGHTING POWER I	'S (OFCR,OFAR) CAN'T BE USED. AMS 33-115-00 FUNCTIONALLY CHK OFCR & / OR PACKS-TO BE PERFORMED NO LATER THAN NEXT REVENUE FLIGHT. TO SADD 05 MAY 2023.(PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE			0.0
						1C 1 PLS MAKE LOG BO	OK ENTRY.			0.2
									-	0.2
(JL1510	200	NRR	Al	2524	777-C252420-01-05-	CABIN FB2 SEAT SHELL O/B SIDE O	GAP COVER PANEL FOUND DISCOLOUR AT COLUMN A	L151	COMP	09/30/2023
	CAB				01					14.0
									-	14.0
JL1528	200	NRR	Al	2524	777-C252420-01-05-	CABIN FB2 SEAT SHELL O/B SIDE (	GAP COVER PANEL FOUND DISCOLOUR AT COLUMN K	L152	WIP	09/26/2023
	CAB				01					13.0
									-	13.0
JL1536	200	LOG	AV	52		AS PER CX B-KPV DEFERRAL REP	ORT ITEM SADD S121: OB2 9 ITEM NOT FOUND IN FAULT TREE (REFER TO	L153	OPEN	09/20/2023
	CAB					,	1808/1 OVER WING DOOR EPAS BATTERY NEED TO REPLACE.(PLS REF TO T" FOR THE REQUIRED ACTION ITEMS)			0.0
						1C 1 PLS MAKE LOG BO	,			0.2
						2C 2 REPLACE THE NO.:	3 LEFT OVER WING DOOR BACKUP BATTERY			1.0
							ATTERY OPERATION TEST			0.5
									-	1.7
JL1544	200	LOG	AV	52			ORT ITEM SADD \$122: OB2 9 ITEM NOT FOUND IN FAULT TREE (REFER TO	L154	OPEN	09/20/2023
	CAB					,	1809/1 NO.3 OVER WING DOOR BACKUP BATTERY NEED TO REPLACE.(PLS REF TO T" FOR THE REQUIRED ACTION ITEMS)			0.0
						1C 1 PLS MAKE LOG BO	,			0.2
						2C 2 REPLACE THE NO.:	3 LEFT OVER WING DOOR BACKUP BATTERY			1.0
						2C 3 PERFORM EPAS BA	ATTERY OPERATION TEST			0.5
									-	1.7
JL1551	200	LOG	AV	52			ORT ITEM SADD \$123: OB2 9 ITEM NOT FOUND IN FAULT TREE (REFER TO	L155	OPEN	09/20/2023
	CAB					,	1810/1 NO.3 RIGHT OVER WING EPAS BATTERY NEED TO REPLACE. (PLS REF TO T" FOR THE REQUIRED ACTION ITEMS)			0.0
						1C 1 PLS MAKE LOG BO	,			0.2
							3 RIGHT OVER WING DOOR BACKUP BATTERY			1.0
						2C 3 PERFORM EPAS BA	ATTERY OPERATION TEST			0.5
									-	1.7

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

PAGE: 22 OF 86 RUN DATE: 10/2/2023

(By JSN) RUN TIME : 9:39

STAGE: ALL

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL

CTRL CODE :	TYPE CODE:	ORIGINATOR:	ALL

TRL CODE :					TYPE CODE:	ORIGINATOR: ALL			
	ZONE	STG						STATUS	UPDATED DA
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
JL1569	200	NRR	SS	25	777-53-904-00-01	CABIN F/C SEAT BACK SHELL AISLE S/W FOUND SCEATCHED AT 1K 2K 1D 2D 1A 2A(TOTAL 6 EA)	L156	WIP	09/23/2023
	CAB								0.0
						1C 1 REMOVE F/C SEAT PARTITION AISLE BUMPER 1K 2K 1D 2D 2A 1A			2.0
						1C 2 REMOVE F/C SEAT PARTITION AISLE LIGHT 1K 2K 1D 2D 2A 1A			2.0
						1C 3 F/C SEAT PARTITION AISLE BUMPER 1K 2K 1D 2D 2A 1A TEDLAR REPLACE			60.0
						1C 4 REINSTALL F/C SEAT PARTITION AISLE BUMPER 1K 2K 1D 2D 2A 1A			2.0
						2C 5 REINSTALL F/C SEAT PARTITION AISLE LIGHT 1K 2K 1D 2D 2A 1A			2.0
								-	68.
1577	200	LOG	AV	52		AS PER CX B-KPV DEFERRAL REPORT ITEM SADD S124: OB2 9 ITEM NOT FOUND IN FAULT TREE (REFER TO	L157	OPEN	09/20/2023
	CAB					REMARK) AS PER CX WO/TASK 9571811/1 NO.3 RIGHT OVERWING DOOR BACKUP BATTERY NEED TO REPLACE.(PLS			0.0
						REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)  1C 1 PLS MAKE LOG BOOK ENTRY.			0.2
						2C 2 REPLACE THE NO.3 RIGHT OVER WING DOOR BACKUP BATTERY			1.0
						2C 2 REPLACE THE NO.3 RIGHT OVER WING DOOR BACKUP BATTERY  2C 3 PERFORM EPAS BATTERY OPERATION TEST			0.5
						20 3 PERFORM EPAS DATTERT OPERATION TEST		_	0.5
									1
1585	100	LOG	ΑI	38		AS PER CX B-KPV DEFERRAL REPORT ITEM SADD S126: HTP T13 (WO) REF W/O: 9571955/10 BOTTLE WATER UPLIFT	L158	OPEN	09/20/2023
	LWR					REQUIRED. POTABLE WATER SYSTEM-DISINFECTANT TO BE PERFORMED IN HKG. DON'T USE POTABLE WATER FOR BEVERAGE. TOILET FLUSH REMAINS SERVICEABLE. BOTTLE WATER UPLIFT REQUIRED. POTABLE WATER			0.0
						SYS-DISINFECTANT TO BE PERFORMED IN HKG. (CONTINUE TO SWS ITEM 1)			
						1C 1 DON'T USE POTABLE WATER FOR BEVERAGE.			0.0
						TOILET FLUSH REMAIN SERVICEABLE. ACTIONED IAW AMM			
						38-10-00-600-801 REV 05 MAY 2023.(PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION			
						ITEMS)  1C 2 PLS MAKE LOG BOOK ENTRY			0.2
						10 2 I LO WAILE LOO BOOK ENTITY		-	
1593	200	NRR	SS	25	777-53-904-00-01	CABIN F/C SEAT MEAL SIDE DOOR TEDLAR FOUND SCRATCHED AT K1 .1D .(M3)AFT .(M1)AFT .1A. (M2)AFT (TOTAL 6	L159	WIP	09/23/2023
1000	CAB	MIXIX	00	25	777-33-304-00-01	EA)	L159	WIP	
	CAB					'			0.
						1C 1 REMOVE F/C SEAT COMPT DOOR 1K 1D (M3)AFT (M1)AFT (M1)AFT 1A			2.0
						1C 2 REMOVE F/C SEAT COMPT DOOR LIGHT 1D			0.5
						1C 3 F/C SEAT COMPT DOOR 1K 1D (M3)AFT (M1)AFT (M2)AFT 1A TEDLAR REPLACE			60.0
						1C 4 REINSTALL F/C SEAT COMPT DOOR 1K 1D (M3)ADT (M1)AFR (M2)AFT 1A TOTAL 6 WA			2.0
						2C 5 REINSTALL F/C SEAT COMPT DOOR LIGHT 1D			0.5
								-	65

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

DEFECT TYPE: ALL

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

AREA: ALL

PAGE: 23 OF 86

2C

STAGE: ALL

RUN DATE: 10/2/2023

RUN TIME : 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE:

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL ALL CUST ENDORSE: ALL

TRADE: ALL

CTRL CODE :					TYPE CODE:	ORIGINATOR: ALL			
	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL1601	400	LOG	AE	71		AS PER CX B-KPV DEFERRAL REPORT ITEM SADD S127: HTP T13 (WO) , ENGINE 1 REF W/O 9571955 /16 ENG #1 IDG	L160	WIP	09/23/2023
	ENG					PRESERVED ON WING. REMOVE IDG FOR SHOP VISIT WITHIN MAXIMUM OF 25 FLIGHT HOURS. SADD RAISED. ACTIONED IAW AMM 24-11-01 REV 05 MAY 2023.(PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)			0.0
						1C 1 PLS MAKE LOG BOOK ENTRY.			0.2
						2C 2 DISCONNECT NO.1 ENG IDG ELECTRICAL CONNECTOR.			2.0
						2C 3 REPLACE NO.1 ENG IDG.			16.0
						2C 4 RECONNECT NO.1 ENG IDG ELECTRICAL CONNECTOR.			4.0
						2C 5 C/O IPI FOR IDG OIL SVC.			2.0
						3C 6 C/O OPERATIONAL TEST FOR RH IDG.			1.0
						3C 7 C/O OPERATIONAL TEST FOR RH IDG.			1.0
						3C 8 CARRY OUT IPI PROCEDURE OF NO.1 ENG IDG FEEDER CABLE INSTALLATION 3C 9 C/O PART-POWER LEAK CHECK			0.5 1.0
								-	27.7
XJL1619	200	NRR	SS	25	777-53-904-00-01	CABIN F/C SEAT PARTITION POST TEDLAR FOUND TORN AT (M1)FWD/ AFT ,(M3)FWD/AFT TOTAL 4 EA	L161	WIP	09/26/2023
	CAB								0.0
								-	0.0
XJL1627	200	NRR	SS	25	777-53-904-00-01	CABIN F/C SEAT MEAL TABLE PNL TEDLAR FOUND SCRATCHED AT 2A 2D 1D 2K 1K(TOP SIDE )2A 1A 2D 2K	L162	WIP	09/26/2023
	CAB					1K(BOTTOM SIDE) TOTAL 10 EA			40.0
								-	40.0
XJL1635	200	NRR	SS	2500	777-53-904-00-01	CABIN F/C SAET FWD LITERATURE SHROUD SURFACE TEDLAR FOUND SCRATCHED AT 2A 1D 2D 1K 2K TOTAL 5EA	L163	WIP	09/23/2023
	CAB								0.0
						1C 1 REMOVE F/C SEAT LITERATURE SHRPUD 1K 2K 1D 2D 2A			1.0
						1C 2 F/C SEAT MAGAZINE COVER 1K 2K 2A 1D 2D TEDLAR REPLACE			50.0
						1C 3 REINSTALL F/C SEAT LITERATURE SHROUD 1K 2K 2A 1D 2D			1.0
								-	52.0
XJL1643	200	NRR	SS	2500	777-53-920-00-01	CAB-G8 GLY L/H AND R/H S8-01 COMPT DR TEDLAR FND DENT.	L164	WIP	09/25/2023
	CAB								0.0
						1C 1 REMOVE G8 GLY LOWER DOOR S8-01.			0.5
						1C 2 G8 GLY LOWER DOOR S8-01 TEDLAR REPLACE			16.0
						1C 3 REINSTALL G8 GLY LOWER DOOR S8-01.			0.5
								-	17.0

REQUESTED BY:

PROJECT: XJ

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 24 OF 86 RUN DATE: 10/2/2023

RUN TIME:

9:39

REFERENCE NO: BMS571R1-2

CUSTOMER: CX

A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE:

JSN RANGE SELECTED: ALL ORIGINATING CUST REF NO: ALL

515653

ATA NO: ALL

PERIOD: ALL ESTIMATED MHR: ALL ZONE: ALL

DISPOSITION CODE: ALL

2C

DEFECT TYPE: ALL

TRADE: ALL

CUST ENDORSE: ALL

ORIG-STAGE: ALL

AREA: ALL STAGE: ALL

CTRL CODE:

TYPE CODE: ORIGINATOR: ALL

STATUS: ALL

	ZONE	STG								STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRI	L SH NO	D DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL1650	200	NRR	SS	2500	777-53-904-00-01	CAB	#1 DOO	R S1 STOWAGE FWD B/HEAD TEDLAR FOUND SCRATCHED	L165	WIP	09/23/2023
	CAB										0.0
						1C	1	REMOVE S1 STOWAGE FWD B/HEAD BUMPER			0.5
						1C	2	REMOVE S1 STOWAGE FWD B/HAED LIGHT			0.5
						1C	3	REINSTALL S1 STOWAGE FWD B/HAED BUMPER			0.5
						1C	4	REINSTALL S1 STOWAGE FWD B/HAED LIGHT			0.5
						2C	5	S1 STOWAGE FWD B/HAED TEDLAR REPLACE			11.0
										-	13.0
XJL1668	400	LOG	AE	71		AS F	PER CX B	3-KPV DEFERRAL REPORT ITEM SADD S128: HTP T13 WORK ORDER (WO) / WORK CARD, ENGINE 2 REF	L166	WIP	09/25/2023
	ENG					HOU	RS. SADI	I/ 16 ENG #2 IDG PRESERVED ON WING. REMOVE IDG FOR SHOP VISIT WITHIN MAXIMUM OF 25. FLIGHT D RAISED. ACTIONED IAW AMM 24-11-01 REV 05 MAY 23(PLS REF TO ATTACHED "CX DEFERRAL REPORT" QUIRED ACTION ITEMS)			0.0
						1C	1	PLS MAKE LOG BOOK ENTRY.			0.2
						2C	2	DISCONNECT NO.2 ENG IDG ELECTRICAL CONNECTOR.			2.0
						2C	3	REPLACE NO.2 ENG IDG.			16.0
						2C	4	RECONNECT NO.2 ENG IDG ELECTRICAL CONNECTOR.			4.0
						2C	5	C/O IPI FOR IDG OIL SVC.			2.0
						3C	6	C/O OPERATIONAL TEST FOR RH IDG.			1.0
						3C	7	C/O OPERATIONAL TEST FOR RH IDG.			1.0
						3C	8	CARRY OUT IPI PROCEDURE OF NO.2 ENG IDG FEEDER CABLE INSTALLATION			0.5
						3C	9	C/O PART-POWER LEAK CHECK			1.0
										-	27.7
XJL1676	200	NRR	SS	2500	777-53-904-00-01	CAB	-G1C GL	Y C-102 C-103 COMPT DR TEDLAR FND DENT	L167	WIP	09/23/2023
	CAB										0.0
						1C	1	REMOVE G1C GLY C-102 C103 COMPT DOOR			0.5
						1C	2	G1C GLY C-102 C-103 COMP DOOR TEDLAR REPLACE			12.0
						1C	3	REINSTALL G61C GLY C-102 C-103 COMPT DOOR			1.0
										-	13.5

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

DEFECT TYPE: ALL

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

AREA: ALL

PAGE: 25 OF 86 RUN DATE: 10/2/2023

STAGE: ALL

RUN TIME : 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL ALL CUST ENDORSE: ALL

TRADE: ALL

CTRL CODE:  ZONE STG  JOB NO AREA TD ATA ORIG CUST REF NO. CTRL SH NO  AS PER CX B-KPV DEFERRAL REPORT ITEM SADD \$129:HTP T13 WORK ORDER (WO) / WORK CARD, ENGINE 1 REF W/O 9571955 / 16 ENG# 1 BUG PRESERVED ON WING. REMOVE FOR SHOP VISIT WITHIN MAXIMUM 25 HRS. SADD RAISED. ACTIONED IAW AMM 24-25-01 REV 01 MAY 23. (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS) 1C 1 PLS MAKE LOG BOOK ENTRY. 2C 2 DISCONNECT THE NO.1 ENG BUG ELECTRICAL CONNECTOR. 2C 3 REPLACE NO.1 ENG BUG.	STATUS STATUS WIP	UPDATED DATI EST Mhr 09/23/2023 0.0 0.2 2.0
JOB NO AREA TD ATA ORIG CUST REF NO. CTRL SH NO DEFECT DESCRIPTION JSN  XJL1684 400 LOG AE 71 AS PER CX B-KPV DEFERRAL REPORT ITEM SADD \$129:HTP T13 WORK ORDER (WO) / WORK CARD, ENGINE 1 REF W/O 9571955 / 16 ENG# 1 BUG PRESERVED ON WING. REMOVE FOR SHOP VISIT WITHIN MAXIMUM 25 HRS. SADD RAISED. ACTIONED IAW AMM 24-25-01 REV 01 MAY 23. (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS) 1C 1 PLS MAKE LOG BOOK ENTRY. 2C 2 DISCONNECT THE NO.1 ENG BUG ELECTRICAL CONNECTOR.	STATUS	EST Mhr  09/23/2023  0.0  0.2  2.0
AS PER CX B-KPV DEFERRAL REPORT ITEM SADD S129:HTP T13 WORK ORDER (WO) / WORK CARD, ENGINE 1 REF  ENG  W/O 9571955 / 16 ENG# 1 BUG PRESERVED ON WING. REMOVE FOR SHOP VISIT WITHIN MAXIMUM 25 HRS. SADD  RAISED. ACTIONED IAW AMM 24-25-01 REV 01 MAY 23. (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE  REQUIRED ACTION ITEMS)  1C 1 PLS MAKE LOG BOOK ENTRY.  2C 2 DISCONNECT THE NO.1 ENG BUG ELECTRICAL CONNECTOR.		09/23/2023 0.0 0.2 2.0
ENG  W/O 9571955 / 16 ENG# 1 BUG PRESERVED ON WING. REMOVE FOR SHOP VISIT WITHIN MAXIMUM 25 HRS. SADD  RAISED. ACTIONED IAW AMM 24-25-01 REV 01 MAY 23. (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE  REQUIRED ACTION ITEMS)  1C 1 PLS MAKE LOG BOOK ENTRY.  2C 2 DISCONNECT THE NO.1 ENG BUG ELECTRICAL CONNECTOR.	****	0.0 0.2 2.0
1C 1 PLS MAKÉ LOG BOOK ENTRY. 2C 2 DISCONNECT THE NO.1 ENG BUG ELECTRICAL CONNECTOR.		2.0
2C 2 DISCONNECT THE NO.1 ENG BUG ELECTRICAL CONNECTOR.		2.0
		12.0
2C 4 RECONNECT NO.1 ENG BUG THE ELECTRICAL CONNECTOR.		3.0
2C 5 C/O IPI FOR NO.1 ENG BUG OIL SVC.		2.0
3C 6 C/O NO.1 ENG PART-POWER LEAK CHECK.		1.0
3C 7 DO THE NO.1 BUG INSTALLATION TEST.		1.0
3C 8 TRANSFER TERMINAL BLOCK ADAPTER FROM OLD TO NEW BACKUP GENERATOR		2.0
3C 9 C/O IPI PROCEDURE FOR NO.1 BACKUP GENERATOR PHASE LEADS		0.5
		23.7
AS PER CX B-KPV DEFERRAL REPORT ITEM SADD \$130: HTP T13 WORK ORDER (WO) / WORK CARD, ENGINE 2 REF L169  ENG W/O 9571955 / 16 ENG# 2 BUG PRESERVED ON WING. REMOVE FOR SHOP VISIT WITHIN MAXIMUM 25 HRS. SADD	WIP	09/25/2023
RAISED ACTIONED IAW AMM 24-25-01 REV 05 MAY 2023.(PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)		0.0
1C 1 PLS MAKE LOG BOOK ENTRY.		0.2
2C 2 DISCONNECT THE NO.2 ENG BUG ELECTRICAL CONNECTOR.		2.0
2C 3 REPLACE NO.2 ENG BUG.		16.0
2C 4 RECONNECT NO.2 ENG BUG THE ELECTRICAL CONNECTOR.		3.0
2C 5 C/O IPI FOR NO.2 ENG BUG OIL SVC.		2.0
3C 6 C/O NO.2 ENG PART-POWER LEAK CHECK.		1.0
3C 7 DO THE NO.2 BUG INSTALLATION TEST.		1.0
3C 8 TRANSFER TERMINAL BLOCK ADAPTER FROM OLD TO NEW BACKUP GENERATOR		2.0
3C 9 C/O IPI PROCEDURE FOR NO.2 BACKUP GENERATOR PHASE LEADS		0.5
	•	27.7
KJL1700         200         NRR         SS         2500         777-53-904-00-01         CAB #1 DOOR G1L GALLEY AFT B/HEAD TEDLAR FOUN DENT         L170	WIP	09/23/2023
CAB		0.0
1C 1 REMOVE G1L GLY AFT B/HEAD PNL		0.5
1C 2 REBOND G1L GLY AFT B/HEAD PNL TEDLAR REPLACE		11.0
1C 3 REINSTALL G1L GLY AFT B/HEAD PNL		0.5
		12.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 26 OF 86

RUN DATE: 10/2/2023

RUN TIME: 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRI CODE : TYPE CODE : ORIGINATOR : ALL

RL CODE :					TYPE CODE:		ORIGINATOR: ALL			
	ZONE	STG							STATUS	UPDATED DA
OB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH N	D DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
L1718	200	NRR	SS	25	777-53-904-00-01	CABIN F/C S	EAT CLOSET COMPT DOOR TEDLAR FOUND SCEATCHED AT M3	L171	WIP	09/23/2023
	CAB									0.0
						1C 1	REMOVE F/C SEAT CLOSET COMPT DOOR			1.0
						1C 2	F/C SEAT CLOSET COMPT DOOR (M3)TEDLAR REPLACE			11.0
						1C 3	REINSTALL F/C SEAT CLOSET COMPT DOOR			1.0
									-	13.0
1726	200	LOG	SS	25			KPV DEFERRAL REPORT ITEM SADD S131: HTP T13(WO) REF W/O 9571960 TO PERFORM AEO-27666	L172	OPEN	09/20/2023
	CAB					WILL BE FEF	-27669 PART 1 NO LATER THAN 6 FC AFT OCTOBER 7 2022 UNTIL DECEMBER 31, 2024.6 FLIGHT CYCLES RY FLIGHTS WITH NO PASSENGERS ONBOARD. AFT EMBODIMENT OF MODIFICATION AS PER AEO-27666 O-27669 PART 1, CLEAR SADD RAISED AGAINST THIS AEO PART 1.(CONTINUE TO SWS ITEM 1)			0.0
						1C 1	SADD RAISED AS PER INSTRUCTIONS IN AEO 29541 REV 00. ACTIONED IAW OTHER AEO-29541 REV REV 00.(PLS			0.0
						1C 2	REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS) PLS MAKE LOG BOOK ENTRY.			0.2
									-	0.:
1734	100	LOG	Al	26		AS PER CX	R-KPV DEFERRAL REPORT ITEM SADD S133: OB2 9 ITEM NOT FOUND IN FAULT TREE (REFER TO	L173	WIP	09/28/2023
	LWR					,	NO : 9571803/1 C/O REPLACEMENT OF CGO COMPARTMENT FIRE EXTINGUISHING BOTTLES SQUIB			0.0
							FOR BOTTLE 2A SERIAL NO: 1610BA PART NO : 473876-3 AS PER AMS LIST ACTIONED IAW AMM 26-23-01			0.0
						REV 05 MAY 1C 1	2023.(PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS) PLS MAKE LOG BOOK ENTRY.			0.2
						2C 2	REMOVE THE FIRE BOTTLE SQUIB			1.0
						2C 2	DISCONNECT THE ELECTRICAL CONNECTOR OF FIRE BOTTLE SQUIB			0.5
						2C 4	CONNECT THE ELECTRICAL CONNECTOR OF FIRE BOTTLE SQUIB			0.5
						2C 5	INSTALL THE FIRE BOTTLE SQUIB			1.0
						3C 6	CARRY OUT CARGO FIRE EXTINGUISHING SQUIBS OPERATIONAL TEST			1.0
						4C 7	DO A CHECK OF THE RESISTANCE BETWEEN THE FIRE EXTINGUISHING BOTTLE AND THE BONDING BRACKET			1.0
						4C 8	CARRY OUT CARGO FIRE EXTINGUISHING PRESSURE SWITCH OPERATIONAL TEST			1.0
						5C 9	CARGO FIRE EXTINGUISHING BOTTLE PRESSURE SWITCH - OPERATIONAL TEST			1.0

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PERIOD: ALL

27 OF 86 PAGE:

RUN TIME :

ESTIMATED MHR: ALL

RUN DATE: 10/2/2023

9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

ORIG-STAGE: ALL ORIGINATING CUST REF NO: ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE : TYPE CODE: ORIGINATOR ·

STATUS: ALL

CTRL CODE :					TYPE CODE:		ORIGINATOR: ALL		CTATUC	LIDDATED DAT
JOB NO	ZONE AREA	STG	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS STATUS	UPDATED DAT EST Mhr
L1742	100	LOG	Al	26	ONIO COCT NEI NO.		KPV DEFERRAL REPORT ITEM SADD S134: OB2 9 ITEM NOT FOUND IN FAULT TREE (REFER TO	L174	OPEN	09/20/2023
·-··-	LWR					REMARK) WO N	NO : 9571801/1 C/O REPLACEMENT OF CARGO COMPARTMENT FIRE EXTINGUISHER BOTTLES SQUIB OR 2D SERIAL NO : 1544BA PART NO: 473876-3 AS PER AMS LIST ACTIONED IAW AMM 26-23-01 REV 05 S REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)	LITT	OFLIN	0.0
						1C 1	PLS MAKE LOG BOOK ENTRY.			0.2
						2C 2	REMOVE THE FIRE BOTTLE SQUIB			1.0
						2C 3	DISCONNECT THE ELECTRICAL CONNECTOR OF FIRE BOTTLE SQUIB			0.5
						2C 4	CONNECT THE ELECTRICAL CONNECTOR OF FIRE BOTTLE SQUIB			0.5
						2C 5	INSTALL THE FIRE BOTTLE SQUIB			1.0
						3C 6	CARRY OUT CARGO FIRE EXTINGUISHING SQUIBS OPERATIONAL TEST			1.0
						4C 7	DO A CHECK OF THE RESISTANCE BETWEEN THE FIRE EXTINGUISHING BOTTLE AND THE BONDING BRACKET			1.0
						4C 8	CARRY OUT CARGO FIRE EXTINGUISHING PRESSURE SWITCH OPERATIONAL TEST			1.0
									-	6.2
L1759	500 F/T	NRM	AE	5708	AEO-28656-01	LHW FUEL TAN	NK ACCESS DOORS 532AB GASKET FOUND WORN	L175	OPEN	09/20/2023
	171									1.0
									-	1.0
L1767	200	NRR	SS	2500	777-53-904-00-01	CABIN PARTITI	TION R/H LOWER SURFACE FOUD SCRATHED	L176	WIP	09/29/2023
	CAB									8.0
									-	8.0
L1775	600	NRM	AE	5700	AEO-28656-02	RHW FUEL TAN	NK ACCESS DOORS632AB GASKET FOUND WORN	L177	OPEN	09/20/2023
	F/T									1.0
									-	1.0
IL1783	200	NRR	SS	2500	777-53-908-00-01	CABIN #2 DOO	OR G3 GLY R/H AISLE S/W FOUND SCRATCHED	L178	WIP	09/24/2023
	CAB									0.0
						1C 1	REMOVE G3 GLY RHS AISLE LIGHT			0.5
						1C 2	REMOVE G3 GLY RHS AISLE PNL			1.0
						1C 3	G3 GLY RHS AISLE TEDLAR REPLACE			11.0
						1C 4	REINSTALL G3 GLY RHS AISLE PNL			1.0
						2C 5	REINSTALL G3 GLY RHS AISLE LIGHT			0.5
									-	14.0
L1791	200	NRR	ΑI	2531	777-53-908-00-01	CABIN G2 GAL	LERY COMPARTMENT 203 LOWER GUIDE BUMPER FOUND DAMAGE	L179	OPEN	09/20/2023
	CAB									5.0
									-	5.0

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

AREA: ALL

PAGE: 28 OF 86

RUN DATE: 10/2/2023

(By JSN) RUN TIME : 9:39

STAGE: ALL

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL JSN RANGE SELECTED: ALL

ORIGINATING CUST REF NO: ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL CTRL CODE : TYPE CODE: ORIGINATOR · ALL

CTRL CODE :					TYPE CODE:		ORIGINATOR: ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL1809	200 CAB	NRR	SS	2500	777-53-908-00-01	CABIN #2 DOOR	G2R GLY L/H AISLE S/W FOUND SCRATCHED	L180	WIP	09/23/2023
	CAB									0.0
							REMOVE G2R GLY LHS AISLE PNL			0.5
							REMOVE G2RGLY LHS AISLE LIGHT			0.5
							G2RGLY LHS AISLE TEDLAR REPLACE REINSTALL G2R GLY LHS AISLE PNL			11.0 0.5
							REINSTALL GZR GLY LHS AISLE LIGHT			0.5
						20 0 1	ACINOTALE OZNOCI ETO MOCE ETOTA		-	
										13.0
XJL1817	200	NRR	SS	2500	777-53-920-00-01	CAB-G7 GLY G7	02 COMPT DR TEDLAR FND DENT.	L181	WIP	09/25/2023
	CAB									0.0
						1C 1 I	REMOVE G7 GLY 702 COMPT DOOR			0.5
							G7 GLY 702 COMPT DOOR TEDLAR REPLACE			6.0
						1C 3 I	REINSTALL G7GLY 702 COMPT DOOR			0.5
									-	7.0
XJL1825	100	LOG	ΑI	26			PV DEFERRAL REPORT ITEM SADD S135: OB2 9 ITEM NOT FND IN FAULT TREE (REF REMARK)WO NO:	L182	WIP	09/20/2023
	LWR					PART :446347-1 F	EPLACE OF CGO FIRE EXTINGUISHING FLOW VALVE FOR SQUIB CARTRIDGE REPLACE SERIAL:2186 FWD CGO LOCATION-FWD PN-446347-1, SN-2186 MEL RAISED AS PER AMS LIST ACTIONED IAW AMM MAY 2003 (DIS DEE TO ATTACHED BOY DEFENDAL REPORT			0.0
							MAY 2023.(PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS) PLS MAKE LOG BOOK ENTRY.			0.2
						-	REMOVE THE FLOW VALVE			2.0
						2C 3 I	DISCONNECT ELECTRICAL PLUG OF THE FLOW VALVE			0.5
						2C 4	CONNECT ELECTRICAL PLUG OF THE FLOW VALVE			0.5
						2C 5 I	INSTALL THE FLOW VALVE			2.0
						3C 6	CARRY OUT FIRE EXTINGUISHING SQUIBS OPERATIONAL TEST			1.0
									-	6.2
XJL1833	200	NRR	ΑI	2531	777-53-908-00-01	CABIN G3 GALLE	ERY 301 RH LOWER MATEL TRIM FOUND MISSING	L183	OPEN	09/20/2023
	CAB									5.0
									-	5.0
XJL1841	100	NRR	AE	5300	777-53-800-00-09	FUSELAGE LOW	/ER HALF TOTAL 15 EA DRAIN VALVE AGED	L184	OPEN	09/20/2023
	FUS									2.0
									-	2.0

515653

REQUESTED BY:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

PAGE: 29 OF 86

STAGE: ALL

RUN DATE: 10/2/2023

REFERENCE NO: BMS571R1-2 (By JSN) RUN TIME : 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL

CTRL CODE:	TYPE CODE:	

RL CODE :					TYPE CODE:		ORIGINATOR: ALL			
	ZONE	STG							STATUS	UPDATED DA
OB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
L1858	100 LWR	LOG	Al	26			PV DEFERRAL REPORT ITEM SADD S136:OB2 9 ITEM NOT FND IN FAULT TREE WO NO: 9571799/1 C/O ARGO FIRE EXTINGUISHER AFT FLOW VALVE FOR SQUIB CARTRIDGE REPLACE SERIAL: 2187 PART :	L185	WIP	09/22/2023
	LVVIX						CGO LOCATION-AFT PN-446347-1 SN-2187 MEL RAISED AS PER AMS LIST. ACTIONED IAW AMM 26-23-02 23. (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)			0.0
							PLS MAKE LOG BOOK ENTRY.			0.2
							REMOVE THE FLOW VALVE			2.0
							DISCONNECT ELECTRICAL PLUG OF THE FLOW VALVE			0.5
							CONNECT ELECTRICAL PLUG OF THE FLOW VALVE			0.5
							INSTALL THE FLOW VALVE			2.0
						3C 6	CARRY OUT FIRE EXTINGUISHING SQUIBS OPERATIONAL TEST			1.0
									-	6
866	600	LOG	ΑE	27			PV DEFERRAL REPORT ITEM SADD \$138:0B2 9 ITEM NOT FOUND IN FAULT TREE (REFER TO REMARK)	L186	COMP	09/23/2023
	WNG						9571807/1 RH WING SPOILER AUXILIARY RETRACT DEVICE (SARD) PYROTECHNIC CARTRIDGE NEED			0.
						- '	PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS) PLS MAKE LOG BOOK ENTRY.			0.2
						10 1	FLS MARE LOG DOOK ENTRY.		_	
										(
1874	200	NRR	SS	2500	777-53-908-00-01	CAB #2 DOOR S	S1R UPPER B/HEAD TEDLAR FOUND SCRATCHED	L187	WIP	09/26/2023
	CAB									10
									-	10
882	500	LOG	ΑE	27			PV DEFERRAL REPORT ITEM SADD S139: 275 022 02 FLAP/SLAT CONTROL 2 (STATUS) EARLY IN	L188	WIP	09/22/2023
	WNG					LATCHED. MEL	STATUS MESSAGE PHASE OF FLIGHT: CRUISE FIM 27-82 TASK 806 FOLLOWED, CONFIRM THE MSG IS APPLIED DUE TIME. MAINT PROCEDURE CARRIED OUT IAW AMM27-00-00 REV SEP23. (PLS REF TO			0.
							DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)			0.2
							PLS MAKE LOG BOOK ENTRY. PERFORM T/S AS			2.0
							C/O WIRING CHECK SLAT PRIMARY CONTROL VALVE V27003 RESISTANCE CHECK			2.0
							DISCONNECT THE ELECTRICAL CONNECTORS			0.5
							REMOVE THE LEFT WHEEL WELL SLAT PRIMARY CONTROL VALVE V27003			6.0
							INSTALL THE LEFT WHEEL WELL SLAT PRIMARY CONTROL VALVE V27003			8.0
							CONNECT THE ELECTRICAL CONNECTORS FOR THE SLAT PRIMARY CONTROL VALVE			1.0
							CARRY OUT BONDING TEST BETWEEN THE VALVE ASSEMBLY AND STRUCTURE			1.0
						. 5	CARACT GOT BOADING TEST BETWEEN THE WALVE MODERNIET AND OTHOGOTORE			2.0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 30 OF 86

RUN TIME :

RUN DATE: 10/2/2023

9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

CUST ENDORSE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

DEFECT TYPE: ALL

NO: ALL

ATA NO: ALL

ZONE : ALL AREA : ALL DISPOSITION CODE: ALL

STAGE

STAGE: ALL

CTRL CODE:

TYPE CODE: ORIGINATOR: ALL

TRADE: ALL

INL CODE .					TIFE CODE.		ONIGINATOR: ALL	
	ZONE	STG					STATU	IS UPDATED DAT
OB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH	O DEFECT DESCRIPTION JSN STATE	IS EST Mhr
JL1890	100	NRR	AV	3100	777-53-832-00-01	PLEASE D	SCONNECT AND CONNECT THE LOWER BODY ANTI-COLLISION LIGHT CONNECTIONS FOR ACCESS L189 WIP	09/25/2023
	FUS							0.0
						1C 1	DISCONNECT CONNECTOR OF LOWER ANTI-COLLISION LIGHT	1.0
						1C 2	RECONNECT CONNECTOR OF LOWER ANTI-COLLISION LIGHT	1.0
						1C 3	PERFORM TEST OF LOWER ANTI-COLLISION LIGHT	0.5
								2.5
IL1908	200	NRR	SS	25	777-53-912-00-01	CABIN FB2	SEAT PARTITION SIDE CONSOLE AREA TEDLAR BUBBLE AT 11G 26K 26D 11K 18K TOTAL 5 EA L190 WIP	09/23/2023
	CAB							0.0
						1C 1	REMOVE FB2 SEAT PARTITION SIDE CONSOLE AREA BUMPER 11G 26G 26D 11K 18K TOTAL 5 EA	2.0
						1C 2	FB2 SEAT PARTITION SIDE CONSOLE AREA BUMPER 11G 11K 26K 26D 11K 18K TEDLAR REPLACE	50.0
						1C 3	REINSTALL FB2 SEAT PARTITION SIDE CONSOLE AREA BUMPER 11G 26G 26D 11K 18K	2.0
								54.0
L1916	200	LOG	AV	33			B-KPV DEFERRAL REPORT ITEM SADD S140:353 101 -1 PORTABLE OXYGEN DISPENSING UNITS L191 OPEN	09/20/2023
	CAB					R3, L4, R4, DATE TO 1	ASKS) REF Z242 PORTABLE OXY CYLINDER 9EA AT LOCATIONS R1, L2, L3(2EA), 5&R5 FND EXPIRED. TO SADD DUE TO SPARE N/S, EXPIRED POB&MASK 9EA WERE REMOVED. ADD BACK SEP23. ACTIONED IAW OTHER MEL 35-31-01 REV MAR23. (PLS REF TO ATT "CX DEFERRAL REPORT" FOR	0.0
						THE REQU	RED ACTION ITEMS) PLS MAKE LOG BOOK ENTRY.	0.2
						10 1	PLS WARE LOG BOOK ENTRY.	
								0.2
JL1924	200	NRR	SS	2500	777-53-904-00-01	CAB-CLOS	ET S2CR-01 COMPT DR TEDLAR FND DENT. L192 WIP	09/23/2023
	CAB							0.0
						1C 1	REMOVE CLOSET S2CR -01COMPT DOOR	0.5
						1C 2	CLOSET S2CR-01 COMPT DOOR TEDLAR REPLACE	6.0
						1C 3	REINSTALL CLOSET S2CR-01 COMPT DOOR	0.5

ORIGINATING CUST REF NO:

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 31 OF 86

RUN TIME :

ESTIMATED MHR: ALL

STAGE: ALL

DISPOSITION CODE: ALL

RUN DATE: 10/2/2023

9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

STATUS: ALL JSN RANGE SELECTED: ALL

ALL

PERIOD: ALL ORIG-STAGE: ALL

ATA NO: ALL ZONE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL

CTRL CODE :					TYPE CODE:	ORIGINATOR: ALL			
	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL1932	100	NRP	AV	3831	777-53-545-01-01	PLEASE DISCONNECT AND CONNECT THE FUS LOWER FWD DRAIN MAST CONNECTIONS FOR ACCESS	L193	WIP	09/27/2023
	FUS								0.0
						1C 1 DISCONNECT THE ELECTRICAL SPLICE CONNECTIONS TO THE DRAIN MAST			0.0
						1C 2 DISCONNECT THE DRAIN HOSE FROM THE DRAIN MAST			0.5
						1C 3 DISCONNECT THE THE GROUND CONNECTION AND BONDING JUMPER TO STRUCTURE			0.5
						1C 4 CONNECT THE THE GROUND CONNECTION AND BONDING JUMPER TO STRUCTURE			0.5
						2C 5 CONNECT THE DRAIN HOSE FROM THE DRAIN MAST			0.5
						2C 6 CONNECT THE ELECTRICAL SPLICE CONNECTIONS TO THE DRAIN MAST			2.0
						2C 7 CHECK THAT THE RESISTANCE BETWEEN THE BONDING JUMPER TERMINAL AND THE STRUCTURE DOES NOT EXCEED 1. MILLIOHMS			0.5
						2C 8 APPLY THE SEALANT TO BONDING JUMPER TERMINAL			0.5
						3C 9 MAKE SURE THAT THE WATER FLOWS FROM THE FORWARD DRAIN MAST WITHOUT LEAKAGE			0.5
						3C 10 DO DRAIN MAST AND GRAY WATER DRAIN LINE HEATERS OPERATIONAL TEST			0.5
								-	6.0
XJL1940	100	NRR	Al	5234	777-52-190-00-01	FWD CGO DOOR ROTARY ACTUATOR FOUND NOISY	L194	WIP	09/29/2023
	LWR								0.0
						1C 1 REMOVE FWD CARGO ROTARY ACTUATORS			6.0
						1C 2 INSTALL FWD CARGO ROTARY ACTUATORS			6.0
						1C 3 DO THE LIFT MECHANISM ADJUSTMENT			10.0
						1C 4 CARRY OUT FWD CARGO ROTARY ACTUATORS INSTALLATION TEST			2.0
								-	24.0
XJL1957	200	LOG	AV	26		AS PER CX B-KPV NOTICE TO FLIGHT AND GROUND CREW NTC001:THIS AIRCRAFT IS INSTALLED WITH 2 CREW	L195	COMP	09/26/2023
	CAB					OXYGEN CYLINDERS. (AEO-26231: OXYGEN - CREW OXYGEN SYSTEM - INSTALLATION OF ADDITIONAL CREW			0.2
						OXYGEN CYLINDER HAS BEEN EMBODIED.		_	
									0.2
XJL1965	200	LOG	AV	11		AS PER CX B-KPV NOTICE TO FLIGHT AND GROUND CREW NTC002: AEO-27365 INCORPORATED THE GOGO 2KU CONNECTIVITY RADOME STC HKCAD STC-2018-11 (FAA STC ST04240CH) ON THIS AIRCRAFT.	L196	COMP	09/26/2023
	CAB								0.2
								-	0.2
XJL1973	200	NRR	PT	5121	777-53-908-00-01	M/D 1-5# DOOR FUSELAGE EDGE FND PAINT CHIPPED TTL:10EA	L197	COMP	09/28/2023
	CAB								30.0
								-	30.0
XJL1981	200	NRR	PT	2500	777-53-904-00-01	M/D B/C SEAT UPPER AROUND BUMPER SURFACE FND PAINT CHIPPED TTL:9EA	L198	OPEN	09/20/2023
	CAB								54.0
								-	54.0

0PPC DISTRIBUTION:

ORIGINATING CUST REF NO:

515653

ALL

REQUESTED BY:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

32 OF 86 PAGE:

ESTIMATED MHR: ALL

RUN DATE: 10/2/2023

9:39

REFERENCE NO: BMS571R1-2 (By JSN) RUN TIME :

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

TRADE: ALL DEFECT TYPE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE :	70NF	CTC			TYPE CODE:	ORIGINATOR: ALL			STATUS	UPDATED DAT
JOB NO	ZONE AREA	SIG	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
(JL1999	200	LOG	AV	12			IND CREW NTC003:AEO-27365 INCORPORATED THE GOGO 2KU	L199	COMP	09/26/2023
	CAB					CONNECTIVITY CABIN STC HKCAD STC-2018-12 (I		2100	OOM	0.2
									-	0.2
JL2005	200	NRR	PT	5121	777-53-908-00-01	M/D 1-5# DOOR FRAME EDGE FND PAINT CHIPPE	D TTI ·10F∆	L200	COMP	09/28/2023
012000	CAB			0121	777 00 000 00 01	WID 1 OF BOOK TO WILL EDOL THE TAINT OF IT I		L200	COMP	20.0
									-	
JL2013	200	NRR	PT	2525	777-53-908-00-01	C/A SEAT SURFACE FND CHIPPED AT: 1#DOOR	E#DOOD TTI - 16EA	1.004	OPEN	20.0
JL2013	CAB	MIXIX	FI	2020	777-33-900-00-01	CIA SEAT SURFACE FIND CHIFFED AT. 1#DOOK	OFFICIAL TIES	L201	OPEN	09/20/2023
									-	
III 2024	200	NRR	DT	0500	777 52 004 00 04	M/D L/D 4 DOOD LINKSE OOVED END DAINT OUR	TTI OFA			8.0
JL2021	200 CAB	NKK	PT	2500	777-53-904-00-01	M/D L/R 1 DOOR HINGE COVER FND PAINT CHIP	III:ZEA	L202	COMP	09/28/2023
									_	4.0
										4.0
JL2039	200 CAB	NRR	PT	5121	777-53-908-00-01	M/D ENTER DOORS FITTING FND FND PAINT CHI	P TTL:10EA	L203	WIP	10/02/2023
	O/ LD								_	10.0
										10.0
JL2047	200 CAB	LOG	Al	56			IND CREW NTC004: L1 WINDSHIELD HAS SCARTCH ON INNER PANE ES IN LENGTH & LESS THAN 0.001 INCH IN DEPTH. WITHIN LIMITS /	L204	WIP	10/02/2023
	CAB					VISION IS NOT IMPAIRED.				0.2
									-	0.2
JL2054	200	LOG	AE	25		AS PER CX B-KPV NOTICE TO FLIGHT AND GROU FROM MOBIL JET II TO ETO2197 POST THE ACCO	IND CREW NTC006: BOTH ENGINE OIL TYPE HAS BEEN CHANGED	L205	COMP	09/22/2023
	CAB					PROMIMOBIL JET II TO ETOZ197 POST THE ACCO	MPLISHMENT OF AEO-25935.			0.2
									-	0.2
JL2062	500	LOG	AE	28			IND CREW NTC007: MAIN FUEL TANK WATER SCAVENGE SYSTEM	L206	COMP	09/22/2023
	F/T					SB 777-28-0078 REV 02.	EM HAVE BEEN MODIFIED PER AEO-19540 ISSUED AGAINST BOEIN	J.		0.2
									-	0.2
JL2070	200	LOG	Al	56			IND CREW NTC008: R2 WINDOW DELAMINATED LWR FWD CORNER	3" L207	WIP	10/02/2023
	CAB					X 0.5" VISION NOT IMPAIRED.				0.2
									-	0.2

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 33 OF 86

ESTIMATED MHR: ALL

RUN DATE: 10/2/2023

RUN TIME: 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE:					TYPE CODE:	ORIGINATOR :	: ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL2088	200	LOG	Al	56			SHT AND GROUND CREW NTC009: L2 WINDOW DELAMINATED ALL FWD EDGE	L208	WIP	10/02/2023
	CAB					APPROX 0.5" WIDE VISION NOT IMPA	AIKEU.			0.2
									-	0.2
XJL2096	200	LOG	ΑI	25			SHT AND GROUND CREW NTC010: THIS AIRCRAFT IS FITTED WITH THE ETECHLOG	L209	COMP	09/28/2023
	CAB						ECORD. THE IPAD EFB DEVICE IS STORED IN THE AML/CDML. THE PAPER  AS A BACKUP ONLY. COMPLY 365 IS INSTALLED IN BOTH FLIGHT DECK IPAD AND  ANUALS.			0.2
									-	0.2
XJL2104	200	LOG	Al	25		AS PER CX B-KPV NOTICE TO FLIGH	HT AND GROUND CREW NTC011: ACTIVE NTC/NTCC ENTRIES HAVE BEEN	L210	COMP	09/22/2023
	CAB						CHLOG WHICH IS NOW THE PRIMARY MEANS TO CONSULT NTC/NTCC ON THIS  AML/CDML SHALL BE USED DURING PAPER FALLBACK ONLY. (REF: AEO-28695)			0.2
						AIRONALT TAIL. LAI LINGOLILO IN A	NINE OF THE DE COLD DOMING I AT ENT ALLBAON ONET. (NET . NEC-2000)		-	0.2
XJL2112	200	LOG	AV	25		AS PER CY R-KPV NOTICE TO FLIGH	SHT AND GROUND CREW NTC012: SB777-22A0046/AEO-29595 AFCS S/W	L211	WIP	09/26/2023
AULZTIZ	CAB	LOO	710	20		2275-COL-AA6-12 EMBODIED ON THI	HIS AIRCRAFT. THIS SB CANCELS FCOM OMB CAT-136 ERRONEOUS AFDS	LZII	VVIP	09/20/2023
						GUIDANCE WHEN ILS SIGNAL INTER EMBODIED.	RFERENCE OCCURS. THIS NTC IS VALID UNTIL 1 MONTH AFTER ALL AIRCRAFTS			0.2
									-	0.2
XJL2120	200	LOG	AV	31		AS PER CX B-KPV NOTICE TO FLIGH	SHT AND GROUND CREW NTC013: AEO-29174/SB 777-31A0342 EMBODIED ON THIS	L212	COMP	09/26/2023
	CAB					, , , , , , , , , , , , , , , , , , , ,	BLOCK POINT V17C INTRODUCTION". THIS NTC IS VALID UNTIL FLEET UPGRADE	22.2	COM	0.2
						COMPLETED.			-	
V II 0400	000	100	4) (	00		AO DED OVER VERVAIGTIGE TO FLICH	NUT AND ODDING ODDING ODDING THE ADODAETIENOING HAVE DEEN FOURDED			0.2
XJL2138	200 CAB	LOG	AV	23			iHT AND GROUND CREW NTC014: THE AIRCRAFT/ENGINES HAVE BEEN EQUIPPED 730A-GECA08- 06 (A.0.8.6) REF SB 777-73-0037/AEO-29704.	L213	OPEN	09/20/2023
	02								_	0.2
										0.2
XJL2146	200 CAB	LOG	Al	25			HT AND GROUND CREW NTCC001: THIS AIRCRAFT IS FITTED WITH THE IENANCE RECORD. THE IPAD EFB DEVICE IS STORED IN THE AML/CDML. THE	L214	COMP	09/28/2023
	CAB						NBOARD AS A BACKUP ONLY. COMPLY 365 IS INSTALLED IN BOTH FLIGHT DECK			0.2
						IPAD AND CABIN IPAD WITH OPERA	ATIONAL MANUALS.		_	
										0.2
XJL2153	200 CAB	LOG	Al	28			HT AND GROUND CREW NTCC002:ACTIVE NTC/NTCC ENTRIES HAVE BEEN CHLOG WHICH IS NOW THE PRIMARY MEANS TO CONSULT NTC/NTCC ON THIS	L215	COMP	09/28/2023
	OAD						AML/CDML SHALL BE USED DURING PAPER FALLBACK ONLY. (REF : AEO-28695)			0.2
									-	0.2

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 34 OF 86 RUN DATE: 10/2/2023

2C

RUN TIME : 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE:

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL ZONE : ALL DISPOSITION CODE : ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

TRL CODE :					TYPE CODE:	ORIGINATOR :	ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
KJL2161	200 CAB	LOG	AV	23		AS PER CX B-KPV NOTICE TO FLIGHT BY PAX, REFER TO GOGO SYSTEM HE	AND GROUND CREW NTCC501: WHEN WI-FI CONNECTIVITY ISSUE REPOR TED EALTH APP ON S	L216	COMP	09/26/2023
	CAB					CCM/SP TABLET. GREEN BAR INDICAT	TES ALL SYSTEMS A RE ONLINE AND NO RESET REQUIRED. REPORT THE CONN IL VIA THE GOGO SYSTEM HEALTH APP AND FLIGHT JOURNAL. DO NOT RA ISE			0.2
									-	0.2
JL2179	200	NRR	Al	2500	777-53-908-00-01	CABIN G3 GALLERY COMPARTMENT	311 BOTTOM BUMPERS FOUND CRACKED	L217	OPEN	09/21/2023
	CAB									3.0
									-	3.0
JL2187	600	NRR	GW	5700	777-57-980-02-01	RHW #7 FIXED FAIRING 676BB SCREV	V (2EA) FOUND SEIZED	L218	COMP	09/26/2023
	WNG									2.0
									-	2.0
L2195	600	NRR	GW	5700	777-57-984-02-01	RHW #8FIXED FAIRING 677DREW (3E/	A) FOUND SEIZED	L219	COMP	09/26/2023
	WNG									3.0
									-	3.0
JL2203	600	NRR	SM	5700	777-57-984-02-01	RHW #8FIXED FAIRING 677DR (3EA) A	NCHOR NUT FOUND WORN	L220	OPEN	09/21/2023
	WNG									1.5
									-	1.5
IL2211	600	NRR	SM	5700	777-57-980-02-01	RHW #7 FIXED FAIRING 676BB ANCHOR NUT (2EA) FOUND WORN	L221	OPEN	09/21/2023	
	WNG									1.0
									-	1.0
IL2229	500	NRR	AE	2780	777-57-806-01-01	MANUAL RETRACT L/E SLAT FOR T/R	MAINTENANCE(WITHOUT ELEC POWER)	L222	WIP	09/24/2023
	WNG									0.0
						1C 1 REMOVE SLAT ELECT	RICAL MOTOR			0.0
						1C 2 DISCONNECT L/E SLA	T ELEC PLUG			0.0
						1C 3 MANUAL RETRACT L/E	E SLAT			0.0
						1C 4 EXTENDED L/E SLAT				0.0
						2C 5 REINSTALL L/E SLAT I				0.0
						2C 6 RECONNECT SLAT MO				0.0
						2C 7 C/O L/E SLAT SYSTEM	ITEST			0.0

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 3

STAGE: ALL

35 OF 86

RUN DATE: 10/2/2023

RUN TIME: 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE : ALL TRADE : ALL CUST ENDORSE : ALL AREA : ALL

CTRL CODE : TYPE CODE : ORIGINATOR : ALL

CTRL CODE :					TYPE CODE:	ORIGINATOR	: ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL2237	600	NRR	CL	5711	777-57-984-02-01	RHW (#5~8)FLAP TRACK AND FAIR	RING INTERNAL FOUND DIRTY	L223	COMP	09/28/2023
	WNG									18.0
									-	18.0
XJL2245	200	NRR	PT	2500	777-53-904-00-01	COCKPIT OBSERVER SEAT HANDE	RAIL SURFACE AND SIDE STOWAGE FOUND PAINT PEEL OFF	L224	OPEN	09/21/2023
	CAB									4.0
									-	4.0
XJL2252	500	NRR	CL	57	777-57-892-01-01	LHW (#1~4 )FLAP TRACK AND FAIR	RING INTERNAL FOUND DIRTY	L225	COMP	09/28/2023
	WNG									18.0
									-	18.0
XJL2260	200	NRR	Al	25	777-53-916-00-01	G4.G5 GALLEY PLACARD FOUND 1	TORN	L226	OPEN	09/21/2023
	CAB									2.0
									-	2.0
XJL2278	200	NRR	Al	25	777-53-920-00-01	G6.G7 GALLEY PLACARD FOUND 1	TORN	L227	WIP	09/29/2023
	CAB								•••	2.0
									-	2.0
XJL2286	500	NRR	CL	5700	777-57-868-01-01	LHW SPOILER LOWER SURFACE 8	KT/F CAVITY FOLIND DIRTY	L228	COMP	09/28/2023
7.022200	WNG		0_	0.00	0. 000 0. 0.	2 0. 0.222020002.0		LZZO	COMP	20.0
									-	
XJL2294	200	NRR	AV	2331	777-23-010-00-01	DEDEODMED ALL TEST FOLIND LO	CTR LATTICE ABOVE ROW 64 SDM 5-2 DOES NOT RESPOND	1.000	MID	20.0
AJL2294	CAB	INIXIX	Av	2331	777-23-010-00-01	PERFORMED ALL TEST FOUND L	STR LATTICE ABOVE ROW 04 SDM 3-2 DOES NOT RESPOND	L229	WIP	09/27/2023
									_	2.0
										2.0
XJL2302	200 CAB	NRR	Al	25	777-53-916-00-01	G5 GALLEY OVEN2.OVEN4.OVEN5	LOWER AREA BUMPER CRACKED	L230	WIP	10/02/2023
	OAD								_	6.0
										6.0
XJL2310	600	NRR	CL	5700	777-57-960-02-01	RHW SPOILER LOWER SURFACE &	& T/E CAVITY FOUND DIRTY	L231	COMP	09/28/2023
	WNG									20.0
									-	20.0

0PPC DISTRIBUTION:

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: RUN DATE: 10/2/2023 RUN TIME :

36 OF 86

9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE : ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

TRL CODE :					TYPE CODE:	ORIGINATOR: ALL			STATUS	UPDATED DAT
IOD NO	ZONE	STG	TD	ATA	ODIC CHET DEE NO	OTDL CLINO	DEFECT DESCRIPTION	ION		
OB NO	AREA	NRR	TD Al	ATA 25	ORIG CUST REF NO.		DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
L2328	200 CAB	NKK	Al	25	777-53-916-00-01	G5 GLY 505 COMPT TURN RETAINER FOUND MAL	FUNCTION	L232	COMP	09/28/2023
	O/ID									1.0
									_	1.0
XJL2336 200 CAB		NRR	Al	25	777-53-916-00-01	G5 GALLEY AFT BABY BASSINET SCREWS LOOSE	EN .	L233	WIP	10/01/2023
	CAB									1.0
									-	1.0
	500	NRR	CL	2781	777-57-504-01-01	LHW L/E SLAT T/E WEDGE & FRONT SPAR FOUND	DIRTY	L234	COMP	09/28/2023
	WNG									20.0
									-	20.0
L2351	100	PNT	PT	51	777-11-000-09-CXNA	STRIP THE RESIDUAL COATING AFTER FUS STRIF	PPING	L235	OPEN	09/21/2023
F	FUS				-01					160.0
									-	160.0
JL2369	200	NRR	AV	3326	777-C330000-01-03-	PERFORM CSCP ALL TEST FOUND DOME LIGHTS	INOP AT LAV D.L.K.	L236	OPEN	09/21/2023
	CAB				01		,,,	2200	01 211	3.0
									-	3.0
IL2377	200	NRR	Al	25	777-53-920-00-01	R5 FWD CLOSET S5R-11.S5R-12 INSIDE COMPT 26	EA BLIMPER MISSING	1007	COMP	
ILZUTT	CAB	MIXIX	Al	20	777-33-320-00-01	101 WD GEGGET GOVETT.GGIVETZ INGIDE GOWITT ZE	LA BOWN EN WIGGING	L237	COMP	09/28/2023
									_	
										1.0
L2385	600 WNG	NRR	CL	2/81	777-57-538-02-01	RHW L/E SLAT T/E WEDGE & FRONT SPAR FOUND	DURIY	L238	COMP	09/28/2023
	WING								_	20.0
										20.0
(JL2393	200	NRR	Al	25	777-53-920-00-01	G6 GLY OVEN1.OVEN2.OVEN3 LOWER BUMPER F	OUND CRACKED	L239	WIP	09/28/2023
	CAB									6.0
									-	6.0
XJL2401	200	NRR	AV	3326	777-C330000-01-03- 01	PERFORM CSCP ALL TEST FOUND ROW 46 LAVAT	TORY SIGN INOP	L240	OPEN	09/21/2023
	CAB				UI					1.0
									-	1.0

0PPC DISTRIBUTION:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

CTRL CODE:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: RUN DATE: 10/2/2023

37 OF 86

RUN TIME : 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL

ORIG-STAGE: ALL PERIOD: ALL

ATA NO: ALL

ZONE: ALL

AREA: ALL

ESTIMATED MHR: ALL DISPOSITION CODE: ALL

ORIGINATING CUST REF NO: DEFECT TYPE: ALL

TRADE: ALL

TYPE CODE:

CUST ENDORSE: ALL

ORIGINATOR: ALL

STAGE: ALL

CINL CODE.					TIFE CODE.	ONIGINATOR. ALL			OTATUO	LIDDATED DATE
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL2419	200 CAB	NRR	SS	25	777-C252000-01-07- R-01	FB2 SEAT STRUCTURE VELCRO TAPE FOUND LC	OSEN AT:11G H 12G H 16G H -26G H TOTAL:26EA	L241	WIP	10/01/2023
	CAB									10.5
									-	10.5
XJL2427	200	NRR	SS	25	777-C252000-01-07- R-01	FB2 SEAT STRUCTURE VELCRO TAPE FOUND LC	OSEN AT:11A D 12A D 15A -26A 16D-26D TOTAL:27EA	L242	WIP	10/01/2023
	CAB				14-01					10.5
									-	10.5
XJL2435	200	NRR	SS	25	777-C252430-01-06-	PEY PAX SEAT BACK REST FOUND DISALIGNMEN	IT AT30DEFG 31DEFG 32DEFG 33DEFG 34DEFG TOTAL:20EA	L243	WIP	09/28/2023
	CAB				01					10.0
									-	10.0
XJL2443	200	NRR	SS	25	777-C252430-01-01-	PEY PAX SEAT STRUCTURE VELCRO TAPE FOUN	ID LOOSEN AT:30DEFG-34DEFG 32HK-34HK 31AC -34AC TOTAL:34EA	L244	WIP	09/28/2023
	CAB				01					17.0
									-	17.0
KJL2450	200	NRR	SS	25	777-C252430-01-04-	PEY PAX SEAT CONSOLE IN ARM TABLE STOWA	GE SHROUD VELCRO TAPE FOUND LOOSEN AT:30DEFG-34DEFG	L245	WIP	09/28/2023
	CAB				01	31AC-34AC 32HK-34HK TOTAL34EA				13.5
									-	13.5
(JL2468	200	NRR	AV	3326	777-C330000-01-03-	PERFORM CSCP ALL TEST FOUND OFAR BUNK 4	AREA LIGHT INOP	L246	WIP	09/26/2023
	CAB				01					1.0
									-	1.0
(JL2476	200	NRR	Al	25	777-53-920-00-01	G6.G7 GALLEY WORK DECK EDGE SEALANT FOL	ND AGED	L247	OPEN	09/21/2023
	CAB							LZŦſ	OI LIV	4.0
									-	
(JL2484	200	NRR	SS	25	777-C252430-01-04-	DEV DAY SEAT CONSOLE IN ADM TADLE FOLIND	DISALIGNMENT AT:30DEFG-34DEFG 32HK-34HK 31AC -34AC	L248	WIP	4.0 09/28/2023
OLZ-10-1	CAB	MIXIX	00	20	01	TOTAL34EA	DIGALIGINALITY AT SOULT GOODEL OF SETTING THE STAGE OF THE	L248	VVIP	13.5
									-	
/ II 0 400	000	NDD	00	0.5	777 0050400 04 04	DEV DAY OF AT COMOCUE IN ADM TABLE OPENA	CIONI FOLIND IAM AT 200 F F O 24D F F O 200 IV 241 IV 244 O 244 O			13.5
(JL2492	200 CAB	NRR	SS	25	777-C252430-01-04- 01	TOTAL:34EA	ON FOUND JAM AT:30D E F G-34D E F G 32H K -34H K 31A C -34A C	L249	WIP	09/28/2023
	OAD								_	13.5
									-	13.5

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 38 OF 86

RUN TIME :

RUN DATE: 10/2/2023

9:39

1.0

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

CIRL CODE :					TYPE CODE:	URIGINATUR: ALL				
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
JL2500	200	NRR	Al	25	777-53-916-00-01	G4.G5 GALLEY WORK DECK EDGE SEALANT FO	DUND AGED	L250	OPEN	09/21/2023
	CAB									4.0
									-	4.0
JL2518	500	NRR	CL	57	777-57-856-01-01	LHW ALL REMOVED ACCESS PANEL INNER SURFACE FOUND DIRTY		L251	COMP	09/28/2023
	WNG									0.0
									-	0.0
JL2526	200	NRR	Al	25	777-53-916-00-01	G4L.G4R GALLEY WORK DECK EDGE SEALANT	FOUND AGED.	L252	OPEN	09/21/2023
	CAB									4.0
									-	4.0
JL2534	200	NRR	AV	3324	777-C330000-01-03-	PERFORM CSCP ALL TEST FOUND ROW 11&60	CTR NO SMOKING SIGN INOP	L253	OPEN	09/21/2023
	CAB				01					2.0
									-	2.0
JL2542	600	NRR	CL	57	777-57-948-02-01	RHW ALL REMOVED ACCESS PANEL INNER SU	RFACE FOUND DIRTY	L254	COMP	09/28/2023
	WNG									0.0
									-	0.0
JL2559	200	NRR	Al	25	777-53-920-00-01	G6 GALLEY 606.607 COMPT SHORT TURN BUTT	ON FOUND MALFUNCTION	L255	COMP	09/25/2023
	CAB									2.0
									-	2.0
JL2567	200	NRR	Al	25	777-53-920-00-01	G6 GALLEY 603.605.607 LOWER COMPT UPPER	T GUIDE 3EA BUMPER CRACKED	L256	WIP	10/01/2023
	CAB							2200	****	6.0
									-	6.0
JL2575	200	NRR	AV	3321	777-C330000-01-01-	PERFORM CSCP ALL TEST FOUND CEILING LIG	HTS INOP AT LAV 4F-1L(LAV H) ,ABOVE DR 2L STOWAGE S2L,ABOVE	L257	OPEN	09/21/2023
	CAB	11111	, , ,	0021	01	DR 2 RIGHT , ROW 2 LEFT ABOVE BIN		L237	OPEN	4.0
									-	
11 2502	200	NRR	٨١	25	777 52 020 00 04			001:-	4.0	
JL2583 200	CAB	INKK	Al	25	777-53-920-00-01	G7 GALLEY 706.707 COMPT TURN RETAINER A	TI INDICATOR BUMPER FOUND MISSING	L258	COMP	09/28/2023
	-								_	1.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 39 OF 86

RUN TIME :

ESTIMATED MHR: ALL

RUN DATE: 10/2/2023 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

STRE CODE.					TIFE CODE.	ONGINATOR: A	-L		STATUS	
IOD NO	ZONE	STG	TD	A.T.A	ODIO QUOT DEE NO	OTDL GUNG	DEFECT DECORPOTION	ION		UPDATED DATE
JOB NO	AREA	NDD	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL2591	200 CAB	NRR	Al	25	777-53-920-00-01	G7 GALLEY 708 WASTE COMPT DOOR AFT	SIDE UPPER AREA 1EA BUMPER CRACKED	L259	WIP	10/01/2023
	OND								_	2.0
										2.0
KJL2609	200	NRR	Al	25	777-53-920-00-01	G7 GALLEY 714.715.726 COMPT SMALL TUI	RN BUTTON FOUND STIFF	L260	WIP	10/01/2023
	CAB									1.0
									-	1.0
(JL2617	200	NRR	Al	25	777-53-920-00-01	G7 GALLEY 702 COMPT SHORT TURN BUT	FON FOUND MALFUNCTION	L261	COMP	09/25/2023
	CAB									1.0
									-	1.0
(JL2625	200	NRR	Al	25	777-53-920-00-01	G7 GALLEY 701.705.707 LOWER COMPT UP	PER T GUIDE 3EA BUMPER CRACKED	L262	WIP	10/01/2023
	CAB									6.0
									-	6.0
(JL2633	200	NRR	AV	4420	777-24-001-00-01	PERFORM IFE TEST FOUND 66D,70E MONI	TORS TOUCHSCREEN DOES NOT RESPOND	L263	WIP	10/01/2023
	CAB									4.0
									-	4.0
(JL2641	200	NRR	AV	4420	777-24-001-00-01	PERFORM IFE TEST FOUND 23A MONITOR	TOUCHSCREEN DOES NOT RESPOND	L264	WIP	09/27/2023
	CAB									2.0
									-	2.0
JL2658	200	NRR	AV	2525	777-24-001-00-01	PERFORM BC SEAT ELECTRICAL OPERATI	ON TEST FOUND 24A SEAT INOP	L265	OPEN	09/21/2023
	CAB							L200	OI LIV	2.0
									-	
(JL2666	200	NRR	AV	2525	777-24-001-00-01	PERFORM BC SEAT OPERATION TEST FOL	IND 23G 20K 21G TTL LIGHT INOP	1,000	ODEN	2.0
JLZ000	CAB	IVIXIX	AV	2020	777-24-001-00-01	TENTONING SEAT OF ENAMON TEST FOR	IND 230,2011,210 TTE EIGHT INOT	L266	OPEN	09/21/2023
									-	3.0
	000	NDD	00	0.5	777 05 000 04 02/ 04	OIA OF AT OTRUGTURE VELORIC TARE EVO	L000FN TT. 40FA			3.0
JL2674	200 CAB	NRP	SS	25	777-25-060-01-CX-01	C/A SEAT STRUCTURE VELCRO TAPE FND	LUUSEN TILTIDEA	L267	OPEN	09/21/2023
	OAD								_	6.0
									-	6.0

0PPC DISTRIBUTION:

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE:

RUN TIME :

40 OF 86

RUN DATE: 10/2/2023 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

ALL

ATA NO: ALL

ZONE: ALL AREA: ALL

DISPOSITION CODE: ALL

DEFECT TYPE: ALL

TRADE: ALL

CUST ENDORSE: ALL

STAGE: ALL

CTRL CODE :	TYPE CODE:	ORIGINATOR:	ALI
CIRL CODE.	ITPE CODE.	URIGINATUR.	ALL

IOD NO	ZONE	STG	TD	ATA	ODIO CHOT DEE NO	OTDL CLINO	DEFECT DESCRIPTION	ICAL	STATUS	UPDATED DATE
JOB NO XJL2682	AREA 200	NRR	SS	ATA 25	ORIG CUST REF NO. 777-C252410-01-01-	CTRL SH NO	DEFECT DESCRIPTION  TAPE FND LOOSEN AT:1A D K-2A D K TTL:6EA	JSN	STATUS	EST Mhr
AJL2002	CAB	NKK	33	25	01	FIRST CLASS SEAT STRUCTURE VELCRO	TAPE FND LOUSEN ATTA D K-ZA D K TTL:0EA	L268	OPEN	09/21/2023
									_	4.0
										4.0
XJL2690	100 FUS	NRP	GW	5346	777-900002-01-1-01	FUS-LH BODY FAIRING 195AL 3EA SCREW	S SEIZED.	L269	COMP	09/27/2023
	100								_	3.0
										3.0
XJL2708	200	NRR	SS	25	777-C252440-04-03- 01	E ZONE EY PAX SEAT BACKREST RECLINE	OPERATION FND TIGHTEN AT:39AC-45ABC TTL:20EA	L270	WIP	09/25/2023
	CAB				· ·					4.0
									-	4.0
XJL2716	200	NRR	SS	25	777-C252000-01-07- R-01	CAB B ZONE B/C SEAT BACK COVER FOUN	ID TORN TTL:13EA	L271	OPEN	09/22/2023
	CAB				K-01					6.5
									-	6.5
XJL2724	200	NRR	SS	25	777-C252000-01-07-	CAB B ZONE B/C SEAT LEGREST COVER F	OUND NOT MATCH TTL:1EA	L272	OPEN	09/22/2023
	CAB				R-01					0.5
									-	0.5
XJL2732	200	NRR	SS	25	777-C252000-01-07-	CAB B ZONE B/C SEAT HEADREST STRUC	TURE FOUND CRACKED TTL:6EA	L273	WIP	10/02/2023
	CAB				R-01					3.0
									-	3.0
XJL2740	200	NRR	SS	25	777-C252000-01-08-	CAB C ZONE PEY SEAT BOTTOM COVER F	OUND NOT MATCH TTL:4EA	L274	OPEN	09/22/2023
	CAB				R-01					2.0
									-	2.0
XJL2757	200	NRR	SS	25	777-C252440-04-03-	E ZONE EY PAX SEAT BACKREST RECLINE	OPERATION FND TIGHTEN AT:39DEFG-46DEFG TTL:32EA	L275	WIP	09/25/2023
	CAB				01			LZ73	****	6.0
									-	
XJL2765	200	NRR	SS	25	777-C252440-04-03-	E 70NE EV DAY SEAT RACKREST DECLINE	OPERATION FND TIGHTEN AT:40HJK-46HJK TTL:21EA	1.070	WID	6.0
AJLZIUJ	CAB	INIXIX	33	20	01	L ZONE LI FAN OLAT DAONNEST RECLINE	OF ENTION THE HOTTEN ALAUTING THE ZIEA	L276	WIP	09/25/2023
									-	6.0
										6.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 41 OF 86

ESTIMATED MHR: ALL

RUN DATE: 10/2/2023

RUN TIME: 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

CIRL CODE:					TYPE CODE:		ORIGINATOR: ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL2773	200	NRR	SS	25	777-C252000-01-08-	CAB C ZONE F	EY SEAT HEADREST STRUCTURE SCREW FOUND LOOSE TTL:12EA	L277	WIP	09/28/2023
	CAB				R-01					2.0
									-	2.0
XJL2781	200	NRR	SS	25	777-C252440-04-03-	D ZONE EY PA	X SEAT BACKREST RECLINE OPERATION FND TIGHTEN AT:59ABC-72AC TTL: 41	L278	WIP	09/25/2023
	CAB				01					8.0
									-	8.0
XJL2799	200	NRR	SS	25	777-C252440-04-03-	D ZONE EY PA	X SEAT BACKREST RECLINE OPERATION FND TIGHTEN AT:60DEFG-72DEG TTL:48EA	L279	WIP	09/25/2023
	CAB				01					9.0
									-	9.0
XJL2807	XJL2807 200	NRR	SS	25	777-C252440-04-03-	D ZONE EY PA	X SEAT BACKREST RECLINE OPERATION FND TIGHTEN AT:59HJK-71HJK TTL:39EA	L280	WIP	09/25/2023
	CAB				01					8.0
									-	8.0
XJL2815	200	NRR	SS	25	777-C252440-04-02-	EY F/R SEAT I	N ARM TABLE FND TIGHTEN AT:39A.C D.E.F.G H.J.K.59A.B.C.H.J.K.60D.E.F.G TTL:19EA	L281	WIP	09/25/2023
	CAB				01			220.	**	6.0
									-	6.0
XJL2823	100	NRM	AV	2431	AEO-27438-01	DISCONNECT	AND RECONNECT MAIN BATTERY AND APU BATTERY FOR POWER PANEL REWORK	L282	WIP	0.0
	LWR									0.0
						1C 1	RECONNECT CONNECTOR OF MAIN BATTERY			1.0
						1C 2	RECONNECT CONNECTOR OF APU BATTERY			1.0
						1C 3	PERFORM MAIN BATTERY RECONNECTION TEST			1.0
						1C 4	DISCONNECT CONNECTOR OF APU BATTERY			1.0
						2C 5	PERFORM APU BATTERY RECONNECTION TEST			1.0
						2C 6	DISCONNECT CONNECTOR OF MAIN BATTERY			1.0
									-	6.0

0PPC DISTRIBUTION:

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

42 OF 86 PAGE:

RUN TIME :

RUN DATE: 10/2/2023

9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

STATUS: ALL ORIG-STAGE: ALL

ATA NO: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL

515653

BMS571R1-2

ZONE: ALL

DISPOSITION CODE: ALL

TRADE: ALL DEFECT TYPE : ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL TYPE CODE: ORIGINATOR: ALL

CTRL CODE:

	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL2831	200 CAB	NRR	SS	2500	777-53-908-00-01	CABIN #2 DOOR G2 GLY R/H AISLE S/W FOUND	SCRATCHED	L283	WIP	09/24/2023
	CAB									0.0
						<ul> <li>1C 1 REMOVE G2 GLY RHS AISLE LIG</li> <li>1C 2 REMOVE G2 GLY RHS AISLE PN</li> </ul>				0.5 1.0
						1C 3 G2 GLY RHS AISLE TEDLAR REI				11.0
						1C 4 REINSTALL G3 2 GLY RHS AISLI				1.0
						2C 5 REINSTALL G2 GLY RHS AISLE	LIGHT			0.5
									-	14.0
XJL2849	100 LWR	NRR	PT	2500	777-53-854-00-01	AFT CGO BILGE AREA RIVETS PAINT FOUND PI	EEL OFF	L284	OPEN	09/22/2023
	LVVIX									4.0
									-	4.0
XJL2856	100	NRR	PT	5121	777-53-854-00-01	AFT CGO DOOR ARM SUPPORT FND PAINT CH	Р	L285	OPEN	09/22/2023
	LWR									2.0
									-	2.0
XJL2864	100	NRR	PT	5121	777-53-818-00-01	FWD CGO DOOR ARM SUPPORT FND PAINT CH	IIP	L286	OPEN	09/22/2023
	LWR									2.0
									-	2.0
XJL2872	100	NRR	PT	5121	777-53-818-00-01	FWD CGO DOOR DEPRESSOR SEAL FOUND PA	INT CHIPPED.	L287	WIP	09/27/2023
	LWR									6.0
									-	6.0
XJL2880	100	NRR	PT	5121	777-53-854-00-01	AFT CGO COMP'T BALL MAT AREA RED LOCK F	OUND PAINT PEELED.TTL30EA	L288	WIP	09/27/2023
	LWR									15.0
									-	15.0
XJL2898	100	NRR	PT	5121	777-53-870-00-01	BULK CGO DOOR SILL AND BLACK LINE FOUND	PAINT PEELED.	L289	COMP	09/28/2023
	LWR									5.0
									-	5.0
XJL2906	100	NRR	PT	5121	777-53-870-00-01	BULK CGO CTR FLOOR PANEL FOUND PAINT P	EELED.	L290	COMP	09/28/2023
	LWR									8.0
									-	8.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

43 OF 86 PAGE: RUN DATE: 10/2/2023

RUN TIME : 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

TRADE: ALL DEFECT TYPE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

CIRL CODE:					TYPE CODE:	ORIGINATOR: ALL				
	ZONE	STG						S	STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN S	STATUS	EST Mhr
XJL2914	100	NRR	PT	5121	777-53-854-00-01	FWD AND AFT CGO DOOR LOWER SILL FITTIN	G BLACK MARKING FOUND PAINT PEELED	L291 C	PEN	09/22/2023
	LWR									5.0
									-	5.0
XJL2922	100	NRR	PT	5121	777-53-818-00-01	FWD CGO COMP'T BALL MAT AREA RED LOCK	FOUND RED PAINT PEELED.TTL:30EA	L292 V	VIP	09/27/2023
	LWR									15.0
									-	15.0
XJL2930	100	NRR	PT	5121	777-53-818-00-01	FWD CGO COMP'T BALL MAT PANEL FOUND P	AINT PEELED.TTL5EA.	L293 (	COMP	09/28/2023
	LWR							L235 C	JOIVII	15.0
									_	
										15.0
XJL2948	100 LWR	NRR	PT	5121	777-53-854-00-01	AFT CGO BALL MAT PNL FOUND PAINT PEEL.	TL:5EA	L294 (	COMP	09/28/2023
	LVVIX									5.0
									-	5.0
XJL2955	100	NRR	PT	5121	777-53-854-00-01	AFT CGO DOOR DEPRESSOR SEAL FOUND PA	AINT CHIPPED.	L295 V	VIP	09/27/2023
	LWR									6.0
									-	6.0
XJL2963	200	NRR	SM	2520	777-53-907-00-01	FWD ZONE OFCR LH &RH CREW SEAT PAN FO	OUND DAMAGED	L296 V	VIP	09/30/2023
	CAB									0.0
						1C 1 PLS REMOVE L/R SEAT				2.0
						1C 2 REMOVE L/R SEAT L/R SIDE A	RM			8.0
						1C 3 SEAT PAN& DOUBLER REPLAC				48.0
						1C 4 REINSTALL L/L SEAT L/R SIDE	ARM			8.0
						2C 5 REINSTALL L/R SEAT				1.0
										67.0
XJL2971	600	NRR	SS	5700	777-57-972-02-01	RHW #6 FIXED FAIRING FOUND EROSION		L297 V	VIP	09/24/2023
	WNG									0.0
						1C 1 DO AN INSPECTION TO FIND T				1.0
						1C 2 CONFIRM DAMAGE WITHIN SR				2.0
						1C 3 MAKE A PERMANENT SEAL TO				3.0
						1C 4 APPLY ONE LAYER OF BMS10-	bu enamel		_	0.0
									_	6.0

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 44 OF 86 RUN DATE: 10/2/2023

0.00

RUN TIME: 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

TYPE CODE:

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

ORIGINATOR: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE:

	ZONE	STG			2 3352.	5110.11 1. 51. 1. 7. <u>1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1</u>		STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL2989	600 WNG	NRR	SS	5700	777-57-982-02-01	RHW #7 FIXED FAIRING FWD CUTOUT FOUND EROSION	L298	WIP	09/24/2023
	WING								0.0
						1C 1 DO AN INSPECTION TO FIND THE DAMAGE DIMENSION 1C 2 CONFIRM DAMAGE WITHIN SRM ADL			1.0
						1C 2 CONFIRM DAMAGE WITHIN SRM ADL 1C 3 MAKE A PERMANENT SEAL TO PERMITTED DAMAGE			2.0 3.0
						1C 4 APPLY ONE LAYER OF BMS10-60 ENAMEL			0.0
								-	6.0
(JL2997	600	NRR	SS	5700	777-57-982-02-01	RHW #8 FIXED FAIRING FWD CUTOUT FOUND EROSION	L299	WIP	09/24/2023
	WNG								0.0
						1C 1 DO AN INSPECTION TO FIND THE DAMAGE DIMENSION			1.0
						1C 2 CONFIRM DAMAGE WITHIN SRM ADL			2.0
						1C 3 MAKE A PERMANENT SEAL TO PERMITTED DAMAGE			3.0
						1C 4 APPLY ONE LAYER OF BMS10-60 ENAMEL		_	0.0
									6.0
JL3003	600	NRR	AE	2708	777-57-954-02-01	RHW FLAPERON LIP DOORS I/B SEAL FOUND TORN	L300	COMP	09/28/2023
	WNG								2.0
								-	2.0
(JL3011	600	NRR	ΑE	2708	777-57-954-02-01	RHW FLAPERON O/B LOWERLOWER SEAL FOUND TORN	L301	COMP	09/28/2023
	WNG								6.0
								-	6.0
JL3029	600	NRR	ΑE	2750	777-57-952-02-01	RHW I/B MAIN FLAP I/B EDGE SEAL FOUND TORN	L302	OPEN	09/22/2023
	WNG								1.0
								-	1.0
(JL3037	600	NRR	ΑE	2750	777-57-860-01-01	LHW I/B MAIN FLAP I/B EDGE SEAL FOUND TORN	L303	OPEN	09/22/2023
	WNG								1.0
								-	1.0
KJL3045	600	NRR	AE	2708	777-57-862-01-01	LHW FLAPERON I/B UPPER LOWER SEAL FOUND TORN	L304	COMP	09/28/2023
	WNG								6.0
								-	6.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 45 OF 86

ESTIMATED MHR: ALL

RUN DATE: 10/2/2023

RUN TIME: 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

ATA NO : ALL ZONE : ALL DISPOSITION CODE : ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL3052	500	NRR	AE	2700	777-57-880-01-01	LHW FLAPERON I/B HINGE AFTER FAIRING SEAL F	OUND TORN	L305	COMP	09/28/2023
	WNG									2.0
									-	2.0
XJL3060	500	NRR	SS	57	777-57-900-02-01	WING LE ACCESS PNLS 611 CB GB FOUND EXTER	NAL SURFACE PAINT IRREGULARITY	L306	WIP	09/27/2023
	WNG									0.0
						1C 1 APPLY THE RESIN COATING TO IRI	REGULAR AREA			3.0
						1C 2 SAND THE RESIN COATING TO MA	KE SURFACE SMOOTHER			3.0
						1C 3 APPLY THE SURFACE PAINT				0.0
									-	6.0
XJL3078	100	NRR	ΑI	2500	777-53-862-00-01	AFT CGO R/H BALL MAT AREA PDU ROLLER FOUN	D WORN.TOTAL 5 PAIRS	L307	WIP	10/02/2023
	LWR									5.0
									-	5.0
XJL3086	100	NRR	Al	2500	777-53-862-00-01	AFT CGO R/H AFT BALL MAT AREA R/H AFT PDU S	ENSOR FOUND WORN. TOTAL 1EA.	L308	WIP	10/02/2023
	LWR									2.0
									-	2.0
XJL3094	100	NRR	Al	2500	777-53-862-00-01	AFT CGO R/H AFT BALL MAT AREA R/H FWD STOP	AXLE PIN FOUND BROKEN. TOTAL 1EA.	L309	WIP	10/02/2023
	LWR									2.0
									-	2.0
XJL3102	800	NRP	CL	52	777-52-531-01-01	M/D ALL DOOR STOP FITTING AREA FOUND DIRTY	1.	L310	COMP	09/28/2023
	CAB									10.0
									-	10.0
XJL3110	800	NRP	CL	52	777-52-531-01-01	M/D ALL DOOR CUTOUT STOP FITTING AREA FOUL	ND DIRTY.	L311	COMP	09/28/2023
	CAB									10.0
									-	10.0
XJL3128	200	NRR	PT	2500	777-53-916-00-01	M/D R5 DOOR BUSTLE PNL FND PAINT CHIP		L312	COMP	09/28/2023
	CAB									4.0
									-	4.0

ORIGINATING CUST REF NO:

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 46 OF 86

RUN DATE: 10/2/2023

RUN TIME : 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

ALL

515653

BMS571R1-2

ZONE AREA 200 CAB	STG	TD	ATA	TYPE CODE:	ORIGINATOR: ALL			STATUS	UPDATED DAT
AREA 200		TD	ATA					SIAIUS	OFDATED DAT
200	NRR	טו	AIA	ODIC CHET DEE NO	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
	INIZIZ	PT	2500	ORIG CUST REF NO. 777-53-908-00-01	CABIN S2CL S2CR CLOSET UPPER EDGE FND PAI				
o,		РΙ	2500	777-53-906-00-01	CABIN SZCE SZCR CLOSET UPPER EDGE FND PAI	NT CHIPPED	L313	OPEN	09/22/2023
								_	10.0
								_	10.0
200	NRR	PT	2500	777-53-916-00-01	M/D R4-01 R4-02 R4-03 R4-04 GALLEY DOOR INTER	RIOR SURFACE FND PAINT CHIPPED	L314	WIP	09/28/2023
CAB									8.0
								-	8.0
200	NRR	PT	2500	777-53-904-00-01	M/D C-103 R-103 R-123 GALLEY DOOR INTERIOR S	URFACE FND PAINT CHIPPED	L315	WIP	10/01/2023
CAB									6.0
								-	6.0
200	NRR	PT	2500	777-53-908-00-01	M/D G201 G202 GALLEY DOOR INTERIOR SURFAC	E FND PAINT CHIPPED	L316	WIP	09/28/2023
CAB									4.0
								-	4.0
200	NRR	PT	2500	777-53-908-00-01	M/D R2-01 R2-02 R2-03GALLEY DOOR INTERIOR S	URFACE END PAINT CHIPPED	I 317	WID	09/28/2023
CAB			2000	55 555 55 5.	MAD THE OF THE OETHER GOOD, RELEET BOOK INVESTIGATION OF	STATION TO STATE OF AN A SECOND STATE OF A SECON	LSTI	VVII	6.0
								-	
200	NDD	DT	0500	777 52 000 00 04	M/D 00 04 04 LEV OF ILINO OLIDEAGE FOLIND DA	INT CHIP			6.0
CAB	INIXIX	РΙ	2500	777-53-906-00-01	M/D G2 G4 GALLET CEILING SURFACE FOUND PAI	INT CHIP	L318	OPEN	09/22/2023
02								_	16.0
									16.0
200 CAB	NRR	PT	2500	777-53-916-00-01	CABIN S1L S1R CLOSET UPPER EDGE FND PAINT	CHIPPED	L319	OPEN	09/22/2023
CAB									10.0
								-	10.0
100	NRR	PT	5121	777-53-920-00-01	M/D G702 703 706 707 606 607 GALLEY DOOR FOU	ND PAINT PEEL TTL:6EA	L320	WIP	09/29/2023
CAB									12.0
								-	12.0
200	NRR	PT	2500	777-53-908-00-01	CABIN S2CL-11 S2CR-11CLOSET INTERIOR SURFA	CE FND PAINT CHIPPED	L321	WIP	09/30/2023
CAB									4.0
								-	4.0
220 CA 220 CA 220 CA 220 CA 220 CA 220	AB  00  AB  00  AB  00  AB  00  AB  00  AB  00  AB	00 NRR	NRR PT AB  NRR PT AB	NRR PT 2500 AB NRR PT 2500	NRR PT 2500 777-53-904-00-01  NRR PT 2500 777-53-908-00-01  NRR PT 2500 777-53-908-00-01  NRR PT 2500 777-53-908-00-01  NRR PT 2500 777-53-908-00-01  NRR PT 2500 777-53-916-00-01  NRR PT 5121 777-53-920-00-01  NRR PT 2500 777-53-908-00-01	NRR PT 2500 777-53-908-00-01 M/D C-103 R-123 GALLEY DOOR INTERIOR S  NRR PT 2500 777-53-908-00-01 M/D G201 G202 GALLEY DOOR INTERIOR SURFACE  NRR PT 2500 777-53-908-00-01 M/D R2-01 R2-02 R2-03GALLEY DOOR INTERIOR SI  NRR PT 2500 777-53-908-00-01 M/D G2 G4 GALLEY CEILING SURFACE FOUND PAI  NRR PT 2500 777-53-916-00-01 CABIN S1L S1R CLOSET UPPER EDGE FND PAINT  NRR PT 5121 777-53-920-00-01 M/D G702 703 706 707 606 607 GALLEY DOOR FOU  NRR PT 2500 777-53-908-00-01 CABIN S2CL-11 S2CR-11CLOSET INTERIOR SURFACE	NRR PT 2500 777-53-908-00-01 M/D G201 G202 GALLEY DOOR INTERIOR SURFACE FND PAINT CHIPPED  NRR PT 2500 777-53-908-00-01 M/D G201 G202 GALLEY DOOR INTERIOR SURFACE FND PAINT CHIPPED  NRR PT 2500 777-53-908-00-01 M/D G2 G4 GALLEY CEILING SURFACE FND PAINT CHIPPED  NRR PT 2500 777-53-908-00-01 M/D G2 G4 GALLEY CEILING SURFACE FND PAINT CHIPPED  NRR PT 2500 777-53-908-00-01 CABIN S1L S1R CLOSET UPPER EDGE FND PAINT CHIPPED  NRR PT 5121 777-53-920-00-01 M/D G702 703 706 707 606 607 GALLEY DOOR FOUND PAINT PEEL TTL-6EA  NRR PT 2500 777-53-908-00-01 CABIN S2CL-11 S2CR-11CLOSET INTERIOR SURFACE FND PAINT CHIPPED	NR	200 NRR PT 2500 777-53-908-00-01 MID C-103 R-103 R-123 GALLEY DOOR INTERIOR SURFACE FND PAINT CHIPPED L316 WIP AB NRR PT 2500 777-53-908-00-01 MID R2-01 R2-02 GALLEY DOOR INTERIOR SURFACE FND PAINT CHIPPED L317 WIP AB NRR PT 2500 777-53-908-00-01 MID R2-01 R2-02 R2-03GALLEY DOOR INTERIOR SURFACE FND PAINT CHIPPED L318 OPEN AB NRR PT 2500 777-53-908-00-01 MID R2-01 R2-02 R2-03GALLEY DOOR INTERIOR SURFACE FND PAINT CHIPPED L318 OPEN AB NRR PT 2500 777-53-908-00-01 MID G2 G4 GALLEY CEILING SURFACE FOUND PAINT CHIPPED L319 OPEN AB NRR PT 2500 777-53-916-00-01 CABIN S1L S1R CLOSET UPPER EDGE FND PAINT CHIPPED L320 WIP AB NRR PT 2500 777-53-908-00-01 MID G702 703 706 707 506 607 GALLEY DOOR FOUND PAINT PEEL TIL SEA L320 WIP AB NRR PT 2500 777-53-908-00-01 CABIN S2CL-11 S2CR-11CLOSET INTERIOR SURFACE FND PAINT CHIPPED L321 WIP

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 47 OF 86

RUN DATE: 10/2/2023

RUN TIME: 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL ZONE : ALL DISPOSITION CODE : ALL

ORIGINATOR: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

TYPE CODE:

CTRL CODE:

CIRL CODE:					TYPE CODE:	ORIGINATOR: ALL			
	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL3227	200	NRR	Al	2524	777-53-908-00-01	CAB-FB2 SEAT BACK SHELL BOTTLE CONSOLE HORIZONTAL TRIM FOUND CRACKED AT 21G.	L322	COMP	09/30/2023
	CAB								1.0
								-	1.0
XJL3235	200	NRR	Al	2524	777-53-908-00-01	CABIN FB2 SEAT OTTOMAN FOOT REST PLASTIC COVER GAP SEAL FOUND MISSING AT 11A 16A 21A 11K 16K	L323	WIP	09/29/2023
	CAB								15.0
								-	15.0
XJL3243	200	NRR	SS	2524	777-53-908-00-01	CABIN FB2 SEAT SHELL BLACK FABRIC FOUND WORN AT 21D 20D 18D 26D	L324	WIP	09/27/2023
	CAB						202.	•••	0.0
						1C 1 REMOVAL SEAT BLACK FABRIC COVER			3.0
						1C 2 REPLACE SEAT BLACK FABRIC			30.0
						1C 3 PLS INSTALL BLACK FABRIC COVER			3.0
								-	36.0
XJL3250	200	NRR	PT	2500	777-53-908-00-01	M/D D LAV WASTE BIN MARKING FND PAINT CHIP	L325	WIP	09/29/2023
	CAB								1.0
								-	1.0
XJL3268	200	NRR	Al	2524	777-53-908-00-01	CABIN FB2 SEAT OTTOMAN AROUND NOMEX TRIM FOUND DAMAGE AT 26D 22G 19K 21K.	L326	COMP	09/30/2023
	CAB								10.0
								-	10.0
XJL3276	200	NRR	SS	2524	777-53-908-00-01	CAB-FB2 SEAT BACK SHELL BOTTLE CONSOLE RED FABRIC TRIM FOUND DAMAGE 19D 11K 17K 12K 25A 18A 16K 22K	L327	WIP	09/27/2023
	CAB					24K 18D 17G 12G 18G 21G 26G			0.0
						1C 1 REMOVAL SEAT RED NOMEX COVER			7.5
						1C 2 REPLACE SEAT RED NOMEX			45.0
						2C 3 PLS INSTALL RED NOMEX COVER			7.5
								-	60.0
XJL3284	200	NRR	Al	2524	777-53-908-00-01	CABIN FB2 SEAT OTTOMAN FOOT REST CUSHION LEATHER FOUND WORN AT 12G	L328	COMP	09/30/2023
	CAB								3.0
								-	3.0
XJL3292	200	NRR	Al	2524	777-53-908-00-01	CAB-FB2 SEAT BACK SHELL BOTTLE CONSOLE PLASTIC TRIM FOUND DETACHED AT 26K.	L329	WIP	09/30/2023
	CAB						2020	****	0.5
								-	
									0.5

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 48 OF 86

RUN TIME :

RUN DATE: 10/2/2023

9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

TINE CODE.					TIFE CODE.	ONGINATOR: AL	L		CTATUC	
IOD NO	ZONE	STG	т-	ATA	ODIO CHOT DEE NO	CTPL CLINO	DEFECT DECORPTION	1011	STATUS	UPDATED DATE
JOB NO	AREA	NDD	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL3300	200 CAB	NRR	Al	2541	777-53-904-00-01	CABIN ZONE A LAV A FLOOR PAN EDGE TF	IM FOUND DAMAGE	L330	OPEN	09/22/2023
	CAD									2.0
									-	2.0
XJL3318	200	NRR	PT	2500	777-53-870-00-01	BULK CGO S/W PNLS SURFACE FND PAINT	CHIPPED TTL:6EA	L331	COMP	09/28/2023
	LWR									18.0
									-	18.0
XJL3326	200	NRR	SS	2525	777-C252000-01-09-	EY PAX SEAT POCKET COVER FND DIRTY	AT: 40H 65K 69H 67C 59C TTL: 5EA	L332	OPEN	09/22/2023
	CAB				R-04					4.0
									-	4.0
XJL3334	200	NRR	SS	2525	777-C252000-01-09-	EY PAX SEAT POCKET COVER BUTTON FN	D LOOSEN AT: 41F 45E 59H 63K 71D 71A TTL: 6EA	L333	OPEN	09/22/2023
	CAB				R-04					1.0
									-	1.0
(JL3342	200	NRR	SS	25	777-C252000-01-06-	CAB A ZONE SEAT OTTOMANS CUSHION F	DUND TORN TTL:6EA	L334	OPEN	09/22/2023
	CAB				R-02					3.0
									-	3.0
KJL3359	200	NRR	SS	25	777-C252000-01-09-	CAB F ZONE EY SEAT ALL HEADREST TTL	28EA FOUND DIRTY	L335	OPEN	09/22/2023
	CAB				R-04			2000	OI LIV	8.0
									-	8.0
KJL3367	200	NRR	SS	25	777-C252000-01-09-	CAB E ZONE EY SEAT ALL HEADREST TTL7	3FA FOLIND DIRTY	L336	OPEN	
(OLOGO)	CAB	TWICK	00	20	R-04	OND E ZONE ET GENT NEETEN BREGT TIEN	OLAT GOND BILLT	L336	OPEN	09/22/2023
									-	
V II 2275	200	NDD	00	0.5	777 0050000 04 00	0AD E 70NE EV 0EAT DOTTOM DDE00 000	VED FOLIND NOT MATCH TTL 2007			4.0
KJL3375	200 CAB	NRR	SS	25	777-C252000-01-09- R-04	CAB F ZONE EY SEAT BOTTOM DRESS CO	PER FOUND NOT MATCH TIL:28EA	L337	OPEN	09/22/2023
	02								_	14.0
										14.0
(JL3383	200 CAB	NRR	SS	25	777-C252000-01-09- R-04	CAB E ZONE EY SEAT BOTTOM DRESS CO	/ER FOUND NOT MATCH TTL:13EA	L338	OPEN	09/22/2023
	CAB									6.5
									-	6.5

0PPC DISTRIBUTION:

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

49 OF 86 PAGE:

RUN DATE: 10/2/2023

RUN TIME : 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

TINE CODE .	ZONE	STG			TIFE CODE.	ORIGINATOR: AL	LL CONTRACTOR		STATUS	UPDATED DATE
JOB NO	AREA	010	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL3391	200	NRR	SS	2525	777-C252440-04-02-	EY PAX SEAT BACKREST TABLE FND DIRT	/ AT:40H 41K 45H 62D 69D 60B 71B TTL:7EA	L339	WIP	09/27/2023
	CAB				01					4.0
									-	4.0
JL3409	600	NRR	GW	5700	777-57-948-02-01	RHW T/E ACCESS PANEL 652LB (3EA) SCRI	EW FOUND SEIZED	L340	COMP	09/26/2023
	WNG									3.0
									-	3.0
JL3417	600	NRR	SM	5700	777-57-948-02-01	RHW T/E ACCESS PANEL 652LB (3EA) ANCI	HOR NUT	L341	OPEN	09/22/2023
	WNG									1.5
									-	1.5
JL3425	500	NRR	GW	5700	777-12-008-00-01	LHW L/E ACCESS PANEL 511FB (1EEA 5110	B(1EA) 511KB(2EA ) 511PB(10EA) SCREW FOUND SEIZED	L342	COMP	09/26/2023
	WNG									14.0
									-	14.0
JL3433	500	NRR	SM	5700	777-12-008-00-01	LHW L/E ACCESS PANEL 511FB (1EEA 5110	B(1EA) 511KB(2EA ) 511PB(10EA) ANCHOR NUT FOUND WORN	L343	OPEN	09/22/2023
	WNG									7.0
									-	7.0
JL3441	500	NRR	AE	5700	777-12-008-00-01	LHW L/E ACCESS PANEL 511FB GB CB SCR	EW FOUND WORN	L344	OPEN	09/22/2023
	WNG									1.0
									-	1.0
JL3458	200	NRR	AV	2525	777-24-001-00-01	PERFORM BC SEAT ELECTRICAL OPERATION	ON TEST FOUND 23D SEAT INOP	L345	WIP	10/01/2023
	CAB									3.0
									-	3.0
JL3466	600	NRR	AE	5700	777-12-008-00-04	RHW L/E ACCESS PANEL 621 ACB BB GB M	B WB ZB QB RB AFB SCREWS FOUND WORN	L346	OPEN	09/22/2023
	WNG									1.0
									-	1.0
JL3474	500	NRR	AE	5700	777-57-856-01-01	LHW T/E ACCESS PANEL 552HB CB LB SCR	EWS FOUND WORN	L347	OPEN	09/22/2023
	WNG									1.0
									-	1.0

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

AREA: ALL

PAGE: 50 OF 86

RUN TIME :

STAGE: ALL

RUN DATE: 10/2/2023

9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL ZONE : ALL DISPOSITION CODE : ALL

DEFECT TYPE : ALL TRADE : ALL CUST ENDORSE : ALL

CTRL CODE :					TYPE CODE:	ORIG	NATOR:	ALL			
	ZONE	STG								STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	RL SH NO		DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL3482	500	NRR	ΑE	5700	777-57-856-01-01	ERFORM LHW T/E REAL	SPAR CIC A	AFTER CLEANING	L348	OPEN	09/22/2023
	WNG										4.0
V II 0 100	500	NDD	۸.	5700	777 57 040 00 04			ASTER OF ENTIRE			4.0
XJL3490	500 WNG	NRR	AE	5700	777-57-948-02-01	ERFORM RHW T/E REA	SPAR CIC F	AFTER CLEANING	L349	OPEN	09/22/2023
	WING										4.0
											4.0
XJL3508	200	NRP	AV	3351	777-33-115-00-02			IT POWER SUPPLY ELECTRICAL CONNECTORS DURING AIRCRAFT POWER OFF	L350	WIP	09/23/2023
	CAB					ERIOD TO PREVENT BA	TERY FAILU	URE.			0.0
						1 LOWER	OWN ALL O\	OVERDOOR PANELS.			2.0
						2 REMOVE	OFAR LH AF	FT MIRROR PANEL ASSY AND A PANEL IN THE RIGHT WALL OF THE AFT CLOSET .			1.0
						3 REMOVE ABOVE S		RY MODULE A SUPPORT PANEL UNDER THE SECOND STEP AND ANOTHER SUPPORT PANEL			1.0
						4 DISCON	ECT ALL OVE	/ERDOOR EMERGENCY LIGHT POWER SUPPLY UNIT ELECTRICAL CONNECTORS.			5.0
						5 RECONN	ECT ALL EME	IERGENCY LIGHT POWER SUPPLY UNIT ELECTRICAL CONNECTORS			5.0
							ECT OFAR E	EMERGENCY LIGHT POWER SUPPLY ELECTRICAL CONNECTORS			1.0
								EMERGENCY LIGHT POWER SUPPLY ELECTRICAL CONNECTORS			1.0
								EMERGENCY LIGHT POWER SUPPLY ELECTRICAL CONNECTORS			1.0
								AFT MIRROR PANEL ASSY AND A PANEL IN THE RIGHT WALL OF THE AFT CLOSET			1.0
								EMERGENCY LIGHT POWER SUPPLY ELECTRICAL CONNECTORS			1.0
						ABOVE S		ITRY MODULE A SUPPORT PANEL UNDER THE SECOND STEP AND ANOTHER SUPPORT PANEL			1.0
								RDOOR PANELS.			2.0
						: 13 CARRY C	JT EMERGE	ENCY LIGHT POWER SUPPLY UNIT INSTALLATION TEST			3.0
											25.0
XJL3516	200	NRR	Al	25	777-53-920-00-01	FAR FWD CLOET LOWE	R DRAWER (	UPPER EDGE TRIM FOUND DISBOND	L351	WIP	10/02/2023
	CAB										3.0
											3.0
XJL3524	200	NRP	SS	25	777-25-060-01-CX-01	/A SEAT PAN VELCRO	APE COVER	R FOUND BROKEN AT L1AFT	L352	OPEN	09/23/2023
	CAB									0. 2	2.0
											2.0
XJL3532	200	NRP	SS	25	777-25-060-01-CX-01	A SEAT COVER FOUND	DIRTY AT R	R1 R2FWD L2AFT L4 R5I/B L5I/B O/B TTL7EA	L353	OPEN	09/23/2023
	CAB										3.0
											3.0

REQUESTED BY:

REFERENCE NO:

PROJECT: XJ

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 51 OF 86 RUN DATE: 10/2/2023

-----

4.0

RUN TIME: 9:39

515653

BMS571R1-2

CUSTOMER: CX A/C TYPE: 777

A/C REGN: B-KPV

ZONE: ALL

AREA: ALL

CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL

ATA NO: ALL

DISPOSITION CODE: ALL

DEFECT TYPE: ALL

TRADE: ALL

CUST ENDORSE: ALL

STAGE: ALL

DE1 E01 111	, , , , ,	-			TTO EDE : TE	THE	CINCL: YEL		
CTRL CODE	:				TYPE CODE:	ORIGINATOR: ALL			
	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCR	RIPTION JSN	STATUS	EST Mhr
XJL3540	200	NRP	SS	25	777-25-060-01-CX-01	C/A SEAT LOWER BACKRES SCREW NUT SPRING FOUND MISSING L1FWD	L354	OPEN	09/23/2023
	CAB								1.0
									1.0
XJL3557	100	NRR	Al	2500	777-53-822-00-01	FWD CGO LH STA540 SIDE GUIDE RAIL JOINT PLATE FND BROKEN. TTL2EA	L355	OPEN	09/23/2023
	LWR								2.0
									2.0
XJL3565	100	NRR	Al	2500	777-53-822-00-01	FWD CGO HANDLING SYSTEM PDU ROLLER FND WORN AT 6R 7R 17R & 20R.	1050	0.05.11	
AJESSOS	LWR	INIXIX	AI	2300	777-33-622-00-01	FIND CGO HANDLING STSTEIN POU ROLLER FIND WORN AT OR /R 1/R & 20R.	L356	OPEN	09/23/2023
									4.0
									4.0
XJL3573	100	NRR	Al	2500	777-53-822-00-01	FWD CGO THE LAST CENTER GUIDE RED LEAF FND STIFF.	L357	OPEN	09/23/2023
	LWR								0.5
									0.5
XJL3581	100	NRR	Al	2500	777-53-812-00-01	MEC INSULATION BLANKET FOUND BROKEN	L358	OPEN	09/23/2023
	LWR								6.0
									6.0
XJL3599	300	NRP	AE	5535	777-55-806-00-01	EMPREMOVE VERTICAL FIN L/E PANEL 321E FOR ACCESS.	L359	WIP	09/23/2023
	EMP						2009	V V II	0.0
						1C 1 REMOVE VERTICAL FIN 321E ACCESS FAIRING FOR ACCESS.			2.0
						1C 2 REMOVE VERTICAL V/FIN HF COMMUNICATION ANTENNA FEEDLIN	√E CONNECTION ATTACH BOLT		0.5
						1C 3 REINSTALL THE L/E FRG 321E			4.0
						1C 4 RECONNECT HF COMMUNICATION ANTENNA FEED LINES CONNEC	CTOR		1.0
						2C 5 CARRY OUT BONDING TEST BETWEEN HF ANTENNA AND THE STR	RUCTURE		0.5
						2C 6 CARRY OUT HF SYSTEM TEST			0.5
									8.5
XJL3607	200	NRR	Al	25	777-53-920-00-01	L5.L4.R4 DOOR BUSTLE EDGE TRIM FOUND TORN.	L360	WIP	09/24/2023
	CAB								6.0
									6.0
XJL3615	100	NRR	SM	5300	777-53-874-00-01	BULK CGO FLOOR PANEL ANCHOR NUT FOUND DAMAGED.TOTAL 4EA	L361	WIP	09/29/2023
	LWR								4.0

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 52 OF 86

RUN TIME :

2C

RUN DATE: 10/2/2023 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE:

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ATA NO: ALL ORIGINATING CUST REF NO: ZONE: ALL DISPOSITION CODE: ALL ALL DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE : TYPE CODE: ORIGINATOR ·

CTRL CODE :					TYPE CODE:	ORIGINATOR: ALL			OTATUO	LIDDATED DATE
JOB NO	ZONE AREA	STG	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION		STATUS STATUS	UPDATED DATE  EST Mhr
XJL3623	100	NRR	Al	2500	777-53-854-00-01	AFT CGO SIDEWALL FOUND WORN	DEFECT DECOMM FIGH		OPEN	09/23/2023
	LWR					, a , 666 6.52		2002	OI LIV	4.0
									-	
XJL3631	200	NRR	Al	56	777-53-904-00-01	M/D R1 DOOR WINDOW INSIDE FOUND DIRTY		1.202	COMP	4.0
AULUUUT	CAB	INIXIX	Ai	30	777-55-904-00-01	WID KT DOOK WINDOW INSIDE I COIND DIKTT		L363	COMP	09/25/2023 5.0
									-	
V II 00 40	000	NDD		50	777 50 004 00 04					5.0
XJL3649	200 CAB	NRR	Al	56	777-53-904-00-01	M/D L1 DOOR WINDOW INSIDE FOUND DIRTY		L364	COMP	09/25/2023
	O/ LD								_	5.0
										5.0
XJL3656	200	NRR	Al	56	777-53-908-00-01	M/D L2 DOOR WINDOW INSIDE FOUND DIRTY		L365	COMP	09/25/2023
	CAB									5.0
									-	5.0
XJL3664	200	NRR	ΑI	56	777-53-908-00-01	M/D R2 DOOR WINDOW INSIDE FOUND DIRTY		L366	COMP	09/25/2023
	CAB									5.0
									-	5.0
XJL3672	700	NRP	CL	32	777-900002-01-1-01	NOSE LANDING GEAR W/W AREA FND DIRTY.		L367	WIP	09/24/2023
	LDG									0.0
						1C 1 CLEAN THE AREA . 1C 2 APPLY CIC.				12.0 6.0
						TO 2 APPLY CIO.			-	
V II 2600	700	NRP	CL	32	777 000000 04 4 04	DILAM O WAWADEA FAID DIDTY				18.0
XJL3680	700 LDG	NKP	CL	32	777-900002-01-1-01	RH MLG W/W AREA FND DIRTY		L368	WIP	09/24/2023
						1C 1 CLEAN THE AREA .				0.0 24.0
						1C 2 APPLY CIC.				10.0
									-	34.0
XJL3698	700	NRP	CL	32	777-900002-01-1-01	LH MLG W/W AREA FND DIRTY.		L369	WIP	09/24/2023
	LDG									0.0
						1C 1 CLEAN THE AREA .				24.0
						1C 2 APPLY CIC.				10.0
									-	34.0

ORIGINATING CUST REF NO:

515653

ALL

REQUESTED BY:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

PAGE: 53 OF 86

RUN DATE: 10/2/2023

18.0

REFERENCE NO: BMS571R1-2 (By JSN) RUN TIME : 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

TRADE: ALL DEFECT TYPE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

				TYPE CODE:	ORIGINATOR:	ALL			
	STG								UPDATED DATE
								STATUS	EST Mhr
	NRR	SS	25			PIRY DATE AT:15A 26D 25D 24D 23D 22D 21D 20D 19D 18D 17D 16D 12D 11D	L370	WIP	10/01/2023
CAB									21.0
								-	21.0
200	NRR	SS	25	777-C252440-04-02-	EY PAX SEAT COAT HOOK FND LOOSEN	AT:63E	L371	OPEN	09/23/2023
CAB				01					1.0
								-	1.0
200	NRR	SS	25	777-C252440-04-02-	EY PAX SEAT COAT HOOK FND MISSING	S AT:59H	L372	OPEN	09/23/2023
CAB				01					1.0
								-	1.0
200	NRR	SS	25	777-C252440-04-02-			L373	OPEN	09/23/2023
CAB				01	64G 65E 65F 66F 67G 69E.G 71E.G 59A 60	A.B TTL:24EA			8.0
								-	8.0
200	NRR	SS	25	777-C252440-04-02-	E ZONE EY PAX SEAT LITERATURE POO	KET SPRING FND LOOSEN AT:42K 44J 45H 39F 40D 41D 41G 42D.E.F 43F 44D	L374	OPEN	09/23/2023
CAB				01	42B 43A TTL:14EA				4.0
								-	4.0
200	NRR	SS	25	777-C252410-01-01-	F/C SEAT RECLINE CABLE FOUND LOOS	EN AT 1D	L375	OPEN	09/23/2023
CAB				01					1.0
								-	1.0
200	NRP	SS	25	777-25-060-01-CX-01	C/A SEAT PAN SPRING FOUND LOOSEN	AT L5O/B	L376	OPEN	09/23/2023
CAB									1.0
								-	1.0
200	NRR	SS	25	777-25-040-03-CX-01	FB2 SEAT AIRBAG INFLATOR FND EXPIR	RY DATE AT:11G 12G 16G 17G 18G 19G 20G 21G 22G 23G 24G 26G TTL:12EA	1 377	WIP	10/01/2023
CAB				-01			2077	****	18.0
								-	18.0
200	NRR	SS	25	777-25-040-03-CX-01	FR2 SEAT AIRRAG INFLATOR FND EXPIR	2Y DATE AT:11K 12K 16K 17K 18K 19K 20K 21K 22K 23K 24K 25K TTI:12EA	1 270	WID	10/01/2023
CAB	11111	00	20	-01	. DE SERVINISMO IN EXPORTING ENTIR		LS/O	VVIE	18.0
								_	
	200 CAB  200 CAB	200 NRR CAB NRR	AREA TD  200 NRR SS  200 NRR SS	AREA       TD       ATA         200 CAB       NRR NRR       SS       25         200 CAB       NRR NRR       SS       25         200 CAB       NRR NRR       SS       25         200 CAB       NRR NRR       SS       25         200 CAB       NRR       SS       25	ZONE AREA         STG ATA         ORIG CUST REF NO.           200 NRR SS 25         7777-25-040-03-CX-01 -01           200 NRR SS 25         7777-C252440-04-02- 01           200 NRR SS 25         7777-C252410-01-01- 01           200 CAB         NRR SS 25         7777-25-060-01-CX-01           200 NRR SS 25         7777-25-040-03-CX-01           200 NRR SS 25         7777-25-040-03-CX-01	ZONE         STG           AREA         TD         ATA         ORIG CUST REF NO.         CTRL SH NO           200         NRR         SS         25         777-25-040-03-CX-01         FB2 SEAT AIRBAG INFLATABLE FND EXFT           200         NRR         SS         25         777-C252440-04-02-         EY PAX SEAT COAT HOOK FND MISSING           200         NRR         SS         25         777-C252440-04-02-         EY PAX SEAT COAT HOOK FND MISSING           200         NRR         SS         25         777-C252440-04-02-         F ZONE EY PAX SEAT LITERATURE POC           CAB         NRR         SS         25         777-C252440-04-02-         E ZONE EY PAX SEAT LITERATURE POC           CAB         NRR         SS         25         777-C252440-04-02-         E ZONE EY PAX SEAT LITERATURE POC           CAB         01         42B 43A TIL:14EA         42B 43A TIL:14EA           200         NRR         SS         25         777-C252410-01-01-         F/C SEAT RECLINE CABLE FOUND LOOSEN           CAB         NRR         SS         25         777-25-060-01-CX-01         FB2 SEAT AIRBAG INFLATOR FND EXPIR           200         NRR         SS         25         7777-25-040-03-CX-01         FB2 SEAT AIRBAG INFLATOR FND EXPIR <tr< td=""><td>  ZONE   STG   AREA   TD   ATA   ORIG CUST REF NO.   CTRL SH NO   DEFECT DESCRIPTION    </td><td>                                     </td><td>  STATUS   AREA   To   ATA   ORIG CUST REF NO.   CTAL SH NO   DEFECT DESCRIPTION   JSN   STATUS   AREA   ORIG CUST REF NO.   CTAL SH NO   DEFECT DESCRIPTION   JSN   STATUS   AREA   ORIG CUST REF NO.   CTAL SH NO   DEFECT DESCRIPTION   JSN   STATUS   AREA   ORIG CUST REF NO.   CTAL SH NO   DEFECT DESCRIPTION   JSN   STATUS   AREA   ORIG CUST REF NO.   CTAL SH NO   DEFECT DESCRIPTION   JSN   STATUS   AREA   ORIG CUST REF NO.   CTAL SH NO   DEFECT DESCRIPTION   JSN   STATUS   DEFECT DESCRIPTION   JSN   STATUS   DEFECT DESCRIPTION   JSN   DEFECT DESCRIPTION  </td></tr<>	ZONE   STG   AREA   TD   ATA   ORIG CUST REF NO.   CTRL SH NO   DEFECT DESCRIPTION		STATUS   AREA   To   ATA   ORIG CUST REF NO.   CTAL SH NO   DEFECT DESCRIPTION   JSN   STATUS   AREA   ORIG CUST REF NO.   CTAL SH NO   DEFECT DESCRIPTION   JSN   STATUS   AREA   ORIG CUST REF NO.   CTAL SH NO   DEFECT DESCRIPTION   JSN   STATUS   AREA   ORIG CUST REF NO.   CTAL SH NO   DEFECT DESCRIPTION   JSN   STATUS   AREA   ORIG CUST REF NO.   CTAL SH NO   DEFECT DESCRIPTION   JSN   STATUS   AREA   ORIG CUST REF NO.   CTAL SH NO   DEFECT DESCRIPTION   JSN   STATUS   DEFECT DESCRIPTION   JSN   STATUS   DEFECT DESCRIPTION   JSN   DEFECT DESCRIPTION

JSN RANGE SELECTED: ALL

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

ORIG-STAGE: ALL

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 54 OF 86

RUN TIME :

ESTIMATED MHR: ALL

RUN DATE: 10/2/2023

9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

PERIOD: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

TYPE CODE: CTRL CODE : ORIGINATOR · ALL

STATUS: ALL

CTRL CODE :					TYPE CODE:	ORIGINATOR	R: ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL3797	500	NRR	GW	5700	777-57-856-01-01	LHW T/E ACCESS PANEL 552BB(3)	BEA) CB(3EA) LB(3EA) SCREW FOUND SEIZED	L379	COMP	09/26/2023
	WNG									9.0
									-	9.0
XJL3805	500	NRR	SM	5700	777-57-856-01-01	LHW T/E ACCESS PANEL 552BB(3)	EA) CB(3EA) LB(3EA) ANCHOR NUT FOUND WORN	L380	OPEN	09/24/2023
	WNG									6.0
									-	6.0
XJL3813	200	NRR	SS	25	777-C252410-01-01-	F/C SEAT RECLINE CABLE FOUND	D LOOSEN AT 1D	L381	OPEN	09/24/2023
	CAB				01					2.0
									-	2.0
XJL3821	200	NRR	ΑI	2531	777-53-904-00-01	CABIN ZONE A G1 GALLERY OVEN	N183 WATER HOSE FOUND LEAK	L382	OPEN	09/24/2023
	CAB									3.0
									-	3.0
XJL3839	200	NRR	Al	2533	777-C250009-01-01-	GALLEY 1L CHILLER TEMPERATU	IRE OUT OF LIMIT	L383	WIP	09/29/2023
	CAB				R-01					0.0
									-	0.0
XJL3847	200	NRR	Al	2531	777-53-904-00-01	CABIN ZONE A G5 GALLERY OVEN	N 2 WATER HOSE FOUND LEAK	L384	OPEN	09/24/2023
	CAB									3.0
									-	3.0
XJL3854	200	NRR	Al	2533	777-C250009-01-01-	GALLEY 4R CHILLER MALFUNCTION	ON	L385	OPEN	09/24/2023
	CAB				R-01			2000	OI LIV	0.0
									-	0.0
XJL3862	200	NRR	AI	2531	777-53-904-00-01	CARIN ZONE A GZ GALLERY OVEN	N 2&3: GALLERY G6 OVEN 1&4 WATER HOSE FOUND LEAK	L386	OPEN	09/24/2023
7020002	CAB	14141	7.0	2001	777 00 00 1 00 01	ONDIN ZONE / OF ONEEER OVER	NEED, SILLERY OF OVER IN THE WIELEN OF TOOLS LET IN	L300	OPEN	3.0
									-	
XJL3870	200	NRR	Al	2531	777 52 000 00 04	CADIN C2 CALLEDY OVEN LOWER	D DI IMPED FOLIND DAMACE		ODEN	3.0
XJL3870	CAB	NKK	AI	2531	777-53-908-00-01	CABIN G3 GALLERY OVEN LOWER	R BUMPER FOUND DAMAGE	L387	OPEN	09/24/2023
										5.0
										5.0

0PPC DISTRIBUTION:

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

55 OF 86 PAGE: RUN DATE: 10/2/2023

RUN TIME :

9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

CIRL CODE :					TYPE CODE:	ORIGINATOR:	ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
(JL3888	200	NRR	Al	2500	777-53-900-00-01	COCKPIT LH RAIN COAT CLOSET INSID	E CATCH FOUND DAMAGE	L388	OPEN	09/24/2023
	CAB									1.0
									-	1.0
JL3896	200	NRR	AV	3327	777-C330000-01-02- 01	GALLEY 2&3 LOWER CEILING PANEL L/I	HAFT AREA LIGHT MALFUNCTION	L389	OPEN	09/24/2023
	CAB				O1					2.0
									-	2.0
JL3904	200	NRR	AV	3327	777-C330000-01-02-	GALLEY 4&5 LOWER CEILING PANEL R/	H FWD AREA LIGHT MALFUNCTION	L390	OPEN	09/24/2023
	CAB				01					2.0
									-	2.0
JL3912	500	NRR	GW	5700	777-12-008-00-03	LHW L/E ACCESS PANEL 521ZB(2EA) UE	3(2EA) TB(2EA) QB(3EA) MB(1EA) FB(1EA) SCREWS FOUND SEIZED	L391	COMP	09/28/2023
	WNG									11.0
									-	11.0
JL3920	500	NRR	SM	5700	777-12-008-00-03	LHW L/E ACCESS PANEL 521ZB(2EA) UE	3(2EA) TB(2EA) QB(3EA) MB(1EA) FB(1EA) ANCHOR NUT FOUND WORN	L392	OPEN	09/24/2023
	WNG									6.0
									-	6.0
JL3938	200	NRP	AV	2532	777-C250008-01-01-	G6 OVEN 2 CONTROL PANEL ON/OFF B	UTTOM MALFUNCITON	L393	OPEN	09/24/2023
	CAB				01					1.5
									-	1.5
JL3946	500	NRR	GW	5708	777-57-864-01-01	LHW T/E ACCESS PANEL561LB(2EEA SO	CREWS FOUND SEIZED	L394	COMP	09/26/2023
	WNG									2.0
									-	2.0
JL3953	500	NRR	SM	5708	777-57-864-01-01	LHW T/E ACCESS PANEL561LB(2EA) AN	CHOR NUT FOUND WORN	L395	OPEN	09/24/2023
	WNG									1.0
									-	1.0
JL3961	100	NRR	CL	2500	777-53-818-00-01	FWD CARGO CEILING PANEL SURFACE	FND DIRTY	L396	WIP	10/02/2023
	LWR									7.0
									-	7.0
										7.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE:

ESTIMATED MHR: ALL

56 OF 86

RUN DATE : 10/2/2023 RUN TIME : 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

ATA NO : ALL ZONE : ALL DISPOSITION CODE : ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

CINE CODE.	ZONE	STG			TIFE GODE.	ONGINATOR: AL	-		STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL3979	100	NRR	CL	2500	777-53-818-00-01	FWD CARGO SIDEWALL PANEL SURFACE F	ID DIRTY	L397	WIP	10/02/2023
	LWR									7.0
									-	7.0
XJL3987	100	NRR	CL	2500	777-53-854-00-01	AFT CARGO CEILING PANEL SURFACE FND	DIRTY	L398	WIP	10/02/2023
	LWR									7.0
									-	7.0
XJL3995	100	NRR	CL	2500	777-53-854-00-01	AFT CARGO SIDEWALL PANEL SURFACE FN	D DIRTY	L399	WIP	10/02/2023
	LWR									7.0
									-	7.0
XJL4001	100	NRR	CL	2500	777-53-870-00-01	BULK CARGO COMP CEILING AND SIDEWAL	PANEL FND DIRTY	L400	OPEN	09/24/2023
	LWR									5.0
									-	5.0
XJL4019	100	NRR	CL	2500	777-53-862-00-01	AFT CARGO AND BULK CGO FLOOR PANEL	END DIRTY	L401	OPEN	09/24/2023
	LWR							2401	OI EN	10.0
									-	10.0
XJL4027	100	NRR	CL	2500	777-53-862-00-01	AFT CARGO ROLLER TRAY FND DIRTY		L402	WIP	09/28/2023
7.02.702.	LWR		0_	2000	00 002 00 0.	7 7 6 1.00 1.02.22.1.1.1.1.1.1.2.2.1.1.1.		L402	VVII	16.0
									-	
XJL4035	100	NRR	CL	2500	777-53-822-00-01	FWD CARGO FLOOR PANEL SURFACE FND	NIPTY	1.400	ODEN	16.0
70L4000	LWR	IVIXIX	OL	2500	777-33-022-00-01	TWD OAROOT EOORT ANEE SORT AGE THE	ZIIXI I	L403	OPEN	09/24/2023 7.0
									-	
XJL4043	100	NRR	CL	2500	777-53-822-00-01	FWD CARGO ROLLER TRAY FND DIRTY		1.404	14/15	7.0
AJL4043	LWR	INIXIX	CL	2500	777-33-822-00-01	FWD CARGO ROLLER TRAT FIND DIRTT		L404	WIP	09/28/2023
									_	16.0
V II 4050	200	NDD	Α.	0544	777 F2 000 00 04	CADINI AV A O D E TOIL ET OUDCUD ANTIGO	LLICION DI ATT FOLIND MICCINO			16.0
XJL4050	200 CAB	NRR	Al	2541	777-53-908-00-01	CABIN LAV A C D F TOILET SHROUD ANTICO	LLISION PLATE FOUND MISSING	L405	OPEN	09/24/2023
	5715								_	4.0
										4.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

## TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 57 OF 86

ESTIMATED MHR: ALL

STAGE: ALL

RUN DATE: 10/2/2023

25.5

RUN TIME : 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

STATUS: ALL ORIG-STAGE: ALL JSN RANGE SELECTED: ALL

PERIOD: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

AREA: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL TYPE CODE: ORIGINATOR ·

CTRL CODE :

CTRL CODE:					TYPE CODE:	:	ORIGIN	ATOR: ALL			
	ZONE	STG								STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SI	H NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL4068	200	NRR	Al	2541	777-53-908-00-01	CABIN L	AV M L H TOILET S	HROUD ANTICOLLISION PLATE FOUND MISSING	L406	WIP	10/02/2023
	CAB										3.0
										-	3.0
KJL4076	200	NRR	Al	2541	777-53-908-00-01	CABIN L	_AV M TOILET SHR(	OUD SEAT COVER DAMPER COVER FOUND CRACKED	L407	OPEN	09/24/2023
	CAB					07.15 2	7.1 10.221 0110	55 52 H 50 12 (5) HIII 21 (50 12 H 50 H 50 H 50 H 50 H	L+01	OI LIV	3.0
										_	3.0
											3.0
JL4084	500	NRR	SS	5700	777-20-251-10-01	LHW L/E	ACCESS PANEL51	1AB EXTERNAL SURFACE FOUND DELAMINATION	L408	WIP	09/25/2023
	WNG										0.0
						1C 1	DO AN INS	PECTION TO FIND THE DAMAGE DIMENSION			1.0
						1C 2	2 DO THE RE	PAIR TO DAMAGED AREA			20.0
						1C 3	3 DO THE PC	ST REPAIR INSPECTION			1.0
						1C 4	APPLY RES	IN AND SMOOTH OUT			2.0
						2C 5	5 APPLY CON	IDUCTIVE COATING			0.5
						2C 6	3 MEASURE	THE RESISTIVITY OF CONDUCTIVE COATING			0.5
						2C 7	7 RESTORE	SURFACE FINISH			0.5
						2C 8	B FILL IN THE	SDR FORM			0.0
										-	25.5
JL4092	500	NRR	SS	5700	777-20-251-10-01	RHW L/F	E ACCESS PANEL6	1GB EXTERNAL SURFACE FOUND DELAMINATION	L409	WIP	09/25/2023
	WNG										0.0
						1C 1	DO AN INS	PECTION TO FIND THE DAMAGE DIMENSION			1.0
						1C 2	2 DO THE RE	PAIR TO DAMAGED AREA			20.0
						1C 3	3 DO THE PC	ST REPAIR INSPECTION			1.0
						1C 4	4 APPLY RES	IN AND SMOOTH OUT			2.0
						2C 5	5 APPLY CO!	DUCTIVE COATING			0.5
						2C 6		THE RESISTIVITY OF CONDUCTIVE COATING			0.5
						2C 7		SURFACE FINISH			0.5
						2C 8		SDR FORM			0.0
										_	

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 58 OF 86

RUN TIME :

ESTIMATED MHR: ALL

RUN DATE: 10/2/2023

9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

TINE CODE .	ZONE	STG			THE GODE.	ONORVATOR: ALL	STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION JSN	STATUS	EST Mhr
(JL4100	500 WNG	NRR	SS	5700	777-20-251-10-01	RHW L/E ACCESS PANEL611KB EXTERNAL SURFACE FOUND DELAMINATION L410	WIP	09/25/2023
	WING							0.0
						1C 1 DO AN INSPECTION TO FIND THE DAMAGE DIMENSION 1C 2 DO THE REPAIR TO DAMAGED AREA		1.0 20.0
						1C 2 DO THE REPAIR TO DAMAGED AREA 1C 3 DO THE POST REPAIR INSPECTION		1.0
						1C 4 APPLY RESIN AND SMOOTH OUT		2.0
						2C 5 APPLY CONDUCTIVE COATING		0.5
						2C 6 MEASURE THE RESISTIVITY OF CONDUCTIVE COATING		0.5
						2C 7 RESTORE SURFACE FINISH		0.5
						2C 8 FILL IN THE SDR FORM		0.0
								25.5
JL4118	200 CAB	NRR	AV	2525	777-24-001-00-01	PC POWER TEST FOUND 31E PC OULET RED LIGHT  L411	OPEN	09/24/2023
	OND							2.0
								2.0
JL4126	300 EMP	NRP	AV	2361	777-55-806-00-01	VERTICAL FIN FWD #1 STATIC DISCHARGER BROKEN.	OPEN	09/24/2023
	LIVII							2.0
								2.0
JL4134	200	NRM	Al	2560	AEO-29097-01	CABIN PASSENGER LIFE VEST FOUND EXPIRED DAY LESS THAN 4.5 MONTHS 154EA L413	WIP	09/28/2023
	CAB							7.5
							-	7.5
JL4142	200	NRM	Al	2560	AEO-29097-01	CABIN SPARE LIFE VEST FOUND EXPIRED DAY LESS THAN 4.5 MONTHS 3EA IN 70AC	WIP	09/26/2023
	CAB							1.0
							-	1.0
JL4159	200	NRM	Al	2560	AEO-29097-01	CABIN SPARE LIFE VEST FOUND EXPIRED DAY LESS THAN 4.5 MONTHS 1EA IN 70HK	WIP	09/28/2023
	CAB							1.0
								1.0
JL4167	200	NRM	Al	2560	AEO-29097-01	CABIN SPARE INFANT LIFE VEST FOUND EXPIRED DAY LESS THAN 4.5 MONTHS 11EA IN 70AC L416	WIP	09/28/2023
	CAB							1.0
								1.0

0PPC DISTRIBUTION:

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

59 OF 86 PAGE:

STAGE: ALL

RUN DATE: 10/2/2023

RUN TIME : 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ATA NO: ALL ORIGINATING CUST REF NO: ZONE: ALL DISPOSITION CODE: ALL ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

L CODE :					TYPE CODE:	ORIGINATOR: ALL				
Z	ZONE	STG							STATUS	UPDATED DATE
NO A	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
	600	NRR	AV	2361	777-57-958-02-01	RH WING TIP 1 EA STATIC DISCHARGER BROKEN.		L417	OPEN	09/24/2023
W	WNG									2.0
									-	2.0
	300	NRR	AV	2361	777-55-830-01-01	LEFT STAB TIP 1EA STATIC DISCHARGER BROKEN.		L418	OPEN	09/24/2023
Е	EMP									2.0
									-	2.0
	300	NRR	AV	2361	777-55-850-02-01	RIGHT STAB. TIP 1EA STATIC DISCHARGER BROKEN.		L419	OPEN	09/24/2023
Е	EMP									2.0
									-	2.0
4209 10	100	NRP	AE	0711	777-900002-01-1-01	FUS-PERFORM THE A/C SPECIAL JACKING.		L420	OPEN	09/24/2023
F'	FUS					REF TO XMN TASK CARD: TA07000101-BOE				0.0
									-	0.0
4217 20	200	NRR	AV	2525	777-25-040-03-CX-01	FB2 BC SEAT COMPLIANCE CHECK OF EMA FOUND 5	6EA EMA EXPIRY DATE OUT OF LIMIT	L421	OPEN	09/24/2023
С	CAB				-01					112.0
									-	112.0
4225 50	500	NRR	AE	5700	777-57-848-01-01	LHW WING TIP L/E FAIRING SEALANT FOUND MISSING	3	L422	COMP	09/28/2023
W	WNG									1.0
									-	1.0
4233 20	200	NRM	ΑI	2560	AEO-29573-01	CABIN PBE INSIDE OFAR AT DOOR 5 ON LOWER SIDE	WALL PANEL ACROSS FROM STAIRCASE FOUND EXPIRED	L423	COMP	09/30/2023
С	CAB									1.0
									-	1.0
4241 20	200	NRR	Al	2531	777-53-908-00-01	CABIN G2R GALLERY COMPARTMENT R2-12 ICE DRA	NER TRACK FOUND DAMAGE	L424	WIP	09/29/2023
С	CAB									5.0
									-	5.0
4258 60	600	NRR	AE	28	777-28-021-10-05	RHW FUEL TANK ACCESS PNLS FOUND DIRTY		L425	COMP	09/26/2023
W	WNG							3	2	8.0
									-	8.0
4258 60	600	NRR	AE	28	777-28-021-10-05	RHW FUEL TANK ACCESS PNLS FOUND DIRTY		L425	- COMP	09/2

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 60 OF 86 RUN DATE: 10/2/2023

RUN TIME :

10/2/2023

9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

TYPE CODE:

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

ORIGINATOR: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE:

	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL4266	500	NRR	AE	28	777-28-021-10-04	LHW FUEL TANK ACCESS PNLS FOUND DIRTY		L426	COMP	09/26/2023
	WNG									8.0
									-	8.0
KJL4274	100	NRR	AE	2152	777-53-830-00-02	FUS-RH PACK HEAT EXCHANGER FOUND CRACKED	).	L427	OPEN	09/24/2023
	FUS									0.0
									-	0.0
(JL4282	100	NRR	AE	2152	777-53-830-00-02	FUS-RH PACK DIFFUSER HOUSING FOUND DE LAM	INATION.	L428	OPEN	09/24/2023
	FUS									0.0
									-	0.0
(JL4290	100	NRR	AE	2152	777-53-830-00-02	FUS-RH PACK RAM AIR INLET DUCT AFT SLEEVE CO	ONNECTOR FOUND TORN.	L429	OPEN	09/24/2023
	FUS							2.20	OI LIV	2.0
									-	2.0
JL4308	100	NRR	AE	2152	777-53-830-00-02	FUS-RH PACK LWR FCV BONDING BROKEN.		L430	OPEN	09/24/2023
.000	FUS			2.02	00 000 00 02	1 GO WIT NOW ENWY OF BONDING BROKEN.		L430	OPLIN	0.0
						1C 1 REPLACE THE BONDING.				1.0
						1C 2 DO THE BONDING TEST.				0.5
									-	1.5
JL4316	300	NRR	SM	5500	777-55-861-00-01	RIGHT SIDE HORIZONTAL STABILIZER T/E ACCESS	PANEL 345GXB 3 EA ANCHOR NUT BROKEN	L431	WIP	10/02/2023
	EMP									3.0
									-	3.0
(JL4324	100	NRR	AE	2152	777-53-830-00-02	FUS-RH PACK THE CONDITIONING LOW LIMIT VALV	ES 2EA BONDINGS BROKEN.	L432	OPEN	09/24/2023
	FUS									0.0
						1C 1 REPLACE THE BONDING.				1.0
						1C 2 DO THE BONDING TEST.				0.5
									-	1.5
(JL4332	100	NRR	AE	2152	777-53-830-00-02	FUS-RH PACK THE CONDITIONING ECONOMY VALV	E BONDING BROKEN.	L433	OPEN	09/24/2023
	FUS									0.0
						1C 1 REPLACE THE BONDING. 1C 2 DO THE BONDING TEST.				1.0 0.5

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 61 OF 86 RUN DATE: 10/2/2023

RUN TIME : 9:39

1.5

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL JSN RANGE SELECTED: ALL ESTIMATED MHR: ALL

ATA NO: ALL DISPOSITION CODE: ALL ORIGINATING CUST REF NO: ALL ZONE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE : TYPE CODE: ORIGINATOR ·

CTRL CODE:					TYPE CODE:	ORIGINATOR: ALL			
	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL4340	100	NRR	ΑE	2152	777-53-830-00-02	FUS-RH PACK RAM AIR INLET DUCT MIDDLE BONDING BROKEN.	L434	OPEN	09/24/2023
	FUS								0.0
						1C 1 REPLACE THE BONDING.			1.0
						1C 2 DO THE BONDING TEST.			0.5
								-	1.5
XJL4357	500	NRR	SS	5700	777-12-008-00-02	RHW L/E ACCESS PANEL611CB EXTERNAL SURFACE FOUND DELAMINATION	L435	WIP	09/25/2023
	WNG								0.0
						1C 1 DO AN INSPECTION TO FIND THE DAMAGE DIMENSION			1.0
						1C 2 DO THE REPAIR TO DAMAGED AREA 1C 3 DO THE POST REPAIR INSPECTION			12.0 1.0
						1C 3 DO THE POST REPAIR INSPECTION 1C 4 APPLY RESIN AND SMOOTH OUT			2.0
						2C 5 FILL IN THE SDR FORM			0.0
						2C 6 APPLY CONDUCTIVE COATING			1.0
						2C 7 MEASURE THE RESISTIVITY OF CONDUCTIVE COATING			0.5
						2C 8 RESTORE SURFACE FINISH			0.0
								-	17.5
XJL4365	200	NRP	AV	3351	777-33-060-01-CX-01	EMERGENCY LIGHT TEST FOUND 1D.2D AISLE EMERGENCY LIGHT COVER MISSING	L436	OPEN	09/24/2023
	CAB								2.0
								-	2.0
XJL4373	200	NRP	AV	3351	777-33-060-01-CX-01	REMOVE THE CEILING PANEL FOUND 67HK. 65HK CONNECTOR CRACK	L437	OPEN	09/24/2023
	CAB								2.0
								-	2.0
XJL4381	100	NRR	ΑE	2100	777-53-830-00-01	LEFT AIR CONDITIONING SYSTEM RAM AIR INLET DUCT OUTBOARD SUPPORT ROD FOUND ROD END BEARING	L438	OPEN	09/24/2023
7021001	FUS	14141	712	2100	777 00 000 00 01	WORN	L430	OPEN	2.0
								-	
V II 4200	200	NDD	۸.	5500	777 55 004 00 04	VEDTICAL OTABILIZED FORWARD TID FAIRING 9274 FA RONDING HINDED FOLIND WIDE DROVEN			2.0
XJL4399	300 EMP	NRR	AE	5500	777-55-824-00-01	VERTICAL STABILIZER FORWARD TIP FAIRING 327 1 EA BONDING JUMPER FOUND WIRE BROKEN	L439	WIP	09/26/2023
	LIVII								0.0
						1C 1 REPLACE THE BONDING.			1.0
						1C 2 DO THE BONDING TEST.			0.5
								-	

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

62 OF 86 PAGE:

RUN DATE: 10/2/2023

RUN TIME : 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

TINE CODE .	70NF	CTC			TIFE CODE.	ONGINATOR: AL	<b>L</b>		STATUS	UPDATED DATE
JOB NO	ZONE AREA	SIG	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL4407	300	NRR	AE	5500	777-55-824-00-01	VERTICAL STABILIZER TIP FAIRING 327 FOL		L440	COMP	09/27/2023
	EMP							2	00	2.0
									-	2.0
XJL4415	200	NRM	CL	2500	AEO-29097-01	CABIN FLASH LIGHT BASE FOUND DIRTY		L441	WIP	10/01/2023
	CAB					0.22.02.0		L441	VVII	5.0
									-	5.0
(JL4423	200	NRM	Al	2560	AEO-29097-01	CABIN EMERGENCY EQUIPMENT SECURITY	Y SEAL FOLIND DAMAGE	L442	WIP	09/28/2023
OL7720	CAB	TATATA	7.0	2000	ALC-2007-01	OADIN EMEROLINOT EQUIT MENT DECORT	SEALT OUTD DAIWHOL	L442	VVIP	1.0
									-	
(JL4431	200	NRR	SS	25	777-C252430-01-03-	DEV DAY CEAT I ECDECT CUIDDODT DDACK	ET CODENI FOLIND I OOCEN AT 22A 20E E 24E 22D 22E C 24D EE C 24V 22U	1.440	MID	1.0
JL4431	CAB	INIXIX	33	25	01	K 32H 31D 30D 31A 34C 33C TOTAL:20EA	ET SCREW FOUND LOOSEN AT:32A 30E F 31E 32D 33F G 34D EF G 34K 33H	L443	WIP	09/26/2023
									_	10.0
11.4440	200	NDD	00	25	777 0050400 04 00	DEV DAY OF AT DAOY DEGT LIVE FIAID COVE	D ACCORDING A LOCAL OF A			10.0
JL4449	200 CAB	NRR	SS	25	777-C252430-01-06- 01	PEY PAX SEAT BACK REST HYD FWD COVE	R &SCREW FOUND MISSING AT:33A 34A TOTAL:2EA	L444	OPEN	09/25/2023
									_	1.0
										1.0
JL4456	200 CAB	NRR	SS	25	777-C252430-01-04- 01	PEY PAX SEAT CONSOLE FWD COVER FOL	ND CRACKED AT:34AC 31FG TOTAL:2EA	L445	OPEN	09/25/2023
	0712								_	2.0
										2.0
JL4464	200 CAB	NRR	SS	25	777-C252430-01-03- 01	PEY PAX SEAT LEGREST HYD SCREW FOU	ND LOOSEN AT:33A C 34A C 30E 32H 32E 33D TOTAL:8EA	L446	WIP	09/26/2023
	CAB								_	4.0
									_	4.0
JL4472	200	NRR	SS	25	777-C252430-01-03- 01	PEY PAX SEAT LEGREST BUTTON CABLE C	PERATION FOUND TIGHTEN AT:33A H TOTAL:2EA	L447	WIP	09/26/2023
	CAB				<b>.</b>					1.0
									-	1.0
JL4480	200	NRR	SS	25	777-C252430-01-06- 01	PEY PAX SEAT BACK REST HYD FWD COVE	R SCREW FOUND MISSING AT:33C	L448	OPEN	09/25/2023
	CAB				01					0.5
									-	0.5

0PPC DISTRIBUTION:

REQUESTED BY:

REFERENCE NO:

DEFECT TYPE: ALL

## TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

63 OF 86 PAGE:

RUN DATE: 10/2/2023

RUN TIME : 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

AREA: ALL

ESTIMATED MHR: ALL DISPOSITION CODE: ALL

ORIGINATING CUST REF NO: ALL

515653

BMS571R1-2

TRADE: ALL

ATA NO: ALL ZONE: ALL CUST ENDORSE: ALL

STAGE: ALL

CTRL CODE:

TYPE CODE: ORIGINATOR: ALL

CIRL CODE :					TYPE CODE:	ORIGINATOR:	ALL		OTAT: : C	LIDD 4775 5 :
	ZONE	STG							STATUS	UPDATED DATE
IOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
JL4498	200 CAB	NRR	SS	25	777-C252430-01-03- 01	PEY PAX SEAT BOTTOM PAN STRUC	TURE FOUND CRACKED AT:33A 30D E F 32G TOTAL:5EA	L449	OPEN	09/25/2023
	CAB									5.0
									-	5.0
JL4506	200	NRR	SS	25	777-C252430-01-05- 01	PEY PAX SEAT ARM REST LOWER PL	UG FOUND MISSING AT:33A 33F 34G (2EA) 33H TOTAL:5EA	L450	OPEN	09/25/2023
	CAB				01					2.5
									-	2.5
JL4514	200	NRR	SS	25	777-C252430-01-05- 01	PEY PAX SEAT ARM REST AFT PLUG	FOUND MISSING AT:33A 34A 32K 34K 32A K TOTAL:6EA	L451	OPEN	09/25/2023
	CAB				O I					3.0
									-	3.0
JL4522	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT AFT FOOTREST WASH	IER FOUND MISSING AT:32A C 30E(2EA) 31D F G 32D 33E(3EA) TOTAL:11EA	L452	OPEN	09/25/2023
	CAB				01					11.0
									-	11.0
JL4530	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT LEGREST OPERATION	FOUND NOISE AT:34A 31E 34D TOTAL:3EA	L453	WIP	09/26/2023
	CAB				01					1.5
									-	1.5
JL4548	200	NRR	SS	25	777-C252430-01-05-	PEY PAX SEAT ARM REST TIRM CAP	FOUND LOOSEN AT:32A 32G 34H TOTAL:3EA	L454	WIP	09/26/2023
	CAB				01					1.5
									-	1.5
JL4555	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT BOTTOM PAN FWD PL	UG SCREW FOUND LOOSEN AT:32C 33C	L455	WIP	09/26/2023
	CAB				01					1.0
									-	1.0
JL4563	200	NRR	SS	25	777-C252430-01-06-	PEY PAX SEAT BACK REST HYD SIDE	BAY SCREW FOUND LOOSEN AT:32C 34C	L456	WIP	09/26/2023
	CAB				01					1.0
									-	1.0
IL4571	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT AFT FOOTREST BUSH	ING FOUND MISSING AT:31A 33E 33F G TOTAL:3EA	L457	OPEN	09/25/2023
	CAB				01			L437	OFLIN	3.0
									-	
										3.0

DISTRIBUTION:

REQUESTED BY:

REFERENCE NO:

0PPC

## TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 64 OF 86

RUN TIME :

RUN DATE: 10/2/2023

9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

ALL

ATA NO: ALL TRADE: ALL CUST ENDORSE: ALL ZONE: ALL DISPOSITION CODE: ALL AREA: ALL

CTDL CODE

DEFECT TYPE: ALL

TYPE CODE

ODICINATOR

STAGE. ALL	S	TAGE:	ALL	
------------	---	-------	-----	--

CTRL CODE :					TYPE CODE:	ORIGINATO	R: ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL4589	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT LEGREST SUPPO	RT BRACKET PIN AND WASHER&CLIP AND BUSHING FOUND MISSING AT:34A	L458	OPEN	09/25/2023
	CAB				01					1.0
									-	1.0
XJL4597	200	NRR	SS	25	777-C252430-01-06-	PEY PAX SEAT BACK REST ATT I	HEADREST SLIDE TRACK FOUND LOOSEN AT:31C	L459	WIP	09/26/2023
	CAB				01					0.5
									-	0.5
XJL4605	200	NRR	SS	25	777-C252430-01-04-	PEY PAX SEAT CONSOLE TOP CA	AP FOUND CRACKED AT:34AC	L460	OPEN	09/25/2023
	CAB				01			2.00	0. 2	1.0
									-	1.0
XJL4613	200	NRR	SS	25	777-C252430-01-06-	DEV DAY SEAT DACK DEST SCDE	EW FOUND LOOSEN AT31C 33A C 31E 30F G D 32E F G 33E 34D E G 32H K 33H K 34H K	1.404	WID	
A0L4010	CAB	MIXIX	00	20	01	TOTAL:20EA	WI OUND EGGSEN ATS 10 30A G 31E 30F G D 32E F G 33E 34D E G 32F R 33F R 34F R	L461	WIP	09/28/2023 10.0
									_	
V II 4004	000	NDD	00	05	777 0050400 04 00	DEV DAY OF AT FOOTBEST ATT				10.0
XJL4621	200 CAB	NRR	SS	25	777-C252430-01-03- 01	PEY PAX SEAT FOOTREST ATTS	SCREW FOUND LOOSEN AT:31A C 30D E F G 32H K TOTAL:8EA	L462	WIP	09/26/2023
	O/ ND								_	4.0
										4.0
XJL4639	200	NRR	SS	25	777-C252430-01-06- 01	PEY PAX SEAT CONSOLE FWD T	OP CAP SCREW FOUND MISSING AT:31C 33F 34K TOTAL:3EA	L463	OPEN	09/25/2023
	CAB				•					1.5
									-	1.5
XJL4647	200	NRR	SS	25	777-C252440-04-04- 01	EY FIRST SEAT INNER SHOUD FO	OUND LOOSEN AT 40HJK 39DEFG 39AC40C 59ABC 60DEFG 59HJK TTL 20EA	L464	OPEN	09/25/2023
	CAB				01					5.0
									-	5.0
XJL4654	200	NRR	SS	25	777-C252430-01-05-	PEY PAX SEAT CONSOLE ARM C	AP SCREW FOUND MISSING AT:31C 30G TOTAL:2EA	L465	OPEN	09/25/2023
	CAB				01					1.0
									-	1.0
XJL4662	200	NRR	SS	25	777-C252430-01-05-	PEY PAX SEAT ARM REST SHRO	UD FOUND CRACKED AT:30D	L466	OPEN	09/25/2023
	CAB				01					1.0
									-	1.0
										1.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD. NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 65 OF 86

ESTIMATED MHR: ALL

RUN DATE: 10/2/2023

RUN TIME : 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

TYPE CODE: CTRL CODE : ORIGINATOR · ALL

CTRL CODE :					TYPE CODE:	ORIGINATOR :	ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL4670	200	NRP	SS	25	777-25-050-08-CX-R- 01	PEY PAX SEAT CONSOLE TV ARM G TOTAL:8EA	AS SPRING OPERATION FOUND MALFUNCTION AT:30D E F G 31A C 32H K	L467	OPEN	09/25/2023
	CAB					TOTAL.ULA				8.0
									-	8.0
XJL4688	200	NRR	SS	25	777-C252440-04-04- 01	EY FIRST SEATSIDE BUMPER PANL	FOUND BROKEN AT 60G	L468	OPEN	09/25/2023
	CAB				O I					1.0
									-	1.0
KJL4696	200	NRR	SS	25	777-C252430-01-01-	PEY PAX SEAT BELT FOUND FRAY A	AT:31A 33A 30G TOTAL:3EA	L469	OPEN	09/25/2023
	CAB				01					1.5
									-	1.5
KJL4704	200	NRR	SS	25	777-C252430-01-05-	PEY PAX SEAT ARM REST OPERATION	ON FOUND NOISE AT:31C	L470	WIP	09/26/2023
	CAB				01					0.5
									-	0.5
(JL4712	200	NRR	SS	25	777-C252430-01-05-	PEY PAX SEAT ARM REST STRUCTU	JRE FOUND LOOSEN AT:30D 31D G 34G 33H TOTAL: 5EA	L471	WIP	09/28/2023
	CAB				01					5.0
									-	5.0
(JL4720	200	NRR	SS	25	777-C252440-04-04-	EY FIRST SEAT SIDE FAIRING SCRE	W FOUND LOOSEN AT 39G	L472	OPEN	09/25/2023
	CAB				01					0.5
									-	0.5
(JL4738	200	NRP	SS	25	777-25-050-08-CX-R-	PEY PAX SEAT CONSOLE PTV ARM	PLUG FOUND MISSING AT:30D	L473	OPEN	09/25/2023
	CAB				01					0.5
									-	0.5
(JL4746	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT LEGREST BUTTON C	ABLE FOUND BROKEN AT:30E	L474	OPEN	09/25/2023
	CAB				01					1.0
									-	1.0
(JL4753	200	NRR	Al	2502	777-C252420-01-05-	CAB-FB2 SEAT BACKSHELL ROLLER	BLIND BLACK FASTENER FOUND MISSING	L475	OPEN	09/25/2023
	CAB				01					5.0
									-	5.0
										0.0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

ATA NO: ALL

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 66 OF 86

RUN DATE: 10/2/2023

RUN TIME : 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

BMS571R1-2

515653

STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL

ZONE: ALL

DISPOSITION CODE: ALL

STAGE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL TYPE CODE: ORIGINATOR: ALL

CTRL CODE:

TINE CODE .					THE GODE.	Ortion viron	, let		STATUS	UPDATED DATE
JOB NO	ZONE AREA	SIG	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
JL4761	200	NRR	AV	3326	777-C330000-01-03-	TOILET LIGHT INSPECTION FOUND CE		L476	OPEN	09/25/2023
	CAB				01			2110	0. 2.1	1.0
									-	1.0
JL4779	200	NRR	AV	3326	777-C330000-01-03-	TOILET LIGHT INSPECTION FOLIND LA	V CALL LIGHT LENS CRACK AT LAV C.E.H.K.L	L477	WIP	09/27/2023
	CAB			0020	01	TOLET EIGHT MOTEOTION TOOMS E	1. 0. EE 210111 EE110 010101(7/11 E170 0,E,11,11,12	L477	VVII	2.5
									-	
JL4787	200	NRR	Al	2502	777-C252420-01-05-	CAR ERS SEAT BACKSHELL BOLLER E	ELIND FOUND DAMAGE AT 19K 20K 21A 18A 15A	L478	WIP	2.5
124707	CAB	IVIXIX	Ai	2002	01	CAB-I BZ SEAT BACKSHELL KOLLEK L	LIND I COND DANIAGE AT 19K 20K 2 IA 10A 13A	L478	VVIP	09/25/2023
									-	
JL4795	200	NRR	SS	2511	777-25-020-02-01	PILOT SEAT VELCRO TAPE FND LOOS	-			5.0
JL4795	CAB	INKK	33	2511	777-25-020-02-01	PILOT SEAT VELCRO TAPE FND LOOS	E	L479	OPEN	09/25/2023
									-	1.0
	000	NDD	00	0544	777 05 000 00 04					1.0
JL4803	200 CAB	NRR	SS	2511	777-25-020-02-01	PILOT SEAT HEADREST FND NOISE		L480	OPEN	09/25/2023
	O/ LD								_	1.0
										1.0
JL4811	200 CAB	NRR	SS	2511	777-25-020-02-01	PILOT SEAT BOTTOM COVER FND WO	RN	L481	WIP	09/26/2023
	CAB								_	1.0
										1.0
JL4829	200 CAB	NRR	SS	2511	777-25-020-02-01	PILOT SEAT BOTTOM CUSHION		L482	OPEN	09/25/2023
	CAB									1.0
									-	1.0
JL4837	200	NRR	SS	2511	777-25-020-02-01	1ST OBS SEAT RECLINE SIDE SCREW	FND LOOSE	L483	OPEN	09/25/2023
	CAB									1.0
									-	1.0

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 67 OF 86 RUN DATE: 10/2/2023

RUN TIME :

9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL JSN RANGE SELECTED: ALL ESTIMATED MHR: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL ORIGINATING CUST REF NO: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE :					TYPE CODE:			ORIGINATOR: ALL			
	ZONE	STG								STATUS	UPDATED DAT
OB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTR	L SH NC	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
JL4845	600	NRR	AE	2800	777-28-015-00-01	RH\	N F/T VEN	IT SCOOP DOOR 644BB FOUND ONE PUNCH HOLE	L484	OPEN	09/25/2023
	F/T										0.0
						1C	1	REMOVE VENT SCOOP ASSEMBLY TO THE ACCESS DOOR			3.0
						1C	2	REINSTALL VENT SCOOP ASSEMBLY TO THE NEW ACCESS DOOR			3.0
						1C	3	CARRY OUT BONDING RESISTANCE TEST BETWEEN THE UPPER DUCT ON THE VENT SCOOP ASSEMBLY AND THE ACCESS DOOR			0.5
						1C	4	APPLY THE SEALANT ALONG THE TOP OF THE SCREWS			1.0
						2C	5	REINSTALL VENT SCOOP ACCESS DOOR			0.0
						2C	6	CARRY OUT BONDING RESISTANCE TEST BETWEEN THE ACCESS DOOR AND THE LOWER WING SKIN			0.5
						2C	7	DO A VISUAL CHECK TO MAKE SURE THAT ACCESS DOOR INSTALLATION IS FLUID TIGHT			0.5
											8.5
JL4852	100 FUS	NRP	SM	5000	777-53-545-01-01	LEF	T FORWA	RD BSTA1035+20 INCH LOWER WING TO BODY FAIRING SUPPORT ANGLE CRACKED	L485	OPEN	09/25/2023
	100										0.0
						1C	1	REMOVE SUPPORT FTG ATT SCREW			4.0
						1C	2	REMOVE CRACK SUPPORT FTG			4.0
						1C	3	TRANSFER HOLES TO NEW FTG			4.0
						1C	4	INSTALL NEW FTG			4.0
						2C	5	INSTALL SUPPORT FTG ATT SCREW			4.0
						2C	6	CARRY OUT FASTENERS SEAL APPLICATION			2.0
						2C	7	PERFORM THE FUEL TANK LEAKAGE CHECK			2.0
						2C	8	TOUCH UP PAINT			1.0
						3C	9 10	REMOVE LEFT WING FUEL TANK ACCESS DOOR 531AB			1.0
						3C 3C	11	INSTALL LEFT WING FUEL TANK ACCESS DOOR 531AB  MAKE SURE NO FUEL LEAKAGE AT THE APPLICEABLE TANK ACCESS DOOR			1.0 0.5
											27.5
JL4860	100	NRR	AE	2152	777-53-830-00-01	FUS	S-LH PACK	CHEAT EXCHANGER FOUND CRACKED.	L486	OPEN	09/25/2023
	FUS										0.0
											0.0
L4878	100	NRR	AE	2152	777-53-830-00-01	FUS	S-RH PAC	K UPR FCV BONDING BROKEN.	L487	OPEN	09/25/2023
	FUS										0.0
						1C	1	REPLACE THE BONDING.			1.0
						1C	2	DO THE BONDING TEST.			0.5
											1.5
						1C	2	DO THE BONDING TEST.			

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

68 OF 86 PAGE: RUN DATE: 10/2/2023

RUN TIME : 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL ALL

TRADE: ALL DEFECT TYPE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

515653

BMS571R1-2

	, , , , , , , , , , , , , , , , , ,	-							
CTRL CODE :					TYPE CODE:	ORIGINATOR: ALL	27	TATUS	UPDATED DATE
IOD NO	ZONE	SIG	TD	4.74	ODIO OLIOT DEE NO	OTPLOUNG			
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.			TATUS	EST Mhr
(JL4886	100	NRR	AE	2152	777-53-830-00-01	FUS-LH PACK RAM AIR INLET DUCT AFT BONDING BROKEN.	488 OI	PEN	09/25/2023
	FUS								0.0
						1C 1 REPLACE THE BONDING.			1.0
						1C 2 DO THE BONDING TEST.			0.5
								-	1.5
(JL4894	300	NRR	PT	5500	777-55-000-06-CX-01	VERTICAL STABILIZER LEADING EDGE 321E FOUND COATING DETERIORATION	489 W	IP .	09/27/2023
	EMP								0.0
						1C 1 DISCONNECT HF ANTENNA FEEDLINE			2.0
						1C 2 REMOVE PNL 321E			0.0
						1C 3 APPLY ANTI-STATIC COATING TO SURFACE			30.0
						1C 4 C/O RESISTANCE CHECK			2.0
						2C 5 RESTORE THE ORIGINAL FINISH COATING			10.0
						2C 6 RECONNECT THE HF ANTENNA FEEDLINE CONNECTOR			2.0
						2C 7 RE-INSTALL THE 321E			0.0
						2C 8 C/O HF SYSTEM TEST			1.0
						3C 9 DISCONNECT HF ANTENNA FEEDLINE			0.0
								-	47.0
JL4902	100	NRR	AE	2152	777-53-830-00-01	FUS-LH PACK TRIM AIR VALVE BONDING BROKEN.	490 OI	PEN	09/25/2023
	FUS								0.0
						1C 1 REPLACE THE BONDING.			1.0
						1C 2 DO THE BONDING TEST.			0.5
								-	1.5
(JL4910	100	NRR	AE	2152	777-53-830-00-01	FUS-LH PACK THE CONDITIONING O/B LOW LIMIT VALVES BONDINGS BROKEN.	491 OI	PEN	09/25/2023
	FUS								0.0
						1C 1 REPLACE THE BONDING.			1.0
						1C 2 DO THE BONDING TEST.			0.5
								-	1.5
JL4928	200	NRR	SS	25	777-C252420-01-02-	FB2 SEAT BACK REST SIDE BAY GEAR INNER STOP SCREW&BUSHING FOUND MISSING AT:17G	492 OI	PEN	09/25/2023
	CAB				02				1.0
								-	1.0
JL4936	200	NRR	SS	25	777-C252420-01-02-	FB2 SEAT BOTTOM PAN FWD BUTTON CAP FOUND BROKEN AT:17K	493 OI	PEN	09/25/2023
	CAB				01				2.0
								-	2.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 69 OF 86

ESTIMATED MHR: ALL

DISPOSITION CODE: ALL

RUN DATE: 10/2/2023

RUN TIME : 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL

ORIG-STAGE: ALL PERIOD: ALL

ATA NO: ALL ZONE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

TRL CODE :	ZONE	STG			TYPE CODE:	ORIGINATOR: ALL	1011	STATUS	UPDATED DAT
OB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
L4944	200 CAB	NRR	SS	25	777-C252440-04-04- 01	EY F/R SEAT CENTER CONSOLE CONNECT STRUCTURE ATT CLAMP FND BROKEN AT:40HJ 39G 39D 39C 59A 60E TTL:6EA	L494	OPEN	09/25/2023
	CAB								12.0
								-	12.0
L4951	200	NRR	SS	25	777-C252420-01-02- 01	FB2 SEAT BOTTOM PAN LOWER BRACKET FWD SCREW FOUND LOOSEN AT:12D 16D 19A 11K TOTAL:4EA	L495	OPEN	09/25/2023
	CAB				01				2.0
								-	2.0
L4969	200	NRR	SS	25	777-C252420-01-02-	FB2 SEAT BOTTOM PAN SIDE BAY BRACKET SCREW FOUND LOOSEN AT:21K	L496	OPEN	09/25/2023
	CAB				01				0.5
								-	0.5
L4977	200	NRR	SS	25	777-C252420-01-02-	FB2SEAT TRACKING BUTTON SCREW FOUND LOOSEN AT:25K 22K 20G 19G TOTAL:4EA	L497	OPEN	09/25/2023
	CAB				01				2.0
								-	2.0
L4985	200	NRR	SS	25	777-C252420-01-02-	FB2 SEAT BACK REST ATT SCREW FOUND LOOSEN AT:17K 26K 16G 23A 21A 17A 16A 25K 21G TOTAL:9EA	L498	OPEN	09/25/2023
	CAB				01				4.5
								-	4.5
L4993	200	NRR	SS	25	777-C252420-01-02-	FB2 SEAT BACK REST SCREW FOUND MISSING AT:20D	L499	OPEN	09/25/2023
_ 1000	CAB	14141	00	20	02	1 DE GENT BROWNEST GONE THIOSING MILES	L499	OPEN	09/25/2025
								-	
_5008	200	NRR	SS	25	777-C252420-01-02-	FB2SEAT BELT AIR BAG FOUND TORN AT:19D 22D 21K 19G 17G TOTAL:5EA	. 500	14/15	0.5
L3006	CAB	INICIN	33	25	02	FDZSEAT BELT AIR DAG FOUND TORN AT 180 220 2TR 180 TTG TOTAL SEA	L500	WIP	10/01/2023
								-	7.5
									7.5
L5016	200 CAB	NRR	SS	25	777-C252420-01-02- 01	FB2 SEAT BACK REST SIDE BAY GEAR ATT SCREW FOUND LOOSEN AT:17A 22D 25D A 25K 23G 22K 20K 17G 16K C 12K G 11G TOTAL:14EA	5 L501	OPEN	09/25/2023
	O/ LD							_	7.0
									7.0
.5024	200	NRR	SS	25	777-C252420-01-02- 02	FB2 SEAT BACK REST HEADREST STRUCTURE SCREW FOUND LOOSEN AT:17A 18A D 19D 22A 23A 25G 24K G 23C 18G 16K TOTAL:12EA	L502	OPEN	09/25/2023
	CAB				<u>.                                    </u>	IOO ION TOTAL IZEN			6.0
								-	6.0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 70 OF 86

RUN DATE: 10/2/2023

0.5

RUN TIME : 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL

ZONE: ALL

DISPOSITION CODE: ALL

STAGE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL

TRL CODE :					TYPE CODE:	ORIGINATOR: ALL	, u. (=) ( ) ( )	5,7,62. 7,22		
	ZONE	STG			332	G. II G. II V. II G. I. I	-		STATUS	UPDATED DATE
OB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
JL5032	200	NRR	SS	25	777-C252420-01-02- 01	FB2 SEAT RECLINE MOTOR GEAR ATT PIN FO	OUND BROKEN AT:17D 19A 20A 24A 16G TOTAL:5EA	L503	OPEN	09/25/2023
	CAB				O1					5.0
									-	5.0
JL5040	200	NRR	SS	25	777-C252420-01-02- 01	FB2 SEAT LEGREST BUTTON SCREW FOUND	D LOOSEN AT:17A 16A 17D 18D 23D 24A 26K 24K 23K 20K 16K T	OTAL:11EA L504	OPEN	09/25/2023
	CAB				01					5.5
									-	5.5
JL5057	200	NRR	SS	25	777-C252420-01-02- 02	FB2 SEAT BACK REST HEADREST SLIDE TRA	ACK FOUND BROKEN AT:15A 17D 19D 20D 21G TOTAL:5EA	L505	OPEN	09/25/2023
	CAB				02					2.5
									-	2.5
IL5065	200 CAB	NRR	SS	25	777-C252420-01-02- 02	FB2 SEAT BOTTOM PAN LOWER BRACKET FV	WD SCREW&NUT FOUND MISSING AT:11D	L506	OPEN	09/25/2023
	CAB								_	1.0
										1.0
L5073	200 CAB	NRR	SS	25	777-C252420-01-02- 02	FB2 SEAT LEGREST MOTOR ATT SCREW FOL	JUND LOOSEN AT:11D 16D 23D 23A 20K 12G TOTAL:6EA	L507	OPEN	09/25/2023
	O/ LD								_	3.0
II 5004	200	NDD	00	0.5	777 0050400 04 00	EDOCE AT DECUME DUTTON CODEW FOUND	LOOOFN AT 44D 22D 20D TOTAL 2FA			3.0
IL5081	200 CAB	NRR	SS	25	777-C252420-01-02- 02	FB2SEAT RECLINE BUTTON SCREW FOUND I	LOUSEN ATTITU 23D 20D TOTAL3EA	L508	OPEN	09/25/2023
									-	
IL5099	200	NRR	SS	25	777-C252420-01-02-	ED20E AT DELT DLICKLE ECLIND EDAV AT:110	D 20D 22A 23A 25D 25G 23G 22G 16G TOTAL:9EA	1.500	NAME.	1.5
120000	CAB	IVIXIX	00	20	02	T DZOLAT DEET BOOKEET OUND THAT AT THE	2 200 22A 23A 200 200 200 220 100 10 1AL.JLA	L509	WIP	10/01/2023
									-	4.5
L5107	200	NRR	SS	25	777-C252420-01-02-	FB2 SEAT BELT BUCKLE FOUND FRAY AT:18/	NA 19A 26K 25K 18K 16K TOTAL :6FA	L510	WIP	10/01/2023
	CAB				01	. 52 52 11 5221 555112 1 55113 1 1 1 1 1 1 1 1 1 1		2310	VVII	9.0
									-	9.0
L5115	200	NRR	SS	25	777-C252430-01-06-	PEY PAX SEAT BACK REST TV SHROUD LOW	VER COVER FOUND LOOSEN AT:33F	L511	WIP	09/28/2023
	CAB				01			LSTI	V V 11	0.5

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

71 OF 86 PAGE: RUN DATE: 10/2/2023

RUN TIME :

9:39

0.5

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

ATA NO: ALL

JSN RANGE SELECTED: ALL STATUS: ALL

ORIG-STAGE: ALL PERIOD: ALL

ORIGINATING CUST REF NO: ALL ZONE: ALL

AREA: ALL

ESTIMATED MHR: ALL DISPOSITION CODE: ALL

STAGE: ALL

DEFECT TYPE: ALL

TRADE: ALL CUST ENDORSE: ALL

							· · · · · · · · · · · · · · · · · ·			
CTRL CODE :		CTC			TYPE CODE:	ORIGINATOR: ALL			STATUS	UPDATED DATE
JOB NO	ZONE AREA	SIG	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL5123	200	NRR	SS	25	777-C252430-01-03-		CARD FOUND TORN AT:33D 32A 33K TOTAL:3EA	L512	OPEN	09/25/2023
	CAB				01			2012	OI LIV	1.0
									-	1.0
XJL5131	200	NRR	SS	25	777-C252430-01-06-	PEY PAX SEAT BACK REST TV SHROUD LOW	FR COVER SCREW FOLIND LOOSEN AT:33D	L513	WIP	09/28/2023
	CAB				01			2010	****	0.5
									-	0.5
XJL5149	200	NRR	SS	25	777-C252430-01-04-	PEY PAX SEAT CONSOLE ARM CAP SCREW F	COLIND LOOSEN AT:33G	L514	WIP	0.3
AGEO 143	CAB	14141		20	01	TETT/WOLKT GONGOLE/WWW.ON GONEWT	COND ECOCENTI SOC	L314	VVIF	0.5
									-	0.5
XJL5156	200	NRR	SS	25	777-C252430-01-01-	PEY PAX SEAT LEGREST DRESS COVER FOU	ND NO MATCH AT:33G	L515	OPEN	0.3
7020100	CAB	14141		20	01	TETT/WOLKT LEGILOT BILLOG GOVERT OU	NO NUMBER OF THE OWNER	L313	OPEN	0.5
									-	
(JL5164 2	200	NRR	SS	25	777-C252430-01-06-	DEV DAY CEAT DACK DECT DD ACKET CODEIA	FOUND LOOSEN AT:33G 34F E G D TOTAL:5EA	1.540	MID	0.5
X3L3104	CAB	INIXIX	00	20	01	FET FAX SEAT BACK REST BRACKET SCREW	TOURD LOOSEN AT .336 341 E G D TOTAL.3EA	L516	WIP	09/28/2023
									-	
V II 5470	200	NRR	SS	25	777-C252430-01-02-	PEY PAX SEAT SIDE FAIRING FOUND LOOSE!	N AT-22D		W//D	2.5
XJL5172	CAB	NKK	33	25	01	PET PAX SEAT SIDE FAIRING FOUND LOUSEI	NAT.32D	L517	WIP	09/28/2023
									-	
XJL5180	200	NRR	00	0.5	777 0050400 04 00	DEV DAY OF AT LEODEOT LIFE LAGIVET DOV	51 0D0 TADE 501ND 1 0005NAT 00D 5 0 045 5 005 5 0 04D 0 001	041/		0.5
	200 CAB	NKK	SS	25	777-C252430-01-03- 01	33H 32C 33A TOTAL:15EA	ELCRO TAPE FOUND LOOSENAT:32D F G 31E F 33F E G 34D G 32H	34K L518	WIP	09/28/2023
									-	7.5
V.II. 5400	000	NDD	00	0.5	777 0050400 04 00	DEV DAY OF AT LEODEST LIFE LARVET DOV.				7.5
XJL5198	200 CAB	NRR	SS	25	777-C252430-01-03- 01	PEY PAX SEAT LEGREST LIFE JACKET BOX F	OUND BROKEN AT:32E 34C 33E 31D TOTAL:4EA	L519	OPEN	09/25/2023
	0/10								_	4.0
										4.0
XJL5206	200 CAB	NRR	SS	25	777-C252430-01-02- 01	PEY PAX SEAT SIDE BAY REAR COVER SCRE	W FOUND LOOSEN AT:31E	L520	WIP	09/28/2023
	OAD								_	0.5
									-	0.5

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 72 OF 86

RUN TIME :

RUN DATE: 10/2/2023

9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

ALL

515653

BMS571R1-2

ATA NO: ALL

ZONE: ALL AREA: ALL

DISPOSITION CODE: ALL

STAGE: ALL

CTRL CODE:

DEFECT TYPE: ALL

TRADE: ALL TYPE CODE:

ORIGINATOR: ALL

CUST ENDORSE: ALL

UPDATED DATE STATUS

JOB NO	ZONE AREA	STG	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	UPDATED DATE  EST Mhr
XJL5214	200	NRR	SS	25	777-C252430-01-03-		ATT SCREW&NUT INSTALL FOUND WRONG AT:32E	L521	OPEN	09/25/2023
	CAB				01					0.5
									-	0.5
XJL5222	200	NRR	SS	25	777-C252430-01-04- 01	PEY PAX SEAT CONSOLE IN ARM TA	ABLE SLIDE TRACK SCREW FOUND MISSING AT:32F	L522	OPEN	09/25/2023
	CAB				01					0.5
									-	0.5
XJL5230	200 CAR	NRR	SS	25	777-C252430-01-03- 01	PEY PAX SEAT AFT FOOTREST BUS	HING FOUND MISSING AT:31E F G TOTAL3EA	L523	OPEN	09/25/2023
	CAB				•			_	1.5	
										1.5
XJL5248	200 CAB	NRR	SS	25	777-C252430-01-03- 01	PEY PAX SEAT LEGREST SUPPORT	BRACKET AND SCREW&NUT AND WASHER FOUND MISSING AT:31D	L524	OPEN	09/25/2023
	OND								_	1.0
V II 5055	000	NDD		0.5	777 0050400 04 05					1.0
XJL5255	200 CAB	NRR	SS	25	777-C252430-01-05- 01	PEY PAX SEAT ARM REST CAP FOU	ND TORN AT:31D 33D TOTAL:2EA	L525	OPEN	09/25/2023
									-	1.0
XJL5263	200 CAB	NRR	SS	25	777-C252430-01-03- 01	PEY PAX SEAT AFT FOOTREST SCREW FOUND LOOSEN AT:30G	L526	WIP	1.0	
AJLJ203			00			FET FAX SEAT AT TOOTNEST SON			09/28/2023	
									-	0.5
XJL5271	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT BOTTOM PAN PLUG	SCREW FOUND MISSING AT:30G	L527	OPEN	0.5
	CAB				01			L021	OI LIV	0.5
									-	0.5
XJL5289	200 CAB	NRR	SS	25	777-C252430-01-03- 01	PEY PAX SEAT CONSOLE SIDE BAY FAIRING FOUND CRACKED AT:30F 32G TOTAL:2EA	FAIRING FOUND CRACKED AT:30F 32G TOTAL:2EA	L528	OPEN	09/25/2023
									2.0	
									-	2.0
XJL5297	200	NRR	SS	25	777-C252430-01-04-	PEY PAX SEAT CONSOLE IN ARM TA	BLE STOWAGE SHROUD FOUND BROKEN AT:30F G 31G 32G E 33D H 34H	L529	OPEN	09/25/2023
	CAB				01	TOTAL:8EA				8.0
									-	8.0

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 73 OF 86

RUN TIME :

RUN DATE : 10/2/2023

9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE : ALL TRADE : ALL CUST ENDORSE : ALL AREA : ALL STAGE : ALL

CTRL CODE :	TYPE CODE:	ALL

CIRL CODE :					TYPE CODE:	ORIGINATOR: ALL				
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL5305	200	NRR	SS	25	777-C252430-01-05- 01	PEY PAX SEAT ARM REST OPERATION FOUND	D LOOSEN AT:30E	L530	WIP	09/28/2023
	CAB				01					0.5
									-	0.5
XJL5313	300	NRR	AE	2700	777-55-822-00-01	RUDDER TAB LOWER LEFT AND RIGHT SIDE B	BULB SEALS TORN	L531	OPEN	09/25/2023
	EMP									3.0
									-	3.0
KJL5321	100	NRR	Al	5600	777-53-904-00-01	CABIN A ZONE LH SIDEWALL WINDOW DUST (	COVER INSIDE FOUND DUSTY	L532	OPEN	09/25/2023
	CAB									8.0
									-	8.0
(JL5339	100	NRR	Al	5600	777-53-904-00-01	CABIN A ZONE RH SIDEWALL WINDOW DUST	COVER INSIDE FOUND DUSTY	L533	OPEN	09/25/2023
	CAB									8.0
									-	8.0
KJL5347	100	NRR	Al	5600	777-53-908-00-01	CABIN B ZONE RH SIDEWALL WINDOW DUST	COVER INSIDE FOUND DUSTY	L534	OPEN	09/25/2023
	CAB									16.0
									-	16.0
KJL5354	100	NRR	Al	5600	777-53-908-00-01	CABIN B ZONE LH SIDEWALL WINDOW DUST (	COVER INSIDE FOUND DUSTY	L535	OPEN	09/25/2023
	CAB									16.0
									-	16.0
(JL5362	100	NRR	Al	2500	777-53-904-00-01	CABIN A RH WINDOW SHADE FOUND STIFF TO	O OPERATE	L536	OPEN	09/25/2023
	CAB								0. 2	5.0
									-	5.0
XJL5370	100	NRR	Al	2500	777-53-904-00-01	CABIN A LH WINDOW SHADE FOUND STIFF TO	) OPERATE	L537	OPEN	09/25/2023
	CAB							L001	OI LIV	5.0
									-	5.0
(JL5388	100	NRR	Al	2500	777-53-908-00-01	CABIN B ZONE LH WINDOW SHADE FOUND ST	IFF TO OPERATE	L538	OPEN	
WL0000	CAB	INIXIX	Λi	2000	777-00-300-00-01	O DIN D ZONE EN WINDOW OF INDE I OUND ST	III 1001 EIVILE	L038	OPEN	09/25/2023
									-	
										8.0

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

74 OF 86 PAGE:

RUN TIME :

RUN DATE: 10/2/2023 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

CINE CODE.	70NE	0.70			TIFE CODE.	ONIGINATOR: ALL			STATUS	UPDATED DATE
JOB NO	ZONE AREA	SIG	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL5396	100	NRR	Al	2500	777-53-908-00-01	CABIN B ZONE RH WINDOW SHADE FOUND S		L539	OPEN	
NJE3330	CAB	INIXIX	Ai	2300	777-33-900-00-01	CADIN B ZONE RA WINDOW SHADE FOUND S	TIFF TO OPERATE	L539	OPEN	09/25/2023 8.0
									-	
/ II 5404	000	NDD	00	0.5	777 0050440 04 04		0/50 17 1050			8.0
(JL5404	200 CAB	NRR	SS	25	777-C252440-04-04- 01	CAB E ZONE EY SEAT TRIMCAP FOUND CRA	UKED A1:46FG	L540	OPEN	09/25/2023
	0.1.2								_	0.5
										0.5
JL5412	200 CAB	NRR	SS	25	777-C252440-04-04- 01	CAB E ZONE EY SEAT ARMREST OPERATION	FOUND LOOSE AT:43FG 42H 44H 45HJ 72C 72D 63HJ TTL:7EA	L541	OPEN	09/25/2023
	CAB									2.5
									-	2.5
JL5420	200	NRR	SS	25	777-C252440-04-04- 01	CAB E ZONE EY SEAT ARMREST OPERATION	FOUND TIGHTEN AT:41JK 42JK 63BC 69BC 66FG 61HJ 61JK TTL:7EA	L542	OPEN	09/25/2023
	CAB				01					2.5
									-	2.5
JL5438	200	NRR	AV	3326	777-C330000-01-03-	LAV D CEILING LIGHT MALFUNCTION		L543	OPEN	09/25/2023
	CAB				01					2.0
									-	2.0
JL5446	200	NRR	SS	25	777-C252440-04-04-	CAB E ZONE EY SEAT ARMREST FOUND MUI	FUNCTION AT:71D 66H 67H TTL:3EA	L544	OPEN	09/25/2023
	CAB				01					6.0
									-	6.0
JL5453	200	NRR	ΑI	25	777-53-904-00-01	CABIN G1 GALLERY TABLE SEALANT CHIPPE	D	L545	OPEN	09/25/2023
	CAB									2.0
									-	2.0
JL5461	200	NRR	SS	25	777-C252440-04-04-	CAB E ZONE FIRST ROW SEAT ARMREST FO	UND LOOSEN AT:59JK 59C 4H TTL:3EA	L546	OPEN	09/25/2023
	CAB				01			20.0	0. 2	1.5
									-	1.5
JL5479	200	NRR	Al	25	777-53-908-00-01	CABIN G2&G3 GALLERY TABLE SEALANT CH	PPFD	L547	WIP	09/29/2023
	CAB				55 555 60 61	OLGO O LLEIN INDEL OLNE WIT ON	·· <del></del>	L041	AAIL.	3.0
									-	
										3.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 75 OF 86

RUN DATE: 10/2/2023

0/2/2020

RUN TIME: 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL5487	200	NRR	Al	5600	777-56-000-01-CX-01	COCKPIT L1&R1 WINDSHIELD MOISTURE SEAL FOUND WORN		L548	WIP	09/28/2023
	CAB									10.0
									-	10.0
XJL5495	200	NRR	SS	25	777-C252000-01-07-	CAB B ZONE B/C SEAT BOTTOM COVER FOUND TORN TTL:1EA	A	L549	OPEN	09/25/2023
	CAB				R-01					0.5
									-	0.5
XJL5503	100	NRW	AE	5336	SWC-28028-01-01	FUS-RAM AIR INLET ACTUATOR DOOR PANEL 191LL 5EA STUD	DS HEAD WORN.	L550	OPEN	09/25/2023
	FUS									3.0
									-	3.0
XJL5511	100	NRW	AE	5336	SWC-28028-01-01	FUS-RAM AIR INLET ACTUATOR DOOR PANEL 191LR 4EA STUI	DS HEAD WORN.	L551	OPEN	09/25/2023
	FUS									3.0
									-	3.0
XJL5529	200	NRR	Al	25	777-53-920-00-01	M/D M LAV FAUCET FOUND WATER LEAKING		L552	WIP	09/29/2023
	CAB									0.0
						1C 1 REPLACE LAV FAUCET				4.0
						1C 2 C/O LAV FAUCET WATER LEAK CHECK			_	0.5
										4.5
XJL5537	200	NRP	AV	3351	777-33-115-00-02	FOUND L1,L4,R1,R2 DOOR EMERGENCY LIGHT LENS LOOSEN		L553	WIP	09/27/2023
	CAB									6.0
									-	6.0
XJL5545	100	NRW	AE	5336	SWC-28028-01-01	FUS-RAM AIR INLET ACTUATOR DOOR PANEL 191LR 2EA HING	GE BONDINGS BROKEN.	L554	OPEN	09/25/2023
	FUS									0.0
						1C 1 REPLACE THE BONDING. 1C 2 DO THE BONDING TEST.				1.0 0.5
						1C 2 DO THE BONDING TEST.			-	
V II 5550	200	NDD	۸۱/	2254	777 00 445 00 00	FOUND LA DOOD NO A EMEDOENOV LIQUE DIM				1.5
XJL5552	200 CAB	NRP	AV	3351	777-33-115-00-02	FOUND L3 DOOR NO 2 EMERGENCY LIGHT DIM		L555	WIP	09/27/2023
	0/10								_	6.0
									_	6.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

76 OF 86 PAGE: RUN DATE: 10/2/2023

14.5

RUN TIME: 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL

ORIG-STAGE: ALL PERIOD: ALL

ATA NO: ALL

ZONE: ALL

ESTIMATED MHR: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE:

TYPE CODE: ORIGINATOR: ALL

CIRL CODE:					TYPE CODE:	ORIGINATOR: ALL			
	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL5560	100	NRR	Al	5200	777-12-102-00-01	AFT CGO DOOR LINING SCREWS AND SPACERS FOUND WORN	L556	OPEN	09/25/2023
	LWR								0.5
								•	0.5
XJL5578	100	NRR	Al	3800	777-38-000-09-CX-01	BULK CGO AFT WASTE TANK RINSE LINE WATER FILTER HOUSING FOUND BROKEN	L557	WIP	10/02/2023
	LWR								3.0
								•	3.0
XJL5586	200	NRR	Al	2500	777-53-912-00-01	CABIN DR3- DR4 LH PAX WINDOW DUST COVER INTERIOR FND DIRTY	L558	WIP	09/26/2023
	CAB								34.0
									34.0
XJL5594	200	NRR	Al	2500	777-53-912-00-01	CABIN DR3- DR4 RH PAX WINDOW DUST COVER INTERIOR FND DIRTY	L559	WIP	09/26/2023
	CAB								34.0
								-	34.0
XJL5602	200	NRR	Al	2500	777-53-916-00-01	CABIN DR4- DR5 LH PAX WINDOW DUST COVER INTERIOR FND DIRTY	L560	WIP	09/29/2023
	CAB								40.0
									40.0
XJL5610	200	NRR	Al	2500	777-53-916-00-01	CABIN DR4- DR5 RH PAX WINDOW DUST COVER INTERIOR FND DIRTY	L561	WIP	09/30/2023
	CAB								40.0
									40.0
XJL5628	200	NRR	Al	2500	777-53-916-00-01	CABIN DR4- DR5 L12, L17, L20, R9, R11 AND DR3-DR4 R17 PAX WINDOW DUST COVER FND SCRATCHED	L562	WIP	09/26/2023
	CAB						2002	****	12.0
									12.0
XJL5636	100	NRR	SM	5200	777-52-190-00-01	FWD CGO DOOR OPERATIONAL SWITCH ACCESS DOOR SPRING FOUND BROKEN	L563	WIP	09/29/2023
	LWR						2505	VVII	0.0
						1C 1 REMOVE BROKEN HINGE ATT FASTENERS			4.0
						1C 2 REMOVE BROKEN HINGE ATT SCREW			1.0
						1C 3 INSTALL NEW HINGE			8.0
						1C 4 TOUCH UP PAINT			0.5
						2C 5 REINSTALL NEW HINGE ATT SCREW			1.0
									14.5

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

CHECK TYPE:

2C

PAGE: 77 OF 86 RUN DATE: 10/2/2023

RUN TIME: 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE : ALL TRADE : ALL CUST ENDORSE : ALL AREA : ALL STAGE : ALL

CTRL CODE : TYPE CODE : ORIGINATOR : ALL

CTRL CODE :					TYPE CODE:		ORIGINATOR:	ALL					
	ZONE	STG										STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NC	)		DEFECT DESCRIPTION		JSN	STATUS	EST Mhr
XJL5644	200	NRR	Al	2500	777-53-916-00-01	CABIN SIDE E	BIN DR INTERIOR SURFA	ACE AT 67A, 68H AN	D EXTERIOR SURFACE AT 67D, 68D FND DEN	IT	L564	WIP	09/28/2023
	CAB												8.0
												-	8.0
XJL5651	100	NRR	SM	5200	777-52-195-00-01	AFT CGO DO	OR OPERATIONAL SWIT	TCH ACCESS DOOR	SPRING FOUND BROKEN		L565	WIP	09/29/2023
	LWR												0.0
						1C 1	REMOVE BROKEN HI	INGE ATT FASTENE	RS				4.0
						1C 2	REMOVE BROKEN HI	INGE ATT SCREW					1.0
						1C 3	INSTALL NEW HINGE						8.0
						1C 4	TOUCH UP PAINT						0.5
						2C 5	REINSTALL NEW HIN	GE ATT SCREW					1.0
													14.5
XJL5669	200	NRR	Al	2500	777-53-912-00-01	CABIN AFT ZO	ONE O/H BIN SIDE TRIM	FND CRACKED AT	40G FWD, 41G AFT, 41A FWD, 42D AFT AND 43	3D FWD & AFT.	L566	WIP	09/28/2023
	CAB												12.0
												-	12.0
XJL5677	200	NRR	SS	25	777-C252430-01-02-	D ZONE PEY	SEAT PAN LOWER WIRE	E COVER FND MISS	NG AT:30F 33E		L567	OPEN	09/25/2023
	CAB				01								2.0
												-	2.0
XJL5685	300	NRR	AV	5500	777-55-828-01-01		FAND CONNECT THE EL	LECTRICAL CONNE	CTOR FROM LEFT AND RIGHT SIDE H/STABILI	IZER L/E TAXI	L568	WIP	09/26/2023
	EMP					CAMERA							2.0
						1C 1	DISCONNECT THE CO	ONNECTOR FROM 1	HE LEFT AND RIGHT SIDE CAMERA				0.0
						1C 2	CONNECT THE CONN	NECTOR FROM THE	LEFT AND RIGHT SIDE CAMERA				0.0
												-	2.0
XJL5693	100	NRR	ΑE	5346	777-53-844-00-01	FUS-KEEL BE	EAM PANEL149C 2EA BL	OCKS MISSING.			L569	OPEN	09/25/2023
	FUS												1.0
												-	1.0
XJL5701	100	NRR	SM	5300	777-53-818-00-01	FWD CGO R/I	H STA825 CEILING SUPF	PORT ANCHOR NUT	FOUND DAMAGED		L570	WIP	09/29/2023
	LWR												1.0
												-	1.0

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 78 OF 86

RUN TIME :

STAGE: ALL

RUN DATE: 10/2/2023

9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL

CTRL CODE :	TYPE CODE:	ORIGINATOR:	ALL

CIRL CODE:					TYPE CODE:	ORIGINATO	R: ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL5719	300	NRR	ΑE	5300	777-53-880-00-01	FORWARD WIN TO BODY FAIRING	G 191GL 191JL 191KL 191PL 191RL TOTAL 200EA SCREWS HEAD WORN	L571	OPEN	09/26/2023
	EMP									0.5
									-	0.5
XJL5727	300	NRP	AV	2361	777-55-806-00-01	VERTICAL FIN TOP #2 STATIC DIS	SCHARGER BROKEN.	L572	OPEN	09/26/2023
	EMP									1.0
									-	1.0
XJL5735	300	NRP	AV	2361	777-55-806-00-01	VERTICAL FIN AFT ALL 6 EA STA	TIC DISCHARGER BROKEN.	L573	OPEN	09/26/2023
	EMP							20.0	0. 2	6.0
									-	6.0
XJL5743	200	NRR	SS	25	777-C252430-01-07-	DEV DAY CEAT DACK DECT DECI	INE CABLE OPERATION FOUND TIGHTEN AT:33F 32G 31G 34H TOTAL:4EA	L574	WIP	10/01/2023
X0L0740	CAB	IVIXIX	00	20	01	FET FAX SEAT BACK REST REGI	INC CABLE OF ENATION FOUND HIGHTEN AT 331 329 319 341 FOTAL 4LA	L574	WIP	2.0
									-	
										2.0
XJL5750	200 CAB	NRM	AV	3531	AEO-29573-01	FOUND PORTABLE OXYGEN BOT G4 DOGHOUSE LOWER, 72G DOG	TLE NEAR EXPIRY DATE AT LAV B, STOWAGE E3R LOWER, G4 DOGHOUSE UPPER, SHOUS MIDDLE, TOTAL 5EA	L575	OPEN	09/26/2023
	OAD								_	9.0
										9.0
XJL5768	200	NRR	Al	2560	777-53-904-00-01	CABIN R2 DOOR AREA BESIDE TI	HE ATTENDANT SEAT FOUND FLASHLIGHT(UTILITY) FOUND DAMAGE	L576	WIP	09/28/2023
	CAB									1.0
									-	1.0
XJL5776	200	NRR	Al	2560	777-53-904-00-01	CABIN R5 DOOR AREA INSIDE TH	E ATTENDANT SEAT FOUND FLASHLIGHT(DME) FOUND LOW POWER	L577	COMP	09/28/2023
	CAB									1.0
									-	1.0
XJL5784	100	NRR	AE	5200	777-53-800-00-07	EXTERNAL ELECTRICAL POWER	RECEPTACLE ACCESS DOOR MISS ALIGNMENT WITH FUSELAGE SKIN	L578	OPEN	09/26/2023
	FUS									0.0
									-	0.0
										0.0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

79 OF 86 PAGE: RUN DATE: 10/2/2023

RUN TIME:

STATUS

UPDATED DATE

9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

STATUS: ALL ORIG-STAGE: ALL

ESTIMATED MHR: ALL DISPOSITION CODE: ALL

ORIGINATING CUST REF NO: ALL

ZONE STG

515653

BMS571R1-2

TRADE: ALL

ATA NO: ALL ZONE: ALL

PERIOD: ALL

AREA: ALL

STAGE: ALL

CTRL CODE:

DEFECT TYPE : ALL

TYPE CODE:

ORIGINATOR: ALL

CUST ENDORSE: ALL

JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL5792	100	NRR	AE	5200	777-53-800-00-07	EXTERNAL EL	ECTRICAL POWER RECEPTACLE ACCESS DOOR 1EA BONDING JUMPER WIRES FOUND BROKEN	L579	OPEN	09/26/2023
	FUS									0.0
						1C 1	REPLACE THE BONDING.			1.0
						1C 2	DO THE BONDING TEST.			0.5

							0.0
						1C 1 REPLACE THE BONDING.	1.0
						1C 2 DO THE BONDING TEST.	0.5
							1.5
XJL5800	100	NRR	ΑE	2900	777-53-844-00-01	AFT KEEL BEAM ACCESS PANEL 149CL INNER CAVITY FOUND CENTER HYD RESERVOIR DRAIN HOSE TORN 1.580 OPEN	
AJEJOOU	FUS	INIXIX	AL	2900	777-33-644-00-01	AFT KEEL BEAM ACCESS PANEL 149CL INNER CAVITY FOUND CENTER HYD RESERVOIR DRAIN HOSE TORN L580 OPEN	09/26/2023
	FU3						1.0
							1.0
XJL5818	200	NRR	CL	5300	777-53-546-01-01	BOTH LEFT AND RIGHT SIDE OVERWING TO BODY FAIRING INNER CAVITY DIRTY  L581 WIP	09/29/2023
7020010	FUS	Milli	OL	0000	777-00-040-01-01	BOTT EET TAMB MOTH ONE OVERWING TO BOST TAIMING INVENTORY DIKTT	
	100						6.0
							6.0
XJL5826	200	NRR	CL	2501	777-53-908-00-01	CAB-FB2 SEAT BACK SHELL BOTTLE CONSOLE RED FABRIC TRIM FOUND DIRTY 11A 12A 16A 17A 19A 20A 21A 23A L582 OPEN	09/26/2023
71020020	CAB		02	200.	00 000 00 0.	22A 26A 16D 17D 11D 12D 20D 21D 22D 24D 25D 26D 11G 16G 20G 23G 24G 25G 18K 20K 23K 25K 17K	
	0/10						0.0
							0.0
XJL5834	200	NRR	ΑE	5300	777-53-546-01-01	APPLY CIC TO BOTH LEFT AND RIGHT SIDE OVERWING TO BODY FAIRING INNER CAVITY AFTER CLEANING L583 OPEN	09/26/2023
	FUS					Of EN	
							3.0
							3.0
XJL5842	100	NRR	SM	5300	777-53-800-00-10	FWD CARGO BILGE AREA BSTA1000 LEFT SIDE FRAME FOUND ELECTRICAL WIRE 1EA STANDOFF BROKEN L584 WIP	09/29/2023
	LWR						1.0
							1.0
							1.0
XJL5859	200	NRR	Al	25	777-53-920-00-01	M/D M LAV TOILET SHROUD COVER FOUND CRACKED L585 OPEN	09/26/2023
	CAB						1.0
							1.0
							1.0
XJL5867	400	NRP	SM	5400	777-900001-01-1-01	#2 PYLON AFT FAIRING I/B FWD & AFT ACC DOOR LOWER 2EA LATCHES SPRING BROKEN. L586 OPEN	09/26/2023
	ENG						0.0
						1C 1 REMOVE BROKEN LATCH	4.0
						1C 2 INSTALL NEW LATCH	4.0
						1C 3 TOUCH UP PAINT	1.0
							9.0
							9.0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 80 OF 86 RUN DATE: 10/2/2023

RUN TIME :

9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL

515653

BMS571R1-2

ATA NO: ALL

CUST ENDORSE: ALL

ZONE: ALL

DISPOSITION CODE: ALL

DEFECT TYPE : ALL

TRADE: ALL

AREA: ALL

STAGE: ALL

CTDI	CODE:	
CIIL	CODL.	

TDL OODE		-			TYPE CODE		ANLA: ALL	STAGE . ALL		
TRL CODE	: ZONE	STG			TYPE CODE:	ORIGINATOR: ALL			STATUS	UPDATED DAT
OB NO	AREA	310	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
L5875	400	NRP	AE	7100	777-900001-01-1-01	#1 ENG FAN COWL 3EA HOIST PLUGS FND BROI	KEN.	L587	OPEN	09/26/2023
	ENG									2.0
									-	2.0
L5883	400	NRP	AE	7100	777-900001-01-1-01	#2 ENG FAN COWL 2EA HOIST PLUGS FND BROI	KEN.	L588	OPEN	09/26/2023
	ENG									1.0
									-	1.0
L5891	200	NRR	Al	2500	777-53-912-00-01	CABIN DOOR 3 FWD CENTER PARTITION AFTER	SIDE KICK STRIP FOUND DETACHED	L589	COMP	09/30/2023
	CAB							2000	001111	2.0
									-	2.0
L5909	400	NRP	ΑE	7500	777-900001-01-1-01	#2 ENG TURBINE COOLING DUCT 5EA CLAMP RI	ETAININGS FND WORN.	L590	OPEN	09/26/2023
	ENG							2000	OI LIV	8.0
									-	8.0
L5917	400	NRP	ΑE	8000	777-900001-01-1-01	#1 ENG STARTER DUCT 6 O'CLOCK 1EA SUPPO	RT ROD FND WORN	L591	OPEN	09/26/2023
	ENG					". <u> </u>		2001	OI LIV	2.0
									-	2.0
L5925	300	NRR	CL	5300	777-55-800-00-01	HORIZONTAL STABILIZER JACKSCREW COMPAR	RTMENT BSTA2174 TO BSTA2412 BILGE AREA DIRTY	L592	OPEN	09/26/2023
	EMP							2092	OI LIV	6.0
									-	6.0
L5933	300	NRR	AE	5300	777-55-800-00-01	APPLY CIC TO HORIZONTAL STABILIZER JACKS	CREW COMPARTMENT BSTA2174 TO BSTA2412 BILGE AREA	L593	OPEN	09/26/2023
	EMP							2000	OI LIV	3.0
									-	3.0
L5941	400	NRP	AE	7100	777-900001-01-1-01	#1 ENG RH FAN COWL ACTUATOR NIPPLE FND I	LEAKAGE	L594	OPEN	09/26/2023
	ENG							2004	OI LIV	3.0
									-	3.0
_5958	200	NRR	AV	2502	777-25-040-03-CX-01	EMA TEST FOUND 19D EMA INTERFACE CABLE	ASSEMBLY INOP	L595	WIP	10/02/2023
	CAB	14141	,	2002	-01			L090	VVIF	3.0
0,15								-		
									3.0	

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 81 OF 86 RUN DATE: 10/2/2023

RUN TIME : 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

	ZONE	STG			TTPE CODE.	ORIGINATOR.	7.22		STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
(JL5966	200	NRR	Al	2500	777-53-916-00-01	CABIN SIDE BIN DR INTERIOR SURFAC	E AT 43H AND 44H FND DENT	L596	WIP	09/28/2023
	CAB									4.0
									-	4.0
JL5974	200	NRR	AV	2502	777-25-040-03-CX-01	INSPECTION EMA FOUND 11G.25G TES	T BLANK PLUG MISSING	L597	WIP	10/02/2023
(	CAB				-01					1.0
									-	1.0
JL5982	200	NRP	AV	3531	777-35-160-01-CX-01	LAV B 2EA SPARE PORTABLE OXYGEN	MACK NEAD EVOIDY DATE	L598	OPEN	
12302	CAB	INIXI	AV	3331	777-33-100-01-02-01	LAV B ZEA GFARE FORTABLE OXTGEN	INASK NEAK EAFIKT DATE	L598	OPEN	09/26/2023
									_	
										2.0
JL5990	200	NRR	CL	2527		M/D #1DOOR TO #3DOOR REMOVED AI	SLE CARPETS AREA FLOOR PNL UPPER SURFACE FND DIRTY	L599	COMP	09/28/2023
CAI	CAB									32.0
									-	32.0
JL6006	300	NRR	SM	5300	777-53-924-00-01	TAIL CONE FUSELAGE EXTERNAL SKIN	BSTA2390 TO BSTA2412 STR1L TO STR2L FOUND 1EA DENT MARK	L600	WIP	10/02/2023
	EMP									0.0
						1C 1 CARRY OUT CRACK FR	EE CHECK			1.0
									-	1.0
JL6014	700	NRR	ΑE	3222	777-32-802-00-01	L/G-NLG RH AFT DOOR OPERATIONAL	ROD GEAR SIDE ATTACHED BOLT 1EA GREASE NIPPLE MISSING.	L601	OPEN	09/26/2023
	LDG									1.0
									-	1.0
JL6022	300	NRR	SM	5300	777-53-924-00-01	TAIL CONF FUSELAGE EXTERNAL SKIN	I BSTA2390 TO BSTA2412 STR2L TO STR3L FOUND 1EA SCRATCH MARK	L602	WIP	09/28/2023
	EMP		•	0000	65 62 . 65 6 .	THE COME I COLLINGE EXTERNAL ONLY	1357/ESSO 13 557/E112011EE 13 0110E1 351/B 1E1 351/Million	L002	VVII	0.0
						1C 1 REMOVE THE SCRATCH	1 DAMAGE			2.0
						1C 2 APPLY A CHEMICAL CO	NVERSION COATING			0.5
						1C 3 ASSESS THE REWORK	AREA			1.0
						1C 4 APPLY 1 LAY OF BMS 1	0-79, TYPE III PRIMER TO THE SURFACE			1.0
						2C 5 CARRY OUT THICKNES	S CHECK			1.0
						2C 6 CARRY OUT CRACK FR	EE CHECK			1.0
									-	6.5

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE:

RUN TIME :

82 OF 86

RUN DATE: 10/2/2023 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL

PERIOD: ALL ZONE: ALL

ESTIMATED MHR: ALL DISPOSITION CODE: ALL

ORIGINATING CUST REF NO: ALL DEFECT TYPE: ALL

515653

BMS571R1-2

ATA NO: ALL TRADE: ALL CUST ENDORSE: ALL

AREA: ALL STAGE: ALL

CTRL CODE:

TYPE CODE: ORIGINATOR: ALL

CINE CODE.					TIFE CODE.	ONGINATOR. ALI	-			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL6030	700	NRR	AE	3245	777-53-810-00-01	L/G-NLG LH SPIN BRAKE METAL PLATE CRA	CKED.	L603	OPEN	09/26/2023
	LDG									4.0
									-	4.0
XJL6048	300	NRR	SM	5500	777-55-820-00-01	VERTICAL STABILIZER T/E ACCESS PANEL 3	24DXL FOUND 5EA ANCHOR NUTS BROKEN	L604	WIP	10/02/2023
	EMP									2.0
									-	2.0
XJL6055	300	NRR	AE	5500	777-55-820-00-01	VERTICAL STABILIZER T/E ACCESS PANEL 3	24DXL 324AL AND 324GK TOTAL 200EA SCREW HEAD WORN	L605	OPEN	09/26/2023
	EMP									0.0
									-	0.0
XJL6063	200	NRR	Al	1100	777-11-000-01-CX-R-	CABIN LAV WATER HEATER ACC PNL INSIDE	FND PLACARDS MISSING AT LAV A(1EA) AND LAV B(2EA)	L606	OPEN	09/26/2023
	CAB				01					3.0
									-	3.0
XJL6071	300	NRR	CL	5300	777-53-880-00-01	PLEASE CLEAN BODY FAIRING BACK SIDE S	URFACE	L607	OPEN	09/26/2023
	EMP							2007	OI LIV	4.0
									-	
XJL6089	100	NRR	SS	2500	777-53-862-00-01	AET CARGO BII GE AREA INSUI ATION BI ANI	KET FOUND BROKEN AT STA 1434+21 TO STA 1434+42 R/H	1.000	ODEN	4.0
AGE0003	LWR	MIXIX	00	2500	777-33-002-00-01	ALL CANGO BILGE AREA INGGERTION BEARI	LET OUR BROKEN AT OTA 1404-21 TO OTA 1404-42 INT	L608	OPEN	09/26/2023
									-	
V II 0007	400	NDD	00	2500	777 52 000 00 04	AFT CARCO DILOF AREA INCILI ATION DI ANI	VET FOUND DROVEN AT OTA 4494, 40 TO OTA 4494, 02 D#1			0.0
XJL6097	100 LWR	NRR	SS	2500	777-53-862-00-01	AFT CARGO BILGE AREA INSULATION BLANI	KET FOUND BROKEN AT STA 1434+42 TO STA 1434+63 R/H	L609	OPEN	09/26/2023
									_	0.0
										0.0
XJL6105	100 LWR	NRR	SS	2500	777-53-862-00-01	AFT CARGO BILGE AREA INSULATION BLANI	KET FOUND BROKEN AT STA 1434+84 TO STA 1434+105 R/H	L610	OPEN	09/26/2023
	LVVIX								_	0.0
									-	0.0
XJL6113	100	NRR	SS	2500	777-53-862-00-01	AFT CARGO BILGE AREA INSULATION BLANI	KET FOUND BROKEN AT STA 1434+168 TO STA 14+189 R/H	L611	OPEN	09/26/2023
	LWR									0.0
									-	0.0

DISTRIBUTION:

REQUESTED BY:

REFERENCE NO:

0PPC

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD. NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 83 OF 86

RUN DATE: 10/2/2023

RUN TIME : 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

ALL

ATA NO: ALL

ZONE: ALL Λ**D**ΕΛ · ΛΙΙ DISPOSITION CODE: ALL

STAGE: ALL

DEFECT TYPE : ALL	TRADE: ALL	CUST ENDORSE: ALL	AREA: ALL	STAGE: A
CTRL CODE :	TYPE CODE:	ORIGINATOR: ALL		

OTTLE GODE :	ZONE	STG			111 2 0002.	ONION WHOM: THE			STATUS	UPDATED DATE
JOB NO	AREA	310	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL6121	100	NRR	SS	2500	777-53-862-00-01		TION BLANKET FOUND BROKEN AT STA 1643 TO STA 1664.TOTAL	L612	OPEN	09/26/2023
	LWR					2EA				0.0
									-	0.0
XJL6139	100	NRR	SS	2500	777-53-862-00-01	AFT CARGO BILGE AREA R/H AND L/H INSULATION	BLANKET FOUND BROKEN AT STA 1685 TO STA 1706.TOTAL 2EA	L613	OPEN	09/26/2023
	LWR									0.0
									-	0.0
XJL6147	100	NRR	SS	2500	777-53-862-00-01	AFT CARGO BILGE AREA INSULATION BLANKET F	DUND BROKEN AT STA 1748 TO STA 1769 R/H	L614	OPEN	09/26/2023
	LWR									0.0
									-	0.0
XJL6154	100	NRR	SS	2500	777-53-862-00-01	AFT CARGO BILGE AREA INSULATION BLANKET F	DUND BROKEN AT STA 1853 TO STA 1874 R/H	L615	OPEN	09/26/2023
	LWR									0.0
									-	0.0
XJL6162	700	NRR	AE	3245	777-32-810-02-01	L/G-RH MLG NO.8 FOUND DEEP CUT.		L616	OPEN	09/27/2023
	LDG									0.0
									-	0.0
XJL6170	400	NRP	AE	2911	777-29-000-02-CX-01	LH HYD COMPARTMENT 5EA DIFFERENT PRESSU	RE INDICATOR COVERS AGED.	L617	WIP	10/02/2023
	FUS									3.0
									-	3.0
XJL6188	400	NRP	AE	2911	777-29-000-02-CX-01	RH HYD COMPARTMENT 5EA DIFFERENT PRESSU	RE INDICATOR COVERS AGED.	L618	WIP	10/02/2023
	FUS									3.0
									-	3.0
XJL6196	400	NRP	AE	2911	777-29-000-02-CX-01	CTR HYD SYS 10EA DIFFERENT PRESSURE INDIC	ATOR COVERS AGED.	L619	WIP	10/02/2023
	FUS									4.0
									-	4.0
XJL6204	700	NRR	AE	3211	777-32-300-00-01	L/G-LH MLG DRAG BRACE LOCK LINK ASSY TOGG	LE 3EA GREASE NIPPLES MISSING.	L620	OPEN	09/27/2023
	LDG									3.0
									-	3.0

515653

REQUESTED BY:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

PAGE: 84 OF 86 RUN DATE: 10/2/2023

9:39

8.5

REFERENCE NO: BMS571R1-2 (By JSN) RUN TIME :

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL ALL DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE : TYPE CODE: ORIGINATOR · ALL

CTRL CODE :					TYPE CODE:	ORIGINATOR:	ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
	500	NRP	AE	5700	777-900001-01-1-01	L & R WING UPPER PANEL (#6~9 SPO	DILER FWD) SEALANT FOUND MISSING & POOR CONDITION	L621	COMP	09/28/2023
	WNG									3.0
									-	3.0
XJL6220	100	NRR	AE	5300	777-53-804-00-01	NOSE RADOME PRESSURE BULKHE	AD LEFT SIDE BULB SEAL TORN	L622	OPEN	09/27/2023
	FUS									2.0
									-	2.0
XJL6238	400	NRP	AE	7800	777-24-030-00-01	#2 ENG LH TR COWL 9 O'CLOCK FWI	D CEAL ASSY END CDACKED	1.000		
AJL0230	ENG	INIXE	AL	7000	7800 777-24-030-00-01	#2 ENG LH TR COWL 9 O CLOCK FWI	D SEAL ASST FIND CRACKED.	L623	OPEN	09/27/2023
									_	4.0
										4.0
XJL6246	400	NRP	AE	5400	777-24-030-00-01	#1 PYLON AFT CAVITY WATER LEVE	LING COMPOUND FND LOOSEN.	L624	OPEN	09/27/2023
	ENG									4.0
									-	4.0
XJL6253	400	NRP	IRP AE	≣ 5400	5400 777-24-030-00-01	#2 PYLON AFT CAVITY WATER LEVELING COMPOUND FND LOOSEN.	L625	OPEN	09/27/2023	
	ENG									4.0
								-	4.0	
XJL6261	100	CUS	AV	25		AC DED MOT FINDING DEDORT (2002	DIAMON ITEM 4: DOTH FIAID & AFT CADOO HANDLEING CONTROL DANGL CONTROL		0.0511	
AJL0201	LWR	003	AV	25	25	AS PER MST FINDING REPORT (2023/9/29) ITEM 1: BOTH FWD & AFT CARGO HANDLEING CONTROL PANEL CONTROL SWITCHS JAM NUT FOUND WHITE POWDER DOPOSITE, PLEASE CLEAN UP AND RECTIFY IF NECESSARY!	L626	OPEN	09/29/2023	
	2,,,,									0.0
										0.0
XJL6279	800	CUS	US AV	52		•	3/9/29) ITEM 2: BOTH FWD & AFT CARGO DOOR CONTROL PANEL CONTROL NG FOUND WHITE POWDER DEPOSITE, PLEASE CLEAN IT AND RECTIFY IF	L627	OPEN	09/29/2023
	LWR					NECESSARY!	NG FOUND WHITE POWDER DEPOSITE, PLEASE CLEAN IT AND RECTIFT IF			0.0
									-	0.0
XJL6287	100	CUS	Al	52		AS PER MST FINDING REPORT (2023	3/9/29) ITEM 3: AFT LAVATORY SERVICE PANEL FOUND MINOR CORROSION	L628	WIP	10/01/2023
	LWR					UNDER THE HINHE AREA, PLEASE C	LEAN UP AND RECTIFY!			0.0
						1C 1 REMOVE THE CORR	OSION			2.0
						1C 2 APPLY A CHEMICAL	CONVERSION COATING			0.5
						1C 3 CARRY OUT THICKN	ESS CHECK			1.0
						1C 4 CARRY OUT CRACK	FREE CHECK			1.0
						2C 5 REMOVE THE PANEL				2.0
						2C 6 INSTALL THE PANEL				2.0

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 85 OF 86

RUN TIME :

ESTIMATED MHR: ALL

RUN DATE: 10/2/2023

9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

TYPE CODE:

ORIGINATING CUST REF NO: ALL ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

ORIGINATOR: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE :

STILL CODE.					THE GODE.	ONIGINATOR:	nuL		STATUS	UPDATED DATE																
IOD NO	ZONE	SIG	TD	4.74	ODIO QUOT DEE NO	OTPL OLLNO	DEFECT DECODIDATION	1011																		
OB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr																
XJL6295 10 FU	100	CUS	AE	36			)) ITEM 4: AFT ADP BLEED AIR DUCT FIT THROUGHT FROM AFT CARGO NCE MARKS (DARK DEPOSITE), PLEASE INVESTIGATION AND CONDITION	L629	OPEN	09/29/2023																
	FUS					CHECK!	NOE MANNO (BANN DEL COTTE), I LEADE INVECTION TION AND CONDITION			0.0																
									-	0.0																
IL6303	800	CUS	PT	36			9) ITEM 5: ALL MED DOOR HANDLE STOWAGE CAVITIES FOUND PAINT SSES, PLEASE CLEAN UP THAN TOUCH UP BEFORE FLIGHT!	L630	OPEN	09/29/2023																
	LWR					CHIPPED DUE PAINT STRIPPING PROCES	SES, PLEASE CLEAN UP THAN TOUCH UP BEFORE FLIGHT!			0.0																
									-	0.0																
IL6311	400	CUS	CUS AE	S AE	AE	S AE	29			9) ITEM 6: #1 ENGINE HYRDAULIC LINES FROM PYLON TO ENGINE SLEEVE	L631	OPEN	09/29/2023													
	ENG						FOUND HYDRAULIC STAIN MARK, PLEASE CLEAN IT THA	E CLEAN IT THAN LEAK CHECK ALL RELATED LINES CONNECTION!			0.0															
						1C 1 CLEAN THE SUBJECT AR	EA			3.0																
													1C 2 C/O LEAK CHK		_	1.0										
																					4.0					
L6329	700		PT	Г 29	29	29	29	29	29		AS PER MST FINDING REPORT (2023/9/29) ITEM 8: NLG LOWER CYLINDER FRONT FACE WARNING STENCIL FOUND L632 FADED, PLEASE RE-APPLY STENCIL IAW AMM!	·	L632	OPEN	09/29/2023											
	LDG												0.0													
									-	0.0																
L6337	700	CUS	AE	AE 12	12	AE 12	E 12	12	12	12	(	·	L633	OPEN	09/29/2023											
	LDG																								LANDING GEAR & SPOLIER CONTROL CABLES CONTAMATED WITH YELLOW DUST DUE LONG TERM PARKING, PLEASE CLEAN IT THAN SERVICING THOSE RELATED CABLES!	
													TELAGE GELANTI TIM GENVIONG THOSE NEBVIED GABLES.	-	0.0											
L6345	500	CUS	ΑE	27	,	AS PER MST FINDING REPORT (2023/9/29) ITEM 10: LH WING O/B FLAP I/B ATTACH FITTING FOUND SHIM PLATE MIGRATION AT MIDDLE MOUNT BOLTS AREA, PLEASE INVESTIGATION AND RECTIFY IAW AMM!	L634	OPEN	09/29/2023																	
	WNG								0.0																	
											-	0.0														
L6352	600	NRR	GW	57	777-28-031-40-02	RHW UPPER ACCESS PANEL661JT SCRE	WS FOUND SEIZED	L635	WIP	10/02/2023																
	WNG			27. 0.	<del>=</del> :							V V I I	1.0													
																			-	1.0						
L6360	600	NRR	SM	57	777-28-031-40-02	RHW UPPER ACCESS PANEL661JT ANCHOR NUT FOUND WORN	L636	OPEN	10/01/2023																	
	WNG									1.0																
									-	1.0																
										1.0																

DISTRIBUTION: 0PPC TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD. PAGE: 86 OF 86 REQUESTED BY: 515653

NRC TALLY LIST WITH ESTIMATE MANHOUR

RUN DATE: 10/2/2023

REFERENCE NO: BMS571R1-2 (By JSN) RUN TIME : 9:39

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL TYPE CODE: CTRL CODE: ORIGINATOR: ALL

STATUS UPDATED DATE ZONE STG

AREA: ALL

STAGE: ALL

JOB NO AREA TD ATA ORIG CUST REF NO. CTRL SH NO DEFECT DESCRIPTION JSN **STATUS** EST Mhr

TOTAL NO OF NRC PRINTED: 636 5,051.3 Total Mhr:

Jobs OPEN: 303 Jobs READY: 0 247 Jobs WIP: Jobs HOLD: 0 Jobs CANC: 0 Jobs DEFER: 0 Jobs COMP: 86

I CERTIFY THAT I HAVE CHECKED THAT ALL THE ABOVE REFERENCED CARDS HAVE BEEN CERTIFIED AS HAVING BEEN COMPLETED.

PLANNING ENGINEER \_\_\_\_\_ DATE \_\_\_\_ CERTIFYING STAFF \_\_\_\_\_ DATE \_\_\_\_\_

STAMP AND SIGNATURE