REQUESTED BY:

PROJECT: VM

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

A/C REGN: B-HNH

PAGE: 1 OF 23

RUN DATE: 9/28/2023 RUN TIME: 9:19

REFERENCE NO: BMS571R1-2

588486

A/C TYPE: 777

CHECK TYPE: 3C

ESTIMATED MHR: ALL

JSN RANGE SELECTED : ALL
ORIGINATING CUST REF NO: ALL

STATUS: ALL

CUSTOMER: CX

ORIG-STAGE: ALL

PERIOD : ALL ZONE : ALL

DISPOSITION CODE: ALL

DEFECT TYPE: ALL

CTRL CODE:

TRADE : ALL
TYPE CODE:

CUST ENDORSE : ALL ORIGINATOR : ALL

ATA NO: ALL

AREA: ALL

STAGE: ALL

CIRL CODE.					I THE CODE.	ORIGINATOR . ALL			
	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	TRL SH NO DEFECT D	DESCRIPTION JSN	STATUS	EST Mhr
VML0014	500	NRR	AE	2800	777-5000-10-025-01	AS FUEL SYS STORAGE REQUIREMENT, PERFORM A/C REFUELING.	L001	COMP	09/07/2023
	F/T								8.0
									8.0
VML0022	100	CUS	AE	3200		TOWING A/C FOR MAINTENANCE/OPERATION NEED.	L002	WIP	08/23/2023
	FUS								0.0
						C 1 TOWING A/C DUE MAINTENANCE OPERATIONAL REQ'D.			5.0
						C 2 TOWING A/C DUE MAINTENANCE OPERATIONAL REQ'D.			5.0
						C 3 TOWING A/C DUE MAINTENANCE OPERATIONAL REQ'D.			5.0
						C 4 TOWING A/C DUE MAINTENANCE OPERATIONAL REQ'D.			5.0
						C 5 TOWING A/C FROM 12BAY O/S TO MIDBAY H1-3			5.0
						C 6 TOWING A/C FROM 11BAY O/S TO 12BAY O/S FOR ENG SUC	TION FEED TEST.		5.0
						C 7 TOWING A/C FROM 12BAY O/S TO 11BAY O/S AFT ENG SUCT	TION FEED TEST.		5.0
						C 8 TOWING A/C FROM 11 BAY O/S INTO 10 BAY FOR C-CHK INP	UT.		5.0
								-	40.0
VML0030	400	LOG	SS	72		AS PER CX B-HNH DEFERRAL REPORT ITEM SADD S201: HTP T14 WORK RE	EQUEST (WR), ENG 1 REF WORK REQUEST L003	OPEN	08/24/2023
	ENG					NO: 67153 ENG 1 ATT LINING-CAD FINDING SEVERAL ERSIONS WERE FOUNI			0.0
						ATTRITION LINING OF THE LH ENGINE. LP COMPRESSOR BLADE ATTRITION	· · · · · · · · · · · · · · · · · · ·		0.0
						FILLING AND EROSION AROUND LP COMPRESSOR (PLS REF TO ATTACHED ACTION ITEMS)	"CX DEFERRAL REPORT" FOR REQUIRED		
						C 1 PLS MAKE LOG BOOK ENTRY.			0.2
						C 2 REMOVE THE FAN BLADES			4.0
						C 3 REPAIR THE ATTRITION LINING WITH FILLER			24.0
						C 4 IDENTIFY THE REPAIR			1.0
						C 5 REINSTALL THE FAN BLADES			8.0
								-	37.2
VML0048	500	LOG	AE	28		AS PER CX B-HNH DEFERRAL REPORT ITEM SADD S202: 282 061 42 FUEL SI	SPAR VALVE R (STATUS) ON CHK FOUND L004	OPEN	08/25/2023
VIVILOUTO	F/T	200	/ \L	20		CB PNL P11 LOCATION A19. R ENG FUEL SPAR VALVE CB TRIPPED UNABLE	. ,	OPEN	
	F/ I					RAISED UNDER CX CONCESSION NO:5648 FOR REPLACE WIRE WITH ORIGIN	NAL WIRE SPEC AFT 2FC. ACTIONED IN		0.0
						ACCORDANCE WITH OTHER WDM 28-22-25 (PLS REF TO ATTACHED "CX DEF	FERRAL REPORT" FOR REQUIRED ACTION		
						TEMS)			
						C 1 PLS MAKE LOG BOOK ENTRY			0.2
								-	0.2
									0.2

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

ORIG-STAGE: ALL

ATA NO: ALL

(By JSN)

PAGE: 2 OF 23 RUN DATE: 9/28/2023

RUN TIME: 9:19

PROJECT: VM

REQUESTED BY:

REFERENCE NO:

CUSTOMER: CX

A/C TYPE: 777

A/C REGN: B-HNH

CHECK TYPE: 3C

ESTIMATED MHR: ALL

JSN RANGE SELECTED: ALL ORIGINATING CUST REF NO: ALL

STATUS: ALL

ZONE: ALL

DISPOSITION CODE: ALL

DEFECT TYPE : ALL

588486

BMS571R1-2

TRADE: ALL CUST ENDORSE: ALL AREA: ALL

PERIOD: ALL

STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

TIVE GODE .	ZONE	CTC			THE GODE.	Sider Viet.		STATUS	UPDATED DA
IOB NO	AREA	SIG	TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
L0055	100	CUS	AV	2553		FWD CARGO CARGO HANDLING CONTROL PANEL IN HEAVY CORROSION	L005	OPEN	08/25/2023
20000	LWR	000	, ·	2000		TWO CANGO DANGO TIAMBEING CONTROL FANEL INTILAY FOUNTOOIGN	L005	OPEN	
	LVVIX								6.0
						1C 1 REMOVE THE FWD CARGO HANDLING CONTROL PANEL			1.0
						1C 2 BUILD UP THE FWD CARGO HANDLING CONTROL PANEL			40.0
						1C 3 INSTALL THE FWD CARGO HANDLING CONTROL PANEL  1C 4 PERFORM THE INSTALLATION TEST			2.0 2.0
						1C 4 PERFORM THE INSTALLATION TEST		_	2.0
									51.0
L0063	100	CUS	AV	2553		AFT CARGO CARGO HANDLING CONTROL PANEL IN HEAVY CORROSION	L006	OPEN	08/25/2023
	LWR								6.0
						1C 1 REMOVE THE AFT CARGO HANDLING CONTROL PANEL			1.0
						1C 2 BUILD UP THE AFT CARGO HANDLING CONTROL PANEL			30.0
					1C 3 INSTALL THE AFT CARGO HANDLING CONTROL PANEL			2.0	
						1C 4 PERFORM THE INSTALLATION TEST			2.0
								-	41.0
L0071	100	SIA	AV	33		FWD CARGO HANDLING CONT PANEL P24 SERVICE LIGHT FOUND CORROSION	L007	OPEN	08/28/2023
	FUS								2.0
								-	2.0
_0089	200	NRW	AV	2330	SWC-28778-01-01	ON CHECK FOUND SEAT 12A,15A,17K IFE MONITOR CAN NOT BOOT UP.(PN:RDFE7820-13)	L008	OPEN	08/29/2023
	CAB							· ·	9.0
								-	
									9.0
_0097	200	NRW	AV	2330	SWC-28778-01-01	ON CHECK FOUND BELOW IFE MONITOR TOUCH SCREEN MALFUCTION AT:39C.40A.40B.40C.40E.40G.41J.42A.42E.42G.43A.43H.44B.44C.44E.44F.44H.45A.45B.46E.47A.47C.47D.48C.48F.48K.	L009	WIP	08/30/2023
	CAB					49G,50A,50F,50G,51H,52H,52K,54J,54K,55B,55D,55E,55F,55J			0.0
						1C 1 PLEASE REMOVE SEAT CUSHION			6.0
						1C 2 REMOVE THE DEFECTIVE MONITOR AND RETURN TO STORE FOR SHOP REPAIR			40.0
						1C 3 INSTALL NEW MONITOR AND PERFORM IFE INDIVIDUAL SYSTEM TEST			44.0
						1C 4 INSTALL SEAT CUSHION			8.0
								-	98.0

588486

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 3 OF 23

RUN TIME:

RUN DATE: 9/28/2023

9:19

PROJECT: VM CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-HNH CHECK TYPE: 3C

STATUS: ALL PERIOD: ALL JSN RANGE SELECTED: ALL ORIG-STAGE: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ATA NO: ALL DISPOSITION CODE: ALL ALL ZONE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE : TYPE CODE: ORIGINATOR · ALL

CTRL CODE :					TYPE CODE:			ORIGINATOR: ALL			
	ZONE	STG								STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTR	L SH NC	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
VML0105	200	NRW	AV	2330	SWC-28778-01-01			OUND BELOW IFE MONITOR TOUCH SCREEN MALFUCTION AT:	L010	WIP	08/30/2023
	CAB					,	, , .	7A,57B,57F,57G,58B,58C,58E,59E,59K,60A,60B,60F,60G,60H,60K,61A,61B,61C,61D,61E,61H,61J,61K,62A,62 .63D,64C,64E,64G,65A,65D,65E,65K			0.0
						1C	1	PLEASE REMOVE SEAT CUSHION			8.0
						1C	2	REMOVE THE DEFECTIVE MONITOR AND RETURN TO STORE FOR SHOP REPAIR			39.0
						1C	3	INSTALL NEW MONITOR AND PERFORM IFE INDIVIDUAL SYSTEM TEST			44.0
						1C	4	INSTALL SEAT CUSHION			10.0
										-	101.0
ML0113	200	NRW	AV	2330	SWC-28778-01-01			OUND BELOW IFE MONITOR TOUCH SCREEN MALFUCTION AT:	L011	WIP	08/30/2023
	CAB					66C,	66D,66E,6	6G,67A,67G,67J,68F,68G,68H,68K,69G,69K,70A,70B,70D,70E,70G,70H,70J,70K,71C,72C,72D			0.0
						1C	1	PLEASE REMOVE SEAT CUSHION			10.0
						1C	2	REMOVE THE DEFECTIVE MONITOR AND RETURN TO STORE FOR SHOP REPAIR			50.0
						1C	3	INSTALL NEW MONITOR AND PERFORM IFE INDIVIDUAL SYSTEM TEST			55.0
						1C	4	INSTALL SEAT CUSHION			12.0
										-	127.0
ML0121	ML0121 400	NRR	SM	7100	777-5000-10-026-01	#1 E	NG NOSE	COWL LIP SKIN MULTIPLE FND CORROSION.	L012	WIP	09/19/2023
	ENG										0.0
						1C	1	REMOVE THE LIP SKIN CORROSION			60.0
						1C	2	PTOTECT THE REWORK AREA			4.0
						1C	3	NDT THICKNESS CHK			0.0
						1C	4	NDT CRACK CHK			0.0
										-	64.0
ML0139	400	NRR	SM	7100	777-5000-10-026-01	#2 E	NG NOSE	COWL LIP SKIN MULTIPLE FND CORROSION.	L013	WIP	09/19/2023
	ENG										0.0
						1C	1	REMOVE THE LIP SKIN CORROSION			60.0
						1C	2	PTOTECT THE REWORK AREA			4.0
						1C	3	NDT THICKNESS CHK			0.0
						1C	4	NDT CRACK CHK			0.0
										-	64.0
ML0147	200	LOG	SS	25				HNH DEFERRAL REPORT ITEM CADD C228: YAO 10 2 YCL, SEAT, ARM CAP, PAX SEAT - ON CHK FND EY	L014	WIP	09/26/2023
	CAB							SIDE FAIRING CRACKED AT 54D,54G,39G,68G. (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR TION ITEMS)			0.0
						1C	1	PLEASE MAKE THE LOG ENTRY			0.2
										-	
											0.2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

4 OF 23 PAGE:

RUN DATE: 9/28/2023

RUN TIME: 9:19

PROJECT: VM CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-HNH CHECK TYPE: 3C

JSN RANGE SELECTED: ALL

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

ALL

ATA NO: ALL

ZONE: ALL

DISPOSITION CODE: ALL

DEFECT TYPE : ALL

588486

BMS571R1-2

TRADE: ALL CUST ENDORSE: ALL

AREA: ALL STAGE: ALL

CTRL CODE :	TYPE CODE:	ORIGINATOR:	ALL

	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA	5.0	TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT I	DESCRIPTION JSN	STATUS	EST Mhr
VML0154	200 CAB	LOG	Al	25		AS PER CX B-HNH DEFERRAL REPORT ITEM ADD 159: GA0 51 2 GALLEY, COFF VALVE, G1C ON CHK FOUND G1C WATER LEAK BEHIND ESPRESSO MATTACHED "CX DEFERRAL REPORT" FOR REQUIRED ACTION ITEMS)  1C 1 PLS MAKE LOG BOOK ENTRY.	COUNTERTOP & SINK AREA, WATER SHUT L015	OPEN	09/14/2023 0.0 0.2
VML0162	100 FUS	CUS	SM	52		WASTE WATER SERVICE DOOR INTERNAL AND EXTERNAL FOUND CORRO	OSION L016	WIP	0.2 09/15/2023 0.0
VML0170	100 FUS	CUS	SM	52		POTABLE WATER SERVICE DOOR FOUND 3EA LATCH MALFUNCTION	L017	OPEN	0.0 09/14/2023 0.0
VML0188	100 FUS	CUS	SM	53		FWD CGO HANDLING CONTROL DOOR INTERNAL FOUND CORROSION	L018	WIP	0.0 09/15/2023 0.0
						1C 1 REMOVE CORROSION AREA LATCH AND FASTENERS 1C 2 REMOVE CORROSION 1C 3 APPLY BONDERITE M-CR 1200S AERO TO REWORK AREA 1C 4 C/O NDT THICKNESS CHK 2C 5 NDT CRACK FREE CHECK 2C 6 INSTALL THE LATCH AND FASTENERS 2C 7 TOUCH UP PAINT			4.0 2.0 1.0 4.0 1.0 8.0 0.5
VML0196	100 FUS	CUS	SM	53		AFT CGO DOOR CONTROL DOOR HINGE SPRING BROKEN	L019	WIP	20.5 09/15/2023 0.0
VML0204	100 FUS	CUS	SM	53		FWD CGO DOOR CONTROL DOOR HINGE SPRING BROKEN	L020	OPEN	0.0 09/14/2023 0.0
VML0212	100 FUS	CUS	SM	53		AFT CGO HANDLING CONTROL DOOR 2EA LATCH SEAL MISSING	L021	OPEN	0.0 09/14/2023 0.0 0.0

588486

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 5 OF 23

RUN DATE: 9/28/2023

RUN TIME: 9:19

PROJECT: VM CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-HNH CHECK TYPE: 3C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE : ALL TRADE : ALL CUST ENDORSE : ALL AREA : ALL STAGE : ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

CTRL CODE :					TYPE CODE:	ORIGINATOR	R: ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
VML0220	100	CUS	SM	53		WASTE WATER SERVICE DOOR F	WD DOOR PANEL CORROSION	L022	OPEN	09/14/2023
	FUS									0.0
									-	0.0
VML0238	100	CUS	SM	53		WASTE WATER DRAIN CONNECTO	OR BOTTOM SURFACE FOUND CORROSION	L023	OPEN	09/15/2023
	FUS									0.0
									-	0.0
VML0246	100	CUS	AV	3522		AS PER CUSTOMER REQUEST, RE	MOVE 4EA PAX OXYGEN CYLINDERS TO SERVE B-KQX. P/N: 804044-15,S/N:	L024	OPEN	09/18/2023
	LWR					C11110245/C13060504/C07070164/	•	2021	0. 2.1	0.1
						1C 1 REMOVE 4EA PAS	SENGER OXYGEN CYLINDERS			4.0
									-	4.1
VML0253	800	NRR	Al	5200	777-25-067-00-01	FUSE-RH OWING SLIDE CABLE CL	LASS FND AGED.	L025	OPEN	09/23/2023
	FUS									3.0
									-	3.0
VML0261	200	LOG	Al	25		AS PER CX B-HNH DEFERRAL REI	PORT ITEM ADD A153: FUSELAGE SURFACE AROUND LAV GALLEY VENT OUTLET	L026	OPEN	09/25/2023
	CAB					PAINT PEELING OFF EXPOSING AL	LUMINIUM SKIN.PROTECTED WITH ALODINE.TO BE PAINTED AT MAIN BASE(PLS REF	2020	OI LIV	0.0
						10 ATTACHED "CX DEFERRAL REI 1C 1 PLS MAKE LOG BO	PORT" FOR REQUIRED ACTION ITEMS) DOK ENTRY.			0.2
									-	0.2
VML0279	300	LOG	PT	51		AS PER CX B-HNH DEFERRAL REI	PORT ITEM ADD A154: VERTICAL STABILIZER PAEL PN: 117W3102 WAS REPLACED	L027	OPEN	09/25/2023
	EMP					AS PER RS 30367, CARRY OUT DEC	CORATIVE PAINTING & STENSIL RS-30367 ON THE PANEL (PLS REF TO ATTACHED	LUZI	OI LIV	0.0
						"CX DEFERRAL REPORT" FOR REC	,			0.2
									-	0.2
VML0287	700	LOG	ΑE	32		AS PER CX B-HNH DEFERRAL REI	PORT ITEM ADD A155: RH NOSE WHEEL DUST CAP MISSING. (PLS REF TO	L028	OPEN	09/25/2023
	LDG						RT" FOR REQUIRED ACTION ITEMS)	2020	OI LIV	0.0
						1C 1 PLS MAKE LOG BO	DOK ENTRY.			0.2
									-	0.2

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 6 OF 23

RUN DATE: 9/28/2023 RUN TIME: 9:19

0.2

PROJECT: VM

REQUESTED BY:

REFERENCE NO:

CUSTOMER: CX

A/C TYPE: 777

A/C REGN: B-HNH

PERIOD: ALL

CHECK TYPE: 3C

ESTIMATED MHR: ALL

JSN RANGE SELECTED: ALL ORIGINATING CUST REF NO: ALL

STATUS: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL

588486

BMS571R1-2

TRADE: ALL

CUST ENDORSE: ALL

ORIG-STAGE: ALL

AREA: ALL STAGE: ALL

		_				000. 2.120.102. 7.22	7.11.27.1. 7.12.2	0.7.02. 7.22				
CTRL CODE		0.70			TYPE CODE:	ORIGINATOR: ALL			STATUS	UPDATED DATE		
JOB NO	ZONE AREA	SIG	TD	ATA	ORIG CUST REF NO.	TRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr		
/ML0295	500	LOG	AE	57	ONIO COOT INEL INC.	S PER CX B-HNH DEFERRAL REPORT ITEM ADD A156:		L029	OPEN	09/25/2023		
VIVILUZ33	WNG	200	AL	31		REA.NOTED CARBON DEPOSITS IN THE DAMAGE .SUS ND WIDTH 10 MM.DAMAGE IN ZONE 14 ON FLAP LOWE APE APPLIED.TO BE INSPECTED WITHIN CONTINUE TO EQUIRED ACTION ITEMS)	PECT UNDTECTED OPERATIONAL DAMAGE.LENGTH 20MM R SURFACE.SRM 57-53-01-1A-2 REFERS.WITHIN LIMITS.SPD I SWS (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FC	1	OPEN	0.0		
							REPAIR WITHIN 4000FC OR TWO YEARS.			0.0 0.2		
						2 PLS MAKE LOG BOOK ENTRY.			_	0.2		
										0.2		
	LOG	ΑE	57			REF ADD A156 PERMANENT REPAIR TO BE CARRIED OUT	L030	OPEN	09/25/2023			
	WNG					TIHIN 4000FC OR TWO YEARS. (PLS REF TO ATTACHE	D "CX DEFERRAL REPORT" FOR REQUIRED ACTION ITEMS)			0.0		
						1 PLS MAKE LOG BOOK ENTRY.				0.2		
									-	0.2		
ML0311	200	LOG	ΑI	25		S PER CX B-HNH DEFERRAL REPORT ITEM CADD C17:	3: GALLEY, STOWAGE & TIM, SOILED LINEN/WASTE	L031	OPEN	09/25/2023		
	CAB							,	O ATTACHED "CX DEFERRAL REPORT" FOR REQUIRED			0.0
						ACTION ITEMS) 1C 1 PLS MAKE LOG BOOK ENTRY.			0.2			
									-	0.2		
ML0329	200	LOG	AI	25		S PER CX R-HNH DEFERRAL REPORT ITEM CADD C22:	B: DOOR PLATE INSERTER LEFT TOP(LOOKING TO TWO)	L032	OPEN	09/25/2023		
WEGGEG	CAB	200	,	20		DOSEN (PLS REF TO ATTACHED "CX DEFERRAL REPO	,	L032	OPEN			
						2 1 PLS MAKE LOG BOOK ENTRY.				0.0 0.2		
						TES MAKE 200 BOOK ENTITY.			-			
										0.2		
/ML0337	200 CAB	LOG	SS	25		.S PER CX B-HNH DEFERRAL REPORT ITEM CADD C23: 3.I 50H 51H 56H 60.I 62H 70.I 70H 73.I 78K 78A 78B 40C 4:	5: ON CHK FND SEATS  A,42A,47B,48A,48B,48C,49A,49C,50A,51A,51C,57A,63B,63C,6	L033	OPEN	09/25/2023		
	CAB					SB,67B,68C,72A,72B,72C,76C,77A,77B,42E,43D,48E,48D, F,70G,74G MEAL TABLE WHITE DIRTY (PLS REF TO ATT	19D,64D,65D,67E,69D,71E,76G,42G,46G,46F,47G,60G,65G,660 ACHED "CX DEFERRAL REPORT" FOR REQUIRED ACTION	•		0.0		
						'EMS) C 1 PLS MAKE LOG BOOK ENTRY.				0.2		
									-	0.2		
'ML0345	200	LOG	SS	25		S PER CX B-HNH DEFERRAL REPORT ITEM CADD C24:	3: REF CL5073, G7 FWD DOUBLE SEAT SEAT COVER	L034	OPEN	09/25/2023		
	CAB						.DD C243: REF CL5073, G7 FWD DOUBLE SEAT SEAT COVER XX DEFERRAL REPORT" FOR REQUIRED ACTION ITEMS)	2004	O. L.	0.0		
						2 1 PLS MAKE LOG BOOK ENTRY.				0.2		
									-			
										0.2		

REQUESTED BY:

DEFECT TYPE: ALL

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

AREA: ALL

STAGE: ALL

PAGE: 7 OF 23 RUN DATE: 9/28/2023

RUN TIME: 9:19

REFERENCE NO : BMS571R1-2

588486

(By

PROJECT: VM CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-HNH CHECK TYPE: 3C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

CUST ENDORSE: ALL

CTRL CODE : TYPE CODE : ORIGINATOR : ALL

TRADE: ALL

CTRL CODE :					TYPE CODE:		ORIGINATOR: ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
VML0352	200 CAB	LOG	Al	25			H DEFERRAL REPORT ITEM CADD C254: ALL CABIN TORCHES TAMPER PROOF STICKER TO BE EF TO ATTACHED "CX DEFERRAL REPORT" FOR REQUIRED ACTION ITEMS)	L035	OPEN	09/25/2023
	0712						O MAYE LOO BOOK ENTRY			0.0
						1C 1 PI	LS MAKE LOG BOOK ENTRY.		_	0.2
										0.2
VML0360	200	LOG	ΑI	25			H DEFERRAL REPORT ITEM MADD M680: DUE TO SPARE NIL STOCK AND EXPIRY OF L1 DOOR	L036	OPEN	09/25/2023
	CAB					· · · · · · · · · · · · · · · · · · ·	.19 SN 0361), L2 DOOR SLIDE NEEDS TO BE REMOVED AND INSTALLED ON L1 POSITION. L2 DOOR ATED UNDER MEL 52-11-01-01B.(PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR REQUIRED			0.0
						,	EMOVE L1 SLIDE PER AMM 25-66-01-000-801.			0.0
						1C 2 R	EMOVE L2 SLIDE PER AMM 25-66-01-000-801 AND INSTALL TO L1 DOOR AMM 25-66-01-400-801.			0.0
							AISE ADD FOR L2 DOOR SLIDE MISSING PER MEL 52-11-01-01B.			0.0
						1C 4 PI	LS MAKE LOG BOOK ENTRY.			0.2
									-	0.2
VML0378	400	LOG	ΑE	72			H DEFERRAL REPORT ITEM PADD P031: REF WORK CARD NO. 777-5000-10-025-01 EDTO	L037	OPEN	09/25/2023
	ENG						TO PADD RAISED, A/C DOWNGRADE DUE TO FUEL AND OIL SYS DISTURBED ON BOTH ENG, PLS FICATION FLIGHT AT NEXT SECTOR.(PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR N. ITEMS)			0.0
							LS MAKE LOG BOOK ENTRY.			0.2
									-	0.2
VML0386	700	LOG	AE	32		AS PER CX B-HNI	H DEFERRAL REPORT ITEM SADD S151: CARRY OUT NOSE LANDING GEAR SHOCK STRUT	L038	OPEN	09/25/2023
	LDG					PRESSURE CHEC	K AFTER FIVE TO TEN IN SERVICE LANDINGS.(PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR	2000	OI LIV	0.0
						REQUIRED ACTIO	,			0.0
						TC T PI	LS MAKE LOG BOOK ENTRY.		_	0.2
										0.2
VML0394	700	LOG	ΑE	32			H DEFERRAL REPORT ITEM SADD S152: CARRY OUT MAIN LANDING GEAR SHOCK STRUT	L039	OPEN	09/25/2023
	LDG					REQUIRED ACTIO	K AFTER FIVE TO TEN IN SERVICE LANDINGS.(PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR N ITEMS)			0.0
							LS MAKE LOG BOOK ENTRY.			0.2
									-	0.2
VML0402	500	NRR	AE	2800	777-5000-10-031-01	FOR C-CHECK RE	CO'D. DEFUEL A/C FOR ENG FUEL SUCTION FEED TEST.	L040	WIP	09/25/2023
	F/T							2040	****	10.0
									_	10.0
										10.0

588486

BMS571R1-2

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 8 OF 23 RUN DATE: 9/28/2023

RUN TIME:

9:19

PROJECT: VM CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-HNH CHECK TYPE: 3C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL ALL

DEFECT TYPE : ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

REQUESTED BY:

REFERENCE NO:

CTRL CODE :	7015	0.7.0			TYPE CODE:	ORIGINATOR: AL	_L		STATUS	UPDATED DATE
JOB NO	ZONE AREA	SIG	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
VML0410	100	LOG	Al	25	ONIO COOT NEI NO.		M SADD S161: REF W/O 9510569/55 AND NRC-27504-16217 FWD CARGO	L041	OPEN	09/25/2023
VIVILO 1 10	LWR	200	,	20		PDU 15R (M25215) CABLE DAMAGED. PDU F	REQUIRES REPLACEMENT.(PLS REF TO ATTACHED "CX DEFERRAL	L041	OPEN	0.0
						REPORT" FOR REQUIRED ACTION ITEMS)  1C 1 PLS MAKE LOG BOOK ENTE	ev			0.0
						TO THE WARE EGG BOOK ENTI	VI.		-	
/ML0428	100	LOG	Al	25		AC DED OV D LINU DEFENDAL DEPORT ITE	M 0ADD 0400, DEF W/O 0540500/57 AND NDO 07504 40040 AFT 0ADOO 6	DII		0.2
/IVILU420	LWR	LUG	AI	23			M SADD S162: REF W/O 9510569/57 AND NRC-27504-16218 AFT CARGO F JIRES REPLACEMENT.(PLS REF TO ATTACHED "CX DEFERRAL REPORT"	DU L042	OPEN	09/25/2023
						FOR REQUIRED ACTION ITEMS)  1C 1 PLS MAKE LOG BOOK ENTE	DV.			0.0 0.2
						TO T PLS MAKE LOG BOOK ENTE	ν.			
								_		0.2
/ML0436	200 CAB	LOG	AV	23			M SADD S163: REF WO 9513638/1 AMS23-000-07-CX2-IFE SYSTEM WIRIN R THAN NEXT REVENUE FLIGHT.(PLS REF TO ATTACHED "CX DEFERRA	_0.0	OPEN	09/25/2023
	CAB					REPORT" FOR REQUIRED ACTION ITEMS)	`			0.0
						1C 1 PLS MAKE LOG BOOK ENTF	RY.		_	0.2
										0.2
/ML0444	200	LOG	G AV 52	52			M SADD S164: WO NO : 9513420/1 CARRY OUT REPLACEMENT OF NO 3 PAS10-5.SN:0112. (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FO	L044	OPEN	09/25/2023
	CAB					REQUIRED ACTION ITEMS)  1C 1 PLS MAKE LOG BOOK ENTRY.			0.0	
									0.2	
									-	0.2
/ML0451	200	LOG	AV	52			M SADD S165: WO NO: 9513421/1 CARRY OUT REPLACEMENT OF NO.3	L045	OPEN	09/25/2023
	CAB					OVER-WING DOOR EPAS BATTERY SERIAL NO : 1866 PART NO : BPAS10-5. (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR REQUIRED ACTION ITEMS)	-		0.0	
						1C 1 PLS MAKE LOG BOOK ENTE	RY.			0.2
									-	0.2
ML0469	200	LOG	AV	52			M SADD S166: WO NO : 9513422/1 CARRY OUT REPLACEMENT OF RIGHT	L046	OPEN	09/25/2023
	CAB					REPORT" FOR REQUIRED ACTION ITEMS)	IO : 2232 PART NO : BPAS10-5. (PLS REF TO ATTACHED "CX DEFERRAL			0.0
						1C 1 PLS MAKE LOG BOOK ENTE	RY.			0.2
									-	0.2
ML0477	200	LOG	AV	52			M SADD S167: WO NO : 9513423/1 CARRY OUT REPLACEMENT OF OVER	L047	OPEN	09/25/2023
	CAB					WING DOOR BACKUP BATTERY BY DOOR R DEFERRAL REPORT" FOR REQUIRED ACTION	R3 SERIAL NO : 2185 PART NO : BOAS10-5. (PLS REF TO ATTACHED "CX DN ITEMS)			0.0
						1C 1 PLS MAKE LOG BOOK ENTE	,			0.2
									-	0.2

ORIGINATING CUST REF NO:

588486

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 9 OF 23

ESTIMATED MHR: ALL

RUN DATE: 9/28/2023

RUN TIME: 9:19

PROJECT: VM CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-HNH CHECK TYPE: 3C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

CTRL CODE :					TYPE CODE:	ORIGINATOR:	ALL				
	ZONE	STG							STATUS	UPDATED DATE	
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr	
VML0485	200	LOG	AV	52			RT ITEM SADD S168: WO NO : 9513424/1 CARRY OUT REPLACEMENT OF EPAS	L048	OPEN	09/25/2023	
	CAB					SQUIB ON PASSENGER ENTRY DOOF DEFERRAL REPORT" FOR REQUIRED	R 5L SERIAL NO : 54438A7 PART NO : 41004509-1.(PLS REF TO ATTACHED "CX LACTION ITEMS)			0.0	
						1C 1 PLS MAKE LOG BOOK	,			0.2	
									-	0.2	
VML0493		LOG	Al	25		AS PER CX B-HNH DEFERRAL REPO	RT ITEM SADD S170: REF WO 9513647/1 PN: 63604-331. 0545 REPLACE THE SLIDE	L049	OPEN	09/25/2023	
	CAB						IDES PER AEO-27810 PART 1 AFTER AIRCRAFT FERRY FLIGHT WITHIN 5 FC ARD.(PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR REQUIRED ACTION			0.0	
						1C 1 PLS MAKE LOG BOOK	KENTRY.			0.2	
									-	0.2	
VML0501	200	LOG	Al	52		AS PER CX B-HNH DEFERRAL REPO	RT ITEM SADD S171: ALL PAX DOORS EXCEPT DOORS 1L AND 1R DEACTIVATED.	L050	OPEN	09/25/2023	
	CAB					(PLS REF TO ATTACHED "CX DEFERF	RAL REPORT" FOR REQUIRED ACTION ITEMS)	2000	OI LIV	0.0	
						1C 1 PLS MAKE LOG BOOK	KENTRY.			0.2	
									-	0.2	
VML0519	200	LOG	LOG AI	G AI	52		AS PER CX B-HNH DEFERRAL REPO	RT ITEM SADD S172: REF WO 9513408/1 PN:4A3795-1. SN:KD597N0821 REPLACE	L051	OPEN	09/25/2023
	CAB		7 11	32		RH OVERWING SLIDE RESERVOIR.(P	LS REF TO ATTACHED "CX DEFERRAL REPORT" FOR REQUIRED ACTION ITEMS)	2001	01 211	0.0	
						1C 1 PLS MAKE LOG BOOK	KENTRY.			0.2	
									-	0.2	
VML0527	100	LOG	Al	26		AS PER CX B-HNH DEFERRAL REPO	RT ITEM SADD S173: REF WO 9513415/1 PN: 473876-3. SN:2657SEL REPLACE	L052	OPEN	09/25/2023	
	LWR						TRIDGES. (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR REQUIRED	2002	01 211	0.0	
						ACTION ITEMS)  1C 1 PLS MAKE LOG BOOK	KENTRY.			0.2	
									-	0.2	
VML0535	200	LOG	AI	26		AC DED CV D UNU DECEDDAL DEDOL	RT ITEM SADD S174: REF WO 9513416/1 PN:473876-3. SN:2127BA REPLACE		0.0511		
VIVILUSSS	CAB	LOG	AI	20			TRIDGES (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR REQUIRED	L053	OPEN	09/25/2023	
	0,10					ACTION ITEMS)	( ENTDY			0.0	
						1C 1 PLS MAKE LOG BOOK	AENIKI.		_	0.2	
										0.2	

ORIGINATING CUST REF NO:

588486

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

## TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 10 OF 23 RUN DATE: 9/28/2023

RUN TIME: 9:19

PROJECT: VM CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-HNH CHECK TYPE: 3C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE : ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE : TYPE CODE: ORIGINATOR · ALL

CTRL CODE :	ZONE	STC			TYPE CODE:	ORIGINATOR :	ALL		STATUS	UPDATED DAT										
JOB NO	AREA	316	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr										
/ML0543	400 ENG	LOG	AE	72		MODIFICATION AS PER AEO-25355 PA BE ON BOARD DURING THE FERRY FL	T ITEM SADD S176: LH ENG LH FAN DUCT PN:315W5295-61.SN:000332 PERFORM RT 1 NO LATER THAN 6 FC FROM APRIL 6,2022.NO PASSENGER IS ALLOWED TO IGHT WITHIN THESE 6 FC.AFTER EMBODIMENT OF THE MODIFICATION ASPER S (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR REQUIRED ACTION	L054	OPEN	09/25/2023										
						•	AGAINST THIS AEO PART 5. ENTRY.		-	0.0 0.2 										
ML0550 400 I ENG	LOG	AE	72		PART 3 NO LATER THAN 6 FC FROM A FERRY FLIGHT WITHIN THESE 6 FC.AF	T ITEM SADD S178: RH ENG LH FAN DUCT PN:315W5295-75 SN:000369.25355 PRIL 6,2022.NO PASSENGER IS ALLOWED TO BE ON BOARD DURING THE **TER EMBODIMENT OF THE MODIFICATION AS PER AEO-25355 PART 3,CLEAR RT 7 (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR REQUIRED ACTION	L055	OPEN	09/25/2023											
						1C 1 PLS MAKE LOG BOOK	ENTRY.		-	0.2										
ML0568	400 ENG	LOG	AE	72		PN:315W5317-4H.SN:000030.PERFORM 6,2022.NO PASSENGER IS ALLOWED 1	T ITEM SADD S180:RH ENG RH FAN DUCT I MODIFICATION AS PER AEO25355 PART 4 NO LATER THAN 6 FC FROM APRIL TO BE ONBOARD DURING THE FERRY FLIGHT WITHIN THESE 6 FC.AFTER AS PER AEO 25355 PART 4, CONTINUE TO SWS (PLS REF TO ATTACHED "CX ACTION ITEMS)	L056	OPEN	09/25/2023										
				S 25	SS 25			ED AGAINST THIS AEO PART 8.		-	0.0 0.2 									
ML0576	200 CAB	LOG	SS	SS	SS	SS	SS 25	3 25	25	25	25		THE CAPTAINS SEAT NO LATER THAN WITH NO PASSENGERS ON BOARD AF AEO-27669 PART 1,CONTINUE TO SWS	T ITEM SADD S181: PERFORM AEO-27666 PART 1, AND AEO-27669 PART 1 FOR 6 FC, AFTER OCT 7,2022, UNTIL DEC 31,2024. THE 6 FC WILL BE FERRY FLIGHTS TER EMBODIMENT OF THE MODIFICATION AS PER AEO-27666 PART 1,AND 6 (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR REQUIRED ACTION	L057	OPEN	0.2			
						ITEMS) 1C 1 CLEAR SADD RAISED 1C 2 PLS MAKE LOG BOOK	AGAINST AEO PART 1. ENTRY.		-	0.0 0.2										
ML0584 200 CAB		LOG	SS	SS 25	SS 25	SS 25	SS 25	SS 25	SS 25	SS 25	S 25	25	25	25	25	THE FIRST OFFICERS SEAT NO LATER CYCLES WILL BE FERRY FLIGHTS WIT	T ITEM SADD S182: PERFORM AEO-27666 PART 2 AND AEO-27669 PART 2 FOR R THAN 6 FC AFTER OCTOBER 7,2022,UNTIL DECEMBER 31,2024.THE 6 FLIGHT TH NO PASSENGERS ON BOARD.AFTER EMBODIMENT OFTHE MODIFICATION AS SWS (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR REQUIRED ACTION	L058	OPEN	0.2 09/25/2023 0.0
						ITEMS)  1 C 1 AND AEO-27669 PART CL5146 BY SYSTEM.	2, CLEAR SADD RAISED AGAINST THIS AEO PART 1. TRANSFERRED FROM CABIN LOG			0.0										
						1C 2 PLS MAKE LOG BOOK	ENTRY.			0.2										

## TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

11 OF 23 PAGE: RUN DATE: 9/28/2023

RUN TIME: 9:19

PROJECT: VM

CUSTOMER: CX

A/C TYPE: 777

A/C REGN: B-HNH

CHECK TYPE: 3C

ESTIMATED MHR: ALL

JSN RANGE SELECTED: ALL ORIGINATING CUST REF NO: ALL

ATA NO: ALL

ORIG-STAGE: ALL

ORIGINATOR: ALL

PERIOD: ALL ZONE: ALL

DISPOSITION CODE: ALL

DEFECT TYPE : ALL

CTRL CODE:

REQUESTED BY:

REFERENCE NO:

588486

BMS571R1-2

TRADE: ALL

STATUS: ALL

TYPE CODE:

CUST ENDORSE: ALL

AREA: ALL STAGE: ALL

OTTAL GODE :					111 2 0002.	Ortionation: ALL			STATUS	UPDATED DATE														
IOD NO		STG	TD	A T A	ODIO CUCT DEE NO	CTDL CLINO	DEFECT DESCRIPTION	ICNI																
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr														
VML0592	200 CAB	LOG	Al	25		WITHIN 5 FC OR 25FH, WHICHEVER OCCURS FI	ADD S183: ACCOMPLISH AMS TASK 28-AWL-01& AMS TASK 28-AWL-03 RST,AFTER STORAGE REACTIVATION FOR THE FERRY FLIGHT FROM	L059	OPEN	09/25/2023														
							RAFT WILL BE PERFORMING BASE MAINTENANCE CHECK.UNTIL THEN PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR REQUIRED																	
						,	RE ALLOWED. THE CENTER TANK MUST NOT BE REFUELLED DURING THE PERIOD.			0.0														
						1C 2 PLS MAKE LOG BOOK ENTRY.				0.2														
									-	0.2														
VML0600	100	LOG	Al	38			ADD \$184: BOTTLE WATER UPLIFT REQUIRED POTABLE WATER	L060	OPEN	09/25/2023														
	LWR						N HKG.DO NOT USE POTABLE WATER FOR BEVERAGE.TOILET FLUSH IED "CX DEFERRAL REPORT" FOR REQUIRED ACTION ITEMS)			0.0														
						1C 1 PLS MAKE LOG BOOK ENTRY.				0.2														
									-	0.2														
VML0618	100	LOG	ΑE	53		AS PER CX B-HNH DEFERRAL REPORT ITEM S	ADD S185: EXTERNAL GROUND POWER RECEPTICAL ACCESS PANEL	L061	OPEN	09/25/2023														
	FUS					NOT FLUSH WTH FUSELARGE SKIN. (PLS REF TITEMS)	TO ATTACHED "CX DEFERRAL REPORT" FOR REQUIRED ACTION			0.0														
						1C 1 PLS MAKE LOG BOOK ENTRY.				0.2														
									-	0.2														
VML0626	200	LOG	Al	52		AS PER CX B-HNH DEFERRAL REPORT ITEM S	ADD S186: REF WO 9513406/1 REPLACE DOOR L4 SLIDE RAFT	L062	OPEN	09/25/2023														
	CAB					PN:63604-331. SN: 0545. (PLS REF TO ATTACHE	D "CX DEFERRAL REPORT" FOR REQUIRED ACTION ITEMS)			0.0														
																				1C 1 PLS MAKE LOG BOOK ENTRY.				0.2
									-	0.2														
VML0634	200	LOG	Al	AI 52	AI 52	AI 52	AI 52	AI 52	AI 52	AI 52	AI 52	AI 52	52		AS PER CX B-HNH DEFERRAL REPORT ITEM S	ADD S187: REF WO 9513410/1 REPLACE DOOR L5 SLIDE RAFT.	L063	OPEN	09/25/2023					
	CAB					PN:62774-415. SN:1090. (PLS REF TO ATTACHE	D "CX DEFERRAL REPORT" FOR REQUIRED ACTION ITEMS)			0.0														
						1C 1 PLS MAKE LOG BOOK ENTRY.				0.2														
									-	0.2														
VML0642	200	LOG	Al	52			ADD S188: L2 DOOR SLIDE ROBBED TO SERVICE DOOR L1.(PLS REF TO	L064	OPEN	09/25/2023														
	CAB					ATTACHED "CX DEFERRAL REPORT" FOR REQ	UIRED ACTION TIEMS)			0.0														
						1C 1 PLS MAKE LOG BOOK ENTRY.				0.2														
									-	0.2														
VML0659	200	LOG	Al	52			ADD S191: REF WO 9513407/1 REPLACE R2 DOORSLIDE RAFT.	L065	OPEN	09/25/2023														
	CAB					PN:62771-128. SN:1949. (PLS REF TO ATTACHE	D "CX DEFERRAL REPORT" FOR REQUIRED ACTION ITEMS)			0.0														
						1C 1 PLS MAKE LOG BOOK ENTRY.				0.2														
									-	0.2														

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

12 OF 23 PAGE:

RUN DATE: 9/28/2023

RUN TIME: 9:19

PROJECT: VM CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-HNH CHECK TYPE: 3C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL

588486

BMS571R1-2

ATA NO: ALL

ZONE: ALL

AREA: ALL

DISPOSITION CODE: ALL

DEFECT TYPE : ALL

TRADE: ALL

CUST ENDORSE: ALL

STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

) THE OODE :	ZONE	STG			711 E 00BE.	ordonation. A			STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
VML0667	200 CAB	LOG	Al	52			M SADD S192: REF WO 9513411/1 REPLACE R4 DOOR SLIDE RAFT. :HED "CX DEFERRAL REPORT" FOR REQUIRED ACTION ITEMS)	L066	OPEN	09/25/2023
						1C 1 PLS MAKE LOG BOOK ENT	RY.			0.0
									-	0.2
/ML0675	200	LOG	Al	52			M SADD S193: REF WO 9513413/1 REPLACE R5 DOOR ESCAPE SLIDE :HED "CX DEFERRAL REPORT" FOR REQUIRED ACTION ITEMS)	L067	OPEN	09/25/2023
	CAB					V	,			0.0
						1C 1 PLS MAKE LOG BOOK ENT	RY.		_	0.2
										0.2
ML0683	200 CAB	LOG	Al	52			M SADD S194: REF WO 9513409/1 REPLACE RH OVERWING EMERGENCY O ATTACHED "CX DEFERRAL REPORT" FOR REQUIRED ACTION ITEMS)	L068	OPEN	09/25/2023
	0.12					1C 1 PLS MAKE LOG BOOK ENT	RY.			0.0 0.2
									-	0.2
ML0691	200	LOG	Al	52			M SADD S195: LH OVERWING SLIDE WAS ROBBED TO SERVICE ANOTHER	L069	OPEN	09/25/2023
	CAB					CX AIRCRAFT BY CX REQUEST. (PLS REF 1	O ATTACHED "CX DEFERRAL REPORT" FOR REQUIRED ACTION ITEMS)			0.0
						1C 1 PLS MAKE LOG BOOK ENT	RY.			0.2
									-	0.2
ML0709	500	LOG	AE	57			M SADD S196: RH WING FIXED LE NACELLE INTERFACE PANEL HAS TWO PER RS 34497.PERFORM PERMANENT REPAIR WITHIN 5FC /23596 TFC	L070	OPEN	09/25/2023
	WNG					LIMIT. (PLS REF TO ATTACHED "CX DEFERI	RAL REPORT" FOR REQUIRED ACTION ITEMS)			0.0 0.2
						1C 1 PLS MAKE LOG BOOK ENT	χγ.		-	
ML0717	400	LOG	ΑE	72		AS PER CX R-HNH DEFERRAL REPORT ITE	M SADD S197: LH ENG LH FAN DUCT PN:315W5295-61.SN:000332 CARRY	L071	OPEN	0.2
	ENG	200	,,_			OUT GENERAL VISUAL INSPECTION ON TR	HALF THERMAL BLANKETS TO ENSURE THERE IS NO DAMAGE OR ANY	LUTI	OPEN	0.0
						DEFERRAL REPORT" FOR REQUIRED ACTION	IE THRUST REVERSER AT EVERY 1 FC (PLS REF TO ATTACHED "CX ON ITEMS)			
						1C 1 PLS MAKE LOG BOOK ENT	RY.		_	0.2
										0.2
ML0725	400 ENG	LOG	AE	72			M SADD S198: RH ENG RH FAN DUCT PN:315W5317-4H.SN:000030 CARRY E TR HALF THERMAL BLANKETS TO ENSURE THERE IS NO DAMAGE OR	L072	OPEN	09/25/2023
	2.10					OUT GENERAL VISUAL INSPECTION ON THE TR HALF THERMAL BLANKETS TO ENSURE THERE IS NO DAMAGE OR ANY SIGN OF ENGINE FIREWALL BREACH TO THRUST REVERSER AT EVERY 1 FC (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR REQUIRED ACTION ITEMS)			0.0	
						1C 1 PLS MAKE LOG BOOK ENT	,			0.2
									-	0.2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

CHECK TYPE:

ZONE: ALL

AREA: ALL

3C

DISPOSITION CODE: ALL

STAGE: ALL

13 OF 23 PAGE: RUN DATE: 9/28/2023

RUN TIME: 9:19

0.0

PROJECT: VM CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-HNH

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ATA NO: ALL

ORIGINATING CUST REF NO: ALL

588486

BMS571R1-2

TRADE: ALL CUST ENDORSE: ALL

DEFECT TYPE : ALL

OTDL CODE	L. /\L	-			TV052 . 7.2.	-	ODICINATOR ALL	ANCA: ALL	OTAGE. ALL			
CTRL CODE	: ZONE	CTC			TYPE CODE:		ORIGINATOR: ALL				STATUS	UPDATED DATE
JOB NO	AREA	316	TD	ATA	ORIG CUST REF NO.	CTRL SH NO		DEFECT DESCRIPTION		JSN	STATUS	EST Mhr
VML0733	400	LOG	AE	72		AS PER CX B-H	NH DEFERRAL REPORT ITEM SADD S199: I	RH ENG LH FAN DUCT PN:315W5295-75.SN:000369 C/	RRY	L073	OPEN	09/25/2023
	ENG					ENGINE FIREWA		IKETS TO ENSURE THERE IS NO DAMAGE OR ANY S IT EVERY 1 FC. (PLS REF TO ATTACHED "CX DEFERI THE THE THE THE THE THE THE THE THE THE				0.0
							PLS MAKE LOG BOOK ENTRY.					0.2
												0.2
VML0741	400	LOG	AE	72				ENG NO.2 INLET COWL CORROSION ON THE EXISTIN		L074	OPEN	09/25/2023
	ENG					DOUBLER AND ACTION ITEMS)	LIP SKIN AT 6 O'CLOCK POSITION (PLS REF	TO ATTACHED "CX DEFERRAL REPORT" FOR REQU	IRED			0.0
						,	PLS MAKE LOG BOOK ENTRY.					0.2
											•	0.2
VML0758	700	LOG	AE	12			= =	MAINT ENTRY TRANSFER FROM ELOG TL4705 S152 (		L075	OPEN	09/25/2023
	LDG						IING GEAR SHOCK STRUT PRESSURE CHE DEFERRAL REPORT" FOR REQUIRED ACTI	CK AFTER FIVE TO TEN IN SERVICE LANDINGS (PLS ON ITEMS)	REF TO			0.0
						1C 1	PLS MAKE LOG BOOK ENTRY.	,				0.2
												0.2
VML0766	700	LOG	AE	12				MAINT ENTRY TRANSFER FROM ELOG TL4703 S151 ( ECK AFTER FIVE TO TEN IN SERVICE LANDINGS(PLS		L076	OPEN	09/25/2023
	LDG						DEFERRAL REPORT" FOR REQUIRED ACTI	,	REF TO			0.0
						1C 1	PLS MAKE LOG BOOK ENTRY.					0.2
											•	0.2
VML0774	200	LOG	AV	31				ROUND CREW NTC001: AEO-29174/SB 777-31A0342 OCK POINT V17C INTRODUCTION". THIS NTC IS VAL	D	L077	OPEN	09/25/2023
	CAB						PGRADE COMPLETED.	OCK POINT VITC INTRODUCTION . THIS NTC IS VAL	D			0.0
												0.0
VML0782	100	LOG	AE	22				ROUND CREW NTC002: SB 777-22A0046/AEO-29595		L078	OPEN	09/25/2023
	FUS							S SB CANCELS FCOM OMB CAT-136 ERRONEOUS AF IS NTC IS VALID UNTIL 1 MONTH AFTER ALL AIRCRA				0.0
												0.0
VML0790	400	LOG	AE	79				ROUND CREW NTC003: THE ENGINE OIL TYPE ON T		L079	OPEN	09/25/2023
	ENG					MAIN ENGINE H	AS BEEN CHANGED FROM MOBIL JET II TO	ETO 2197 POST THE ACCOMPLISHMENT OF AEO-25	939.			0.0

588486

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

14 OF 23 PAGE:

RUN DATE: 9/28/2023

RUN TIME: 9:19

PROJECT: VM CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-HNH CHECK TYPE: 3C

ESTIMATED MHR: ALL

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ORIGINATING CUST REF NO: ATA NO: ALL ZONE: ALL ALL

DISPOSITION CODE: ALL

TRADE: ALL DEFECT TYPE : ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

CIRL CODE :					TYPE CODE:	ORIGINATOR:	ALL		0747110	
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
VML0808	200 CAB	LOG	Al	56			E TO FLIGHT AND GROUND CREW NTC004: SMALL BUBBLE IN L2 WINDOW, ONT. IT IS WITHIN LIMIT AS PER AMM 56-11-00-200-802 AND VISIBILITY NOT	L080	OPEN -	09/25/2023 0.0
VML0816	100 FUS	LOG	AE	46		ETECHLOG AS THE MASTER MAINTEN	E TO FLIGHT AND GROUND CREW NTC005: THIS AIRCRAFT IS FITTED WITH THE ANCE RECORD.THE IPAD EFB DEVICE IS STORED IN THE AML/CDML. THE ARD AS A BACKUP ONLY. COMPLY 365 IS INSTALLED IN BOTH FLIGHT DECK NAL MANUALS.	L081	OPEN -	09/25/2023
VML0824	100 FUS	LOG	AE	28		BEEN MIGRATED FROM PAPER TO E-T	E TO FLIGHT AND GROUND CREW NTC006: "ACTIVE NTC/NTCC ENTRIES HAVE ECHLOG WHICH IS NOW THE PRIMARY MEANS TO CONSULT NTC/NTCC ON AMIL/CDML SHALL BE USED DURING PAPER FALLBACK ONLY.(REF:	L082	OPEN -	0.0 09/25/2023 0.0
VML0832	200 CAB	LOG	AV	30		REPORTED BY PAX,REFER TO GOGO S SYSTEMS ARE ONLINE AND NO RESET THE GOGO SYSTEM HEALTH APP AND 1C 1 IF RED AND AMBER IS	E TO CABIN AND GROUND CREW NTCC501:WHEN WI-FI CONNECTIVITY ISSUE SYSTEM HEALTH APP ON SCCW/SP TABLET.GREEN BAR INDICATES ALL REQUIRED.REPORT THE CONNECTIVITY ISSUE WITH SPECIFIC DETAIL VIA FLIGHT JOURNAL.DO NOT RAISE ECABIN LOG ENTRY. CONTINUE TO SWS SHOWN ON THE GOGO SYSTEM HEALTH APP, FOLLOW THE INSTRUCTION SHOWN IN THE RIMED OR WI-FI CONNECTIVITY UNSERVICEABLE THROUGHOUT THE FLIGHT, RAISE ECABIN TENANCE ACTION.	L083	OPEN	09/26/2023 0.0 0.0
VML0840	200 CAB	LOG	SS	25		HNH-CMC-140313-01) ECONOMY SEAT(	E TO CABIN AND GROUND CREW NTCC001: PER CX REQUEST(WORK ORDER ARIES) MEAL TABLE ARE SUFFERING FROM UPPER SURFACE DELAMINATION VEALS ON REGIONAL SECTORS. UNTIL THE MEAL SERVICE IS REVISED. THERE MEAL TABLE DELAMINATION.	L084	OPEN -	0.0 09/26/2023 0.0
VML0857	200 CAB	LOG	Al	25		THE ETECHLOG AS THE MASTER MAIN	E TO CABIN AND GROUND CREW NTCC002: THIS AIRCRAFT IS FITTED WITH TENANCE RECORD. THE IPAD EFB DEVICE IS STORED IN THE AML/CDML. THE ARD AS A BACKUP ONLY. COMPLY 365 IS INSTALLED IN BOTH FLIGHT DECK NAL MANUALS.	L085	OPEN -	0.0 09/26/2023 0.0
VML0865	200 CAB	LOG	Al	25		BEEN MIGRATED FROM PAPER TO E-T	E TO CABIN AND GROUND CREW NTCC003: "ACTIVE NTC/NTCC ENTRIES HAVE ECHLOG WHICH IS NOW THE PRIMARY MEANS TO CONSULT NTC/NTCC ON N AML/CDML SHALL BE USED DURING PAPER FALLBACK ONLY.(REF:	L086	OPEN -	0.0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 15 OF 23 RUN DATE: 9/28/2023

RUN TIME: 9:19

102.0

PROJECT: VM

CUSTOMER: CX

A/C TYPE: 777

A/C REGN: B-HNH

CHECK TYPE: 3C

ESTIMATED MHR: ALL

JSN RANGE SELECTED: ALL ORIGINATING CUST REF NO: ALL

ATA NO: ALL

PERIOD: ALL ZONE: ALL

DISPOSITION CODE: ALL

DEFECT TYPE: ALL

588486

BMS571R1-2

TRADE: ALL

STATUS: ALL

CUST ENDORSE: ALL

ORIG-STAGE: ALL

AREA: ALL STAGE: ALL

CTRL CODE :					TYPE CODE:	ORIGINATOR: ALL			
100 110	ZONE	STG			0010 0110T DEE 110	OTEL SULVI	1011	STATUS	UPDATED DATE
JOB NO	AREA	041	TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
/ML0873	200 CAB	CAN	Al	25		REFER TO CANNIBALIZATION FORM VM002- REMOVE 1EA CABLE P/N:1611025-02 ON R3 OFF-WING SLIDE FROM B-HNH TO SUPPORT B-HNX.	L087	OPEN	09/26/2023
	CAB								0.0
								-	0.0
/ML0881	200	NRW	AV	2330	SWC-28778-01-01	ON CHECK FOUND BELOW IFE MONITOR TOUCH SCREEN MALFUCTION AT:	L088	WIP	09/27/2023
	CAB					39E,39F,40F,40J,40K,41C,41D,41E,41F,41G,41H,41K,42D,43B,43D,43E,43F,43G,43J,44A,44H,45F,45G,45H,46A,46C,46H,46J .46K.47B.47G.47H.48H.48J.49B.49C.49K			0.0
						1C 1 PLEASE REMOVE SEAT CUSHION			10.0
						1C 2 REMOVE THE DEFECTIVE MONITOR AND RETURN TO STORE FOR SHOP REPAIR			36.0
						1C 3 INSTALL NEW MONITOR AND PERFORM IFE INDIVIDUAL SYSTEM TEST			40.0
						1C 4 INSTALL SEAT CUSHION			12.0
								-	98.0
ML0899	200	NRW	AV	2330	SWC-28778-01-01	ON CHECK FOUND BELOW IFE MONITOR TOUCH SCREEN MALFUCTION AT:	L089	WIP	09/27/2023
	CAB					50C,51A,51C,51D,51F,51J,51J,52A,52B,52F,52J,52J,53D,54A,54B,54D,54H,55A,55C,55G,55H,55K,56E,56K,57C,57D,57E,57K,	L003	VVII	
CAB					58A,58D,58F,59A,59C,59D			0.0	
						1C 1 PLEASE REMOVE SEAT CUSHION			10.0
						1C 2 REMOVE THE DEFECTIVE MONITOR AND RETURN TO STORE FOR SHOP REPAIR			34.0
						1C 3 INSTALL NEW MONITOR AND PERFORM IFE INDIVIDUAL SYSTEM TEST			38.0
						1C 4 INSTALL SEAT CUSHION			12.0
								-	94.0
ML0907	200	NRW	AV	2330	SWC-28778-01-01	ON CHECK FOUND BELOW IFE MONITOR TOUCH SCREEN MALFUCTION AT:	L090	WIP	09/27/2023
	CAB					60C,60E,60J,61F,61G,63A,63F,63K,64A,64B,65G,65H,65J,66B,66J,66K,67D,67F,68A,68B,68E,69B,69C,69E,69H			0.0
						1C 1 PLEASE REMOVE SEAT CUSHION			10.0
						1C 2 REMOVE THE DEFECTIVE MONITOR AND RETURN TO STORE FOR SHOP REPAIR			25.0
						1C 3 INSTALL NEW MONITOR AND PERFORM IFE INDIVIDUAL SYSTEM TEST			28.0
						1C 4 INSTALL SEAT CUSHION			12.0
								-	75.0
ML0915	200	NRW	AV	2330	SWC-28778-01-01	ON CHECK FOUND BELOW IFE MONITOR TOUCH SCREEN MALFUCTION AT:	L091	WIP	09/27/2023
	CAB					71B,71D,71E,71G,71J,72A,72E,72E,72F,72F,73A,73E,73E,73H,73J,74E,74E,74F,74F,74H,75A,75C,75E,75E,75H,76A,76B,76E,	L031	VVII	
	0, 12					76G,76H,77E,77G,78E,78G,78K,79C,79D,80E			0.0
						1C 1 PLEASE REMOVE SEAT CUSHION			10.0
						1C 2 REMOVE THE DEFECTIVE MONITOR AND RETURN TO STORE FOR SHOP REPAIR			38.0
						1C 3 INSTALL NEW MONITOR AND PERFORM IFE INDIVIDUAL SYSTEM TEST			42.0
						1C 4 INSTALL SEAT CUSHION			12.0
								-	

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 16 OF 23

RUN DATE: 9/28/2023

RUN TIME: 9:19

PROJECT: VM CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-HNH CHECK TYPE: 3C

JSN RANGE SELECTED: ALL

588486

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

CUST ENDORSE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

ALL

ATA NO: ALL

ZONE: ALL

DISPOSITION CODE: ALL

STAGE: ALL

DEFECT TYPE: ALL

TRADE: ALL

AREA: ALL

CTRL CODE:					TYPE CODE:	ORIGINATOR	: ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
VML0923	200	NRC	Al	3800	777-53-676-00-01	M/D LAV C WATER FAUCET FOUND	LEAKING	L092	OPEN	09/26/2023
	CAB									4.0
									-	4.0
VML0931	200	NRC	Al	3800	777-53-676-00-01	M/D LAV E WATER FAUCET FOUND	LEAKING	L093	OPEN	09/26/2023
VIVI20001	CAB	11110	7 (1	0000	777 00 070 00 07	WID DIV E WATERTAGOETT COND	LL/ WING	L093	OPEN	
										4.0
									-	4.0
VML0949	200	NRR	ΑI	3800	777-C254000-01-08-	M/D LAV F WATER FAUCET FOUND	LEAKING	L094	OPEN	09/26/2023
	CAB				01					4.0
									-	
										4.0
VML0956	200	NRC	Al	3800	777-53-676-00-01	M/D GLY G1 WATER FILTER CARTR	RIDGE PACKING FOUND BROKEN	L095	OPEN	09/26/2023
	CAB									1.0
									-	1.0
VML0964	200	NRC	ΑI	25	777-53-676-00-01	M/D GLY G212 DRAWER PNL FOUN	D DETACHED	L096	OPEN	09/26/2023
	CAB							2000	0. 2	4.0
									_	
										4.0
VML0972	200	NRR	SS	2500	777-53-906-00-01	CAB - B/E SEAT BACK AISLE AREA	TEDLAR FOUND TORN AT: 17G 16G 15G 14G 12G 14K 15K 18K TOTAL 8 EA	L097	OPEN	09/27/2023
	CAB									0.0
						1C 1 REMOVE BC SEAT	AISLE S/W ENP CAP AT 17G 16G 15G 14G 12G 14K 15K 18K			2.0
						1C 2 BC SEAT AISLE S/W	/ TEDLAR REPLACE AT 17G 16G 15G 14G 12G 12K 15K 18K			80.0
						1C 3 REINSTALL BC SEA	T AISLE S/W ENDCAP AT 17G 16G 15G 14G 12G 14K 15K 18K			2.0
						1C 4 REMOVE BC SEAT	AISLE S/W TV AT 17G 16G 15G 14G 12G 14K 15K 18K			2.0
						2C 5 REINSTALL BC SEA	T AISLE S/W TV AT 17G 16G 15G 14G 12G 14K 15K 18K			2.0
									-	88.0

588486

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

AREA: ALL

STAGE: ALL

17 OF 23 PAGE: RUN DATE: 9/28/2023

RUN TIME: 9:19

PROJECT: VM CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-HNH CHECK TYPE: 3C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL ALL

DEFECT TYPE : ALL TRADE: ALL CUST ENDORSE: ALL

CTRL CODE :	TYPE CODE:	ORIGINATOR: ALL	
			CTAT

CTRL CODE :					TYPE CODE:	ORIGINATOR: ALL				
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
VML0980	200	NRR	SS	2500	777-53-910-00-01	CABIN #2 DOOR G3 GLY L/H AISLE S/W FOUND SCRATCHED		L098	OPEN	09/27/2023
	CAB									0.0
						1C 1 REMOVE G3 GLY LHS AISLE PNL				0.5
						1C 2 REMOVE G2 GLY LHS AISLE PNL				0.5
						1C 3 REMOVE G3 GLY LHS AISLE LIGHT				0.5
						1C 4 REMOVE G2 GLY RHS AISLE LIGHT				0.5
						2C 5 G3 GLY LHS AISLE TEDLAR REPLACE				11.0
						2C 6 G2 GLY LHS AISLE TEDLAR REPLACE				11.0
						2C 7 REINSTALL G3 GLY LHS AISLE PNL				0.5
						2C 8 REINSTALL G2 GLY LHS AISLE PNL				0.5
						3C 9 REINSTALL G3 GLY LHS AISLE LIGHT				0.5
						3C 10 REINSTALL G2 GLY LHS AISLE LIGHT				0.5
									-	26.0
VML0998	200	NRR	SS	2500	777-53-910-00-01	CABIN #2 DOOR G2 GLY L/H AISLE S/W FOUND SCRATCHED		L099	OPEN	09/27/2023
	CAB									0.0
									-	0.0
VML1004	200	NRR	SS	2500	777-53-906-00-01	CABIN #1 DOOR G1 GLY L/H AISLE S/W FOUND SCRATCHED		L100	OPEN	09/27/2023
	CAB									0.0
						1C 1 REMOVE G1 GLY LHS AISLE PNL				0.5
						1C 2 REMOVE G1 GLY LHS AISLE LIGHT				0.5
						1C 3 G1 GLY LHS AISLE TEDLAR REPLACE				11.0
						1C 4 REINSTALL G1 GLY LHS AISLE PNL				0.5
						2C 5 REINSTALL G1 GLY LHS AISLE LIGHT				0.5
									-	13.0
VML1012	200	NRR	SS	2500	777-53-910-00-01	CAB-G2 GLY G204 COMPT DR TEDLAR FND DENT.		L101	OPEN	09/27/2023
	CAB									6.0
									-	6.0
VML1020	200	NRC	Al	25	777-53-676-00-01	M/D FWD ZONE CLOSET C21 C22 DOOR LATCH FOUND LOOS	SEN	L102	OPEN	09/27/2023
	CAB									2.0
									-	2.0
VML1038	200	NRC	Al	25	777-53-676-00-01	M/D FWD ZONE CLOSET C11 DOOR LOWER TRIM HOLE FOU	ND ELONGATED	L103	OPEN	09/27/2023
	CAB									4.0
									-	4.0

588486

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 18 OF 23 RUN DATE: 9/28/2023

RUN TIME: 9:19

PROJECT: VM CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-HNH CHECK TYPE: 3C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL ZONE : ALL DISPOSITION CODE : ALL

DEFECT TYPE : ALL TRADE : ALL CUST ENDORSE : ALL AREA : ALL STAGE : ALL

CTRL CODE : TYPE CODE: ORIGINATOR : ALL

	ZONE	STG			2 0052.		· · · · ·		STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
VML1046	200	NRC	Al	25	777-53-676-00-01	M/D FWD ZONE CLOSET C11 COMPAR	TMENT INSIDE WIRE COVER FOUND MISSING	L104	OPEN	09/27/2023
	CAB									1.0
									-	1.0
/ML1053	200	NRC	Al	25	777-53-676-00-01	M/D FWD ZONE GLY&LAV& CLOSET AF	T PARTITION AREA LITERATURE POCKET FOUND POOR CONDITION TTL:7EA	L105	OPEN	09/27/2023
	CAB									7.0
									-	7.0
/ML1061	200	NRC	Al	25	777-53-676-00-01	M/D FWD ZONE GLY G1C AFT PARTITION	ON R/H LOWER AREA TEDLAR FOUND DENT	L106	OPEN	09/27/2023
	CAB									2.0
									-	2.0
ML1079	200	NRC	Al	25	777-53-676-00-01	M/D FWD ZONE GLY G1 COUNTER HOT	CUP AFT PARTITION AREA TEDLAR FOUND DENT	L107	OPEN	09/27/2023
	CAB									2.0
									-	2.0
ML1087	200	NRC	Al	25	777-53-676-00-01	M/D FWD ZONE GLY G1C COUNTER AN	ID COMPARTMENT AREA PLACARD FOUND WORN	L108	OPEN	09/27/2023
	CAB									4.0
									-	4.0
ML1095	200	NRC	Al	25	777-53-676-00-01	M/D FWD ZONE GLY G1 COUNTER AND	COMPARTMENT AREA PLACARD FOUND WORN	L109	OPEN	09/27/2023
	CAB									4.0
									-	4.0
ML1103	200	NRC	Al	25	777-53-676-00-01	M/D FWD ZONE GLY G1C C111 C112 C1	13 C114 C1040COMPARTMENT AREA TURN-RETAINER FOUND WEAK TTL:9EA	L110	OPEN	09/27/2023
	CAB									4.0
									-	4.0
ML1111	200	NRC	Al	25	777-53-676-00-01	M/D FWD ZONE GLY G1C C114 DRAWE	R SLIDING TRACK FOUND WEAK	L111	OPEN	09/27/2023
	CAB									2.0
									-	2.0
ML1129	200	NRC	Al	25	777-53-676-00-01	M/D FWD ZONE GLY G1C C114 DRAWE	R DOOR FOUND DETACHED	L112	OPEN	09/27/2023
	CAB							<b>_</b>		2.0
									-	2.0
										2.0

588486

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

DEFECT TYPE: ALL

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

AREA: ALL

STAGE: ALL

PAGE: 19 OF 23 RUN DATE: 9/28/2023

RUN TIME: 9:19

PROJECT: VM CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-HNH CHECK TYPE: 3C

STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL JSN RANGE SELECTED: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL ALL CUST ENDORSE: ALL

CTRL CODE : TYPE CODE: ORIGINATOR · ALL

TRADE: ALL

CTRL CODE :					TYPE CODE:	ORIGINATOR: AL	L			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
VML1137	200	NRR	Al	25	777-52-840-02-01	M/D R2 DOOR HINGE ARM FLAP DOOR WHI	TE PLASTIC BLOCK STOP FND MISSING	L113	OPEN	09/27/2023
	CAB									0.5
										0.5
VML1145	200	NRC	ΑI	25	777-53-679-00-01	M/D G7 GLY FAUCET FND WATER LEAKAGE		L114	OPEN	09/27/2023
	CAB									3.0
										3.0
VML1152	200	NRC	Al	25	777-53-676-00-01	M/D FWD ZONE GLY G1&G1C COMPARTME	NT AREA SCREW FOUND WORN	L115	OPEN	09/27/2023
	CAB									2.0
										2.0
VML1160	200	NRC	Al	25	777-53-676-00-01	M/D FWD ZONE GLY G1C WASTE CONTAINE	ER FOUND TORN	L116	OPEN	09/27/2023
	CAB									2.0
										2.0
VML1178	200	NRC	SM	25	777-53-676-00-01	M/D FWD ZONE GLY G1C WASTE COMPART	MENT UPPER TRIM AND SEAL FOUND MISSING	L117	OPEN	09/27/2023
	CAB									2.0
										2.0
VML1186	200	NRC	SM	25	777-53-676-00-01	M/D FWD ZONE GLY G1 WASTE COMPARTM	MENT UPPER SEAL FOUND MISSING	L118	OPEN	09/27/2023
	CAB									2.0
										2.0
VML1194	200	NRC	Al	25	777-53-676-00-01	M/D FWD ZONE GLY G1C WASTE COMPART	MENT FLAP DOOR FOUND MIS-ALIGN	L119	OPEN	09/27/2023
	CAB									2.0
										2.0

588486

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

DEFECT TYPE: ALL

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

AREA: ALL

PAGE: 20 OF 23 RUN DATE: 9/28/2023

STAGE: ALL

RUN TIME: 9:19

PROJECT: VM CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-HNH CHECK TYPE: 3C

STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL JSN RANGE SELECTED: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL ALL CUST ENDORSE: ALL

CTRL CODE : TYPE CODE: ORIGINATOR · ALL

TRADE: ALL

CTRL CODE :	:				TYPE CODE:	ORIGINATOR: ALL			
	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
VML1202	700	NRP	AE	32	777-900001-01-1-01	LIFT THE A/C FOR MAINTENANCE.	L120	WIP	09/27/2023
	LDG								0.0
						1C 1 REMOVE BODYFAIRING 191SL &192SR			0.0
						1C 2 AIR MOD SIMULATION PREPARATION			0.0
						1C 3 LIFT THE AIRCRAFT WITH JACK			0.0
						1C 4 PLS CARRY OUT WOW LOAD SENSOR CALIBRATION			0.0
						2C 5 LOWER THE AIRCRAFT OFF OF THE JACK			0.0
						2C 6 REINSTALL THE BODYFAIRING191SL&192SR			0.0
						2C 7 AIR MODE SIMULATION RESTORATION			0.0
								-	0.1
VML1210	200	NRP	SS	2527	777-C252000-01-02- 01	CABIN ALL FLOOR CARPETS FOUND WORN	L121	WIP	09/28/2023
	CAB				U I				0.0
						1C 1 REMOVE CABIN ALL FLOOR CARPETS.			87.0
						1C 2 FABRICATE CABIN ALL FLOOR CARPETS.			0.0
						1C 3 INSTALL CABIN ALL FLOOR CARPETS.			173.0
						1C 4 REMOVE SEAT TRACK COVER			12.0
						2C 5 INSTALL SEAT TRACK COVER			15.0
								-	287.0
VML1228	500	NRR	ΑE	2800	TA28000201	DUE C-CHK REQ'D, SUMP DRAIN ALL FUEL TANKS TO EMPTY.	L122	OPEN	09/27/2023
	F/T								6.0
								-	6.0
VML1236	200	NRR	Al	25	777-53-904-00-01	G1C GLY C105 COMPARTMENT DOOR LATCH FOUND MALFUNCTION	L123	OPEN	09/28/2023
	CAB						2.20	0. 2	1.0
								_	1.0
									1.0
VML1244	200	NRR	SM	25	777-53-904-00-01	G1C GLY C104 COMPARTMENT DOOR HINGE FOUND LOOSEN	L124	OPEN	09/28/2023
	CAB								4.0
								-	4.0
VML1251	200	NRR	Al	25	777-53-904-00-01	G1C GLY C104&C101 COMPARTMENT INSIDE BUMPER FOUND MISSING TTL:4EA	L125	OPEN	09/28/2023
	CAB								2.0
								-	
									2.0

ORIGINATING CUST REF NO:

588486

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

21 OF 23 PAGE:

ESTIMATED MHR: ALL

RUN DATE: 9/28/2023

RUN TIME: 9:19

PROJECT: VM CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-HNH CHECK TYPE: 3C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE : ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

OTTLE GODE :	ZONE	STG			111 2 3352.	GINGII VII GIV.			STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
VML1269	200	NRR	Al	25	777-53-904-00-01	G1C GLY C101 COMPARTMENT DOOR HINGE FOUN	DLOOSEN	L126	OPEN	09/28/2023
	CAB									2.0
									-	2.0
VML1277	200	NRR	Al	25	777-53-904-00-01	G1C GLY C101 C120 COMPARTMENT DOOR LATCH	FOUND LOOSEN	L127	OPEN	09/28/2023
	CAB									2.0
									-	2.0
VML1285	200	NRR	Al	25	777-53-904-00-01	G1C GLY C102 COMPARTMENT T GUIDE FOUND WO	RN	L128	OPEN	09/28/2023
	CAB									2.0
									-	2.0
VML1293	200	NRR	Al	25	777-53-904-00-01	G1C GLY C104&C101 COMPARTMENT DOOR INNER	SURFACE FOUND DENT	L129	OPEN	09/28/2023
	CAB									2.0
									-	2.0
VML1301	200	NRR	Al	25	777-53-904-00-01	G1 GLY G113 OVEN SEAL FOUND TORN		L130	OPEN	09/28/2023
	CAB									2.0
									-	2.0
VML1319	200	NRR	Al	25	777-53-904-00-01	G1 GLY G114 OVEN SEAL FOUND TORN		L131	OPEN	09/28/2023
	CAB									2.0
									-	2.0
VML1327	200	NRR	Al	25	777-53-904-00-01	G1 GLY G113 G114 LOWER AREA BUMPER FOUND 1	ORN	L132	OPEN	09/28/2023
	CAB									4.0
									-	4.0
VML1335	200	NRR	Al	25	777-53-904-00-01	G1 GLY G123 COMPARTMENT DOOR LATCH FOUND	MALFUNCTION	L133	OPEN	09/28/2023
	CAB									1.0
									-	1.0
VML1343	200	NRR	Al	25	777-53-904-00-01	G1 GLY G123 COMPARTMENT DOOR STOP FOUND I	BROKEN	L134	OPEN	09/28/2023
	CAB									1.0
									-	1.0

ORIGINATING CUST REF NO:

588486

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

22 OF 23 PAGE:

RUN TIME:

RUN DATE: 9/28/2023 9:19

PROJECT: VM CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-HNH CHECK TYPE: 3C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

TRADE: ALL DEFECT TYPE : ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

TRL CODE :					TYPE CODE:	ORIGINATOR: ALL			STATUS	UPDATED DATE
JOB NO	ZONE AREA	SIG	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
/ML1350		NRR	Al	25	777-53-904-00-01					
VIVIL 1330	200 CAB	INKK	AI	25	777-55-904-00-01	G1 GLY G122 G120 COMPARTMENT DOOR LATCH FO	DUND LOOSEN	L135	OPEN	09/28/2023
	OND									1.0
										1.0
/ML1368	200	NRR	Al	25	777-53-904-00-01	G1 GLY G122 COMPARTMENT DOOR INNER SURFAC	CE FOUND DENT	L136	OPEN	09/28/2023
	CAB									2.0
									-	2.0
/ML1376	200	NRR	ΑI	25	777-53-904-00-01	G1 GLY G121COMPARTMENT DOOR INNER LOWER	BUMPER FOUND MISSING	L137	OPEN	09/28/2023
	CAB									1.0
									-	1.0
/ML1384	200	NRR	Al	25	777-53-904-00-01	G1 GLY OVEN SCREW FOUND WORN.TTL:8EA		L138	OPEN	09/28/2023
	CAB		<i>,</i>		66 66 66 6	OF GET OVER GONEW FOOD WORKS. FE.SEX		L130	OFLIN	2.0
									-	
										2.0
/ML1392	200 CAB	NRC	Al	25	777-53-676-00-01	M/D FWD ZONE GLY G1 COUNTER AREA G104 GR10	3 TURN-RETAINER FOUND WEAK TTL:2EA	L139	OPEN	09/28/2023
	CAD									1.0
									-	1.0
ML1400	200	NRR	Al	25	777-53-904-00-01	G1 GLY G101 COMPARTMENT LOWER L SEAL COVE	R FOUND BROKEN	L140	OPEN	09/28/2023
	CAB									2.0
									-	2.0
ML1418	200	NRR	Al	25	777-53-904-00-01	G1 GLY G103 COMPARTMENT LOWER AREA BUMPE	R FOUND DETACHED	L141	OPEN	09/28/2023
	CAB									1.0
									-	1.0
/ML1426	200	NRR	Al	25	777-53-904-00-01	G1 GLY GR101 COMPARTMENT LOWER AREA BUMP	ER FOLIND DETACHED	L142	OPEN	09/28/2023
WIE 1 120	CAB	14141	7.0	20	777 00 00 1 00 01	OT GET GRANT COMM / NAME AT EGWER / NAE A EGWER	ENTOGING BETWOILED	L142	OPEN	1.0
									-	
										1.0
ML1434	200 CAB	NRR	Al	25	777-53-904-00-01	G1 GLY GR101 COMPARTMENT UPPER AREA BUMPI	ER FOUND MISSING	L143	OPEN	09/28/2023
	CAB									1.0
									-	1.0

DISTRIBUTION: 0PPC TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD. PAGE: 23 OF 23 REQUESTED BY: 588486 RUN DATE: 9/28/2023

NRC TALLY LIST WITH ESTIMATE MANHOUR

REFERENCE NO: BMS571R1-2 (By JSN) RUN TIME: 9:19

A/C TYPE: 777 PROJECT: VM CUSTOMER: CX A/C REGN: B-HNH CHECK TYPE: 3C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL ORIGINATING CUST REF NO: ALL ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

145

TOTAL NO OF NRC PRINTED:

0

0

Jobs CANC:

Jobs DEFER:

Jobs COMP:

		···								
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
VML1442	200	NRR	Al	25	777-53-904-00-01	G1&GR GLY COMPARTMENT LOWER T GUIDE FOUND WORN TTL:6EA		L144	OPEN	09/28/2023
	CAB									6.0
				25	777-53-676-00-01	M/D FWD ZONE GLY G1 WASTE COMPARTMENT FLAP DOOR FOUND SPRING WEAK	L145	OPEN	6.0	
VML1459	200	NRC	ΑI						09/28/2023	
	CAB									2.0
								-	2	

Jobs OPEN: 127 Jobs READY: 0 Jobs WIP: 17 Jobs HOLD: 0

PLANNING ENGINEER \_\_\_\_\_ DATE \_\_\_\_

I CERTIFY THAT I HAVE CHECKED THAT ALL THE ABOVE REFERENCED CARDS HAVE BEEN CERTIFIED AS HAVING BEEN COMPLETED.

1,596.0

Total Mhr:

CERTIFYING STAFF \_\_\_\_\_ DATE \_\_\_\_\_

STAMP AND SIGNATURE