

Forklift Safety Inspection Report

Site: Meridian Distribution Center

Equipment ID: FL-2291

Inspector: Carla Whitfield, Certified Safety Inspector

Inspection Date: February 18, 2026

Findings

Hydraulic lift mechanism shows minor fluid seepage at the cylinder seal.

Brake response time within acceptable range.

Recommended Action

Replace cylinder seal within 14 days.

Re-inspect after repair.

Additional Notes

Operator training records reviewed and confirmed current as of this inspection.

Next scheduled inspection: May 18, 2026.

Signed: C. Whitfield