AVIATION **SAFETY** NETWORK

AN EXCLUSIVE SERVICE OF FLIGHT SAFETY FOUNDATION

- Home
- <u>Database</u>
- Investigation
- Statistics
- Contact us
- About



Home » ASN Aviation Safety WikiBase

This information is added by users of ASN. Neither ASN nor the Flight Safety Foundation are responsible for the completeness or correctness of this information. If you feel this information is incomplete or incorrect, you can <u>submit</u> <u>corrected information</u>.

Share 0

Date: Friday 26 January 2018

Time:



Type: Airbus A320-233

Owner/operator: Volaris
Registration: N505VL
MSN: 4798
Year of manufacture: 2011

Engine model: IAE V2527E-A5

Fatalities: Fatalities: 0 / Occupants:

Other fatalities: 0
Aircraft damage: None

Category: Serious incident

Location: Tijuana-Rodriguez Airport (TIJ/MMTJ) - Mexico

Phase: Taxi

Nature: Passenger - Scheduled

Departure airport: Tijuana-Rodriguez Airport (TIJ/MMTJ)

Destination airport: Mazatlán-Gen. Rafael Buelna Airport (MZT/MMMZ)

Confidence Rating: Information verified through data from accident investigation authorities

Narrative:


Volaris flight VOI590, an Airbus A320-233, was taxiing to the runway when engine no.1 failed.

The crew decided to return to the apron.

Sources:

https://bea.aero/en/investigation-reports/notified-events/detail/serious-incident-to-the-airbus-a320-registered-n505vl-and-operated-by-volaris-on-26-01-2018-at-tijuana-investigation-led-by-caa---mexico/

Location



Revision history:

Date/time Contributor Updates 21-Feb-2024 18:59 ASN Added

21-Feb-2024 18:59 ASN Updated [Location,]

Corrections or additions? ... Edit this accident description

The Aviation Safety Network is an exclusive service provided by:

Quick Links:

ASN Home Send Correction / Feedback

FSF Home Disclaimer

Copyright

Contact Us Privacy Policy

Press / Media





©2025 Flight Safety Foundation