## AVIATION **SAFETY** NETWORK

## AN EXCLUSIVE SERVICE OF FLIGHT SAFETY FOUNDATION

- Home
- <u>Database</u>
- Investigation
- Statistics
- Contact us
- About



Home » ASN Aviation Safety WikiBase

This information is added by users of ASN. Neither ASN nor the Flight Safety Foundation are responsible for the completeness or correctness of this information. If you feel this information is incomplete or incorrect, you can <u>submit</u> <u>corrected information</u>.

Share 0

Post

Date: Sunday 29 November 2020

Time:



Type: <u>Airbus A320-251N</u>
Owner/operator: Thai Air Asia
Registration: HS-BBX

MSN: 7195 Year of manufacture: 2016

Engine model: CFMI CFM LEAP-1A26E1 Fatalities: Fatalities: 0 / Occupants:

Other fatalities: 0 Aircraft damage: None

Category: Serious incident

Location: Phuket International Airport (VTSP) - Thailand

Phase: Taxi

Nature: Passenger - Scheduled

Departure airport: Chiang Mai International Airport (CNX/VTCC)

Destination airport: Phuket International Airport (HKT/VTSP)

Confidence Rating: Information verified through data from accident investigation authorities

Narrative:

Engine 1 caught fire during taxi after landing at Phuket International Airport.

Sources:

https://bea.aero/en/investigation-reports/notified-events/detail/serious-incident-to-the-airbus-a320-registered-hs-bbx-operated-by-thai-air-asia-on-29-11-2020-at-phuket/

Revision history:

**Date/time Contributor Updates** 13-Apr-2023 16:54 harro Added

21-Mar-2024 11:21 ASN Updated [Date, ]

The Aviation Safety Network is an exclusive service provided by:

## **Quick Links:**

ASN Home Send Correction / Feedback

FSF Home Disclaimer

Copyright

Contact Us Privacy Policy

Press / Media



CONNECT WITH US: **f in o** 

©2025 Flight Safety Foundation