


100.0 mm reference — measure after printing

Print at 100% / ACTUAL SIZE (no 'fit to page'). Tape FLAT to a rigid board. If 100 mm line is off, measure a real square and pass --square to the calib tools.