# Multi Robot Localization Update

An update on what progress has been made and what is planned By Caleb Lu

### Outline

- Summary of project/task
- Current Progress
- Current Issues
- Planned Work
- Questions

# Summary

### Summary

The Goal of the assignment is to use:


- BeagleBone Blue Board (BBB)
- (Currently) **3** XS2C Xbee/Zigbee Boards

To simulate indoor localization using trilateration

### Zigbee/XBee Setup

- The Xbee boards are going to be set up into two configurations.
  - Coordinator
  - Endpoint
- The Robot/BBB will be connected to the XBee module that is set up as the **Coordinator**
- The beacons will be set up as endpoints.

This configuration will allow for Indoor trilateration.



## **Current Progress**

### **Current Progress**

- Current progress is that 1 of the board is setup to be the coordinator. This is the one setup to be on the robot/BBB.
- Tested/other 2 XBee boards are having issuing interfacing with the XCTU interface program
  - Currently doing some troubleshooting
- Started looking into resources to bingin programming a file to connect read the XBee board from the BBB.
  - Have not decided on what language to use. Currently looking into C++ or Python based on the resources found
- Connected with the BBB over PuTTY to ensure communication is working

### **Current Issues**

### **Broken Components**

Issue Tier List: Yellow = Light | Orange = Medium | Red = Servere

- BeagleBone Blue has damage/two encoder inputs are coming off
- XBee/Zigbee S2C Boards ⅔ of them do not connect to the XCTU Program. Meaning I can only interact and format one of the boards

### Additional Components needed

Issue Tier List: Yellow = Light | Orange = Medium | Red = Servere


- XBee interface Board
- XBee/Zigbee S2C Boards 1

Both are needed for a bare minimum test for communication. This is urgent but needs to be solved in a week to a week and a half.

### BBB Damage

Damage found on the BBB

- The 2 of the Encoder Inputs are damaged
  - Unsure where this happened but reporting the damage just in case there is a future issue.
- Has little to no impact to me and what I'm doing so severity level is low.



#### Communication Issues

Discovering radio modules...

Search finished. 1 device(s) found



1 device(s) found



Devices discovered:



Port: COM8 - 9600/8/N/1/N - AT

Name: COORDINATOR

MAC Address: 0013A20040DDE2C7

Discovering radio modules...

Search finished. No devices found.



0 device(s) found



Devices discovered:

Found XBee Module

### XBee Module Difference



Non-Working on the Left, Working one on the Right

## Planned Work

### Plan for the coming week - Documentation

- 1. Update Lab Notebook/Documentation
- 2. Transfer to Latex Presentation

### Plan for the coming week - Technical

- 1. Test XBee boards ensure broken
- 2. Write program for reading XBee from BBB
- 3. Test if program connects/receives data from XBee board connected to BBB

### Progress Walls

- Need extra XBee interface board
- Need extra XBee Module/radio and cable

#### Overall work that needs to be done

#### Short term time frame:

- XBee Configurations
- BBB Configurations
- BBB to XBee program

#### Long term time frame:

- 4 XBee Modules/radios
- 4 micro-USB cables
- RSS and RFID Reading
- Trilateration algorithm

# Questions?

### References

Images:

•

Sites: