

Programming Guidance

1. List of required tools

NO.	Item	Model
1	Cross screwdriver	M4
2	Computer	Windows system
3	Programmer	ST-LINK/V2
4	Software	ST Visual Programmer
5	Programme File No.	4.2.3.02.0389B

2. The place of the control board





Remove the 16 screws(the red circle on above cover) , and then remove the cover. After this, the control board would be shown.

3. Suggestion of programmer

Recommended model of programmer is ST-LINK/V2



4. Connection diagram of the programmer

Connect the PC with the programmer by the USB port, and 4pin port should be connected to the programming port on the control board.

