Suedo Code

Wednesday, November 1, 2023 8:14 AM

Process for Going up the stairs:

- 1. Set stair parameters and number of stairs
- 2. Load device
- 3. Set to rolling mode
- 4. Roll to bottom of stairs
- 5. Switch modes to climbing
- 6. Robot moves up one step following preset path
 - a. Preset path for each leg:
 - i. Round or cornered path from one step to the next
- 7. Set robot to rolling mode
 - a. Roll to the edge of next step
- 8. Repeat process 5-7 until top of stairs are reached