repeats the experiment, personal error occurs. For example, consider the case of the thickness of a wire measured using a screw gauge. The readings taken may be different for different trials. In this case, a large number of measurements are made and then the arithmetic mean is taken.

If n number of trial readings are taken in an experiment, and the readings are a_1, a_2, a_3,..... a_n. The arithmetic mean is

$$a_m = \frac{a_1 + a_2 + a_3 + ...a_n}{n} \quad (1.1)$$

or

$$a_m = \frac{1}{n}\sum_{i=1}^{n} a_i \quad (1.2)$$

Usually this arithmetic mean is taken as the best possible true value of the quantity.

Certain procedures to be followed to minimize experimental errors, along with examples are shown in Table 1.8.

iii) Gross Error

The error caused due to the shear carelessness of an observer is called gross error.
For example

(i) Reading an instrument without setting it properly.

(ii) Taking observations in a wrong manner without bothering about the sources of errors and the precautions.

(iii) Recording wrong observations.

(iv) Using wrong values of the observations in calculations.

These errors can be minimized only when an observer is careful and mentally alert.

Table 1.8 Minimizing Experimental Error

Type of error	Example	How to minimize it
Random error	Suppose you measure the mass of a ring three times using the same balance and get slightly different values. 15.46 g, 15.42 g, 15.44 g	Take more data. Random errors can be evaluated through statistical analysis and can be reduced by averaging over a large number of observations.
Systematic error	Suppose the cloth tape measure that you use to measure the length of an object has been stretched out from years of use. (As a result all of the length measurements are not correct).	Systematic errors are difficult to detect and cannot be analysed statistically, because all of the data is in the same direction. (Either too high or too low)

UNIT-1(XI-Physics_Vol-1).indd 21 05-01-2022 22:11:43