

Production Report

MERCEDEZ GLE 580 Rear Bumper LINE 1

Date:10/05/2026

Shift:M A E

Team Leader:André Gonçalves

Team:B

Hour	Goal With 90% Efficiency	Productio n per Hour	Tempo (min)			Total	Working Stations	Equipament	Breakdown	Subcode	Breakdown Description
	A		Unplanned Downtimes	Planned Downtimes							
15:30	6	5	10		10	AS_320	Fixture_Table	Welding_Failure	Weld_Porosity	Trainee made the wrong fix	
16:00	6	5									
16:00	11	11	11		11	WA_310	Welding_Gun	Mechanical_Breakdown	Bearing_Failure	Welding gun arm bearing seized mid-cycle	
17:00	17	16									
17:00	11	7	9	10	10	FT_330	Robot_Arm	Break	Servo_Fault	Robot axis 3 servo alarm triggered during positioning	
18:00	28	23			9			Robot_Fault			
18:00	11	4	23		23	VT_340	Fixture_Table	Welding_Failure	Arc_Instability	Arc instability detected on weld seam C4	
19:00	39	27									
19:00	11	10	30		30	RK_350	Conveyor_Belt	Conveyor_Stoppage	Belt_Jam	Part jammed at transfer point between RK_350 and exit rail	
20:00	50	37		0							
20:00	11	11	11	30	30	WA_310	Control_Panel	Break	PLC_Fault	PLC I/O module fault caused line stop at WA_310	
21:00	61	48			11			Eletrical_Breakdown			
21:00	11	12	2	0	2	AS_320	Gripper_Unit	Pneumatic_Failure	Gripper_Malfunction	Gripper lost pressure and dropped part during loading	
22:00	72	60									
22:00	11	8	23	10	10	FT_330	Welding_Tip	Break	Unplanned_Tool_Swap	Welding tip worn out ahead of schedule, unplanned swap required	
23:00	83	68			23			Tooling_Change			
23:00	9	2	6		6	VT_340	Vision_Camera	Robot_Fault	Vision_System_Failure	Vision camera failed to detect part position, line halted	
23:50	92	70									
	22	125	50								

Presences Control:

-

-

-

-

-

-

-

-

-

-

Products General Informations

NOK Parts3

of Workers2

Scrap Rate [%]4,3%

FTTQ93%

Downtime175

Name for KPIsmercedes_gle_580_rear_bumper_line_1_a_

Reworked Parts5

OEE78,41%

Productivity (PPLH)4,5

Efficiency90,00%

Cycle Time316

Production Status

More data about product specifity and production status. Not relevant for this Data Analytics/Engineering project