

ID	date	line	schedule	unplanned stoppages	planned stoppages	work station	equipment	failure type	sub code	failure description
10052026 Shift B.xlsx	10/05/2026	CTRL MERCEDEZ GLE 580 REAR BUMP	15:30	10		AS_320	Fixture_Table	Welding_Failure	Weld_Porosity	Trainee made the wrong fix
10052026 Shift B.xlsx	10/05/2026	CTRL MERCEDEZ GLE 580 REAR BUMP	16:00	11		WA_310	Welding_Gun	Mechanical_Breakdown	Bearing_Failure	Welding gun arm bearing seized mid-cycle
10052026 Shift B.xlsx	10/05/2026	CTRL MERCEDEZ GLE 580 REAR BUMP	17:00		10			Break		
10052026 Shift B.xlsx	10/05/2026	CTRL MERCEDEZ GLE 580 REAR BUMP	17:00	9		FT_330	Robot_Arm	Robot_Fault	Servo_Fault	Robot axis 3 servo alarm triggered during positioning
10052026 Shift B.xlsx	10/05/2026	CTRL MERCEDEZ GLE 580 REAR BUMP	18:00	23		VT_340	Fixture_Table	Welding_Failure	Arc_Instability	Arc instability detected on weld seam C4
10052026 Shift B.xlsx	10/05/2026	CTRL MERCEDEZ GLE 580 REAR BUMP	19:00	30		RK_350	Conveyor_Belt	Conveyor_Stoppage	Belt_Jam	Part jammed at transfer point between RK_350 and ext rail
10052026 Shift B.xlsx	10/05/2026	CTRL MERCEDEZ GLE 580 REAR BUMP	20:00		30			Break		
10052026 Shift B.xlsx	10/05/2026	CTRL MERCEDEZ GLE 580 REAR BUMP	20:00	11		WA_310	Control_Panel	Electrical_Breakdown	PLC_Fault	PLC I/O module fault caused line stop at WA_310
10052026 Shift B.xlsx	10/05/2026	CTRL MERCEDEZ GLE 580 REAR BUMP	21:00	2		AS_320	Gripper_Unit	Pneumatic_Failure	Gripper_Malfunction	Gripper lost pressure and dropped part during loading
10052026 Shift B.xlsx	10/05/2026	CTRL MERCEDEZ GLE 580 REAR BUMP	22:00		10			Break		
10052026 Shift B.xlsx	10/05/2026	CTRL MERCEDEZ GLE 580 REAR BUMP	22:00	23		FT_330	Welding_Tip	Tooling_Change	Unplanned_Tool_Swap	Welding tip worn out ahead of schedule, unplanned swap required
10052026 Shift B.xlsx	10/05/2026	CTRL MERCEDEZ GLE 580 REAR BUMP	23:00	6		VT_340	Vision_Camera	Robot_Fault	Vision_System_Failure	Vision camera failed to detect part position, line halted

ID	date	line	shift	team leader	num operators	total expected output	total produced	nok parts	reworked parts	accidents	near misses	customer complaints	observations	version	cycle time
10052026 Shift B.xlsx	10/05/2026	CTRL MERCEDEZ GLE 580 REAR BUMP	afternoon	ANDRÉ GONÇALVES		2	92	70	3	5				A	316