
CPU
Recovery
RESET
SPI_NOR
DC-DC&LDO
POWER TREE
GOLDEN FINGER
M.2 KEY-B
DCXO-24Mhz
DECOUPLE CAP
Maix-II
NGFF Module
If the working voltage is higher than the tolerance voltage, the IO port will be damaged.
Open-source hardware with MaixLinux, A.I. at edge.
Sipeed Technology Co, Ltd.
Sheet: /
File: Maix-II_3100.sch
Title: Maix-II_3100(Schematic)
Size: C
Date: 2020-12-25
Rev: 1.00
KiCad E.D.A. eeschema (5.1.6)-1
Id: 1/1