

BOM Validation Report

Identifier: 81355130 | Generated: 2026-04-23 06:46 UTC

Pump Metadata

Field	Value
VT pump Common Name	VMF 28B PUMP
No of Stages	04
Region	India
Customer Tag Number	1
Application	Irrigation
Liquid Handled	Raw Water
Manufacturing Clearance	YES
Scope of Supply	Bare Pump + Accessories
Flow (m3/h)	2,664.00 m3/h
Nett Gen Head	139.24 m
Bowl Head (m)	139.74 m
Shut off Head (m)	191.00 m
Bowl Efficiency (%)	89.44 %
Pump BKW (kW)	1,133.50 KW
Motor Rating (kW)	1,300.00 KW
Full Load Speed (RPM)	990 RPM

■ Discrepancies Found: 4 parts require attention

Part Name	Conflict	Assessment	Confirmed
Loose Stuffing Box	CS: SS410 BOM: FG260 SAP: absent	CS and BOM disagree; SAP has no entry for this part. Manual review required.	YES
Neck Ring	CS: absent BOM: SS410 SAP: CF8M/SS410	SAP appears incorrect — SAP is the reference. Correct material: SS410 .	Pending
Sand Collar	CS: CUTLESS + SS410 BOM: MS SAP: absent	CS and BOM disagree; SAP has no entry for this part. Manual review required.	YES
Water Deflector	CS: FG260 BOM: NITRILE RUBBER SAP: absent	CS and BOM disagree; SAP has no entry for this part. Manual review required.	YES

■ Extraction Warnings: 5 parts

These are **not material errors**. The CS PDF extractor assigned a consumable material (e.g. graphited cotton, nitrile rubber) to a structural part — likely due to a merged/spanning row in the drawing. The CS value was excluded from comparison. Please verify the CS drawing manually and fix the extractor if needed.

Part Name	CS Material (excluded)	Warning
Gland Sleeve	—	CS material looks like a consumable assigned to a structural part. Likely PDF row-span error. CS value excluded from comparison.
Intermediate Shaft	—	CS material looks like a consumable assigned to a structural part. Likely PDF row-span error. CS value excluded from comparison.
Ratchet	—	CS material looks like a consumable assigned to a structural part. Likely PDF row-span error. CS value excluded from comparison.
Split Gland	—	CS material looks like a consumable assigned to a structural part. Likely PDF row-span error. CS value excluded from comparison.
Thrust Block	—	CS material looks like a consumable assigned to a structural part. Likely PDF row-span error. CS value excluded from comparison.

Summary

Total parts compared: **40** | Discrepancies flagged: **4** | Extraction warnings: **5** | Unresolved (not in nomenclature): **18** | User confirmed errors: **5** | User dismissed (false positives): **22**

Full Part Comparison (Reference)

Part Name	CS	BOM	SAP	Status
Adjusting Ring	MS IS 2062 GR B	MS	—	OK
Alignment Pad	—	FG 260	—	OK
Bearing Bush	—	SS410	CUTLESS + SS410	OK
Bearing Bush Carrier	—	FG260	—	OK
Bearing Housing Sub-Assembly	—	SS304	—	OK
Cooling Coil	SS410	—	—	OK
Delivery Bend & Motor Stool	MS	MS	MS	OK
Diffuser	WCB + COATING	—	WCB + COATING	OK
Flexible Coupling	—	—	Forged Steel	OK
Gland Sleeve	—	SS410	SS410	WARN
Impeller	—	—	CF8M + COATING	OK
Impeller Distance Sleeve	—	SS410	—	OK
Impeller Nose Cap	CF8M+COATING	—	—	OK
Impeller Wear Ring	—	—	NOT APPLICABLE	OK
Intermediate Bearing Sleeve	—	SS410	SS410	OK
Intermediate Shaft	—	SS410T	SS410	WARN
Logging Ring	—	FG260	FG260	OK
Loose Stuffing Box	SS410	FG260	—	ERROR
Muff Coupling	—	SS410	SS410	OK
Neck Ring	—	SS410	CF8M/SS410	FLAG
Oil Level Indicator	—	—	—	OK
Oil Retainer Bush	SS410	—	—	OK
Pump Bearing Sleeve	SS410	SS410	SS410	OK
Pump Shaft	SS410	SS410T	SS410	OK
RM Pipe (Intermediate)	—	MS	MS	OK
RM Pipe (Taper/Bottom)	—	MS	—	OK
RM Pipe (Top)	MS	MS	—	OK

Part Name	CS	BOM	SAP	Status
Ratchet	—	—	—	WARN
Sand Collar	CUTLESS + SS410	MS	—	ERROR
Sleeve Nut	—	SS410	—	OK
Sole Plate	—	MS	—	OK
Split Collar	CUTLESS + SS410	SS410	—	OK
Split Gland	—	FG260	FG260	WARN
Strainer	—	SS304	SS304	OK
Suction Bell Mouth	—	—	FG260 + COATING	OK
Taper Connecting Piece	—	—	—	OK
Thrust Bearing	SS410	—	—	OK
Thrust Block	—	—	—	WARN
Top Shaft	SS410	SS410T	SS410	OK
Water Deflector	FG260	NITRILE RUBBER	—	ERROR

Appendix A — Confirmed Discrepancies

Part Name	Type	Reason
Loose Stuffing Box	MATERIAL_MISMATCH	CS specifies SS410 and BOM specifies FG260, indicating a material mismatch with no SAP data.
Ratchet		CS extraction suspect: 'NITRILE RUBBER' looks like a consumable material assigned to structural part 'Ratchet'. Likely a PDF row-span extraction error. CS material excluded from comparison.
Thrust Block		CS extraction suspect: 'NITRILE RUBBER' looks like a consumable material assigned to structural part 'Thrust Block'. Likely a PDF row-span extraction error. CS material excluded from comparison.
Sand Collar	MATERIAL_MISMATCH	CS specifies SS410 (via CUTLESS + SS410) and BOM specifies MS, indicating a material mismatch with no SAP data.
Water Deflector	MATERIAL_MISMATCH	CS specifies FG260 and BOM specifies NITRILE_RUBBER, indicating a material mismatch with no SAP data.

Appendix B — Dismissed (False Positives)

Gland Sleeve — remapped to: Alignment Pad

Intermediate Shaft — remapped to: Intermediate Shaft

Neck Ring — remapped to: Neck Ring

Split Gland — remapped to: Split Gland

RISING MAIN PIPE (INT) — remapped to: RM Pipe (Intermediate)

INTERMEDIATE SHAFT-1 — remapped to: Intermediate Shaft

SOLID COUPLING — remapped to: Muff Coupling

LEAK OFF BUSH — remapped to: Logging Ring

INT. BRG. BUSH — remapped to: Bearing Bush

INT. BRG. BUSH, (LOOSE STUFFING BOX) — remapped to: Bearing Bush

BUSH CARRIER (LOOSE STUFFING BOX) — remapped to: Bearing Bush Carrier

PUMP BRG BUSH (DIFFUSER) — remapped to: Bearing Bush

PUMP BRG BUSH (BELL MOUTH) — remapped to: Bearing Bush

INTERMEDIATE BRG SLEEVE — remapped to: Intermediate Bearing Sleeve

THRUST HOUSING — remapped to: Bearing Housing Sub-Assembly

IMPELLER LOCK NUT (R.H.) — remapped to: Lock Nut

IMPELLER LOCK NUT (L.H.) — remapped to: Lock Nut

THRUST BRG LOCK NUT — remapped to: Lock Nut

O'RING (DIFFUSER & R.M. PIPE BOT) — remapped to: Abutment Ring

O'RING (DIFFUSER & R.M. PIPE) — remapped to: Abutment Ring

O'RING (R.M. PIPES) — remapped to: Adapter Plate
O'RING (LOOSE STUFFING BOX) — remapped to: Loose Stuffing Box