

# IR-2026-0828 — Inspection Report — Lube Oil Unit U-105

Issued 2026-08-28 | Operations | 50-UZ-105

Findings: milky oil in sight glass; cooler outlet area damp. Recommend oil sample and cooler pressure test.  
Notification **200049301** raised.