

# MOC-2026-014 Rev 1 — Bearing arrangement upgrade

|       |            |                                                   |
|-------|------------|---------------------------------------------------|
| Rev 0 | 2026-01-21 | Approval to upgrade bearings after P-101B failure |
| Rev 1 | 2026-01-28 | Close-out after implementation on B               |

**Implemented:** 50-PA-101B upgraded to Arrangement 2 on 2026-01-24 under order 400078901. Root cause of failure: lubricant contamination.

**Planned:** 50-PA-101A Arrangement 2 at next overhaul Q1 2027.

**Recommendation:** monthly oil sampling of U-105 (50-UZ-105).