Different levels of Risk Aversion Nuclear Coal 6.0×10^{5} Gas Wind Solar Storage 4.0×10^{5} 2.0×10^{5} 0 0 0.25 0.5 0.75 Level of Risk Aversion