Non-Conformance Report NCR-2026-0871

SYNTHETIC DEMO DOCUMENT

Field	Value
Supplier	SUPP_04288
Name	Prime Solutions 778
Part	Door drive unit DDU-4
Fleet	RegioFlex EMU
Defect	Motor overheating
Units affected	37 of 220
Detected	2026-09-22
Severity	Major
Delivery rating	75.7% (expected ~91%)

Root cause (supplier statement): change of motor sub-supplier in May 2026 without notification (PCN missing).
Containment: 100% inspection at incoming goods.
Corrective action due: 2026-11-15.