MCDU-40-2024-067533

CDU sustained major damage when it was dropped from a forklift onto its left side. The incident took place on-site at NAL1-DC1 in New Albany Ohio.

CDU shows extensive internal and external damage. The Belimo Actuator Valve punched a heavy indent on the left side of the cabinet and the top panel also buckled upon impact. Support brackets for the Heat Exchanger are bent on the left side and broken off completely on the right side of the unit. The Primary and Secondary Source / Return pipes are also bent and shifted out of place along with connected internal piping.






DRAIN