Loss Solutions Group, LLC
Toll Free 866.899.8756
Fax 860.639.5158
www.LossSolutionsGroup.com

August 28, 2025

Ms. Becky Vogan
Hanover Insurance
PO Box 15147
Worcester, MA 01615

RE:	Insured:	ALSON-THORNTON, LLC
	Claim Number:	85-00813568
	LSG Matter Number:	426600.4004-00
	Date of Loss:	June 27, 2025

Dear Ms. Vogan,

Thank you for choosing Loss Solutions Group as your equipment loss consultant. This report serves to provide an analysis of the above-referenced claim.

Assignment:

Loss Solutions Group was contacted by Ms. Becky Vogan of Hanover Insurance. The scope of this assignment was to address the extent of damage, salvage value, and repair / replacement costs associated with the insured's damaged fence. The damage was reportedly related to a vehicle accident event on June 27, 2025.

Findings and Analysis:

Loss Solutions Group contacted the insured, Mr. Miguel Alson with Alson-Thornton, LLC (510-654-4545 ext. 5108), to advise him of our involvement in reviewing this claimed event. During our conversation, Mr. Alson described damage to his business's twelve foot (12') high, approximately thirty foot (30') long fence at the back of the parking lot, consisting of two (2) rolling panels that fold against each other near a red brick building's corner, designed to accommodate a loading dock. He noted that one (1) structural pole is severely bent due to a vehicle incident, and the fence's bottom is rusted out, with the structure (installed around 2002 and roughly twenty-three (23) years old) in below-average condition due to multiple attempted repairs and extensive rust. Separately, he mentioned a rear slide gate repair related to a vandalism incident, not the vehicle accident, which remains functional, but risks collapse when opened, with the vendor proposing potential repairs which he added to the quote.

© 2022 by Loss Solutions Group, LLC. All rights reserved.

Loss Solutions Group contacted the insured's fence vendor, Alta Fence Co., Inc. (925-777-9877), and spoke with Mr. Rhonda Young to discuss the claimed event and proposed repairs. The vendor reported that the rusted gate damaged by a vehicle accident requires replacing one (1) ten foot (10') high by nineteen foot (19') wide swing gate with a new gate, four (4) hinges, truss rods, tighteners, and three (3) strands of four (4)-point barbed wire, similar in like kind and quality, reusing eight (8) existing 6" V-groove wheels and hardware. A new 2 7/8" terminal post will be flanged to a concrete curb. Lastly, Mr. Young broke out the cost for the rear slide gate repair costing $1,883.00, stating that this repair was added but was related to vandalism, not the vehicle accident.

Scope of Damage

Loss Solutions Group submits that the insured reportedly sustained significant damage to their fence reportedly related to a vehicle accident event on June 27, 2025.

Age & Condition

The insured reported that the affected equipment was around twenty-three (23) years old and in below average condition at the time of the claimed event.

Reparability

Loss Solutions Group has reviewed the information provided, and we have discussed the damage with the vendor involved. We submit that the front property swing gate and rear fence line repair paths are warranted due to the damage reportedly sustained during the claimed event.

Cost Analysis

Loss Solutions Group has researched the costs using alternate vendor resources, historical references, similar equipment costs, and vendor experience and we have discussed the pricing with the vendor involved. The following is a breakdown of the associated costs.

ALTA FENCE CO., INC. (925-777-9877) QUOTE DATED ON 8/8/2025 TOTALING $11,113.00

Loss Solutions Group has reviewed the amount of $11,113.00 for the replacement of the insured's damaged fence.

Front Property Swing Gate: this job includes amounts for replacing the damaged ten foot (10') high by nineteen foot (19') wide swing gate with a new gate, four new (4) hinges, truss rods, tighteners, and three (3) strands of four (4)-point barbed wire. This job also reuses the eight (8) existing 6" V-groove wheels as they were still in good condition.

Rear Fence Line Repair: the rear fence line repair involves replacing one (1) ten foot (10') high 2 7/8" terminal post and reconnecting the existing chain link fence with necessary hardware. We submit these components are required to complete the repairs and the costs are fair and reasonable.

© 2022 by Loss Solutions Group, LLC. All rights reserved.

Loss Solutions Group has reviewed the labor costs for the vendor to diagnose the damage and to perform the repairs. We submit that these amounts are fair and reasonable to complete the scope of work as presented to us.

Note: A difference was noted between the claim cost and Loss Solutions Group's researched cost totaling $1,883.00. The difference is associated with the rear slide gate repair which the insured reported is unrelated to the vehicle accident, stemming from a separate vandalism incident. The gate remains functional, but risks collapse when opened, and the vendor included these proposed repairs in the quote as a potential add on.

RCV

Loss Solutions Group submits an amount of $9,230.00 (RCV) as being fair and reasonable to return the insured to a pre-loss condition. A further breakdown of the pricing is available in the attached spreadsheet.

ACV

Loss Solutions Group submits an actual cash value (ACV) amount of $6,897.80 based on linear age depreciation of the materials only. We estimate the average life expectancy of the equipment to be around fifty (50) years.

Salvage

Loss Solutions Group submits that there is little to no salvage value associated with this claimed event.

Summary:

Loss Solutions Group's findings herein are based upon all information that was available at the time of this writing. The opinions are based upon reviewed documentation, interviews, research, experience, historical references, training and education.

1. The insured, Alson-Thornton, LLC, claimed that their business's front swing gate and rear fence line were damaged related to a claimed vehicle accident event on June 27, 2025. A total amount of $11,113.00 was presented.

2. The insured reported that the affected equipment was around twenty-three (23) years old and in below average condition at the time of the claimed event.

3. Loss Solutions Group has reviewed the information provided, and we have discussed the damage with the vendor involved. We submit that the front property swing gate and rear fence line repair paths are warranted due to the damage reportedly sustained during the claimed event.

© 2022 by Loss Solutions Group, LLC. All rights reserved.

4. Loss Solutions Group submits an amount of $9,230.00 (RCV) as being fair and reasonable to return the insured to a pre-loss condition.

    a. A difference was noted between the claim cost and Loss Solutions Group's researched cost totaling $1,883.00. The difference is associated with the rear slide gate repair, which the insured reported is unrelated to the vehicle accident, stemming from a separate vandalism incident. The gate remains functional, but risks collapse when opened, and the vendor included these proposed repairs in the quote as a potential add on.

5. Loss Solutions Group submits an ACV amount of $6,897.80 based on linear age depreciation of the materials only. We estimate the average life expectancy of the equipment to be around fifty (50) years.

6. Loss Solutions Group submits that there is little to no salvage value associated with this claimed event.

If you have any questions or if you need any additional information, please feel free to contact Tanner Beuret at (866) 899-8756 ext. 755, or via email at tbeuret@losssolutionsgroup.com. Team Leader Nick Ramos can be reached at (866) 899-8756 ext. 724, or via email at nramos@losssolutionsgroup.com.

Best regards,

Tanner Beuret
Technical Consultant
Loss Solutions Group, LLC

© 2022 by Loss Solutions Group, LLC. All rights reserved.

INSURED: ALSON-THORNTON, LLC
LSG MATTER #: 426600.4004-00
CLAIM #: 85-00813568
DATE OF LOSS: 6/27/2025
CAUSE OF LOSS: VEHICLE ACCIDENTS

COLOR DENOTES PRICING DISCREPANCY

ALTA FENCE CO., INC. (925-777-9877) QUOTE DATED ON 8/8/2025 TOTALING $11,113.00

REF #	ITEM	CLAIM PRESENTED			LSG RESEARCHED RCV			AGE (YEARS)	USEFUL LIFE (YEARS)	ACV (MAX DEPRECIATION 75%)	DEPRECIATION	CONDITION	NOTES
		QTY	UNIT COST	TOTAL	QTY	UNIT COST	TOTAL						
1	COST FOR 3 REPAIRS	1	$ 11,113.00	$ 11,113.00	0	$ -	$ -	N/A	N/A	$ -	$ -	N/A	COST FOR REPAIRS TO 1) FRONT PROPERTY SWING GATE. 2) REAR SLIDE GATE REPAIR. 3) REAR FENCE LINE REPAIR. THIS COST WAS PROVIDED TO US IN A LUMP SUM CUST. WITH HELP FROM THE VENDOR, WE WERE ABLE TO BREAK THIS COST DOWN AS FOLLOWS.
2	MATERIALS FOR FRONT PROPERTY SWING GATE REPLACEMENT AND REAR FENCE LINE REPAIR	0	$ -	$ -	1	$ 5,070.00	$ 5,070.00	23	50	$ 2,737.80	$ 2,332.20	BELOW AVERAGE	JOBS 1 & 3: FRONT PROPERTY SWING GATE REPLACEMENT AND REAR FENCE LINE REPAIR
3	LABOR FOR JOBS 1 & 3	0	$ -	$ -	32	$ 130.00	$ 4,160.00	N/A	N/A	$ 4,160.00	$ -	N/A	LABOR FOR ROUGHLY 4 METAL WORKERS AND PIPE FITTERS FOR ONE DAY OF WORK TO DEMO AND REPLACE THE LARGE FRONT PROPERTY SWING GATE AND TO REPLACE THE DAMMAGED REAR FENCE LINE.
4	MATERIALS AND LABOR FOR REAR SLIDE GATE REPAIR	0	$ -	$ -	0	$ 1,883.00	$ -	N/A	N/A	$ -	$ -	N/A	MATERIALS AND LABOR FOR JOB #2 (REAR SLIDE GATE REPAIR) THIS JOB IS NOT RELATED TO THE VEHICLE ACCIDENT EVENT.
SUB-TOTAL				**$ 11,113.00**			**$ 9,230.00**			**$ 6,897.80**	**$ 2,332.20**		
SALES TAX				$ -			$ -			$ -	$ -		
TOTAL				**$ 11,113.00**			**$ 9,230.00**			**$ 6,897.80**	**$ 2,332.20**		

TOTAL PRESENTED	**$ 11,113.00**
TOTAL RESEARCHED RCV	**$ 9,230.00**
TOTAL ACV	**$ 6,897.80**
TOTAL DEPRECIATION	**$ 2,332.20**

© 2022 by Loss Solutions Group, LLC. All rights reserved.

Alta Fence Co., Inc.
P.O. Box 1523
Martinez, California 94553
Federal ID # 94-2768404 License No. 448540
P: 925-777-9877 F: 925-777-9677 Email: altafence@att.net

8/8/2025

(Front Property Swing gate)
Demo (1) damaged existing 10' high x 19' wide swing gate and haul away. (1) 10' high x 19'wide slide gate will be reused and reinstalled. Install (1) new 10' high x 19' wide swing gate with new hinges (4) total made from 1 7/8 frame with 10' high 2" diamond 9ga fabric inner 1 7/8 horizontal and vertical rails x brace in each space with 3/8 truss rods + truss tightener + 3 strands of 4-point barbwire. Attach new top and bottom 2"x1"x1/4 c-channel track to swing frame to be able to install existing slide gate with new hardware. (8) existing 6" v-grove wheels will be reused for installation of slide gate. Install slide to swing gate frame and readjust both to function properly. Install (1) gate keeper to keep gate stationery in the open position. Install (1) cane bolt to keep stationery in the closed position with (1) new lockable Rollo latch for locking mechanism. Old gate frame + hardware will be hauled away.

(Rear Slide Gate Repair)
Replace (2) old pipe track wheels on (1) existing 10' high slide gate and readjust top and bottom pipe track and gate as best as possible. Straighten (1) existing 2 3/8 safety post as best as possible. Weld track brackets in place and wire brush clean paint when completed.

(Rear Fence line Repair)
Replace (1) existing damaged 10' high 2 7/8 terminal post with new and flange to concrete curb with new 6'x6"x1/4" plate and 1/2x3" Simpson strong tie concrete anchors. Reconnect existing 10'high chain link fence with existing hardware replaces as needed. Straighten (1) existing 2 3/8-line post as best as possible flange to concrete curb if needed.

$11,113.00

*****If Bonds are required, add 3% to Job total as a Change Order*****



GRAINGER Catalog Find A Branch KeepStock Help 1-800-GRAINGER Register Sign In

All Products | Enter keyword, item, model or part # | Bulk Order | My Account

Product Categories / Material Handling / Storage & Workspace / Partitions & Machine Guards / Wire Partitions & Cages / Complete Wire Security Cages / RAPIDWIRE Welded Partition Cage: 10 ft x... Email Print

Roll over image to zoom.

Product Image Feedback Compare

RAPIDWIRE Welded Partition Cage: 10 ft x 20 ft 10 ft, Gray, 2 Sides, Powder-Coated, 10 ft x 20 ft

Item **38XY40** Mfr Model **1020102W**

Web Price $2,926.94 / each

This item requires special shipping, additional charges may apply.

Qty 1 Add to Cart

Ship Pickup

Ships from supplier. Expected to arrive on or before **Thu. Sep 18**.

Ship to **75201** | Change

Shipping Weight **505 lbs**

Ship Availability Terms

Add to List

Product Details

Catalog Page **N/A**

Brand **RAPIDWIRE**	Lockable **Yes**
Color **Gray**	Overall Interior Depth **20 ft**
Door Exterior Swing Direction **In; Out**	Overall Interior Height **10 ft**
Finish **Powder-Coated**	Overall Interior Width **10 ft**
Number of Walls/Sides **2**	Method of Construction **Welded**
Overall Exterior Depth **20 ft**	Includes **Wedge Anchors**
Overall Exterior Height **10 ft**	Wire Mesh Opening Height **2 in**
Overall Exterior Width **10 ft**	Wire Mesh Opening Width **2 in**
Includes Ceiling Panel **No**	Manufacturer Part Number **1020102W**
Includes Installation Hardware **Yes**	UNSPSC **56111513**
Item/Primary Noun **Complete Wire Security Cages**	Country of Origin **USA (subject to change)**
Lock Type **Keyed Different Cylinder**	

Product Description

WireCrafters welded-wire security cages assemble with bolts and nuts to provide protected, enclosed areas for work or storage. Their panels consist of crossed wires that are welded everywhere they intersect to form a mesh. Welded-wire panels are more durable and stable than woven-wire panels. They will not unravel View More

Product Details Feedback

Customers Also Viewed

ULINE 1-800-295-5510

My Account | Contact Us | Sign In | Cart $0.00

Search GO

Products | Uline Brand | Quick Order | Catalog Request | Special Offers | About Us | Careers

Home > All Products > Warehouse Equipment / Supplies > Wire Security Rooms > Preconfigured Wire Security Rooms

Wire Security Room with Hinged Door - 16 x 16 x 8', 3-Sided



Protect and control access to work areas, inventory and equipment.

- 10-gauge wire mesh panels with 1 1/2" square openings.
- 2" square, 11-gauge steel posts.
- 4' wide hinged door with built-in cylinder lock. Keys included.
- 1/4" thick steel base plates with 2 mounting holes.
- Mounts along an existing wall.
- Floor mounting hardware included.

More Images & Video

MODEL NO.	ROOM SIZE L x W	ROOM HEIGHT	PRICE EACH	STYLE	IN STOCK SHIPS TODAY
H-7068-3	16 x 16'	8'	$2,900	3-Sided	1 ADD

SHIPS UNASSEMBLED VIA MOTOR FREIGHT

+ Additional Info + Parts + Shopping Lists Request a Catalog