FP setup.txt

Wmax	x	Υ	A	В	F
6600 6700 6900	-118 -136 -160	242 256 272	7081.420 7059.365 7038.316	0.4833174 0.4532019 0.4151335	24360.32 23830.20 24553.32
Wmax	X	Υ	A	В	F
5100 6600 6700 6900 8700	42 -45 -65 -87 -80	-4 85 98 112 105	4778.959 6647.712 6649.732 6656.855 8283.733	0.2563284 0.2907861 0.2827171 0.2677551 0.3433082	22795.92 24191.40 24169.32 24087.68 24400.32
Wmax	X	Υ	A	В	F
5100	-660	-40	4988.301	0.0988712	22149.6
6600	-815	25	6667.911	0.1235779	22713.00
6700	-830	32	6666.918	0.1206329	22848.00
6900	-850	45	6747.922	0.1206028	22828.92
Wmax	X	Υ	A	В	F
4922	-170	10	4884.445	0.0192411	21925.76
4996	-170	10	4957.103	0.0196521	21885.48
6609	-350	65	6557.890	0.0256097	22067.76
6690	-340	105	6638.560	0.0258417	22043.56
6773	-365	125	6720.991	0.0261278	22067.76
	6600 6700 6900 Wmax 5100 6600 6700 6900 8700 Wmax 5100 6600 6700 6900 Wmax 4922 4996 6609 6690	6600 -118 6700 -136 6900 -160 Wmax X 5100 42 6600 -45 6700 -65 6900 -87 8700 -80 Wmax X 5100 -660 6600 -815 6700 -830 6900 -850 Wmax X 4922 -170 4996 -170 6609 -350 6690 -340	6600 -118 242 6700 -136 256 6900 -160 272 Wmax X Y 5100 42 -4 6600 -45 85 6700 -65 98 6900 -87 112 8700 -80 105 Wmax X Y 5100 -660 -40 6600 -815 25 6700 -830 32 6900 -850 45 Wmax X Y 4922 -170 10 4996 -170 10 6609 -350 65 6690 -340 105	6600 -118 242 7081.420 6700 -136 256 7059.365 6900 -160 272 7038.316 Wmax X Y A 5100 42 -4 4778.959 6600 -45 85 6647.712 6700 -65 98 6649.732 6900 -87 112 6656.855 8700 -80 105 8283.733 Wmax X Y A 5100 -660 -40 4988.301 6600 -815 25 6667.911 6700 -830 32 6666.918 6900 -850 45 6747.922 Wmax X Y A 4922 -170 10 4884.445 4996 -170 10 4957.103 6609 -350 65 6557.890 6690 -340 105 6638.560	6600 -118