

Moore Transition Table:

Q2	Q1	Q0	X	Q2+	Q1+	Q0+	J2	K2	J1	K1	J0	K0	Z
0	0	0	0	1	0	0	1	X	0	X	0	X	0
0	0	0	1	0	0	1	0	X	0	X	1	X	0
0	0	1	0	1	0	1	1	X	0	X	X	0	0
0	0	1	1	0	1	0	0	X	1	X	X	1	0
0	1	0	0	1	1	0	1	X	X	0	0	X	0
0	1	0	1	0	1	1	1	0	X	X	0	1	X
0	1	1	0	1	1	1	1	1	X	X	0	X	0
0	1	1	1	1	0	0	0	0	X	X	1	X	0
1	0	0	0	0	0	0	0	X	1	0	X	0	X
1	0	0	1	1	1	0	1	X	0	0	X	1	X
1	0	1	0	0	0	0	1	X	1	0	X	X	0
1	0	1	1	1	1	1	0	X	0	1	X	X	1
1	1	0	0	0	0	1	0	X	1	X	0	0	X
1	1	0	1	1	1	1	1	X	0	X	0	1	X
1	1	1	0	0	0	1	1	X	1	X	0	X	0
1	1	1	1	0	0	1	1	X	1	X	0	X	0
1	1	1	1	1	1	0	0	X	0	X	1	X	0