Clamp Meter



Category: **Electrical & Electronic Test Instruments** Type: **Short SOP** Priority: **Medium**

10 labs

Covers these lab items: Clamp-meter; Tong tester AC/DC

What it is used for

Use a clamp meter to measure current without disconnecting a conductor, and measure other electrical values when supported by the meter.

How to use

1. Inspect the meter, clamp jaws, leads, probes, and display for damage.
2. Select the correct measurement function, range, and AC or DC mode as required.
3. Clamp around a single conductor only when measuring current.
4. Close the jaws fully and keep the conductor centered where possible.
5. Read the stable value and note the unit shown on the display.
6. Use test leads only in the correct sockets and only for supported measurements.
7. Remove the meter safely and switch it off after testing.

⚠ Safety

- Use a meter with a suitable CAT rating and voltage rating for the circuit.
- Never clamp around both live and return conductors together for current measurement.
- Do not use damaged leads or touch exposed metal probe tips.
- Follow electrical isolation and PPE requirements for the work area.

Care & storage

- Keep the clamp jaws clean and free of debris.
- Store the meter and leads in a dry protective case.

Disclaimer: This SOP is prepared from general information available on the internet. For detailed instructions, refer to the manufacturer's original manual / file.