# Tachometer




Category: **Electrical & Electronic Test Instruments** Type: **Short SOP** Priority: **Medium**

7 labs

**Covers these lab items:** Laser Tachometer; Tachometer

## What it is used for

Use a tachometer to measure the rotational speed of a compatible rotating shaft, wheel, or machine component.

## How to use

1. Inspect the tachometer, sensor, display, and accessories for damage.
2. Select the correct measurement mode and units according to the instrument manual.
3. For a laser tachometer, apply a suitable reflective mark to the stopped target if required.
4. Position the sensor at the specified distance and angle for the instrument type.
5. Keep clear of rotating parts and take the reading according to the manufacturer's procedure.
6. Record the stable speed value and units shown on the display.
7. Switch off the instrument and remove any temporary reflective mark if appropriate.

## ⚠ Safety

- Never touch or approach rotating machinery while taking a measurement.
- Do not aim a laser at anyone's eyes.
- Install reflective tape only when the machine is stopped and safely isolated.
- Use suitable guards and follow site machine-safety procedures.

## Care & storage

- Clean the sensor and display with a suitable soft cloth.
- Store the tachometer in its case and protect it from dust and impacts.

*Disclaimer: This SOP is prepared from general information available on the internet. For detailed instructions, refer to the manufacturer's original manual / file.*