
PINS


- IN1-4 MxPWMy (4) PD0, PD1, PC4, PC5
- ~~Sleep~~ GPO (1) PE3
- PT_OUT GPI (2) PF3, PF4
- IR_OUT WTxCCP0 (1) PD3
- PIR_OUT GPI PA7
- TRIG [1] GPO PE2
- Echo [1] WTxCCP0 PD6


Donot use PD0 PB6 PD1 PB7

PA 1:0
PA 5:2
PB 3:2
PD C:7
PF 0
P [3:0]









#Notes

Pins

- In 1-4 MxPwMy (4)
- ~~Sleep~~ GPO → Any general purpose, dont use weird (1)
  ↑ active Low
- PT_OUT GPI (edge int) (2)
- IR OUT PWT_x CCPO
- PIR_OUT GPI (Input)
- TRIG [T] GPO (output)
- Echo [T] WT_n CCPO (ultrasonic)







Photo sensor for wheels





Infared module



Do not use PD0 + PB6

Table 10-1 Pin with special