

	Risk Management, Production & Post-Production Review, SILQ		Doc No.: RM-0094
	<i>This document contains confidential, proprietary information of Pathway Innovation LLC and shall not be copied or reproduced without prior written permission there from. If any portion of this document is in hardcopy form, it must be considered and treated as an uncontrolled. Users of this document must verify that they are using the most current revision of the controlled document before performing work</i>		Rev.: A
			Page 1 of 3

1.0 Purpose

- 1.1 To provide the results of the risk management production and post-production review for the SILQ 2-way Cleartract Foley Catheters.

2.0 Scope

- 2.1 Applies to the SILQ catheter for the period of April 2020 to Feb 2023.

3.0 References

- 3.1 QP-004 – Risk Management
- 3.2 RM-0018 – Risk Management Plan, SILQ ClearTract Foley Catheter
- 3.3 RM-0019 – Risk Management Report, HA, SILQ ClearTract Foley Catheter
- 3.4 RM-0020 – Risk Management Report, DFMEA, SILQ ClearTract Foley Catheter
- 3.5 RM-0021 – Risk Management Report, PFMEA, SILQ ClearTract Foley Catheter

4.0 Results & Discussion

4.1 Complaints

- 4.1.1 Since this is the first review, all reported complaints were included in this review. A review of the complaint log shows there has only been 1 complaint in 2021 since the product was introduced into the market in 2020. The issue reported was that the catheter would not stay in place as a result of the balloon rupturing. It was determined that the clinician over inflated the balloon from what was labeled on the product.

- 4.1.2 There is an existing failure mode incorporated in the referenced risk management documents for this issue.

11	User Error (Operational)	11.1	Procedure complication – device inoperative	Delay in treatment	1	Catheter dislodges for patient – insufficient balloon inflation	Warning and limitations statements (Information) Define balloon fill volume	IFU SLQ-4006	2	2	N/A	N/A	N/A
		11.2	Partial / leaking connection to drain bag	Rash/Infection – Skin	2	Inadequate connection with collection bag	Product instruction for connection	IFU SLQ-4006	2	4	N/A	N/A	N/A
		11.3	Unskilled/ untrained clinician	Patient discomfort	2	Clinicians – does not read some or all information in IFU	Product labeling will clearly state to read the IFU prior to performing clinical application (Information)	Product Labeling SLQ-4000, SLQ-4001, SLQ-4006	2	4	N/A	N/A	N/A
							Warning and limitations statements (Information)	IFU SLQ-4006					
					3	Balloon not deflated or partially deflated during removal	Warning and limitations statements (Information)	IFU SLQ-4006	2	6	N/A	N/A	N/A
					3	Excessive tensile – Catheter not secure, weight of collection bag pulls on catheter	Warning and limitations statements (Information)	IFU SLQ-4006	2	6	N/A	N/A	N/A
					2	Balloon burst - excessive balloon inflation	Warning and limitations statements (Information) Define balloon fill volume	IFU SLQ-4006	2	4	N/A	N/A	N/A

Figure 1: Risk identified from HA refer to RM-0019

	Risk Management, Production & Post-Production Review, SILQ		Doc No.: RM-0094
	This document contains confidential, proprietary information of Pathway Innovation LLC and shall not be copied or reproduced without prior written permission there from. If any portion of this document is in hardcopy form, it must be considered and treated as an uncontrolled. Users of this document must verify that they are using the most current revision of the controlled document before performing work		Rev.: A
			Page 2 of 3

3	Balloon inflates to secure catheter in place	Balloon leaks / deflates	2	Procedural Complication – Catheter dislodges	Wall thickness	Design follows standard ASTM F623	TR-0072, TR-HDX-0001 (Balloon Volume Maintenance)	1	2	2	4	N/A	N/A	N/A	N/A	N/A
					Performance degrades over time	Material Selection (Design)	Stability Evaluation TR-0073									
		Balloon won't inflate	1	Procedural Complication – No patient harm	Wall thickness	Design follows standard ASTM F623	TR-0072, TR-HDX-0001 (Balloon Volume Maintenance)	1	2	2	2	N/A	N/A	N/A	N/A	N/A
					Performance degrades over time	Material Selection (Design)	Stability Evaluation TR-0073									

Figure 2: Risk identified from DFMEA refer to RM-0020

4	Balloon forming / dipping	Incomplete / Malformed Balloon	3	Non-Functional Device / Balloon Burst	Operator Error	Supplier Qualification, Receiving Inspection In-Process Inspection	Ningbo Yingmed Catheter Inspection Plans (Form) HDX-6XXX SLQ-6XXX	1	2	2	6	N/A	N/A	N/A	N/A	N/A
---	---------------------------	--------------------------------	---	---------------------------------------	----------------	--	---	---	---	---	---	-----	-----	-----	-----	-----

Figure 3: Risk Identified from PFMEA, refer to RM-0021

4.2 Nonconforming Product

4.2.1 Since this is the first review, all nonconformance reports were included in this review. Five non-conformance reports occurred, which are indicated in the following table:

Table 1: NCR Summary

NCR No	Part No	NCR Description
21-0006	HDX-8006	No PCD (BIs) attached to these 5 lots when they should have before sent to sterilization.
21-0007	HDX-8006	Date printed on labels in incorrect format.
21-0011	SLQ-6004	Text printed on catheters were illegible, missing information, smudged and contained duplication defects.
22-0009	SLQ-6000	CofA insufficient, bad print on 2 samples
22-0010	SLQ-6002	CofA insufficient, particulates on one sample, bad print on one sample

4.2.2 These non-conformances are indicated as failure modes in referenced risk management documents.

Table 2: NCR Summary correlated with Identified Risks

NCR No	Risk Doc No.	Risk Identification / Failure Mode
21-0006	RM-0021	#14 Sterilization / No BI's Placed
21-0007	RM-0021	#7 Labeling / Incorrect Print Information
21-0011	RM-0021	#6 Catheter Size Printing / Illegible
22-0009	RM-0021	#6 Catheter Size Printing / Illegible
22-0010	RM-0021	#6 Catheter Size Printing / Illegible

	Risk Management, Production & Post-Production Review, SILQ	Doc No.: RM-0094
	<i>This document contains confidential, proprietary information of Pathway Innovation LLC and shall not be copied or reproduced without prior written permission there from. If any portion of this document is in hardcopy form, it must be considered and treated as an uncontrolled. Users of this document must verify that they are using the most current revision of the controlled document before performing work</i>	Rev.: A
		Page 3 of 3

- 4.2.2.1 Failure modes for documentation error and particulates are not identified in the PFMEA #1 receiving inspection risk. These failure modes will be added to the report.

4.3 Corrective Action

- 4.3.1 There were zero (0) CAPAs opened during this period associated with the finished device.

5.0 Conclusion

- 5.1 For the period indicated, production and post-production information was reviewed for SILQ 2-way Cleartract Foley Catheters and two new hazards were identified. The risk management ratings for the probability and detection are up-to-date and will remain unchanged.

6.0 Change History

Revision	Change Description
A	Initial release