

GD&T Cheat Sheet: Symbols

How a feature control frame is organized

	Tolerance	A	B	C
1	2	3		

1. Symbol 2. Tolerance value & modifiers 3. Datum references

Form

Straightness

Flatness

Circularity (Roundness)

Cylindricity

Orientation

Perpendicularity

Parallelism

Angularity

Location

Position

Concentricity

Symmetry

Profile

Profile of a line

Profile of a surface

Runout

Circular runout

Total Runout