


GD&T Cheat Sheet: Symbols

How a feature control frame is organized



1. Symbol 2. Tolerance value & modifiers 3. Datum references

Form

 Straightness

 Flatness

 Circularity (Roundness)

 Cylindricity

Orientation

 Perpendicularity

 Parallelism

 Angularity

Location

 Position

 Concentricity

 Symmetry

Profile

 Profile of a line

 Profile of a surface

Runout

 Circular runout

 Total Runout