

## **Technical Service Information**

## FORD AXOD FLARE ON 2-3 SHIFT

**COMPLAINT:** Flare or slip on 2-3 shift, or premature failure of direct clutches.

CAUSE: The cause may be a cracked direct clutch piston. For procedure to check the piston, see

Figure 1.

**CORRECTION:** Replace the direct clutch piston.

