

Technical Service Information

THM 440-T4 LOWER CHANNEL PLATE CHANGE

CHANGE: Additional feed hole for revised hydraulics.

REASON: Elimination of governor oil and addition of drive servo apply oil and manual 2-1 servo oil

passages.

PARTS AFFECTED:

New gasket has revised feed hole locations to accommodate channel plate and case changes

(FIGURE 1).

INTERCHANGEABILITY:

The "'4T60" gasket WILL interchange with the "4T60-E" gasket.




Figure 1