

Technical Service Information

FORD AOD "SQUAWK" ON 2-3 SHIFT

COMPLAINT: Clutch noise or "Squawk" on the 2-3 shift, in 1989 models only.

CAUSE: In 1989 there was a new design stamped steel direct clutch housing (See Figure 1)

introduced, that creates the noise.

CORRECTION: Install the previous design cast steel direct clutch housing.

