

THM 440-T4 INPUT CLUTCH ACCUMULATOR ELIMINATED

CHANGE: The Input Clutch Accumulator has been eliminated from the channel plate (See Figure

1).

A "Wave" plate was added to the input clutch pack. **REASON:**

PARTS AFFECTED: (1) CHANNEL PLATE - The input clutch accumulator piston, piston pin, and

accumulator spring have been eliminated from the channel plate, which also changes

the casting (See Figure 1).

(2) **INPUT HOUSING** - Top snap ring groove moves ,060" closer to the top of the

input housing, to 1 ccommodate the added wave plate (See Figure 2).

(3) INPUT CLUTCH STEEL PLATES - The steel plates are ,027" thinner to 1

ccommodate the added wave plate (See Figure 3). The new steel plates are,049" thick, and the old steel plates are ,076" thick.

(4) INPUT CLUTCH "STACK" - The input clutch stack has been revised to accommodate the new changes. Refer to Figure 3 for proper assembly of the new input

clutches.

BOTH PRESSURE PLATES AND FOUR LINED PLATES REMAIN THE

SAME AS PREVIOUS MODELS WITH NO DIMENSIONAL CHANGES.

INTERCHANGEABILITY:

Not recommended to interchange with previous models.






Figure 1
AUTOMATIC TRANSMISSION SERVICE GROUP






Figure 2
AUTOMATIC TRANSMISSION SERVICE GROUP






Figure 3